

20082001

ASS. REC. BY:

REF: CS3/AIG 19015265 / FC 9302

Special Instruction:

Surveyor: Ran

ASSIGNMENT (Office)

Wijman

From (Person): Chin Lee Yng of AIG Date/Time: 29.8.19 1:03 pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 4297U Insured: GBG 80052

at Workshop m/s Carparts Pte LTD Tel: 9722 7833

of 160 Sin Ming Drive #05-18

Policy No: 0999994235 Claim No: 5218042330SG

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 25.8.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

wp1

Date/Time: 29.8.19 1:22 pm Person Contacted: Kevin H.O.D. Endorsement: \_\_\_\_\_

Vehicle: IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	GBG 80052 X
	SJW 4297U X



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019 <a href="#">Edit Reg</a>		29 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>AIK CHIN HIN MACHINERY CO</b> , Co. Reg. No.: 20030400C								
Main Claimant:	<b>CARFEELS PTE LTD</b>								
Vehicle Reg. No.:	<b>SJW4297U</b>	Date of Loss:	25/08/2019 00:00 - :59						
Claim Type:	<b>TP / 5218042330SG</b>	Policy/Cover Note No.:	0999994235 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBG8005Z</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Carfeels Pte Ltd - Sin Ming (HQ)</b> BLK 160 SIN MING DRIVE, #05-18 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 09/09/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
• AIG_SG (02/09/2019): TP GIA REPORT									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBG8005Z AND SJW4297U ON 25/08/2019

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: Thursday, 28 August, 2019 1:03:18 PM

Hi LKK,

Vehicle in workshop, kindly contact Kevin to arrange for survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Rachel Ling [<mailto:jin@tcmg.com.sg>]  
**Sent:** Wednesday, August 28, 2019 2:59 PM  
**To:** Lim, Sheng Yang  
**Cc:** 'Ling Leong Hui'; 'Jenny'; 'Mdm Ling'  
**Subject:** [EXTERNAL] PRE REPAIR INSPECTION NOTICE FOR SJW 4297 U | YOUR REF: GBG 8005 Z

This message is from an external sender; be cautious with links and attachments.

**Our Ref:** TCMG/SJW 4297 U/0819/CF  
**Your Ref:** GBG 8005 Z

Dear Sirs,

**PRE-REPAIR INSPECTION NOTICE**  
**ACCIDENT INVOLVING SJW 4297 U AND GBG 8005 Z ON 25 AUGUST 2019 ALONG TPE TOWARDS CHANGI NEAR TAMPINES AVENUE 12 EXIT**

We act for **Ark Global Enterprise Pte Ltd**, the owner and/or driver of motor vehicle no. **SJW 4297 U**, which was involved in an accident along TPE towards Changi near Tampines Avenue 12 exit on 25<sup>th</sup> August 2019 at 20:30 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **GBG 8005 Z** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Carfeels Pte Ltd, (Block 160 Sin Ming Drive #05-18, Sin Ming Autocity, Singapore 575722 - Kevin @ 9722 7833).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Regards,  
Rachel Ling

TOMMY CHOO, MARK GO LLC  
151 Chin Swee Road  
#14-15/16 Manhattan House  
Singapore 169876

Tel: 6532 2455  
Fax: 6538 9850

**IMPORTANT NOTICE**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 263D

#### Vehicle Details

Vehicle No.: SJW4297U  
Vehicle to be Exported: No  
Intended Deregistration Date: 30 Aug 2019  
Vehicle Make: VOLKSWAGEN  
Vehicle Model: PASSAT 1.8T AT 3C23H7  
Primary Colour: Brown  
Manufacturing Year: 2010  
Engine No.: CDA090044  
Chassis No.: WVVZZZ3CZAP033137  
Maximum Power Output: 118.0 kW (158 bhp)  
Open Market Value: \$31,058.00  
Original Registration Date: 24 Mar 2010  
First Registration Date: 24 Mar 2010  
Transfer Count: 1  
Actual ARF Paid: \$31,058.00 *< 30% \$15529*

#### Intended PARF Rebate Details

PARF Eligibility: Yes ✓  
PARF Eligibility Expiry Date: 23 Mar 2020  
PARF Rebate Amount: \$15,529.00

#### Intended COE Rebate Details

COE Expiry Date: 23 Mar 2020  
COE Category: B - Car (1601cc & above)  
COE Period(Years): 10  
QP Paid: \$23,180.00  
COE Rebate Amount: \$1,302.00  
Total Rebate Amount: \$16,831.00

The information contained herein is correct as at 30 Aug 2019

*Remaining months of COE: 6 months 29 days (6.9 months) OK*

*Depr: \$8000/yrly (\$666.66/monthly)*

$$6.9 \times \$666.66 = \$4599.95$$

$$\begin{aligned} \$4599.95 + \$15529 &= \$20128.95 \\ &\underline{\hspace{1.5cm}} \\ &= \$22,000 \end{aligned}$$

**SELL YOUR CAR TODAY**  
List car till sold & let us handle the paperwork.



POST AN AD

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Best Condition! 1 owner! 1 yr Warranty!



1 owner, fantastic condition  
Must Sell! View to appreciate  
and negot!  
A Star Motors - Starfish

Republic Auto | CERTIFIED PRE-OWN  
MERCEDES BENZ

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 20 re

13 vehicles

Volkswagen Passat

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
<b>Search Selection</b> Volkswagen Passat	Any	Any	2010	Any	Any	Any
 <b>Volkswagen Passat CC 2.0A TSI Sunroof</b>	-	N.A	26-Aug-2010	1,984 cc	-	Luxury
Consignment Unit! Guarantee Buy Back At \$20k, Reliable Drive And Easy To Maintain! High Loan And Low Interest Rates/Balloon Scheme Available! High Trade In! Call Now To Arrange For Viewing!						
Car Empire Automobiles Pte Ltd						
Posted: 26-Aug-2019 Tags: 2010 Volkswagen Passat, 2010 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen						
 <b>Volkswagen Passat CC 2.0A TSI Sunroof</b>	<b>\$28,888</b>	N.A	06-Jan-2010	1,984 cc	198,000 km	Luxury
Car In Good Condition. Able To Renew Another 10 Years. LTA Approved Wrap.						
Posted: 20-Aug-2019 Tags: 2010 Volkswagen Passat, 2010 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen						
 <b>Volkswagen Passat CC 1.8T</b>	<b>\$20,000</b>	N.A	04-Jan-2010	1,798 cc	148,500 km	Luxury
Road Tax Paid Till 03/01/2020, Great Original Sound System, Interior LED Multi Colour Lighting, Good Fuel Consumption For 1.8 Turbo (About 10-12 Km/L, Up To 15km/L Without Aircon), Everything In Good Condition Especially Engine, Bigand Spacious Look Like A 2 Litre...						
Posted: 14-Aug-2019 Tags: 2010 Volkswagen Passat, 2010 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen						
 <b>Volkswagen Passat 1.8T</b>	<b>\$23,800</b>	<b>\$12,220 /yr</b>	07-May-2010	1,798 cc	106,768 km	Luxury
100% Loan Approval!Luxury Yet Sporty Sedan For Your Business And Family Leisure. Improved Engine Performance That Gives Good Road Holding, Safety And Comfortable.Owned By A Expatriate CEO Wife Who Used It Only For Weekend Family Leisure.Offer Deal! And...						
Car House Pte Ltd						
Posted: 10-Aug-2019 Tags: 2010 Volkswagen Passat, 2010 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen						
<b>GET YOUR COE RENEWAL LOAN</b>						
<b>Is your COE expiring? Let us help you renew it!</b>						
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.						
 <b>Volkswagen Passat CC 1.8T</b>	-	N.A	10-Nov-2010	1,798 cc	-	Luxury
100% Genuine Low KM Done! VW Specialist Workshop Receipts To Prove! Many Wear And Tear Parts Changed During These 3 Years! Mechatronic Changed Too! All Got Receipts To Prove! Amazing Condition For A 9 Years Old Car! Engine No Judder Or Vibration! Gearbox...						
Posted: 05-Aug-2019 Tags: 2010 Volkswagen Passat, 2010 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen						
<b>Volk</b>	<b>.8T</b>	-	N.A	24-Dec-2010	1,798 cc	Luxury
Compare	100% Lo	aintained, Low Mileage, Superb Condition, Just Serviced, Fuel Economy Car Suitable For Daily Usage,				



**UPLOAD A PHOTO**  
of your beloved car to Facebook  
& tag @mobillubes #askforMobil

**OR FOLLOW US**  
on Lazada

Flash it at our booth to  
redeem a token to play  
F1 Red Bull Simulator!



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Lexus LS350 Luxury MR at \$329,800.



5Yrs Warranty by Normal Users,  
Very Low Mileage, Immaculate  
Condition, Call Now!  
Speedo Motoring Station

**PRIME MOTOR & LEASING**

JOINING YOUR CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.



Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Volkswagen Passat

Advanced Search

Image	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	<b>Search Selection</b>	Volkswagen Passat	Any	Any	2011	Any	Any	Any	Available
	Volkswagen	Passat CC 1.8T	\$30,888	\$11,610 /yr	01-Jan-2011	1,798 cc	-	Luxury	Available
Consignment Unit, Recently Overhaul From Volkswagen Warranty Till 11/2020.view At Phoenix Motor Trading Enterprise									
Posted: 27-Aug-2019 Tags: 2011 Volkswagen Passat, 2011 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen									
	Volkswagen	Passat CC 1.8T	\$37,777	\$11,490 /yr	26-Jul-2011	1,798 cc	70,000 km	Luxury	Available
Lowest Dep! Lowest Mileage! Powerful, Stylish, Spacious To Fit Your Family Size. Non Smoker Unit, Serviced Regularly Without Fail. Really Well Taken Care By Previous Owner. View To Believe! Trade In/Scrap Available, Call Us For A Non Obligatory Viewing Now! By Appointm...									
Posted: 22-Aug-2019 Tags: 2011 Volkswagen Passat, 2011 volkswagen passat, volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen									
	Volkswagen	Passat 1.8A TSI	\$55,000	\$24,830 /yr	15-Apr-2011	1,798 cc	72,265 km	Luxury	Available
Turbo.									
Posted: 21-Aug-2019 Tags: 2011 Volkswagen Passat, 2011 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen									
	Volkswagen	Passat CC 1.8A TSI	\$30,800	\$10,930 /yr	27-Jan-2011	1,798 cc	110,644 km	Luxury	Available
1 Owner Affected By TDSR In 2013, Husband To Wife Transfer. Full Service Records By VW Since Day 1, Owner Bought Servicing Package In 2018 Too. Cond is Superb, Zero Things Require To Be Done. Test Drive To Believe! Owner Consignment, Car With Owner. Call Now T...									
Posted: 11-Aug-2019 Tags: 2011 Volkswagen Passat, 2011 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen									
<b>GET YOUR COE RENEWAL LOAN</b>									
Is your COE expiring? Let us help you renew it!									
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Volkswagen	Passat 1.8A TSI	\$29,000	\$8,390 /yr	16-May-2011	1,798 cc	124,531 km	Luxury	Available
Serviced And Maintained By SKM Motor, Well Maintained Condition, Trade In, Flexible Loan Available, Viewing Strictly By Appointment Only.									
360 VR Cars									
Posted: 09-Aug-2019 Tags: 2011 Volkswagen Passat, 2011 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen									

511610  
↓  
\$3390

Save this search criteria, to get email alerts whenever a match is found.

Model Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	28/08/2019 11:21
Date Of Accident	25/08/2019 20:30
Exact Location Of Accident	TPE TOWARDS CHANGI NEAR TAMPINES AVE 12 EXIT
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW4297U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ARK GLOBAL ENTERPRISE PTE LTD
Co Reg No	201327263D
Email Address	CASS@ARK-INTERNATIONAL.BIZ
Mobile Phone No	
Alternative Phone No	OFFICE-93210914

#### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100204318-01
Cover Note Number	

#### Driver

Name of Driver	YUSNI BIN ABD RAHMAN
NRIC No	S1589458Z
Date Of Birth	05/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	27/08/1991
Driving Experience	27 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93210914
Fax Number	
Contact Number	OFFICE-93210914
EMail Address	LAWAN1BY1@YAHOO.COM

Address	APT BLK 224C SUMANG LANE #06-97 SINGAPORE
Postcode	823224
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	<b>ROAD:</b> 10 UBI AVENUE 3 , <b>POSTCODE:</b> 408865 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 65470000 - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG8005Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	FONG SOON TAT
NRIC/Passport Number	402996412
Contact Number	86182216
Address	
Postcode	
Insurance Company Name	

Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJV6667C  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver UDAI SHANKER DUBEY  
NRIC/Passport Number S8711605J  
Contact Number 81553957  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number NA  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SMF3294M  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name YUSNI BIN ABD RAHMAN  
Approximate Age 56  
Injuries Sustain REFER POLICE REPORT  
Injured person in which vehicle? SJW4297U  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES



Address

APT BLK 224C SUMANG LANE  
#06-97 SINGAPORE

Postcode

823224

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\*   
\_\_\_\_\_  
Policyholder's Signature  
Date & Time: 27 Aug 2017  
1:57

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:





**SINGAPORE  
POLICE FORCE**



T/20190826/2125

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20190826/2125

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 26/08/2019 16:30		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: YUSNI BIN ABD RAHMAN			Address: 224C SUMANG LANE #06-97 MATILDA EDGE SINGAPORE 823224		
ID Type / ID No.: NRIC NO / S1589458Z			Contact No.:		Mobile: 93210914
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 05/07/1963	Type of Informant: Driver		
Race:		Language:		Institution / School Name:	
Occupation: OTHERS		Driving Licence Information: Class: 2B,3		Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/08/2019 20:30	Type of Location:
Location: Along Road 1 TAMPINES EXPRESSWAY				
TAMPINES EXPRESSWAY TOWARDS CHANGI AIRPORT NEAR TAMPINES AVENUE 12 EXIT.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision:				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBG8005Z	Lorry				Slightly Damaged	0
SJW4297U	Car				Seriously Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190826/2125

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190826/2125

## CONTINUATION OF REPORT

Driver: <input type="checkbox"/>			
Name	YUSNI BIN ABD RAHMAN		ID No. S1589458Z
Related Vehicle	SJW4297U (Car)		Contact No. 93210914
Hospital/Clinic	CHANGI GENERAL HOSPITAL		Class of Driving Licence & Expiry Date Class: 2B,3 Date of Expiry: NIL
Date Treatment	25/08/2019	Date Discharge	25/08/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Vehicle Owner			
Name	FONG SOON TAY		ID No. NIL
Related Vehicle	NIL		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

AT THE ABOVEMENTIONED DATE AND TIME.

AT AROUND 8.30PM I WAS TRAVELLING ALONG TPE TOWARDS CHANGI AIRPORT. I WAS ON THE FIRST LANE GOING TOWARDS TAMPINES AVE 12 EXIT. I WAS 20 METRES AWAY. I SAW A CAR INFRONT OF ME APPLIED HIS BRAKES AND I APPLIED MINE AS WELL. AT ABOUT 5 METRES AWAY HE APPLIED A JAM BRAKE WHICH I DID AS WELL I MANAGED TO STOP INCHES AWAY FROM THE CAR. A SPLIT SECOND LATER A LORRY HIT ME HARD FROM BEHIND AND I REBOUNDED AGAINST MY SEALBELT WHICH CAUSED ME TO LURCH FORWARD AND HIT THE CAR INFRONT OF ME. I STEPPED OUT OF MY CAR. I REALIZED I WAS IN A 5 CAR PILE UP.

THAT IS ALL.



SINGAPORE  
POLICE FORCE



T/20190826/2125

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000


3 of 3  
Report No. T/20190826/2125

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: TP / MUHAMMAD MOINUR RAHMAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 26/08/2019 16:30
Officer In Charge Of Case: TP / GIT / Insp TAN CHIN YONG Contact No.: 65476178	Classification Of Case: 
Authentication Stamp NP168	Signature: 



### MOTORCAR (Rear)

#### Rear Partion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	MIS	/	
1138	993627	Rear Number Plate Base	MIS	/	
1139	993630	Rear Number Plate Garnish	MIS	/	
1140	993632	Rear Number Plate Lamp	CRA	/	2
1141	992958	Rear Bumper	CRA	/	
1142	993085	Rear Bumper Upper		/	
1143	993017	Rear Bumper Lower	CRA	/	
1144	993054	Rear Bumper Side		/	
1145	993103	Rear Bumper Tow Cover	BR	/	
1146	992341	Rear Bumper Clips	NCC	/	6
1147	992976	Rear Bumper Bracket	NCC	/	2
1148	993068	Rear Bumper Side Retainer	NCC	/	
1149	993045	Rear Bumper Reinforcement	DD	/	
1150	992970	Rear Bumper Beam		/	
1151	993077	Rear Bumper Sponge	CRA	/	
1152	992999	Rear Bumper Damper		/	
1153	993040	Rear Bumper Protector		/	
1154	993036	Rear Bumper Pad		/	
1155	993026	Rear Bumper Moulding	CHROME BR	/	2
1156	993044	Rear Bumper Reflector		/	
1157	993023	Rear Bumper Lower Spoiler		/	
1158	994023	Reverse Sensor	SWITCH	/	
1159	993327	Rear End Panel	BUC	/	
1160	993339	Rear End Panel Top Garnish	CRA	/	
1161	993333	Rear End Panel Inner Trim		/	
1162	990333	Boot Compartment Inner Trim		/	
1163	993851	Rear LH Taillamp	BR	/	
1164	993853	Rear LH Taillamp Garnish		/	
1165	993859	Rear LH Taillamp Panel	BUC	/	
1166	995116	Rear RH Taillamp	BR	/	
1167	993853	Rear RH Taillamp Garnish		/	
1168	993859	Rear RH Taillamp Panel	BUC	/	
1169	993554	Rear Apron Panel		/	
1170	992895	Bootlid	BUC	/	
1171	991328	Bootlid Emblem	LH	/	3
1172	990356	Bootlid Handle	FLORO	/	
1173	995250	Bootlid Moulding	SC	/	
1174	990376	Bootlid Reflector		/	
1175	995222	Bootlid Lamp LH	BR	/	
1176	992899	Bootlid Lamp RH	BR	/	
1177	995243	Bootlid Lock	SC	/	
1178	990377	Bootlid Rubber	DD	/	2
1179	990382	Bootlid Hinge	BR	/	
1180	993877	Bootlid Spoiler		/	
1181	994543	Tailgate		/	
1182	991328	Tailgate Emblem		/	
1183	994643	Tailgate Outer Handle		/	
1184	994640	Tailgate Moulding		/	
1185	994545	Tailgate Garnish		/	
1186	994648	Tailgate Reflector		/	
1187	994549	Tailgate Lamp		/	
1188	994646	Tailgate Protector		/	
1189	994676	Tailgate Wiper Arm		/	
1190	994677	Tailgate Wiper Blade		/	
1191	994679	Tailgate Wiper Nozzle		/	
1192	994555	Tailgate Wiper Motor		/	
1193	994602	Tailgate Glass		/	
1194	994606	Tailgate Glass Rubber		/	
1195	994604	Tailgate Glass Moulding		/	
1196	994607	Tailgate Glass Sealant		/	
1197	994629	Tailgate Lock		/	
1198	994651	Tailgate Rubber		/	
1199	994611	Tailgate Hinge		/	
1200	994594	Tailgate Damper		/	
1201	994613	Tailgate Inner Board		/	

Vehicle No: SJW42971

NAC	INC	Item	CON	A
1202	993784	Spare Tyre Board	BR	7
1203	994328	Spare Tyre Panel	FLC	
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim	CRA	
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender		
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel	DD	2
1231	993431	Rear RH Fender Inner Trim	CRA	
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993401	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Aug 2019 <a href="#">Edit Reg</a>		29 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$90.00</b> <a href="#">Edit Estimates</a>	<b>\$90.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float:right">[Created by adjuster]</span>									
Insured:	AIK CHIN HIN MACHINERY CO, Co. Reg. No.: 20030400C								
Main Claimant:	CARFEELS PTE LTD								
Vehicle Reg. No.:	SJW4297U	Date of Loss:	25/08/2019 00:00 - :59 [113 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5218042330SG	Policy/Cover Note No.:	0999994235 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBG8005Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Carfeels Pte Ltd - Sin Ming (HQ) BLK 160 SIN MING DRIVE, #05-18 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 09/09/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float:right"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (02/09/2019): TP GIA REPORT									
<b>ALL ASSOCIATED TASKS</b> <span style="float:right"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJW4297U (5218042330SG)  
[GBG8005Z]  
TP  
CARFEELS PTE LTD  
Aug 25 2019 12:00AM  
[AIK CHIN HIN MACHINERY CO]  
Carfeels Pte Ltd - Sin Ming

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
<b>Assessment Reports</b>											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print			
1	02/09/19 11:15	<b>Accident Statement</b> From: OD - Reg. No: GBG8005Z, Claimant: AIK CHIN HIN MACHINERY CO							Load HTML			
<b>Photos/Images</b>											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
2	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
3	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
4	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
5	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
6	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
7	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
8	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
9	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
10	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
11	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
12	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
13	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
14	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
15	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
16	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
17	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
18	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
19	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
20	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
21	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
22	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
23	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
24	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
25	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
26	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
27	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
28	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
29	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
30	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
31	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
32	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
33	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
34	29/08/19 17:57	General View							Load JPG <input checked="" type="checkbox"/>			
35	03/09/19 10:58	General View							Load JPG <input checked="" type="checkbox"/>			
36	03/09/19 10:58	General View							Load JPG <input checked="" type="checkbox"/>			
37	03/09/19 10:58	General View							Load JPG <input checked="" type="checkbox"/>			
38	03/09/19 10:58	General View							Load JPG <input checked="" type="checkbox"/>			
39	03/09/19 10:58	General View							Load JPG <input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
40	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
41	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
42	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
43	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
44	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
45	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
46	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
47	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
48	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
49	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
50	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
51	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
52	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
53	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
54	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
55	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
56	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
57	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
58	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
59	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
60	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
61	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
62	03/09/19 10:58	General View		<input checked="" type="checkbox"/>
63	03/09/19 10:58	General View		<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG19015265/FCF3E2

**Date:** 18/09/2019

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994235
<b>Claimant</b>		
<b>Vehicle No :</b> SJW4297U	<b>Insured Vehicle No :</b>	GBG8005Z
Date of Loss: 25/08/2019	Nature of Claim: TP	Claim No: 5218042330SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJW4297U</b>	Engine No:	CDA090044
Make & Model:	VOLKSWAGEN PASSAT, 1.8 T (B5) (A)	Chassis No:	WWWZZZ3CZAP033137
Reg. Date:	24/03/2010 (Man. Year: 2010)	Odometer:	277599 km
Colour:	Brown		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	29/08/2019	
Date Inspected:	29/08/2019 Inspected At:	Carfeels Pte Ltd - Sin Ming (HQ) BLK 160 SIN MING DRIVE, #05-18 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	12.0 days	

**Adjuster:** PARASURAM SHANMUGAM

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Buckled	0.00 F	*-F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*-F
3	1		*FRT NUMBER PLATE GARNISH	Cracked	0.00 F	*-F
4	1		*FRT BUMPER	Cracked	0.00 F	*-F
5	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
6	2		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
7	1		*FRT BUMPER BEAM	Dented	0.00 F	*-F
8	1		*FRT BUMPER SPONGE	Broken	0.00 F	*-F
9	2		*FRT BUMPER SIGNAL LAMP	* Check	0.00 F	*-F
10	1		*FRT BUMPER GRILLE (CHROME)	Cracked	0.00 F	*-F
11	1		*FRT BUMPER LOWER SPOILER	* Check	0.00 F	*-F
12	1		*FRT BUMPER SENSOR	Shorted	0.00 F	*-F
13	1		*FRT LH BUMPER FOG LAMP COVER	* Check	0.00 F	*-F
14	1		*FRT RH BUMPER FOG LAMP COVER	Crumpled	0.00 F	*-F
15	1		*FRT LH BUMPER FOG LAMP	* Check	0.00 F	*-F
16	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*-F
17	1		*FRT GRILLE	Cracked	0.00 F	*-F
18	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
19	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*-F
20	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
21	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Distorted	0.00 F	*-F
22	1		*FRT LH HEADLAMP ASSY	* Check	0.00 F	*-F
23	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*-F
24	1		*BONNET	Repair	0.00 F	*-F
25	1		*BONNET LOCK	* Check	0.00 F	*-F
26	1		*BONNET HINGE	* Check	0.00 F	*-F
27	1		*AIR CON CONDENSER	* Check	0.00 F	*-F
28	1		*RADIATOR	* Check	0.00 F	*-F
29	1		*FRT WINDSCREEN GLASS	Cracked	0.00 F	*-F
30	1		*FRT WINDSCREEN MOULDING	Necessary	0.00 F	*-F
31	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*-F
32	1		*ERP BRACKET	Necessary	0.00 F	*-F
33	1		*STEERING WHEEL AIRBAG	Dislodged	0.00 F	*-F
34	1		*STEERING WHEEL AIRBAG SENSOR	Necessary	0.00 F	*-F
35	1		*DASHBOARD AIRBAG	Dislodged	0.00 F	*-F
36	1		*DASHBOARD AIRBAG SENSOR	Necessary	0.00 F	*-F
37	1		*AIRBAG CONTROL UNIT	* Check	0.00 F	*-F
38	1		*FRT RH SEAT BELT ASSY	Jammed	0.00 F	*-F
39	1		*FRT LH SEAT BELT ASSY	Jammed	0.00 F	*-F
40	1		*REAR NUMBER PLATE	Missing	0.00 F	*-F
41	1		*REAR NUMBER PLATE BASE	Missing	0.00 F	*-F
42	1		*REAR NUMBER PLATE GARNISH	Missing	0.00 F	*-F
43	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*-F
44	1		*REAR BUMPER	Cracked	0.00 F	*-F
45	1		*REAR BUMPER LOWER	Cracked	0.00 F	*-F
46	1		*REAR BUMPER TOW COVER	Broken	0.00 F	*-F
47	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
48	2		*REAR BUMPER BRACKET	Necessary	0.00 F	*-F
49	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
50	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*-F
51	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*-F
52	2		*REAR BUMPER MOULDING CHROME	Broken	0.00 F	*-F
53	1		*REVERSE SENSOR	Shorted	0.00 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*REAR END PANEL	Buckled	0.00 F	*. F
55	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*. F
56	1		*REAR LH TAILLAMP	Broken	0.00 F	*. F
57	1		*REAR LH TAILLAMP PANEL	Buckled	0.00 F	*. F
58	1		*REAR RH TAILLAMP	Broken	0.00 F	*. F
59	1		*REAR RH TAILLAMP PANEL	Buckled	0.00 F	*. F
60	1		*BOOTLID	Buckled	0.00 F	*. F
61	3		*BOOTLID EMBLEM	Cracked	0.00 F	*. F
62	1		*BOOTLID HANDLE + LOGO	Short Circuit	0.00 F	*. F
63	1		*BOOTLID LAMP LH	Broken	0.00 F	*. F
64	1		*BOOTLID LAMP RH	Broken	0.00 F	*. F
65	1		*BOOTLID LOCK	Short Circuit	0.00 F	*. F
66	1		*BOOTLID RUBBER	Dented	0.00 F	*. F
67	2		*BOOTLID HINGE	Bent	0.00 F	*. F
68	1		*SPARE TYRE BOARD	* Check	0.00 F	*. F
69	1		*SPARE TYRE PANEL	Buckled	0.00 F	*. F
70	1		*REAR LH FENDER INNER TRIM	Cracked	0.00 F	*. F
71	1		*REAR RH FENDER INNER PANEL	Repair	0.00 F	*. F
72	1		*REAR RH FENDER INNER TRIM	Cracked	0.00 F	*. F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >