ASS. REC. BY: | REF:

ASSIGNMENT

CDE 2023 May

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FW 7741 G Yr Regn: 2003 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda NF 125 c.c 125

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 9338 T/Radio: Insured / Std / NI / NA

Eng/No: NF125MDE0067422

C/No: NF125MD0067422

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90 R17

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Maxxis

Front		Rear	
R/Bal.	3 mm	R/Bal.	3 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 19/08/2019 D.O.I. 29/08/2019

Survey held at SG 98 Motor AMK

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear 4 H/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AXA SMC 5166L
	MV 4.2K
	LTA 666.00
	HL 3.5K

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:	
Transportation:	
__S + RS.__SI	
Photos	
Others	
TOTAL	