

10/00000

INS. CASE OWNER:

PLTIV

CC 4 ASM 5296, D9689

LKK
IDAC:

Surveyor:

Bryan

DOI:

ASSIGNMENT

29/8/19

Date / Time:

29/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5166L

Name of Insured:

TRAMS - LAB SERVICES P/L

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

19/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

FOO SRY MWI

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

89M02X7E(174285

Policy No.:

VFX / P1690320

Make / Model:

RENAVIT

Place of Accident:

Holland Rd.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

FW 37419



INSRS:
WSP: 59 98
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

29/8

liability nuclear send TP - CRG AVF / email cot. (req AVF).

23/10/2019

jump 45 2900/- with 4 days

17/8

liability email send TP - TP INVOICES 01/8

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5 2100.00 (4 days) Reduction: 1867.90 % 79.

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

(\$ x days)

Loss of Income (LOI):

\$5

(\$ x days)

LOB only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ASSIGNMENT

08E 2023 May

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FW7741G

Yr Regn:

2003 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda NF 125

c.c.

125

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp Reading

9338

T/Radio:

Insured / Std / NI / NA

Eng/No:

NF125HDE.0067422

C/No:

NF125MD0067422

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

19/08/2019

D.O.I.

29/08/2019

Survey held at

SG 98 Motor AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear 4 H/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AXA 8HC 5166L
	MV 4.2K
	LTA 666.00
	HL 3.5K
23/10/19 Jmmw 2/5 2908/- with 4 days 3 rev (Red = 4186790/2912)	

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Notes

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel end (\$

Report Format:

Emp Sign / MRC:

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 2 September 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FW 7741G

Honda Wave 125S

ACCIDENT DATE: 19 August 2019

Description	Qty	Quotation \$
1 Rear Tail Lamp ✓ broken	1	125.00 ✓
2 Pillion Bar - cut	1	85.00 ✓
3 Rear Reflection - cracked	1	135.00 ✓
4 Rear Mudguard ✓ broken	1	195.00 ✓
5 Swing Arm - BA	1	320.00 ✓
6 Shock Absorber - 2 destroyed	1	390.00 ✓
7 Rear Rim - 2 destroyed	1	280.00 ✓
8 Exhaust Pipe - brass ✓ cut/	1	560.00 ✓
9 Wheel Hub 2 Dam	1	95.00 ✓
10 Rear LH Footrest ✓ cut	1	65.00 ✓
11 Footrest Bracket ✓ cut	1	95.00 ✓
12 Front Footrest ✓ History	1	68.00 ✓
13 Footrest Rubber ✓ cut	1	65.00 ✓
14 Handle Bar HN	1	98.00 X
15 Meter Cover ✓ broken	1	105.00 ✓
16 Mirror - broken	1 set	130.00 ✓
17 Head Lamp - cut	1	380.00 ✓
18 Head Lamp Cover ✓ cut	1	165.00 ✓
19 Throttle Grip ✓ DM	1	85.00 ✓
20 Front LH Side Panel ✓ cut	1	95.00 ✓
21 Fork Tube X HN	1 set	360.00 X
22 Front LH Signal ✓ cut	1	90.00 ✓
23 Front Centre Panel ✓ broken	1	95.00 ✓
Sub-Total		4,081.00
Less 10%		408.10
Sub-Total		3,672.90

3623.00

3260.70

◀ Service Request Details

Claim

S9M01XJE

Reference

None 

Loss Date

August 19, 2019

Report Date

Aug 21, 2019 12:00:00 AM

Request Date

August 28, 2019

Due Date

September 4, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Linda

T: 3.16p.m

V: 14

E: ✓

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

FW7741G



MODEL
TBC

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

3

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

New Message

Catherine Chong (LKK Auto)

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Tuesday, 27 August, 2019 4:43 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Sg Motor
Subject: [EXTERNAL] Please arrange PRI on bike FW 7741G
Attachments: FW 7741G-PRI- AXA.pdf

Categories: Raghav

Attn: Motor Claim Dept

Dear Sir / Madam

Please arrange PRI on bike FW 7741G as per attached.

Please provide a list of surveyors and their respective company name.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Friday, 27 September 2019 12:45 PM
To: 'claims'
Cc: 'Ng Wai Yin'; 'Jasmine Tan'; 'diskyao@ava-ins.com'; 'alichelim@ava-ins.com'
Subject: YOUR REF: SHC 5166L (OUR REF: CC4/ASM19015296/Dgb3) *** ACCIDENT INVOLVING SHC 5166L & FW 7741G ON 19/08/2019 ***

27 SEPTEMBER 2019

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/ASM19015296/Dgb3

YOUR REF : SHC 5166L

ACCIDENT INVOLVING SHC 5166L (AXA) AND FW 7741G ALONG/AT HOLLAND RD TWDS ULU PANDAN RD ON 19/08/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SG 98 MOTOR PTE LTD acting on behalf of the owner of FW 7741G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your driver's favour as his taxi had collided onto third party parked vehicle. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

We also wish to advise that there is an excess of \$5,000/- is attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- 1) Any settlement equal to or above the excess, you shall be liable to make the payment of \$5000/-; or
- 2) Any settlement below the excess, you shall be liable for the amount settled.

We shall keep you informed of the third party claim settlement and thereafter kindly let us have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by us for the above subject matter, we expressly reserve all our rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

As Insurers, we shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / ceciliachong@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at ceciliachong@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Pls retract any liability / offer made, and reject claim based on TP's 1st police report

Type

 Question

Message

Hi Team, I noted that TP made 2 police reports. He indicated in the first report that he was in the midst of encroaching lane when the accident happened. In view of that, please reject TP claim first. Thank you!

Reply

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 17 March 2020 12:44 PM
To: 'Sg Motor'
Cc: Sg Motor
Subject: RE: Accident involving FW 7741G and SHC 5166L on 19/8/2019 along Holland Ave
Attachments: TP GIA with police report 21082019.PDF

Your Ref: **FW 7741G** Without Prejudice
Our Ref: CC4/ASM19015296/Dgb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHC 5166L(AXA) & FW 7741G ON 19/08/2019

We refer to the above matter.

We have reviewed the matter and we are of the view that our driver is not liable for the accident. Refer to attached for your client's first police report made. Your client admitted that he was making a lane change and leads to the collision.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: Sg Motor [mailto:sgmotor2000@yahoo.com.sg]
Sent: Thursday, 24 October 2019 12:15 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Subject: Re: Accident involving FW 7741G and SHC 5166L on 19/8/2019 along Holland Ave


Dear Cecilia

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19015296/Dga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER		Date : 03-04-2020		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5166L	Veh. Inspected	FW 77416	
Policy No.	VFX/P1680520	Coverage (\$)	0.00	
Claim No.	S9M01XJE	Excess (\$)	0.00	
Assign From		Assign Date	29/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA NF125	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	NF125MD0Q67422	Colour	BLACK	
Odometer	9338	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90 R17	MAXXIS	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	70/90 R17	MAXXIS	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/08/2019	Inspection Date	29/08/2019	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 7741G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAIL LAMP (CONSISTENT)	BROKEN	125.00	125.00
1	PILLION BAR (CONSISTENT)	CUT	85.00	85.00
1	REAR REFLECTION (CONSISTENT)	CRACKED	135.00	135.00
1	REAR MUDGUARD (CONSISTENT)	BROKEN	195.00	195.00
1	SWING ARM (CONSISTENT)	BENT	320.00	320.00
1	SHOCK ABSORBER (CONSISTENT)	DISTORTED	390.00	390.00
1	REAR RIM (CONSISTENT)	DISTORTED	280.00	280.00
1	EXHAUST PIPE (CONSISTENT)	CUT	560.00	560.00
1	WHEEL HUB (CONSISTENT)	DAMAGED	95.00	95.00
1	REAR LH FOOTREST (CONSISTENT)	CUT	65.00	65.00
1	FOOTREST BRACKET (CONSISTENT)	CUT	95.00	95.00
1	FRONT FOOTREST (CONSISTENT)	DAMAGED	68.00	68.00
1	FOOTREST RUBBER (CONSISTENT)	CUT	65.00	65.00
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	98.00	-
1	METER COVER (CONSISTENT)	BROKEN	105.00	105.00
1	SET MIRROR (CONSISTENT)	BROKEN	130.00	130.00
1	HEAD LAMP (CONSISTENT)	CUT	380.00	380.00
1	HEAD LAMP COVER (CONSISTENT)	CUT	165.00	165.00
1	THROTTLE GRIP (CONSISTENT)	DAMAGED	85.00	85.00
1	FRONT LH SIDE PANEL (CONSISTENT)	CUT	95.00	95.00
1	SET FORK TUBE (CONSISTENT)	NOT NECESSARY	360.00	-
1	FRONT LH SIGNAL (CONSISTENT)	CUT	90.00	90.00
1	FRONT CENTRE PANEL (CONSISTENT)	BROKEN	95.00	95.00
LESS 10% DISCOUNT			-408.10	-362.30
			3,672.90	3,260.70
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BROKEN	15.00	15.00
1	METER ASSY (SN)(CONSISTENT)	NOT NECESSARY	380.00	-
			395.00	15.00

Report Ref No. CC4/ASM19015296/Dga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE PARTS ,ALIGN & ETC.		320.00	150.00
	SUPPLY BODY DECAL STICKER .		120.00	80.00
	REMOVE REPLACE REAR RIM ,SWING ARM ,SHOCK ABSORBER ,SPROCKET CHAIN-WHEEL TUB.		220.00	180.00
			700.00	410.00
	GRAND TOTAL		4,767.90	3,685.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00

Report Ref No. CC4/ASM19015296/Dga3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

59NR01XUE

Reference

CCA/ASM19015296/Dga3a2

Loss Date

19 August 2019

Report Date

21 Aug 2019 12:00:00 AM

Request Date

28 August 2019

Due Date

Vendor Name

L&K AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

FW7741G

Make

TPVD UNKNOWN

Model

TBC

Service Address

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter
peter.wang@axa.com.sg

Actions

Next Step

Wait for Approval Invoice

Add Invoice

Additional Instructions

Document Type

Document SubType

Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR













DATE UPLOADED

SHCS146L INS GUA

Reports & Statement

GIA Report

Merimen

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2020
 REJECT EMAIL TO TP.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2020
 TP GIA with police report - 59M01XJE.PDF	Reports & Statement	GIA Report	WANG Peter	14 March 2020
 TP GIA - SKA843Z.PDF	Reports & Statement	GIA Report	WANG Peter	6 March 2020
 TP-IA 7741.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 September 2019
 SHC5166L INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	28 August 2019
 TP PRI FROM WORKSHOP.m4g	Letters and Correspondence	Workshop	DHAKAL Raghav	28 August 2019