

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

| | | | |
|-------------------------------|--|--------------------|-------------------|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 13/07/2019 |
| Vehicle Reg. No.: | SHD3494Y | Driveable? | YES |
| Party At Fault: | UNKNOWN | | |
| Driver (TP): | JOHN GREGORY OLSEN | | |
| Make/Model: | HYUNDAI I40, 1.7 D CRDI (A) | Vehicle Reg. Date: | 08/09/2016 |
| Vehicle Colour: | BLUE | Gen Condition: | GOOD |
| Engine No: | D4FDGU669975 | Chassis No: | KMHLB41UMGU093478 |
| Odometer: | 1 KM | | |
| Paint Type: | | | |
| List Item Discount: | 20.00 % | | |
| Total Loss? | NO | | |
| Est. Duration of Repair (day) | 3 | | |
| Description of Accident/Loss | REFER POLICE REPORT NO: T/2019716/2147 | | |
| Present Location: | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) | | |

| COST OF CLAIMS | Amount |
|--------------------------|-----------------|
| Parts | 3,502.80 |
| Miscellaneous Items | 11.00 |
| Labour | 1,880.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S\$) | 5,393.80 |

+ GST 7.00% (S\$) 377.57

Nett Amount (S\$) 5,771.37

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Lany Ng

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant
Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

| | | | |
|-------------------------------|--|--------------------|-------------------|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 13/07/2019 |
| Vehicle Reg. No.: | SHD3494Y | Driveable? | YES |
| Party At Fault: | UNKNOWN | | |
| Driver (TP): | JOHN GREGORY OLSEN | | |
| Make/Model: | HYUNDAI I40, 1.7 D CRDI (A) | Vehicle Reg. Date: | 08/09/2016 |
| Vehicle Colour: | BLUE | Gen Condition: | GOOD |
| Engine No: | D4FDGU669975 | Chassis No: | KMHLB41UMGU093478 |
| Odometer: | 1 KM | | |
| Paint Type: | | | |
| List Item Discount: | 20.00 % | | |
| Total Loss? | NO | | |
| Est. Duration of Repair (day) | 3 | | |
| Description of Accident/Loss | REFER POLICE REPORT NO: T/2019716/2147 | | |
| Present Location: | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) | | |

| COST OF CLAIMS | Amount |
|--------------------------|-----------------|
| Parts | 3,502.80 |
| Miscellaneous Items | 11.00 |
| Labour | 1,880.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S\$) | 5,393.80 |

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Aug 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3494Y/29/08/2019 14:17**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|---|-------|-------|--------------|
| 1 | 1 | | *FRONT BUMPER <i>cut</i> | 20.00 | 0.00 | *544.50 FL |
| 2 | 1 | | *FRONT BUMPER TOP BRACKET - LH <i>X sun</i> | 20.00 | 0.00 | *22.40 FL |
| 3 | 1 | | *FRONT BUMPER BRACKET - LH <i>X sun</i> | 20.00 | 0.00 | *24.60 FL |
| 4 | 10 | | *FRONT BUMPER CLIPS <i>new</i> | 20.00 | 0.00 | *22.00 FL |
| 5 | 1 | | *HEADLAMP - LH <i>hazed</i> | 20.00 | 0.00 | *1,388.00 FL |
| 6 | 1 | | *FRONT FENDER - LH <i>Rehls</i> | 20.00 | 0.00 | *663.00 FL |
| 7 | 1 | | *FRONT FENDER APRON PANEL - LH <i>X sun</i> | 20.00 | 0.00 | *637.00 FL |
| 8 | 1 | | *FRONT FENDER SHIELD - LH <i>X sun</i> | 20.00 | 0.00 | *174.90 FL |
| 9 | 1 | | *FRONT SIDE MIRROR - LH <i>Broken</i> | 20.00 | 0.00 | *670.00 FL |
| 10 | 1 | | *FRONT WHEEL COVER - LH <i>hazed</i> | 20.00 | 0.00 | *107.10 FL |
| 11 | 1 | | *ADVERTISEMENT - FRONT FENDER LH <i>X sun</i> | 0 | 0.00 | *100.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)

4,353.50

- List Item Discount on L Items (S\$)

850.70

Total Parts (S\$)

3,502.80

ComfortDelGro Engineering Pte Ltd/SHD3494Y/29/08/2019 14:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Larry Ng

Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----------------------------|-----|----------------------|--------------|
| Miscellaneous Items | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 |
| Sub Total (S\$) | | | 11.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|--------------------------------|-----------------------|----------|--------------------------|
| Labour Items | | | |
| 1 | PANEL BEATING | New | 400 800.00 |
| 2 | SPRAY PAINTING | New | 450 900.00 |
| 3 | WIRING CHARGE | New | 20 50.00 |
| 4 | TUFF KOTE | New | 20 50.00 |
| 5 | FRONT WHEEL ALIGNMENT | New | 800.00 |
| Gross Labour Cost (S\$) | | | 1,880.00 |

ComfortDelGro Engineering Pte Ltd/SHD3494Y/29/08/2019 14:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS
 < END OF ESTIMATES >

Kabin 100%
M 29/8/11 1505 km
3 Pys
PIP
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before other survey painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 5280 Facsimile + 65 6280 9755

Workshops:
59 Loyang Drive Singapore 508855 24 Senoko Loop Singapore 758136
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609296 301 Yishun Industrial Park A Singapore 769731

Date/Time: 29.08.2019 11:51 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305328654

CUSTOMER

COMFORT TRANSPORTATION PTE LTD *VAR2*
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)


| | |
|-----------------------------------|----------------------------------|
| REGN NO.: SHD3494Y | MILEAGE |
| MAKE : HYUNDAI | FUEL E.....1/2.....F |
| MODEL I-40 | DATE/TIME IN 13.07.2019 06:00 |
| YR OF MANU 08.09.2016 | TARGET DATE |
| CHASSIS CODE KMHLB41UMGU093478 | COMPLETION DATE/TIME |

ACCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 13.07.2019
NATURE: 3P 13.07.2019 (C)

| S/NO | LABOR CODE | DESCRIPTION |
|------|------------|--------------------|
| | | TOKIO - Left Front |



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD3494Y

Vehicle No.: SHD3494Y

Larry Ng

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

JOB NO : 305324231
 REGN NO : SH 7686H
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID
 DATE OF REGN : 26.07.2017
 DATE/TIME IN : 12.08.2019 05:2
 ACCIDENT DATE : 11.08.2019

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION

| QTY | IND | UNIT | PRICE | DISC% | AMOUNT | JOB / PARTS DESCRIPTION |
|------|--------|------|--------|-------|----------------------|--------------------------------------|
| 0000 | L | | 600.00 | | 600.00 | PANEL BEATING |
| 0001 | 23-502 | | | | | SPRAYPAINT ON AFFECTED AREA |
| 0002 | 17-01 | | 20.00 | | 20.00 | CHECK ALL LIGHTING |
| 0003 | 20-204 | | 60.00 | | 60.00 | REMOVE/REFIX UPHOLSTERY ASST REPAIR |
| 0004 | 20-20 | | 120.00 | | 120.00 | REMOVE/REFIX RR W/SCREEN TO ASST R/P |
| 0005 | 20-22 | | 40.00 | | 40.00 | REMOVE/REFIX REVERSE SENSOR |
| | | | | | SUB-TOTAL : 1,440.00 | |
| | | | | | TOTAL : 5,960.06 | |

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

MVA NAME & SIGNATURE

DATE :

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.08.2019

REPAIR ESTIMATE

Time: 15:15:27

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305328654
 REGN NO : SHD3494Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.09.2016
 DATE/TIME IN : 28.08.2019 16:15
 ACCIDENT DATE : 13.07.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

| | | | | | | |
|------|-------------------|---------------------------|------|----------|-------|----------|
| 0001 | 04-01-0103-2322-A | I40V3 BUMPER W LIP & FOG | 1 | 544.50 | 20.00 | 435.60 |
| 0002 | 04-01-0103-0574-A | I40VC PANEL-FENDER LH+ | 1 | 663.00 | 20.00 | 530.40 |
| 0003 | 04-01-0103-0600-G | I40VC MIRROR ASSY-O/S REA | 1 | 670.00 | 20.00 | 536.00 |
| 0004 | 04-01-0103-0658-G | I40VC CAP ASSY-WHEEL HUB | 1 | 107.10 | 20.00 | 85.68 |
| 0005 | 04-01-0103-0781-A | I40V2 LAMP ASSY-HEAD LH# | 1 | 1,388.00 | 20.00 | 1,110.40 |
| 0006 | 04-01-0103-0639-G | I40VC BRACKET-FR BUMPER S | 1 | 24.60 | 20.00 | 19.68 |
| 0007 | 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 L | 22.00 | 20.00 | 17.60 |

SUB-TOTAL : 2,735.36

JOB NATURE

| | | | | | | |
|------|--------|-----------------------------|--|-------|--|--------|
| 0000 | L | MERIMEN FEE | | 11.00 | | |
| 0001 | PB | PANEL BEATING | | | | 400.00 |
| 0002 | 23-502 | SPRAYPAINT ON AFFECTED AREA | | | | 450.00 |
| 0003 | 17-01 | WIRING CHARGE | | | | 20.00 |

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.08.2019

REPAIR ESTIMATE

Time: 15:15:27

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305328654
 REGN NO : SHD3494Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.09.2016
 DATE/TIME IN : 28.08.2019 16:1
 ACCIDENT DATE : 13.07.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 20-00 TUFF COAT ON AFFECTED PARTS.

20.00

SUB-TOTAL : 901.00

TOTAL : 3,636.36

 MVA NAME & SIGNATURE
 DATE :

 SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

Our Job Ref No : 305328654

Date : 30. Aug. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD3494Y

Date of Accident: 13. Jul. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SLG7401B

2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,735.36

(b) Labour Charges \$901.00

Total for Part-By-Part Repair Cost \$3,636.36

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____


Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 2/9/19

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | \$7.49 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:
