Taufikh - LKK. ESTIMATED ACCIDENT REPAIR COST TP Claim EQ



ACCIDENT TIME REPORTED	21:35hrs	
ACCIDENT DATE	23-Aug-19	
BUS CAPTAIN NAME	CHUA HWA KUANG	
EMPLOYEE NUMBER		

BUS REGISTRATION NUMBER	SBS6326Y	
BUS TYPE (SD/DD)	SD	1 112
BUS ROUTE NUMBER		
BUS ADVERTS (Y/N)	N	

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
77200628	OS PANELLING BESIDE COCKPIT	btv 1	\$2,186.38
77016434	SIKAFLEX BLACK	uli 2	\$32.00
	WHITE & GREY COLOR STICKER	ne 1	\$20.00
	BUMPER FRONT O/S/F	one 1	\$1,207.00
		ζ.	
		7% GST	\$241.18
		PARTS TOTAL COST	\$3,686.56
	77200628	77200628 OS PANELLING BESIDE COCKPIT 77016434 SIKAFLEX BLACK WHITE & GREY COLOR STICKER	77200628 OS PANELLING BESIDE COCKPIT 77016434 SIKAFLEX BLACK WHITE & GREY COLOR STICKER BUMPER FRONT O/S/F 7% GST

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REMOVE & REPLACE DAMAGED PARTS	1300	\$1,950.00
TO REPAIR AND PUTTY SIDE PANEL	975	\$2,600.00
SPRAY PAINTING	1625	\$1,920.00
	Michael	
	7% GST	\$452.90
	LABOUR TOTAL COST	\$6,922.90

PAGE 1

ESTIMATED ACCIDENT REPAIR COST



Date In For Repairs

SECTION 3: REPAIRS TO BUS ADVERTISMENT VINYLS/PANELS (ADVERTISEMENT COST)

TOTAL	ADVERTISEN	MENIT DED	AIR COST

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date Out From Repairs	
BUS TYPE (SD / DD)		Number of Days Under Repair	7
	LOSS OF USE COST		\$2,100.00

SUMMARY		
SECTION NO.	COST	
1	\$3,686.56	
2	\$6,922.90	
3		
4		
5	\$2,100.00	
GRAND TOTAL	\$12,709.46	

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: