



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19015321/Bga3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:KITTY

Date : 13-04-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |          |                |            |
|--------------|----------|----------------|------------|
| Insured Veh. | YN 9162L | Veh. Inspected | SKJ 5450T  |
| Policy No.   | CN058964 | Coverage (\$)  | 0.00       |
| Claim No.    | S9M01YRI | Excess (\$)    | 0.00       |
| Assign From  |          | Assign Date    | 29/08/2019 |

### 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | TOYOTA CAMRY 2.0  | c.c          | 1998       |
| Engine No.   | HIDDEN            | Year of Reg. | 2013       |
| Chassis No.  | MR053BK5104011664 | Colour       | SILVER     |
| Odometer     | 104326            | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | POOR              |              |            |

### 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 215/60 R16 | MICHELIN | 6 mm    |
| L/H Front Tyre | 215/60 R16 | MICHELIN | 6 mm    |
| R/H Rear Tyre  | 215/60 R16 | MICHELIN | 6 mm    |
| L/H Rear Tyre  | 215/60 R16 | MICHELIN | 6 mm    |

### 4. Description of Damages

|                                                                                      |
|--------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------------|

### 5. General Information

|                |                                                                       |                 |            |
|----------------|-----------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 28/08/2019                                                            | Inspection Date | 29/08/2019 |
| Survey held at | TEAM AUTOPRO PTE LTD<br>160 SIN MING DRIVE<br>#01-14 SINGAPORE 575722 |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                 |
|-------------------------------------|-----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 10 Working Days |
|-------------------------------------|-----------------|