

ASS. REC. BY:

REF: CS/SPF/19015329/Kyf302

Special Instruction:

ole

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hafizul Farhan Rahmat

of SPF

Date/Time: 29.8.19 9.16am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 574C

Insured:

QX 32E

at Workshop m/s

Car Times Autoluxxon

Tel:

64715111

of

160 Sin ming Drive #02-04

Policy No:

Claim No:

AEMD/105/009/2019/086

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

mup"

H.O.D. Endorsement:

Date/Time:

29.8.19 9.49am

Person Contacted:

Cindy

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

QX 32E X

SLC 574C X

Do Not Finalise

REF: SPF

ASSIGNMENT

From Date: 29.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 574C

at Workshop n/s Car Times Autolubon

of 160 sn mng Drive 402-04

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Date: Person Contacted:

Vehicle: IN / OUT

Veh No. SLC 574C

Yr Bogn 04 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading 99141 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU1 1116457

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 3 mm

L/Bal. 2 mm L/Bal. 3 mm

D.O.A. 23/8/19 D.O.L. 29/8/19

Survey held at

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

1st O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12/19 Upper Range \$2500/- - \$3000/-
 11/12/19 Submit L/S \$2750/- Repair 4 days. Weekend 0 day
 (Red \$564-40, 67%)

RECEIVED 11 DEC 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

11/12/19 Typist

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

220

Transportation:

) \$ + RS. \$

) Photo:

) Others:

TOTAL

220

Report Format :

Lump Sum / I.B.I: (\$)

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Thursday, 29 August 2019 9:16 AM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF); Rosalyn TAN (SPF)
Subject: Pre-repair survey for SLC574C (vs QX32E DOA:23/8/19)

Message Classification: Unclassified

Hi,

Kindly conduct pre-repair survey on **SLC574C** at:

CarTimes Autolution
160 Sin Ming Drive
#02-04 AutoCity
Singapore 575722

Contact: Yuki, Tel: 6471 5111

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4860 / FAX: (65) 6478 4850



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 14:47
Date Of Accident	23/08/2019 12:30
Exact Location Of Accident	OUTRAM ROAD OUTSIDE WANGZ HOTEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC574C
Insured/Policyholder	
Name Of Registered Owner	PENNEFATHER JOAN DEBBIE
NRIC No	S1283192G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93663474
Alternative Phone No	OTHERS-93663474

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108747918
Cover Note Number	

Driver

Name of Driver	TUPAZ DAVID JOE
NRIC No	S8115285C
Date Of Birth	15/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	08/06/2009
Driving Experience	10 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87494766
Fax Number	
Contact Number	
Email Address	DAVIDTUPAZ213@GMAIL.COM

Address	BLK 188A BEDOK NORTH STREET4 #08-66
Postcode	461188
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2449999 - FAX NO: 62447258
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190824/2157;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX32E
Vehicle Make/Model/Colour	SUBARU / IMPREZA 5MT
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	SIM NGIN KIT
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TUPAZ DAVID JUDE

Approximate Age 38

Injuries Sustain

Injured person in which vehicle? SLC574C

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address BLK 118A BEDOK NORTH STREET4 #08-66

Postcode 46118

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Reporting Centre
Name: Singapore 415933
NRIC/TEL: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg


Accident Sketch Plan Pg. 1

SKETCH PLAN

Outram Rd
(outside Wangz Hotel)

A - SLC 574C

B - QX32E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/8/19 at 1230hrs, I was driving along Outram Rd towards G14
When I was in the yellow box Vehicle B came ^{from} the right & Hit on to
my front right portion of my vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre 23 Kaki Bukit Ave 4

Name: Singapore 415933


NRIC/Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190824/2157

Police Station Of Origin:
Bedok North N.P.C.
30 Bedok North Road SINGAPORE 489676
Tel No: 1800-2449999

1 of 3

Report No: T/20190824/2157

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/08/2019 19:31	Vide Report No.	Station Diary No. 117
--	-----------------	--------------------------

Informant's Particulars

Name of Informant: TUPAZ DAVID JUDE			Address: APT BLK 188A BEDOK NORTH STREET 4 #08-66 SINGAPORE 461188		
ID Type / ID No. NRIC NO / S8115285C			Contact No.: Home/Office Mobile: 87494766		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 15/05/1981	Type of Informant: Driver		
Race: Filipino			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury: Government Vehicle	Drink Drive: No	Date/Time of Accident: 23/08/2019 12:20	Type of Location: Straight Road
Location: Along Road 1 OUTRAM ROAD				
ALONG OUTRAM ROAD		Road Surface: Dry	Road Speed Limit:	
Weather: Clear		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
QX32E	Car	SUBARU	IMPENZA 5MT	White		0
SLC574C	Car	HONDA	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR	White	Slightly Damaged	1

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190824/2157

Police Station Of Origin:
Bedok North N.P.C.
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

2 of 3
Report No: T/20190824/2157

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SIM NGIN KIT	ID No.	NIL
Related Vehicle	QX32E (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TUPAZ DAVID JUDE	ID No.	S8115285C
Related Vehicle	SLC574C (Car)	Contact No.	87494766
Hospital/Clinic	UNIHEALTH CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3A Date of Expiry: NIL
Date Treatment	24/08/2019	Date Discharge	24/08/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 23 August 2019 at about 1220hrs, I was driving my vehicle along Outram Road on Lane 3 towards Singapore General Hospital, sending my passenger to her drop off location. As I was driving along Lane 3, all of a sudden, a Police vehicle registration number QX32E emerged from my right side and abruptly entered Lane 3 without signaling. I could not brake in time and as such, the right side of my front bumper collided with the left side of the front bumper of the police vehicle. I then stopped my vehicle and approached the Police Officer whom identified himself as Sim Ngian Kit. The Police Officer refused to provide his telephone number and told me to take down the police vehicle registration number will do. I then took photos of the accident scene and went to a nearby carpark to exchange particulars as both our vehicles were blocking traffic. I then left after which

On 24 August 2019, I went to Unihealth Clinic located at Block 214 Bedok North Street. I #01-171 as I was feeling pain in my neck, hip and my right foot. I was then issued with 3 days of medical leave reference MC No: D000002718.

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T20190824/2157

Police Station Of Origin
Bedok North N.P.C
30 Bedok North Road SINGAPORE 489676
Tel No. 1800-2449999

3 of 3

Report No. T20190824/2157

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

G/

Staff Sgt TRAVINDER JIT SINGH

Signature Of Informant

Signature Of Interpreter:

Not applicable

Date/Time

24/06/2019 19 31

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65475414

Classification Of Case:

Authentication Stamp

18/158

SINGAPORE POLICE

SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	192G
Vehicle Details	
Vehicle No.:	SLC574C
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4036461
Chassis No.:	RU11116457
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,115.00
Original Registration Date:	29 Apr 2016
First Registration Date:	29 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$10,161.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2026
PARF Rebate Amount:	\$7,620.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$46,667.00
COE Rebate Amount:	\$30,348.00
Total Rebate Amount:	\$37,968.00

The information contained herein is correct as at 27 Aug 2019

OK

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd

160 Sin Ming Drive AutoCity

#02-04 Singapore 575722

Tel : 6471 5111

Email : claims@cartimes.com.sg

Vehicle No. SLC574C

Car Model : Honda VEZEL

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT(S\$)
	LIST ITEM		
1	FRT RH FENDER	580.00	X
1	FRT RH WHEEL ARC	195.00	✓
1	FRT BUMPER	907.00	✓
1	FRT BUMPER LOWER LID	366.00	✓
1	LH FENDER INNER SHEILD	257.00	X
1	BUMPER RH SIDE RETAINER	30.00	✓
1	FRT RH HEADLAMP	1850.00	✓
1	FRT RH FOGLAMP	150.00	X
1	FRT RH FOGLAMP COVER	47.00	✓
1	FRT RH HEADLAMP BRACKET	68.00	X
1	FRT RH ABSORBER	450.00	X
1	FRT RH LOWER ARM	385.00	X
1	KUNCLE ARM	580.00	X
1	WHEEL BEARING	480.00	X
1	WHHEL HUB	280.00	✓
1	LINKAGE	108.00	X
1	FRT RH RIM	960.00	X
		7693.00	
		20%	
		1538.60	
		6154.40	
	Special Nett items		
1 set	FENDER INNER SHEILD CLIP	30.00	X
1 set	FRT BUMPER CLIP	30.00	✓
1 set	FRT BUMPER SENSOR	280.00	X
	special nett	340.00	
	TOTAL PART	6494.40	

Not Withain

L1 Sur @ 2750k

Survey After Paint

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Vehicle No. SLC574C

Car Model : Honda VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00	3501
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	4001
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	120.00	201
4	To remove & replace front sensor & check for proper function	120.00	501
5	To remove & replace front undercarrige part	~ 180.00	X
	PERFROM WHEEL ALIGMENT	~ 80.00	X
	Labour Total :	2300.00	
	TOTAL (PARTS & LABOUR):	8414.40	

8794.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19015329/Kyf3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : HAFIZUL FARHAN RAHMAT		Date : 13-12-2019	
		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	QX 32E	Veh. Inspected
			SLC 574C
	Policy No.		Coverage (\$)
			0.00
	Claim No.	AEMD/105/009/2019/086	Excess (\$)
			0.00
	Assign From	HAFIZUL FARHAN RAHMAT	Assign Date
			29/08/2019
2. Vehicle Particulars & Condition			
	Make & Model	HONDA VEZEL (A)	c.c
			1496
	Engine No.	HIDDEN	Year of Reg.
			2016
	Chassis No.	RU11116457	Colour
			METALLIC PEARL WHITE
	Odometer	99141	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			STANDARD ALLOY RIM
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	215/60 R16	DUNLOP
			2 mm
	L/H Front Tyre	215/60 R16	DUNLOP
			2 mm
	R/H Rear Tyre	215/60 R16	DUNLOP
			3 mm
	L/H Rear Tyre	215/60 R16	DUNLOP
			3 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	23/08/2019	Inspection Date
			29/08/2019
	Survey held at	160 SIN MING DRIVE #02-04	
	Repairer	CAR TIMES AUTOLUTION PTE LTD	
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.		
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 574C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT RH FENDER	TO REPAIR SEE LABOUR	580.00	-
1	FRT RH WHEEL ARCH	BUCKLED	195.00	195.00
1	FRT BUMPER	BENT	907.00	801.70
1	FRT BUMPER LOWER LID	BUCKLED	366.00	366.00
1	LH FENDER INNER SHIELD	SERVICEABLE	257.00	-
1	BUMPER RH SIDE RETAINER	DISTORTED	30.00	30.00
1	FRT RH HEADLAMP	CUT	1,850.00	1,850.00
1	FRT RH FOGLAMP	SERVICEABLE	150.00	-
1	FRT RH FOGLAMP COVER	DENTED	47.00	47.00
1	FRT RH HEADLAMP BRACKET	TO REPAIR SEE LABOUR	68.00	-
1	FRT RH ABSORBER	SERVICEABLE	450.00	-
1	FRT RH LOWER ARM	SERVICEABLE	385.00	-
1	KNUCKLE ARM	SERVICEABLE	580.00	-
1	WHEEL BEARING	NOT NECESSARY	480.00	-
1	WHEEL HUB	SERVICEABLE	280.00	-
1	LINKAGE	SERVICEABLE	108.00	-
1	FRT RH RIM	SERVICEABLE	960.00	-
	LESS 20% DISCOUNT		-1,538.60	-657.94
			6,154.40	2,631.76
<u>SPECIAL NETT ITEMS</u>				
1	SET FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRT BUMPER SENSOR (SN)	SERVICEABLE	280.00	-
			340.00	30.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRT RH FENDER AND FRT RH HEADLAMP BRACKET.		1,000.00	350.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		800.00	400.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		120.00	20.00
	TO REMOVE & REPLACE FRONT SENSOR & CHECK FOR PROPER FUNCTION.		120.00	50.00
	TO REMOVE & REPLACE FRONT UNDERCARRIAGE PART.	NOT NECESSARY	180.00	-
	PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			2,300.00	820.00
GRAND TOTAL			8,794.40	3,481.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CS/SPF19015329/Kyf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.