

22/03/2002

ASS. REC. BY:

REF: CS/MSG/1015334/R1t43⁵²

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

Merimen

From (Person): Katherine Wong of MSG Date/Time: 29/08/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SFV 60P Insured: SKR 9893 Eat Workshop m/s Volkswagen Group Singapore Pte Ltd Tel: 6305 7293of 247 Alexandra RoadPolicy No: 29119035AMY Claim No: 604289

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement: _____

Date/Time: 05:22pm @ 29/08/2019 Person Contacted: Chairman Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKR 9893E : X
	SFV 60P : X
2/9 @ 16:48	Revised via preli advise. merimen.
	Part by Part \$ 39301 (Red: 4772 : 54%)

477F

Veh No. SFV 60P Yr Regd: 2013 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN SHARAN 2.0 cc 1984

Colour	Blue	A/C	Insured / Std / Nil / NA
--------	------	-----	--------------------------

Sp. Reading 102471 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No WVW2227N ~~2578~~ / 00 2578

Gen. Cond. Good / Fair / Poor / BurntSteering: *Worder* / Jammed / Leaked / Burnt or

Brake: (Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim cr

Tyre Size: F: 225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front 6 mm Rear 8 mm
R/Bal. 6 mm R/Bal. 8 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/08/19 . D.O.I. 30/08/19

Survey held at Volksunion

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
-------------	----------------------

RECEIVED 26 SEP 2013

25/9/2019

Date/Time, File Pass to?

☐: Prelim. Report

Days Of Repair: 3

2579 typist

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to

21

Add Fee:	Site Insp.	(\$
----------	------------	-----

Survey Fee:

$$) \quad S + R \rightarrow S$$

Report Format :

Lump Sum / (P.B.): (\$ 3930

☐ Interview (\$☐ Tech. Invs (\$)☐ Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019 11:18		29 Aug 2019 17:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ANG KAY SONG, ID: S7837262A								
Main Claimant:	KEVIN CHENG WENG CHEONG, ID: S7433477F								
Vehicle Reg. No.:	SFV60P	Date of Loss:	27/08/2019 19:00 - :59 [71 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29119035QMY (Comprehensive) Coverage: 20/03/2019 - 19/03/2020						
Vehicle Reg. No. (Insured):	SKR9893E	Policy No. (Claimant):							
Repairster:	Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD, 159934 Alexandra - Tel: 63057293								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/08/2019]								
Driver/Custodian (Insured):	ANG KAY SONG (), NRIC: S7837262A Email:								
Adj Asg. Remarks:	Survey appt 30/08/19, 4pm. Owner waiting at Alexandra w/shop. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Liab: 100%. Contact: Charmaine @ 6305 7176 / 6305 7299.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 02 Sep 2019

Preliminary Advice

Insured Vehicle No	: SKR9893E	Accident Date	: 27/08/2019
TP Vehicle No	: SFV60P	Assignment Date	: 29/08/2019
Make	: VOLKSWAGEN SHARAN	Est. Duration of Repair	: 3.00
Date of Inspection	: 30/08/2019		
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD (-) 247 ALEXANDRA ROAD SINGAPORE 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,702.00
Revised Amount	:S\$	3,930.00
Check Items (Estimated)	:S\$	1,492.00
Total	:S\$	5,422.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

MSH
winner
us
MSH
OUT.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2019 13:59
Date Of Accident	27/08/2019 19:20
Exact Location Of Accident	UPPER THOMSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFV60P
Insured/Policyholder	
Name Of Registered Owner	KEVIN CHENG WENG CHEONG
NRIC No	S7433477F
Email Address	KEVIN@KEVINANDKAIVEN.NET
Mobile Phone No	(LOCAL) +65-98738046
Alternative Phone No	OFFICE-98738046

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SHARAN SUCC. HL 147 TSID6F
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company


Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 2880 7107 AVW
Cover Note Number	

Driver

Name of Driver	TAN TOON LIN KAREN
NRIC No	S7520907Z
Date Of Birth	21/07/1975
Occupation	INDOOR
Date Of Driving Pass	25/07/1994
Driving Experience	25 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-91180778
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 August (Tue), approx 720pm, I (SFV 60P) stopped at the traffic light when it turned red (at the junction of Upper Thomson Road & Marymount Lane).

After I (SFV 60P) stopped, I heard a bang at my bumper. Driver of SKR 9893 E had banged the rear of my car (SFV 60P).

Vehicle which banged my vehicle: SKR 9893 E

Driver Details: Ang Kay Song
(Hp 97988038)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7520907Z**



Name
TAN TOON LIN KAREN
(CHEN DUNLIN KAREN)
陈敦琳

Race
CHINESE

Date of birth **21-07-1975** Sex **F**

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

License Number **S7520907Z**

Name
TAN TOON LIN KAREN
(CHEN DUNLIN KAREN)

Birth Date: **21 Jul 1975**
Issue Date: **04 May 2017**

0026806708



3745476



NRIC No. **S7520907Z**



Date of issue
22-07-2005

S75 BUKIT TIMAH ROAD #05-28
FLORIDIAN SINGAPORE 689649

NRIC No. **S7520907Z** Date: **09/06/2019**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	25 Jul 1994

NP 428A



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	477F
Vehicle Details	
Vehicle No.:	SFV60P
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Sep 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI AT 7N14H3
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	CCZ384986
Chassis No.:	WVWZZZ7NZE002578
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$40,238.00
Original Registration Date:	28 Aug 2013
First Registration Date:	28 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$48,334.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2023
PARF Rebate Amount:	\$31,417.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$76,389.00
COE Rebate Amount:	\$30,432.00
Total Rebate Amount:	\$61,849.00

The information contained herein is correct as at 02 Sep 2019

OK

75,000
61,849

13,151

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/1

Document no.
Document date 28-08-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001842/ 1
Job order date 28-08-2019
Service Advisor CHARMAINE KONG

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
KEVIN
CHENG WENG CHEONG
975 BUKIT TIMAH ROAD
#23-02
Singapore 575728

License plate	Model code	First registration	VIN	Model	Mileage
SFV60P	7N14H3	28-08-2013	WVWZZZ7NZE002578	Sharan succ. HL 147 TSID6F	65,179

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
7N0807417E GRU	Cover For Bumper Primed <i>repaired</i>	1	pcs.	1,144.79	#1	1,144.79	1,224.93
7N0807521C 9B9	Spoiler Satin Black <i>cut - repair de</i>	1	pcs.	252.03	#1	252.03	269.67
7N0807863	Attachment Strip <i>?</i>	1	pcs.	178.03	#1	178.03	190.49
7N0807251A	Foam Insert <i>?</i>	1	pcs.	126.41	#1	126.41	135.26
7N0807305A	Bumper Bracket <i>?</i>	1	pcs.	754.12	#1	754.12	806.91
7N0807375	Guide Piece (BUMPER BRACKET LH) <i>?</i>	1	pcs.	76.72	#1	76.72	82.09
7N0807376	Guide Piece (BUMPER BRACKET RH) <i>?</i>	1	pcs.	76.72	#1	76.72	82.09
7N0919491	Sensor Bracket <i>rec</i>	1	pcs.	19.48	#1	19.48	20.84
7N0919491A	Sensor Bracket <i>rec</i>	1	pcs.	19.48	#1	19.48	20.84
7N0919491B GRU	Sensor Bracket Primed <i>rec</i>	1	pcs.	19.48	#1	19.48	20.84
7N0919492B GRU	Sensor Bracket Primed <i>rec</i>	1	pcs.	19.48	#1	19.48	20.84
D 822150A1	Bonding Agent For Plastic <i>rec</i>	1	pcs.	56.90	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive <i>rec</i>	1	pcs.	74.29	#1	74.29	79.49
7N0061195	Load Edge Protection <i>rec</i>	1	pcs.	204.07	#1	204.07	218.35
	LABOUR	3	pcs.	840.00	#1	840.00	2,696.40
	Spray Painting	3	pcs.	800.00	#1	800.00	2,568.00

Quotation valid till 04-09-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	7,942.00	7%	609.14	8,702.00	9,311.14
Total	760.00	7,942.00		609.14	8,702.00	9,311.14

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

Reserv before paint

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Tax invoice

Preview

Page 1/2

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
KEVIN
CHENG WENG CHEONG
975 BUKIT TIMAH ROAD
#23-02
Singapore 575728

Document no.
Document date 24-09-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001875/ 1
Job order date 30-08-2019
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SFV60P	7N14H3	28-08-2013	WWWZZZ7NZE002578	Sharan succ. HL 147 TSID8F	103,319

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
7N0807417E GRU	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Cover For Bumper Primed	1	pcs.	1,144.79	#1	1,144.79	1,224.93
	XR-2/9/2019						
7N0807521C 9B9	Spoiler Satin Black	1	pcs.	252.03	#1	252.03	269.67
	C/D-2/9/2019						
7N0919491	Sensor Bracket	1	pcs.	19.48	#1	19.48	20.84
	XR-2/9/2019						
7N0919491A	Sensor Bracket	1	pcs.	19.48	#1	19.48	20.84
	XR-2/9/2019						
7N0919491B GRU	Sensor Bracket Primed	1	pcs.	19.48	#1	19.48	20.84
	XR-2/9/2019						
7N0919492B GRU	Sensor Bracket Primed	1	pcs.	19.48	#1	19.48	20.84
	XR-2/9/2019						
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	#1	56.90	60.88
	XR-2/9/2019						
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	#1	74.29	79.49
	XR-2/9/2019						
7N0061195	Load Edge Protection	1	pcs.	204.07	#1	204.07	218.35
	Resquest Mewin 16/9/2019						
	LABOUR	1	pcs.	840.00	#1	840.00	898.80
	Spray Painting	1	pcs.	800.00	#1	800.00	856.00
	MSIG DIRECT SETTLEMENT @ 3RD PARTY VEHICLE SKR9893E D.O.A: 27-08-19 SURVEY BY: LKK RASUL						

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	480.00	3,450.00	7%	275.10	3,930.00	4,205.10
Total	480.00	3,450.00		275.10	3,930.00	4,205.10

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial
Vehicles

Tax invoice

Preview

Page	2/2
Document no.	
Document date	24-09-2019
Customer no.	5211001211
Customer GST-ID	200412212G
Dealer	39999
Job order number	2019001875/ 1
Job order date	30-08-2019
Service Advisor	CHARMAINE KONG

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
KEVIN
CHENG WENG CHEONG
975 BUKIT TIMAH ROAD
#23-02
Singapore 575728

License plate	Model code	First registration	VIN	Model	Mileage
SFV60P	7N14H3	28-08-2013	WWWZZZ7NZE002578	Sharan succ. HL 147 TSID6F	103,319

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

This is an authorised document. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019 11:18		29 Aug 2019 17:14 Edit Adj Rpt	\$3,930.00 Edit Estimates	\$3,930.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ANG KAY SONG, ID: S7837262A		
Main Claimant:	KEVIN CHENG WENG CHEONG, ID: S7433477F		
Vehicle Reg. No.:	SFV60P	Date of Loss:	27/08/2019 19:00 - :59 [71 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 604289	Policy/Cover Note No.:	A29119035QMY (Comprehensive) Coverage: 20/03/2019 - 19/03/2020
Vehicle Reg. No. (Insured):	SKR9893E	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD, 159934 Alexandra - Tel: 63057293		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/09/2019]		
Driver/Custodian (Insured):	ANG KAY SONG (), NRIC: S7837262A Email:		
Adj Asg. Remarks:	Survey appt 30/08/19, 4pm. Owner waiting at Alexandra w/shop. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Liab: 100%. Contact: Charmaine @ 6305 7176 / 6305 7299.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFV60P (604289)

[SKR9893E]

TP

KEVIN CHENG WENG CHEONG

Aug 27 2019 7:00PM

[ANG KAY SONG]

Volkswagen Group Singapore Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page ▼	Thumbnail	Print
1	02/09/19 16:48	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	26/09/19 09:26	General View	1	Load JPG	✓
2	26/09/19 09:26	General View	1	Load JPG	✓
3	26/09/19 09:26	General View	1	Load JPG	✓
4	26/09/19 09:26	General View	1	Load JPG	✓
5	26/09/19 09:26	General View	1	Load JPG	✓
6	26/09/19 09:26	General View	1	Load JPG	✓
7	26/09/19 09:26	General View	1	Load JPG	✓
8	26/09/19 09:26	General View	1	Load JPG	✓
9	26/09/19 09:26	General View	1	Load JPG	✓
10	26/09/19 09:26	General View	1	Load JPG	✓
11	26/09/19 09:26	General View	1	Load JPG	✓
12	26/09/19 09:26	General View	1	Load JPG	✓
13	26/09/19 09:26	General View	1	Load JPG	✓
14	26/09/19 09:26	General View	1	Load JPG	✓
15	26/09/19 09:26	General View	1	Load JPG	✓
16	26/09/19 09:26	General View	1	Load JPG	✓
17	26/09/19 09:26	General View	1	Load JPG	✓
18	26/09/19 09:26	General View	1	Load JPG	✓
19	26/09/19 09:26	General View	1	Load JPG	✓
20	26/09/19 09:26	General View	1	Load JPG	✓
21	26/09/19 09:26	General View	1	Load JPG	✓
22	26/09/19 09:26	General View	1	Load JPG	✓
23	26/09/19 09:26	General View	1	Load JPG	✓
24	26/09/19 09:26	General View	1	Load JPG	✓
25	26/09/19 09:26	General View	1	Load JPG	✓
26	26/09/19 09:26	General View	1	Load JPG	✓
27	26/09/19 09:26	General View	1	Load JPG	✓
28	26/09/19 09:26	General View	1	Load JPG	✓
29	26/09/19 09:26	General View	1	Load JPG	✓
30	26/09/19 09:26	General View	1	Load JPG	✓
31	26/09/19 09:26	General View	1	Load JPG	✓
32	26/09/19 09:26	General View	1	Load JPG	✓
33	26/09/19 09:26	General View	1	Load JPG	✓
34	26/09/19 09:26	General View	1	Load JPG	✓
35	26/09/19 09:26	General View	1	Load JPG	✓
36	26/09/19 09:26	General View	1	Load JPG	✓
37	26/09/19 09:26	General View	1	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/09/19 09:26	General View	 Load JPG	✓
39	26/09/19 09:26	General View	 Load JPG	✓
40	26/09/19 09:26	General View	 Load JPG	✓
41	26/09/19 09:26	General View	 Load JPG	✓
42	26/09/19 09:26	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/08/19 11:21	OI SKR9893E GIA REPORT	 Load PDF	
2	29/08/19 11:21	TP SFV60P GIA REPORT	 Load PDF	
3	29/08/19 11:21	Estimate	 Load PDF	
4	29/08/19 11:42	Acknowledge PRI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015334/R1TF3S2
Date: 02/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29119035QMY
Claimant Vehicle No : SFV60P **Insured Vehicle No :** SKR9893E
Date of Loss: 27/08/2019 **Nature of Claim:** TP **Claim No:** 604289

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFV60P**
 Make & Model: VOLKSWAGEN SHARAN, 2.0 TSI AT 7N14H3 (A) Engine No: CCZ384986
 Reg. Date: 28/08/2013 (Man. Year: 2013) Chassis No: WVVZZZ7NZE002578
 Colour: Blue Odometer: 102471 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,022.00	1,810.00	1,212.00	40.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,120.00	3,560.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,702.00	3,930.00	4,772.00	54.84
+ GST 7.00/7.00% (S\$)	609.14	275.10	334.04	54.84
Nett Amount (S\$)	9,311.14	4,205.10	5,106.04	54.84

INSPECTION

Date of Assignment: 29/08/2019
 Date Inspected: 30/08/2019 Inspected At: Volkswagen Group Singapore Pte Ltd (-)
 247 ALEXANDRA ROAD
 Singapore 159934
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2019)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFV60P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,144.79 FS	*1,144.79 FS
2	1		*SPOILER SATIN BLACK	Cut	252.03 FS	*252.03 FS
3	1		*ATTACHMENT STRIP	Serviceable	178.03 FS	*- FS
4	1		*FOAM INSERT	Serviceable	126.41 FS	*- FS
5	1		*BUMPER BRACKET	Serviceable	754.12 FS	*- FS
6	1		*GUIDE PIECE (BUMPER BRACKET LH)	Serviceable	76.72 FS	*- FS
7	1		*GUIDE PIECE (BUMPER BRACKET RH)	Serviceable	76.72 FS	*- FS
8	1		*SENSOR BRACKET	Necessary	19.48 FS	*19.48 FS
9	1		*SENSOR BRACKET	Necessary	19.48 FS	*19.48 FS
10	1		*SENSOR BRACKET PRIMED	Necessary	19.48 FS	*19.48 FS
11	1		*SENSOR BRACKET PRIMED	Necessary	19.48 FS	*19.48 FS
12	1		*BONDING AGENT FOR PLASTIC	Necessary	56.90 FS	*56.90 FS
13	1		*2K-PLASTIC ADHESIVE	Necessary	74.29 FS	*74.29 FS
14	1		*LOAD EDGE PROTECTION	Cracked	204.07 FS	*204.07 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,022.00	1,810.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING.	New	480.00	480.00
2	CHECK SHORT CIRCUIT / HARNESS REPAIR.	New	280.00	0.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING.	New	2,400.00	800.00
Gross Labour Cost (\$\$)			5,680.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >