

ASS. REC. BY:

REF: CS/SPF/9015335/Et9367

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Hafizul Fathan Rahmatof SPF: Date/Time: 30 August 2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 300H Insured: QX 512L

at Workshop m/s SMRT Auto Services Pte Ltd Tel: 6866 2671 / 6866 2672

of 60 Woodlands Industrial Park E4

Policy No: Claim No: AEMD / 105/009 / 2019/087

Sum Insured: Excess:

Make of Veh: D.O.A. 28 August 2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 10:27am @ 30/08/2019 Person Contacted: shanti Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	QX 512L : N/A MSG/19007377/K4 D.O.A. 25/04/2019
	SHF 300H : X

16/9 @ 11:24am - email poh Guan cannot finalise.

Do Not Finalise

Steve

REF: SPF

ASSIGNMENT

From: Date: 30-8-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHF 300H

at Workshop n/s SMRT

of 60 woodland Industrial Park E4

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mup'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SHF 300H

Tr Regn 14/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prous

C.C. 1798

Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading 138175

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J10KB3F4 9935 76487

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

with like

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 28/8/19

D.O.A. 30/8/19

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair range - \$800 - 1000
2 working days / weekend08/19/2122
Q x 512LRepair day 2
weekend - 1
Total - 3

Part by Part \$873.36 (Red: 6678.94! 88%)

RECEIVED 16 SEP 2019

Date/Time, File Pass to?

1) 16/9 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 873.36

☐ : Preli. Report☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + PG, SI

) Photos

) Others

TOTAL

220

220

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Friday, 30 August 2019 9:34 AM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF); Rosalyn TAN (SPF); SUR
Subject: Pre-repair survey for SHF300H (vs QX512L / DOA:28.8.2019)

Our ref: AEMD/105/009/2019/087

Hi,

Kindly conduct pre-repair survey on **SHF300H** at:

SMRT Auto Services Pte Ltd
60 Woodlands Industrial Park E4
Singapore 757705

Contact: Shanti, DID: 6866 2671 / 68662672

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4860 / FAX: (65) 6478 4850



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 16 September 2019 11:24 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHF300H

Dear Poh Suan,

As this case is under SPF, we have instruction from them not to finalize.

Therefore we will submit according to our surveyor marking.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 13 September 2019 10:23 AM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHF300H

Hi Steve,

Attached herewith the repair estimate of SHF 300H having Case No: TAX/08/19/2122.

There is no change to the approved amount of \$873.36 @ 2 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Friday, 13 September 2019 10:04 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Scan Data from FX-D421D6

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHF300H
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8258413
Chassis No.:	JTDKB3FU903576487
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	14 Dec 2017
First Registration Date:	14 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$26,835.00
Total Rebate Amount:	\$30,585.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2019 15:56
Date Of Accident	28/08/2019 20:40
Exact Location Of Accident	SELEGIE ROAD TOWARDS SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF300H
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	TAN YANG HUAT
NRIC No	S1178442I
Date Of Birth	08/09/1956
Occupation	OUTDOOR
Date Of Driving Pass	01/03/1979
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES N.P.C
Police Station Address	ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/201908292008

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX512L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

Selegie Road towards Serangoon Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

No. Of Passenger (Including Driver)



**SINGAPORE
POLICE FORCE**



T/20190829/2008

1 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20190829/2008

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/08/2019 01:21		Vide Report No.: E/20190828/0107		Station Diary No.: 11	
Informant's Particulars					
Name of Informant: TAN YANG HUAT			Address: APT BLK 877 TAMPINES STREET 84 #12-50 SINGAPORE 520877		
ID Type / ID No.: NRIC NO / S1178442I			Contact No.: Home/Office: Mobile: 97390848		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 08/09/1956	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 28/08/2019 20:40	Type of Location: Straight Road
Location: Along Road 1 SELEGIE ROAD				
Selegie Road towards Serangoon Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: BETWEEN MOVING VEHICLE - BACK TO FRONT				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX512L	Car	TOYOTA	ALTIS	White	Slightly Damaged	3
SHF300H	TAXI	TOYOTA	PRIUS	Maroon	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190829/2008

2 of 3

Report No. T/20190829/2008

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

CONTINUATION OF REPORT

Driver			
Name	TAN YANG HUAT	ID No.	S1178442I
Related Vehicle	SHF300H (TAXI)	Contact No.	97390848
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28/08/2019 at about 2040hrs, I was driving my SMRT Taxi Reg No: SHF300H along Selegie Road towards Serangoon Road. I was travelling along the left most lane. There was a car parked along the road with no driver in it. As such I overtake the parked car and re enter the lane. I then saw a police car Reg No: QX512L with its reverse light on reversing slowly towards the direction of my taxi. There were a distance of two car length between me and the police car. I sounded my car horn however the police car still continue to reverse and hit onto my taxi front. However, the impact is minimal as the police car stopped immediately after its rear bumper touch my taxi.

The police car driver went out. I also went out and saw my taxi front bumper left part was slightly scratch and the bumper was dislodge. The police rear bumper right side were slightly damaged and scratched. There is a hole on the rear bumper but I believe is not cause by the accident.

I was told not to move my car and the traffic police were called to attend to the accident and took down my particulars and statement. There were about 3 passengers in the police car. Both me and the police driver were not injured. The passengers whom I believe are also police officers also does not seem injured. I was then told to lodge a traffic police accident report vide A/20190828/0107. The traffic police also took the SD Card from my taxi In-car camera.



**SINGAPORE
POLICE FORCE**



T/20190829/2008

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 3

Report No. T/20190829/2008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sr Staff Sgt MUHAMAD FAISAL BIN MOHD
SALEH

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
29/08/2019 01:21

Officer In Charge Of Case:
TP / DDGVT /
SI MU WEI JUN
Contact No.: 65476225

Classification Of Case:



SINGAPORE
POLICE FORCE

Authentication Stamp
NP168

SIGNATURE



Case Details

Case Reference Number : TAX/08/19/2122
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF300H

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8304-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Non Insurance Claimant
 Accident Date and Time : 28/08/2019 12:40 PM
 Vehicle Age(In Months) : 20

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	✓ DD
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72	Replace	✓ BR
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	25.00	682.65	Replace	0	0	Check	X N/A
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	25.00	1,919.18	Replace	0	0	Check	X N/A
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	X N/A
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	X N/A
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	X N/A
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give	X N/A
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									4,469.48	Surveyor Total 433.35				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									4,469.48	Final Sur Total 433.35				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
Total:			756.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	10	
3	Main	TO REPLACE SUNDRY PARTS	100.00	10	
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			340.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,469.48	433.35
Total Labour Cost	507.00	200.00
Total Spray Painting	756.00	200.00
Other	340.00	40.00
Overall Total	6,072.48	873.35
Lump Sum Repair Option		
Lump Sum Total	0.00	873.35
Surveyor Approved Amount		873.35
No of Repair Days*	4	2
Remarks	-	<p>7562.30</p> <p>P/P repair, take after spray. Finalize sent to stevechen@lkkauto.com</p>

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

STEVE CHEN

Signature


2/9/19

Save

Clear

Survey Date

30/08/2019

LKK Auto Consultants hence notify
the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details	
Registration Number	SHF300H
Case Reference Number	TAX/08/19/2122
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN YANG HUAT
Type of Accident	Rear To Head
Accident Date and Time	28/8/2019 8:40 PM
Accident Reported Date and Time	29/8/2019 3:16 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103102
Special Instruction to ARC, if any	TP
Prepared Date and Time	29/8/2019 8:46 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$756.00	\$200.00
Total Spare Part Cost	\$4,469.48	\$433.36
Total Other Cost	\$340.00	\$40.00
TOTAL COST	\$6,072.48	\$873.36 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / Non Insurance Claimant
ARC / Surveyor Sign Off Date	29/08/2019 8:58 PM	30/08/2019 2:35 PM
Signature		
Remarks	P/P repair, take after spray. Finalize sent to stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0092	Invoice Number	
Quotation Date	09.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$756.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$10.00
TO REPLACE SUNDRY PARTS	\$100.00	\$10.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$340.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace
		81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Check X
		81185476 91	UNIT, HEADLAMP, LH	0.00	\$2,556.90	0.00	\$0.00	Replace	Check X
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given X
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check X
		52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check X
		53802471 00	FENDER SUB-ASSY, FR, LH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given X
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given X
Total					\$5,959.30		\$433.36		

433.36
+200.00
+240.00
873.36

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19015335/Etf3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : HAFIZUL FARHAN RAHMAT		Date : 25-09-2019	
		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 512L	Veh. Inspected	SHF 300H
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/087	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	30/08/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU903576487	Colour	MAROON
Odometer	138175	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R15	WEST LAKE	5 mm
L/H Front Tyre	195/50 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/50 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/50 R15	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/08/2019	Inspection Date	30/08/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 300H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, FR BUMPER (DISC 25%)	DENTED	495.50	371.63
1	SUPPORT, FR BUMPER LH (DISC 25%)	BROKEN	82.30	61.73
1	LAMP ASSY, FOG, LH	NOT NECESSARY	910.20	-
1	UNIT, HEADLAMP, LH	NOT NECESSARY	2,558.90	-
1	GRILLE, RADIATOR	NOT NECESSARY	165.00	-
1	REINFORCEMENT FRONT UPPER	NOT NECESSARY	691.10	-
1	ABSORBER, FR BUMPER	NOT NECESSARY	70.30	-
1	FENDER SUB-ASSY, FR, LH	NOT NECESSARY	933.10	-
1	EMBLEM, SIDE PANEL (HYBRID)	NOT NECESSARY	52.90	-
			5,959.30	433.36
LABOUR				
	PANEL BEATING & BODY WORK.		507.00	200.00
	SPRAY PAINT.		756.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	10.00
	TO REPLACE SUNDRY PARTS.		100.00	10.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,603.00	440.00
GRAND TOTAL			7,562.30	873.36
RECOMMENDED COST OF REPAIRS				873.36

Report Ref No. CS/SPF19015335/Etf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$800-\$1,000

RECOMMENDED REPAIR DAYS : 2

WEEKEND : 1

TOTAL DAYS : 3

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.