

ASS. REC. BY:

REF:

CS/MSG/19015338/Krf362

Special Instruction:

Surveyor

Kinnath

ASSIGNMENT (Office)

From (Person): Jocelyn Ng Shin Bun

of

MSG

Date/Time: 30.8.19 10.14 p.m

Estimated Cost: 6594.2539

Bill to:

① TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 1878X

Insured:

at Workshop m/s Chew Gwn

Tel: 6484 1626

of BIK 10 Amk

Policy No: A80458027 QMY

Claim No: 604247

Sum Insured:

Excess: 9500.00

Make of Veh:

(Client's Record)

D.O.A. 27.8.2019

CA / REV REP. / REV 24 HRS

MV: \$72K

H.O.D. Endorsement:

Date/Time: 30.8.19 11.30am

Person Contacted:

Kelly

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SLA 1878X: K

30/8/19 Report via merimen

2/9/19 Rece approved \$6437.84 from Asian

2/9/19 Informed Kelly c/A on part by part, provides (cost + 10%)
ex \$500 by email

ASS. REC. BY:

REF: MSG/CS/MSG/19015338/KV3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: nu Excess: 5000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 872K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLQ 1828A Yr Regn: 06, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MS Pulsar cc 1197Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 37827 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSK DD AC 134. 010 4708Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STB A/Rlm orTyre Size: F: 215/45 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Newton

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 27/8/19 D.O.I. 30/8/19

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass to

9/9/19 @ 1030am Xiao Yen will check & call back

19/9/19 Recd email from Jocelyn approval on LS repair

8/11 11pm @ 6500 email & confirm (Ref 3810.88, 3790)

RECEIVED 13 NOV 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 13/11 - typist

Report Format: meimenLump Sum / I.B.I.: 6500/-Days Of Repair: 5Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee

Transportation

S - RS - SI

F - RS

Others

TOTAL

200

11

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		30 Aug 2019 10:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		TAN CHOON CHUAN, ID: S1314876G, Tel: +6594346476, Email: NOEMAIL							
Vehicle Reg. No.:		SLQ1878X	Date of Loss:	27/08/2019 17:00 - :59 [25 Months and 29 Days From LTA Reg Date (Man Yr)]					
Claim Type:		OD / 604247	Policy/Cover Note No.:	AB0458027QMY (Comprehensive) Coverage: 29/06/2019 - 28/06/2020					
		Excess:	S\$500.00						
Repairer:		Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/08/2019]							
Driver/Custodian:		TAN CHOON CHUAN (61 / Male), NRIC: S1314876G, Tel: +6594346476 Email: NOEMAIL							
Adj Asg. Remarks:		Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. No estimate provided. Please revert, thank you.							
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLQ1878X (604247)**

OD

Aug 27 2019 5:00PM

[TAN CHOON CHUAN]

Chew Goon Motor

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 13/11/2019 10:19 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6500.00) - SLQ1878X - Claim Handler: Jocelyn Ng Shin Bun

Approved:6500.00:A If C under part by part repair, Veh is still below 3 years. Check items to be verified and confirmed.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 11 Nov 2019

Preliminary Advice

Vehicle No	: SLQ1878X	Accident Date	: 27/08/2019
Make	: NISSAN PULSAR	Policy No.	: A80458027QMY
Assignment Date	: 30/08/2019	Excess	: S\$500.00
Date of Inspection	: 30/8/2019	Est. Duration of Repair	: 5
Inspection At	: CHEW GOON MOTOR		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,310.88
Revised Amount	:S\$	6,500.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,500.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	39,164.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,836.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Sent: Thursday, 19 September 2019 12:06 PM
To: Chew Goon Motor(ad3)
Cc: Veron Chen (LKKAUTO); Eric; chewgoon@singnet.com.sg; Ng Chen How
Subject: RE: SLQ 1878X-DOA: 27/8/2019 (MSIG OD)

Dear Kelly,

Thank you for your email.

We note on the reason for vehicle repaired on lumpsum basis and have gotten managerial approval to allow this OD repair on a special case basis.

Please be informed that this approval should not be quoted as precedent to future cases and that all repair job at lumpsum basis have to be approved by us before the repair job start.

Thank you
Have a great week ahead!

Jocelyn Ng
Executive, Claims Services
D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Chew Goon Motor(ad3) [mailto:ad3@chewgoonmotor.com.sg]
Sent: Saturday, 14 September, 2019 12:35 PM
To: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Cc: Veron Chen | LKK Auto <veronchen@lkkauto.com>; Eric <eric@chewgoonmotor.com.sg>; chewgoon@singnet.com.sg
Subject: SLQ 1878X-DOA: 27/8/2019 (MSIG OD)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Jocelyn,

We would like to appeal for vehicle to be done on lumpsum basis.

Reason being this vehicle make & model is uncommon in Singapore, the original parts are not readily available.

Attached is letter for insured stating the same.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAuto)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Saturday, 14 September 2019 12:35 PM
To: Jocelyn Ng
Cc: Veron Chen (LKKAuto); Eric; chewgoon@singnet.com.sg
Subject: SLQ 1878X-DOA: 27/8/2019 (MSIG OD)
Attachments: SLQ1878X.pdf

Dear Jocelyn,

We would like to appeal for vehicle to be done on lumpsum basis.
Reason being this vehicle make & model is uncommon in Singapore, the original parts are not readily available.

Attached is letter for insured stating the same.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Veron Chen (LKKAUTO)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Tuesday, 10 September 2019 2:35 PM
To: Veron Chen (LKKAUTO)
Cc: Eric; chewgoon@singnet.com.sg
Subject: RE: SLQ 1878X-DOA: 27/8/2019 (MSIG OD)
Attachments: SLQ1878X.pdf

Dear Veron,

Kindly refer to the attached.

Thanks & Regards,
Xiao Yan

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Sent from Mail for Windows 10

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Monday, September 2, 2019 2:14:55 PM
To: SUR <sur@lkkauto.com>; Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>; chewgoon@singnet.com.sg
<chewgoon@singnet.com.sg>
Subject: SLQ 1878X-DOA: 27/8/2019 (MSIG OD)

Dear Kelly,

As instructed by our client, please proceed to repair the **insured vehicle SLQ 1878X, under part by part repair (Excess S\$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Note: Please provides us cost price (Costs plus 10% basis)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Lump Sum Repair Acknowledgement

By signing this letter, I authorise (w/shop)

Chew Geon Motor

to repair my vehicle back to road worthy condition on a lump sum basis.

I understand and acknowledge that a lump sum repair takes into consideration repairs and / or replacements with the use of reconditioned and ex-stocks parts wherever possible.

Vehicle No: SLQ 187.8X

Co. Reg No:

Make / Model: Nissan / Pulsar

Owner/ Driver Name: Tan Choon Chuan

Signature:

I/C No:

Acknowledgement Date:

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 2 September 2019 2:15 PM
To: SUR; Chew Goon Motor(ad3) (ad3@chewgoonmotor.com.sg);
chewgoon@singnet.com.sg
Subject: SLQ 1878X-DOA: 27/8/2019 (MSIG OD)

Dear Kelly,

As instructed by our client , please proceed to repair the **insured vehicle SLQ 1878X, under part by part repair (Excess S500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Note: Please provides us cost price (Costs plus 10% basis)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLQ1878X (604247)**

OD

Aug 27 2019 5:00PM

[TAN CHOON CHUAN]

Chew Goon Motor

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on **02/09/2019 13:44 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6437.84) - SLQ1878X - Claim Handler: Jocelyn Ng Shin Bun

Approved:6437.84:A if C under part by part repair, Veh is still below 3 years. Check items to be verified and confirmed.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 30 Aug 2019

Preliminary Advice

Vehicle No	: SLQ1878X	Accident Date	: 27/08/2019
Make	: NISSAN PULSAR	Policy No.	: A80458027QMY
Assignment Date	: 30/08/2019	Excess	: S\$500.00
Date of Inspection	: 30/8/2019	Est. Duration of Repair	: 5
Inspection At	: CHEW GOON MOTOR		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,310.88
Revised Amount	:S\$	6,437.84
Check Items (Estimated)	:S\$	2,059.61
Total	:S\$	8,497.45

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	39,164.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,836.00

Remarks

(X) The vehicle is economical for repair.

(X) Repairer request to carry out the repair using list price on Lump Sum basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	876G
Vehicle Details	
Vehicle No.:	SLQ1878X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	PULSAR 1.2L DIG-T
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	HRA2410165A
Chassis No.:	VSKDDAC13U0104708
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$17,532.00
Original Registration Date:	29 Jun 2017
First Registration Date:	29 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$7,532.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2027
PARF Rebate Amount:	\$5,649.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$33,515.00
Total Rebate Amount:	\$39,164.00

The information contained herein is correct as at 30 Aug 2019

OK

[? Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 876G

Vehicle Details

Vehicle No.: SLQ1878X
Vehicle to be Exported: No
Intended Deregistration Date: 28 Aug 2019
Vehicle Make: NISSAN
Vehicle Model: PULSAR 1.2L DIG-T
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: HRA2410165A
Chassis No.: VSKDDAC13U0104708
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$17,532.00
Original Registration Date: 29 Jun 2017
First Registration Date: 29 Jun 2017
Transfer Count: 0
Actual ARF Paid: \$7,532.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jun 2027
PARF Rebate Amount: \$5,649.00

Intended COE Rebate Details

COE Expiry Date: 28 Jun 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$33,527.00
Total Rebate Amount: \$39,176.00

The information contained herein is correct as at 28 Aug 2019

OK



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1

Individual Ownership

MOTOR MAX PLUS
Comprehensive

Certificate No. A 80458027 QMY

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle

SLQ1878X

2. Name of Policyholder

TAN CHOON CHUAN

3. Effective Date of the Commencement of Insurance for the purposes of the Act

29/06/2019

4. Date of Expiry of Insurance

28/06/2020

5. Persons or Classes of Persons entitled to drive*

TAN CHOON CHUAN

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.



Signature / Date

Counter-Signatory:

Assure Pte Ltd

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Amy Ler
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2019 11:02
Date Of Accident	27/08/2019 17:45
Exact Location Of Accident	JUNCTION OF SENKANG EAST AVE & SENKANG EAST RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ1878X
Insured/Policyholder	
Name Of Registered Owner	TAN CHOON CHUAN
NRIC No	S1314876G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94346476
Alternative Phone No	OTHERS-94346476
Vehicle Particulars	
Manufacturer	NISSAN
Model	PULSAR 1.2L DIG-T
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80458027QMY
Cover Note Number	
Driver	
Name of Driver	TAN CHOON CHUAN
NRIC No	S1314876G
Date Of Birth	21/01/1958
Occupation	OUTDOOR
Date Of Driving Pass	14/06/1979
Driving Experience	40 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94346476
Fax Number	
Contact Number	OTHERS-94346476
EMail Address	NOEMAIL

Address BLK 486C TAMPINES AVENUE 9 #07-74
 Postcode 522488
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

RED LIGHT THERE ARE THREE CAR IN FRONT OF ME. GREEN LIGHT ON FRONT THREE CAR MOVE AND I FOLLOW. AS I MOVE ON THE CAR IN FRONT SUDDENLY BRAKE WHICH WERE TOO SUDDEN THAT I HIT MY BRAKE THE CAR STILL SLIGHT FORWARD TO KNOCK ON THE CAR IN FRONT OF ME. THAT IS WHAT HAD HAPPEN, THAT ALL I HAD TO SAY.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR4167G
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver CHIA WEI PENG FABIAN
 NRIC/Passport Number S8711067B
 Contact Number 92220913
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 26/8/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

Sketch Plan #2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Road light there are three¹⁰ in front of me, from light on
 front three¹⁰ more and I follow, so I move on the car in front
 suddenly brake which were too sudden that I hit my brake the
 car still trying to forward to knock on the car in front of me that
 is what had happen that all I had to say

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 28/4/19

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Not Notified
Wp & 650dp
Et & 500dp

5days

A80458027QMY

Policy No:

29.08.2019

Date:

Accident Date : 27.08.2019

Fax: 62564315

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	根 Amount 额 \$ cts.
Estimate Cost of Repair to "Nissan Pulsar" Reg. No. SLQ1878X			
1pc	Bonnet		B 1,204.90 N ✓
1pc	Bonnet Rubber Seal		LS 77.50 N ✓
8pc	Bonnet Insulator Clips	2.60	LS 20.80 N ✓
1pc	Bonnet Lock		DIT 244.10 N ✓
1pc	Grille		CM 422.70 N ✓
1pc	Grille Emblem		LS 82.00 N ✓
1pc	Grille Chrome Moulding		LS 285.00 N ✓
2pcs	Headlamps (LED)	1,436.40	B 2,872.80 N ✓
1pc	Front Bumper		B 1,117.40 N ✓
12pcs	Front Bumper Clips	2.60	LS 31.20 N ✓
2pcs	Front Bumper Top Retainers	28.20	DIT 56.40 N ✓
1pc	Front Bumper Bracket LH		DIT 143.20 N ✓
1pc	Front Bumper Sponge		CM 176.00 N ✓
1pc	Front Bumper Reinforcement		LS 454.50 N ✓
1pc	Front Bumper Tow Cover		LS 28.10 N ✓
1pc	Front Bumper Corner Retainer LH		DIT 35.20 N ✓
1pc	Support Panel		B 329.60 N ✓
1pc	Support Panel Top Ganish		CM 417.20 N ✓
11pcs	Support Panel Top Ganish Clips	2.60	LS 28.60 N ✓
	Less 10%		8,027.20
			802.72
			7,224.48
1pc	Front Number Plate		B 45.00 SN ✓
1pc	Air Con Condenser		LS 443.40 SN ✓
1pc	Radiator		LS 638.00 SN ✓
	To Conduct Electrical Check, Focus Headlamp		30.00 200
	To Remove / Refit Air Con Condenser & Refill Gas		120.00 1000
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 500
	Labour Charge - Panel Beating, Repairing Of Chassis Member, Inner Panel, Front Fenders etc. Cnt, Weld Support & Parts Replacment.		900.00 6000
	To Spray Painting Affected Areas		850.00 7200
	Total :		10,310.88

LIK Auto Consultancy hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary money must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		30 Aug 2019 10:14 Edit Adj Rpt	\$6,500.00 Edit Estimates	\$6,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN CHOON CHUAN, ID: S1314876G, Tel: +6594346476, Email: NOEMAIL								
Vehicle Reg. No.:	SLQ1878X	Date of Loss:	27/08/2019 17:00 - :59 [25 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 604247	Policy/Cover Note No.:	A80458027QMY (Comprehensive) Coverage: 29/06/2019 - 28/06/2020						
		Excess:	\$500.00						
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/09/2019]								
Driver/Custodian:	TAN CHOON CHUAN (61 / Male), NRIC: S1314876G, Tel: +6594346476 Email: NOEMAIL								
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. No estimate provided. Please revert, thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (13/11/2019): Alert - Adj Mandate Approved (\$6500.00) - SLQ1878X - Claim Handler: Jocelyn Ng ... MSIG_SG (02/09/2019): Alert - Adj Mandate Approved (\$6437.84) - SLQ1878X - Claim Handler: Jocelyn Ng ... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ1878X (604247)

OD

Aug 27 2019 5:00PM

[TAN CHOON CHUAN]

Chew Goon Motor

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)
View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)		Thumbnail	Print
1	28/08/19 11:24	Accident Statement	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/08/19 14:21	Adjuster Immediate Advice	1	Load HTM	
2	11/11/19 11:02	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	02/09/19 09:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
27	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
28	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	11/11/19 10:58	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	11/11/19 10:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	11/11/19 10:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	29/08/19 19:19	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Load PDF
2	29/08/19 19:19	PARF COE		Load PDF
3	29/08/19 19:21	Transfer Fee Details		Load PDF
4	29/08/19 19:26	Email from Chew Goon Motor (Kelly) - to arrange survey		Load PDF
5	29/08/19 19:26	TP GIA Report - SLR4187G		Load PDF
No	Relabel/Reorder		Thumbnail	Print
1	30/08/19 14:22	LKK Auto Consultants Pte Ltd (HQ)		Load PDF
2	13/11/19 10:04	MARK ESTIMATE		Load PDF
3		FINAL MARKING		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	28/08/19 11:24	Chew Goon Motor (AMK)		Load HTML
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	28/08/19 11:13	Chew Goon Motor (AMK)		Load JPG
2	28/08/19 11:13	Accident Photo		Load JPG
3	28/08/19 11:13	Accident Photo		Load JPG
4	28/08/19 11:13	Accident Photo		Load JPG
5	28/08/19 11:13	Accident Photo		Load JPG
6	28/08/19 11:13	Accident Photo		Load JPG
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	28/08/19 11:16	Chew Goon Motor (AMK)		Load JPG
2	28/08/19 11:16	Sketch Plan		Load JPG
3		Sketch Plan #2		Load JPG

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div> <div></div> <div></div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19015338/KVF3E2

Date: 14/11/2019

REFERENCE

Insured/Claimant:	TAN CHOON CHUAN	Policy No:	A80458027QMY	
Date of Loss:	27/08/2019	Nature of Claim:	OD	Claim No: 604247

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ1878X		
Make & Model:	NISSAN PULSAR, 1.2 L DIG-T (A)	Engine No:	HRA2410165A
Reg. Date:	29/06/2017 (Man. Year: 2017)	Chassis No:	VSKDDAC13U0104708
Colour:	Metallic Grey	Odometer:	37827 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Neuton 7 mm	Rear Left Side:	Neuton 7 mm
Front Right Side:	Neuton 7 mm	Rear Right Side:	Neuton 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,350.88	6,598.40	1,752.48	20.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,490.00	470.00	23.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,310.88	8,088.40	2,222.48	21.55
Approved Total (Overridden) (S\$)		6,500.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	9,810.88	6,000.00	3,810.88	38.84
+ GST 7.00/7.00% (S\$)	686.76	420.00	266.76	38.84
Nett Amount (S\$)	10,497.64	6,420.00	4,077.64	38.84

INSPECTION

Date of Assignment: 30/08/2019

Date Inspected: 30/08/2019 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Nov 2019)	
Parts:	N/A	NISSAN PULSAR 1.2 L DIG-T (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ1878X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Bent	1,204.90 FN	*1,204.90 FN
2	1	*BONNET RUBBER SEAL	Cut	77.50 FN	*77.50 FN
3	8	*BONNET INSULATOR CLIPS	Necessary	20.80 FN	*20.80 FN
4	1	*BONNET LOCK	Distorted	244.10 FN	*244.10 FN
5	1	*GRILLE	Cracked	422.70 FN	*422.70 FN
6	1	*GRILLE EMBLEM	Necessary	82.00 FN	*82.00 FN
7	1	*GRILLE CHROME MOULDING	Dented	285.00 FN	*285.00 FN
8	1	*HEADLAMPS (LED)	N/S Mtg Cracked	2,872.80 FN	*1,436.40 FN
9	1	*FRONT BUMPER	Bent	1,117.40 FN	*1,117.40 FN
10	12	*FRONT BUMPER CLIPS	Necessary	31.20 FN	*31.20 FN
11	1	*FRONT BUMPER TOP RETAINERS	O/S Repair / N/S Distorted	56.40 FN	*28.20 FN
12	1	*FRONT BUMPER BRACKET LH	Distorted	143.20 FN	*143.20 FN
13	1	*FRONT BUMPER SPONGE	Cracked	176.00 FN	*176.00 FN
14	1	*FRONT BUMPER REINFORCEMENT	Repair	454.50 FN	*- FN
15	1	*FRONT BUMPER TOW COVER	Serviceable	28.10 FN	*- FN
16	1	*FRONT BUMPER CORNER RETAINER LH	Distorted	35.20 FN	*35.20 FN
17	1	*SUPPORT PANEL	Buckled	329.60 FN	*329.60 FN
18	1	*SUPPORT PANEL TOP GARNISH	Cracked	417.20 FN	*417.20 FN
19	11	*SUPPORT PANEL TOP GARNISH CLIPS	Necessary	28.60 FN	*28.60 FN
20	1	*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
21	1	*AIR CON CONDENSER	Punctured	443.40 FS	*443.40 FS
22	1	*RADIATOR	Punctured	638.00 FS	*638.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	9,153.60	7,206.40
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	802.72	608.00
Total Parts (\$\$)	8,350.88	6,598.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT ELECTRICAL CHECK, FOCUS HEADLAMP	New	30.00	20.00
2	TO REMOVE / REFIT AIR CON CONDENSER & REFILL GAS	New	120.00	100.00
3	TO REMOVE / REFIT, RADIATOR SYSTEM, BLEED, REFILL COOLANT	New	60.00	50.00
4	TO SPRAY PAINTING AFFECTED AREAS	New	850.00	720.00
5	LABOUR CHARGE - PANEL BEATING, REPAIRING OF CHASSIS MEMBER, INNER PANEL, FRONT FENDERS ETC. CUT, WELD SUPPORT & PARTS REPLACEMENT	New	900.00	600.00
Gross Labour Cost (S\$)			1,960.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >