

ASS. REC. BY:

REF: CS3/Asm19015349/Hqf302

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Cynthia Loh

of

Asm (AxA)

Date/Time: 30.8.19 11.51 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 1586 R

Insured:

SCA 138x

at Workshop m/s My Car Consultant

Tel:

98686000

of 53 Ubi Ave 1 # 01-33

Policy No:

Claim No:

S9MOIYUL

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"imp"

H.O.D. Endorsement:

Date/Time: 30.8.19 1.08 p.m

Person Contacted:

Kai Ling

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLG 1586R -x
	SCA 138x -x
	Dismantle: 5/9/2019
	After = 17/9/19
11/10/19	Submit PRS

H-ANN

REF: ASM(AxA)

PRS

ASSIGNMENT

From:

Date: 30.8.2019

Veh No: SLG 1586 R Yr Regn: 22/09/2016

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLG 1586R

Make: H. civic 1.6 VTI CAT. 1597

at Workshop m/s My Car Consultant
of 53 Old Ave 1 #01-33

Colour: Gray A/C: Insured / Std / NI / NA

Sp. Reading: 089226km T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: MRHFC 5650GT 000369

Claims No.

Gen. Cond: Good (Fair) Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil (S/Rim) / STD A/Rim or

(Policy Condition)

X			X
N/S		O/S	
X		X	

Tyre Size: F: 215/55/R16

R: 215/55/R16

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental → (Front and Rear)

Bal. or Market Value:

Front Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 5 mm R/Bal. 5 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 5 mm L/Bal. 5 mm

Est. Repairs: 14 days Res.: Yes or No

D.O.A. 28/8/2019 D.O.I. 30/8/19

Lum Sum: % 3 Val: Yes or No

Survey held at my car consultant

CA / REV / REP. / 24 HRS

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Remarks: This vehicle NON Estimate.
→ (PRS) case #

MV - 72000
PV - 51997
NV - 20000

RECEIVED 11 OCT 2019

MV - 7172

range → 13K - 16K
repair Days → 14 day

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

1) 11/10 transfer

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Add Fee: : Site Insp (\$

Survey Fee: 100

2)

: Interview (\$

Transportation: \$ + RS, SI

Report Format : PRS

: Tech. Invs (\$

Photos

Lump Sum / I.B.I: (\$

: Weekend (\$

Others

TOTAL

100

◀ Service Request Details

Claim

S9M01YUL

Reference

None 

Loss Date

August 28, 2019

Report Date

Aug 30, 2019 11:51:00 AM

Request Date

August 30, 2019

Due Date

September 6, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Kai Ling

T: 1.01 p.m

v: 14

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLG1586R

Model
CIVIC

Service Address

...

Primary Contact/Insured

INA ENGINEERING & CONSTRUCTION PTE LTD
2 TUAS AVENUE 9, 639169, Singapore
68623887
ANGELINE@TIB.COM.SG

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages Invoices History Documents ⁶ Assessment Metrics Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: My Car Consultant <admin@mycar.sg>
Sent: Friday, 30 August, 2019 11:23 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] OUR REF: SLG1586R YOUR REF: SCA138X PRE-REPAIR INSPECTION FOR SLG1586R
Attachments: SAS2660323.PDF
Categories: Raghav

WITHOUT PREJUDICE

OUR REF: SLG1586R
YOUR REF: SCA138X

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SLG1586R
ACCIDENT INVOLVING SLG1586R AND SCA138X

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Warm Regards,
Kai Ling

My Car Consultant Pte Ltd
53 Ubi Avenue 1
Paya Ubi Industrial Park
#01-33 S(408934)

Tel: +65 9868 6000 / Fax: 6925 5219

CONFIDENTIALITY NOTICE: This message (including any attachments) is confidential and may be privileged. It may be read, copied and used only by the intended recipient. If you have received it in error please contact the sender (by return e-mail) immediately and delete this message. Any unauthorized use or dissemination of this message in whole or in parts is strictly prohibited.



Immediate Advice

To : AXA Insurance Pte Ltd

11/10/2019

Survey Details:

Date of loss	28-Aug-19
Date of appointment	30-Aug-19
Date of survey	30-Aug-19
Location of survey	MY CAR CONSULTANTS PTE LTD

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SLG 1586R
Make and Model	HONDA CIVIC 1.6VTI CVT
Date of registration	22/9/2016
Excess	-
Market Value	\$ 72,000.00
Parf Rebate	\$ 51,997.00
Nett Loss	\$ 20,003.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>14</u>
---------------------------	-----------



Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$13,000.00 - \$16,000.00.

Mandate:

Liability(TP)		%
Proposed repair cost		\$
Loss of use		\$ no. of days
Loss of rental		\$ no. of days
Loss of income		\$ no. of days
LTA search fees		\$
Others		\$
Proposed Total		#VALUE!

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SLG1586R		
Vehicle Type:	N18 - Passenger (Co) Company Car (Single Rate)		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	HONDA		
Vehicle Model:	CIVIC 1.6 VTI CVT		
Chassis No.:	MRHFC5650GT000369		
Propellant:	Petrol		
Engine No.:	R16B21600497		
Engine Capacity:	1597 cc		
Maximum Power Output:	92.0 kW (123 bhp)		
Maximum Laden Weight:	1670 kg		
Unladen Weight:	1249 kg		
Year Of Manufacture:	2016		
Original Registration Date:	22 Sep 2016		
Lifespan Expiry Date:	-		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium:	\$53,000.00		
COE Expiry Date:	21 Sep 2026		
Road Tax Expiry Date:	21 Sep 2019		
PARF Eligibility Expiry Date:	21 Sep 2026		
Inspection Due Date:	21 Sep 2019		
Intended Transfer Date:	02 Sep 2019		
CO2 Emission:	153.00 (g/km)		
CEV/VES Rebate Utilised Amount:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 21 Sep 2019. You may renew the road tax from 22 Jun 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Sep 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 22 Sep 2019 to 21 Mar 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	371.00	-	371.00
Total Amount Payable:			396.00
Amount Payable (From 22 Sep 2019 to 21 Sep 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	742.00	-	742.00
Total Amount Payable:			767.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	436R
Vehicle Details	
Vehicle No.:	SLG1586R
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	R16B21600497
Chassis No.:	MRHFC5650GT000369
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,491.00
Original Registration Date:	22 Sep 2016
First Registration Date:	22 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,491.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2026
PARF Rebate Amount:	\$14,618.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$37,379.00
Total Rebate Amount:	\$51,997.00

- 9745.5

The information contained herein is correct as at 02 Sep 2019

OK *Balance: 7 year 1 month*
Depreciation: 8900 year

MV = 72000
PV = 51997
NV = 20000

8900 / 12 = 741 months

62300 + 741 + 9745.5
= 72786 #

MV - 7172

Honda Civic Price Range Depreciation 2016 Vehicle Type

Advanced Search

Home » Used Cars » Motorist Pte Ltd » Honda Civic 1.6A VTi

Honda Civic 1.6A VTi

Overview Financial Insurance Accessories Similar Research Photos Map

CONSIGNMENT

Price	\$76,000		
Depreciation ⓘ	\$9,380 /yr View models with similar depre	Reg Date	26-Sep-2016 (7yrs 22days COE left)
Mileage	41,000 km (14k /yr)	Manufactured ⓘ	2016
Road Tax ⓘ	\$742 /yr	Transmission	Auto
Dereg Value ⓘ	\$51,573 as of today (change)	OMV ⓘ	\$19,491
COE ⓘ	\$52,301	ARF ⓘ	\$19,491
Engine Cap	1,597 cc	Power	92.0 kW (123 bhp)
Curb Weight ⓘ	1,249 kg	No. of Owners ⓘ	1
Type of Vehicle	Mid-Sized Sedan		

Features

1.6L I-VTEC Engine, 123 BHP, 5 Speed Automatic With Paddle Shifters, ABS, SRS Airbags, Eco Assist. View specs of the Honda Civic (2016)

Accessories

Leather Seats, Factory Fitted Audio System, 16" Sports Rims, Retractable Side Mirrors With Indicators, Reverse Camera, Solar Film.

Description

Well Maintained Unit Under Honda 5 Yrs Warranty And Unlimited Mileage. New Facelift Honda Civic 1.6L, 1 Owner, 41000km Genuine Low Mileage, Trade In /high Loans Welcome, Low Interest Rate From 2.28%. Call/Whatsapps To View This Beauty, Strictly By Appointment Only.

Category

PARF Car, Consignment Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Owner Consignment Car


This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » List of owner consignment cars
- » List of consignment agents



Price Chart

Summary



Click on the point to view the vehicle

- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Posted on: 02-Sep-2019 | Last Updated on: 03-Sep-2019

Upfront Payment

» more Financial info

Transfer Fee ⓘ	\$25	
Down	\$22,800 (change)	Maximum 70% Loan
1s Compare	\$765	Based on 2.98% interest rate

Seller Information

Company Motorist Pte Ltd
» dealer's pricelist

Exclusive Roadshow Deal - up to \$10,000 off all Toyota Models.
Bedok Mall, Level 1 Atrium, 28 Aug - 3 Sep 2019



Honda Civic Price Range Depreciation 2017 Vehicle Type

Advanced Search

Home » Used Cars » ValueCars Auto Traders » Honda Civic 1.6A VTi

Honda Civic 1.6A VTi

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$86,800		
Depreciation ⓘ	\$9,470 /yr View models with similar depre	Reg Date	20-Oct-2017 (8yrs 1mth 16days COE left)
Mileage	17,077 km (9.1k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$742 /yr	Transmission	Auto
Dereg Value ⓘ	\$50,429 as of today (change)	OMV ⓘ	\$19,532
COE ⓘ	\$44,002	ARF ⓘ	\$19,532
Engine Cap	1,597 cc	Power	92.0 kW (123 bhp)
Curb Weight ⓘ	1,249 kg	No. of Owners ⓘ	1
Type of Vehicle	Mid-Sized Sedan		

Features

1.6L I-VTEC Engine, 123Bhp, 5 Speed Automatic With Paddle Shifters, ABS, SRS Airbags, Eco Assist, Cruise Control, Stock Sports Rims, Leather Seats. View specs of the Honda Civic (2016)

Accessories

Keyless Entry/Start/Stop, Factory Fitted Audio System, Multi Function Steering, Solar Films, Reverse Camera, Fog Lights, Leather Seats, Sport Rims.

Description

1 Owner Only. Flexible Loan Available. Serviced And Maintained By Agent Since Day 1, Super Low Mileage, 5 Years Warranty From Agent, Almost New Interior And Exterior Condition, Accident Free. Come View And We Discuss Further, Thanks.

Category

PARF Car, Low Mileage Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 01-Sep-2019 | Last Updated on: 03-Sep-2019

Upfront Payment » more Financial info

Transfer Fee ⓘ	\$25	
Down	\$26,040 (change)	Maximum 70% Loan
1s Compare	\$874	Based on 2.98% interest rate



Shortlist Compare Add note
Report Error More Actions

Seller Information

Company	ValueCars Auto Traders » dealer's pricelist » 46 vehs sold 18 vehs available
Address	61 Ubi Avenue 2 #02-06 Search cars nearby this location
Location	Automobile Megamart
Office No	68410062
Contact Person(s)	Mr Lim 90888810

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2019 15:41
Date Of Accident	28/08/2019 19:15
Exact Location Of Accident	SLE (MANDAI EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG1586R
Insured/Policyholder	
Name Of Registered Owner	HOSHIZAKI SINGAPORE PTE LTD
Co Reg No	199906436R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62252612

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01014324
Cover Note Number	

Driver

Name of Driver	FONG KAH MENG ALVIN
NRIC No	S7441999B
Date Of Birth	19/12/1974
Occupation	OUTDOOR
Date Of Driving Pass	11/10/1996
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90177516
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 56 BUKIT BATOK ST 31 #10-15
 Postcode 659445
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 6
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : RYKIEL FONG
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPPORT: T/20190829/7010.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCA138X } (BMW 1730A1 A/T P/AB 4DR 2ED)
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLA6535L
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJP3145T
Vehicle Make/Model/Colour
Details Of Properties VEHICLE D
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SJH9920A
Vehicle Make/Model/Colour
Details Of Properties VEHICLE E
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SLG56K
Vehicle Make/Model/Colour
Details Of Properties VEHICLE F
Vehicle Category PRIVATE CAR
Name of Driver

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name FONG KAH MENG ALVIN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLG1586R
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind a policy liability.
4. The issue and acceptance of this Form by Insurers' companies is not an admission of policy liability on the part of the insurance companies.
5. Any fees responding may be referred to the Police for Investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MY CAR



**SINGAPORE
POLICE FORCE**



T/20190829/7010

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190829/7010

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/08/2019 11:05		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: FONG KAH MENG, ALVIN			Address: 56 BUKIT BATOK STREET 31 #10-15 SINGAPORE 659445		
ID Type / ID No.: NRIC NO / S7441999B			Contact No.:		Mobile: 90177516
Nationality: SINGAPORE CITIZEN			Email: newkokuo@yahoo.com.sg		
Sex: Male	Age: 44	Date of Birth: 19/12/1974	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SALESMAN			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident					
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 28/08/2019 19:15	Type of Location: Straight Road	
Location: SELETAR EXPRESSWAY					
Weather: Clear		Road Surface: Dry		Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC1613U	Bus/Coach/Mi nibus					0
SCA138X	Car					0
SJH9920A	Car					0
SJP3145T	Car					0
SLA6535L	Car					0



**SINGAPORE
POLICE FORCE**



T/20190829/7010

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190829/7010

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLG1586R	Car				Slightly Damaged	1
SLG56K	Car					0
XD6101Y	trailer					0

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	FONG KAH MENG, ALVIN	ID No.	S7441999B
Related Vehicle	SLG1586R (Car)	Contact No.	90177516
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the stated time and date, I was driving my vehicle SLG1586R at SLE mandai exit. I was driving at the extreme left lane proceeding to exit mandai ave, as the traffic was heavy, the traffic was moving slow. Suddenly i felt a great impact on the rear of my vehicle and the impacted causes my vehicle to move forward and collided on the front vehicle, XD6101Y

After the accident, I alighted from my vehicle to make a check and discovered that there is a chain collision involving 8 vehicle . There are 6 vehicle behind my vehicle and 1 vehicle in front of my vehicle. the first vehicle was a trailer, XD6101Y followed by, SLG1586R, SCA138X, SLA6535L, SJP3145T, SJH9920A, SLG56K and PC1613U. It observed that the last vehicle, a bus, PC1613U had collided onto the vehicle causing the rest of the vehicle to collide to the front vehicle.

After the accident the trailer, XD6101Y, did not alight from the vehicle and just drove off.

After the accident I felt uncomfortable and consult the doctor and get 5 days MC.



**SINGAPORE
POLICE FORCE**



T/20190829/7010

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190829/7010

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / TPiB / ANG YI TING, STEPHANIE Contact No.: 65476414

Authentication Stamp
NP168

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 29/08/2019 11:05
Classification Of Case:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM19015349/Hqf3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 15-10-2019	
ATTN : CYNTHIA LOH		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SCA 138X	Veh. Inspected	SLG 1586R
Policy No.		Coverage (\$)	0.00
Claim No.	S9M01YUL	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	30/08/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA CIVIC 1.6 VTI CVT	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHFC5650GT000369	Colour	GREY
Odometer	89226 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R16	CONTINENTAL	5 mm
L/H Front Tyre	215/55 R16	CONTINENTAL	5 mm
R/H Rear Tyre	215/55 R16	CONTINENTAL	5 mm
L/H Rear Tyre	215/55 R16	CONTINENTAL	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information			
Accident Date	28/08/2019	Inspect Date / Time	30/08/2019 (01:37 PM)
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$13,000-\$16,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	

Report Ref No. CS3/ASM19015349/Hqf3e2

Inspected By

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.