

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen SKODA Commercial Vehicles

Quotation

Non binding - Preview

Page 1/2

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
MOHAMED
JOHARI KAZURA
42 ARAB STREET
Singapore 199741

Document no.
Document date 26-08-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001674/1
Job order date 13-08-2019
Service Advisor YEN MEI WONG

License plate SDN7728S Model code AD14PY First registration 28-12-2018 VIN WVZZZZ5NZJW972674 Model Tiguan Highline 1.4 TSI 110kW DSG Mileage 5,243

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	200.00	#1	200.00	214.00
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
5NA807217J GRU	Cover For Bumper Primed	1	pcs.	1,076.60	28.00% #1	775.15	829.41
5NA807049A	Guide Piece	1	pcs.	19.18	28.00% #1	13.81	14.78
	BUMPER SIDE BRACKET LH						
5NA805903A 9B9	Spoiler Satin Black	1	pcs.	216.81	28.00% #1	156.10	167.03
5NA807248H	Foam Insert	1	pcs.	51.36	28.00% #1	36.98	39.57
5NA853211A 9B9	Trim Satin Black	1	pcs.	40.33	28.00% #1	29.04	31.07
	LHS FOG LAMP TRIM COVER						
5NA854661 9B9	Cooling Air Grill Satin B	1	pcs.	55.28	28.00% #1	39.80	42.59
	LHS FOG LAMP UPPER GRILLE						
5NA919399 GRU	Sensor Bracket Primed	1	pcs.	13.79	28.00% #1	9.93	10.63
5NA919400 GRU	Sensor Bracket Primed	1	pcs.	13.79	28.00% #1	9.93	10.63
3Q0919297B GRU	Sensor Primed	1	pcs.	185.02	28.00% #1	133.21	142.53
3Q0919133 9B9	Seal Ring Satin Black	1	pcs.	2.25	28.00% #1	1.62	1.73
	SENSOR O-RING						
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	28.00% #1	53.49	57.23
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	28.00% #1	40.97	43.84
5NA955103A	Pressure Cylinder With Je	1	pcs.	118.08	28.00% #1	85.02	90.97
	NOZZLE CYLINDER LH						
5NA807937 GRU	Cap Primed	1	pcs.	40.91	28.00% #1	29.46	31.52
	NOZZLE CAP LH						
5NC941113D	Led Headlight	1	pcs.	1,805.67	28.00% #1	1,300.08	1,391.09
	LHS H/LAMP						
5NA941699B	Halogen Fog Lights With S	1	pcs.	222.97	28.00% #1	160.54	171.78
	LHS FOG LAMP						
5NA821105	Fender	1	pcs.	571.20	28.00% #1	411.26	440.05
5NA821135B	Cross Support	1	pcs.	36.27	28.00% #1	26.11	27.94
	LHS FENDER BRACKET						
5NA854731E 9B9	Wheel Cover Satin Black	1	pcs.	148.69	28.00% #1	107.06	114.55
	LHS FENDER PROTECTOR PAD						
3C0853586	Grommet	8	pcs.	1.52	28.00% #1	8.76	9.37
	LABOUR	4	pcs.	475.00	#1	1,900.00	2,033.00
	Spray Painting	4	pcs.	500.00	#1	2,000.00	2,140.00

Quotation valid till 20-08-2019

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	560.00	7,328.32	1,333.23	7%	552.18	1,333.23	7,888.32	8,440.50
Total	560.00	7,328.32	1,333.23		552.18	1,333.23	7,888.32	8,440.50

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page 2/2

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
MOHAMED
JOHARI KAZURA
42 ARAB STREET
Singapore 199741

Document no.
Document date 26-08-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001674/ 1
Job order date 13-08-2019
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SDN7728S	AD14PY	28-12-2018	WVGZZZ5NZJW972674	Tiguan Highline 1.4 I TSI 110kW DSG	5,243

Customer

Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5-6 days
30/08/19 @1640
Excess: 1500
Revert
Resurvey before paint