

ASS. REC. BY:

REF: CS/MSG 11015351/DTF307

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Christina Wang

of

MS19

Date/Time:

30.8.19 1329p

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 671B

Insured:

YN 6057C

at Workshop m/s

SG 98 motor

Tel:

64524898

of

Bik 4001 Ama Industrial park 1 #01-21

Policy No:

A29003359 MKC

Claim No:

604200

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27.8.219

CA / REV / REP. / REV 24 HRS

map

3.9.2019

H.O.D. Endorsement:

Date/Time:

30.8.19 131p.m

Person Contacted:

Rose

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

FBL 671B - X

YN 6057C - X

SLA-


Revised via menmen preli advise.

REF:

REF:

ASSIGNMENT

From: Date:
 Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No:
 at Workshop m/s
 of
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBL 671 B Yr Regn: 2016 / May
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Paggio Gilera C.C. 198
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 61078 T/Radio: Insured / Std / NI / NA
 Eng/No: M464M0010409
 C/No: ZAPM4640100007085
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 120 / 70 R14
 R: 140 / 60 R13
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Michelin
 Front 3 mm Rear 3 mm
 R/Bal. 3 mm L/Bal. 3 mm
 L/Bal. mm L/Bal. mm
 D.O.A. 27/08/2019 D.O.I. 03/09/2019
 Survey held at SG 98 AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/8 front y 0/8 Body y 0/8 Rev
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSG YN 6057C
22/11/2019	Inspected with Rose H/S 2250/- with 3 days 7 in (Red: 3062.50: 57%)
RECEIVED 22 NOV 2019	
22/11/2019	

Date/Time, File Pass to? 22/11/2019 ☐ : Preli. Report
☒ : Final Report
 Date/Time, File Return to?
 2)
 Report Format: TP
 Lump Sum / I.B.I: (\$) 2250/-
 Days Of Repair: 3
 Resurvey No. of Trip: 2
 Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)
 Survey Fee: 190
 Transportation:
 Photos 11
 Others
 TOTAL 161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		30 Aug 2019 13:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		PROXY EXPRESS SERVICE, Co. Reg. No.: 52311500L [Created by insurer]							
Main Claimant:		NASIRUDDIN BIN MOKHTAR, ID: S8703306F							
Vehicle Reg. No.:	FBL671B	Date of Loss:	27/08/2019 11:00 - :59 [39 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 604200	Policy/Cover Note No.:	A29003359MKC (Comprehensive) Coverage: 12/08/2019 - 11/08/2020						
Vehicle Reg. No. (Insured):	YN6057C	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/08/2019]								
Driver/Custodian (Insured):	CHEW HENG LACK (59 / Male), NRIC: S1446484J, Tel: +6596227441 Email:								
Adj Asg. Remarks:	on WP. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Leena @ 6452 4898.								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 05 Sep 2019

Preliminary Advice

Insured Vehicle No : YN6057C

TP Vehicle No : FBL671B

Make : PIAGGIO GILERA RUNNER

Date of Inspection : 03/09/2019

Inspection At : SG 98 MOTOR PTE LTD (HQ)

BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21
SINGAPORE 569622

Accident Date : 27/08/2019

Assignment Date : 30/08/2019

Est. Duration of Repair : 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front, o/s body, o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	790.00
Revised Amount	:S\$	360.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	360.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/08/2019 16:07
Date Of Accident	27/08/2019 11:00
Exact Location Of Accident	TUAS DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL671B
Insured/Policyholder	
Name Of Registered Owner	NASIRUDDIN BIN MOKHTAR
NRIC No	S8703306F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93373064
Alternative Phone No	OTHERS-93373064

Vehicle Particulars

Manufacturer	PIAGGIO
Model	GILERA RUNNER ST 200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5080462812-03
Cover Note Number	

Driver

Name of Driver	NASIRUDDIN BIN MOKHTAR
NRIC No	S8703306F
Date Of Birth	15/02/1987
Occupation	INDOOR
Date Of Driving Pass	18/08/2006
Driving Experience	13 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93373064
Fax Number	
Contact Number	OTHERS-93373064
EMail Address	NOEMAIL

Address	BLK 313 #02-457 UBI AVENUE 1
Postcode	400313
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 JURONG WEST AVENUE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO: 67912972
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190827/2094;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6057C
Vehicle Make/Model/Colour	MITSUBISHI / CANTER FEB21ER4SDEB
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

27 AUG 2019
IDAC KAKI BUKIT (VAC)
Reporting Centre: 23 Kaki Bukit Ave 4
Name: Singapore 415933
NRIC/TEL: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- REFER TO POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time: 27 Aug 2019 11:00

[Signature]
Driver's Signature
(If driver is not the policyholder)

Date & Time:

27 AUG 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signature

Name: Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190827/2094

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 4

Report No. T/20190827/2094

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/08/2019 15:03	Vide Report No.:	Station Diary No.: 278
--	------------------	---------------------------

Informant's Particulars

Name of Informant: NASIRUDDIN BIN MOKHTAR			Address: APT BLK 313 UBI AVENUE 1 #02-457 SINGAPORE 400313	
ID Type / ID No.: NRIC NO / S8703306F			Contact No.: Home/Office: Mobile: 93373064	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 32	Date of Birth: 15/02/1987	Type of Informant: Vehicle Owner	
Race: Malay			Language:	Institution / School Name:
Occupation: SERVICE SPECIALIST			Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 27/08/2019 11:00	Type of Location: Car Park
Location: Along Road 1 TUAS DRIVE 1 Number 14 Tuas Drive 1				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL671B	Motorcycle				Slightly Damaged	0
YN6057C	Lorry				No Damage	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190827/2094

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 4
Report No. T/20190827/2094

CONTINUATION OF REPORT

Vehicle Owner			
Name	NASIRUDDIN BIN MOKHTAR		ID No. S8703306F
Related Vehicle	FBL671B (Motorcycle)		Contact No. 93373064
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHEW HENG LACK		ID No. S1446484C
Related Vehicle	YN6057C (Lorry)		Contact No. 96227441
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 27/08/2019 at a bout 1100hrs I was at my workplace at 14 Tuas Drive 1. My motor bike registered number FBL671B was parked in the vicinity of my company parking lot. My friend namely Arun called me and informed me that he heard a loud sound and went to make a check. Arun saw that my motorbike had been dropped and a Chinese man was trying to make my motorbike stand. Arun helped the Chinese man to steady my motorbike.

Upon my arrival I saw that the Chinese man was driver of the lorry registered number YN6057C that was right in front of my motor bike. I asked the Chinese man if he had knocked my motorbike and he denied that he had hit onto my motorbike. I was going to question him further when he just got in his lorry and drove off.

I then went to my company guard house to get the driver particulars and saw the CCTV camera. The CCTV camera clearly showed that the Chinese man had hit onto my motorbike.

I discovered that my motorbike brake lever was dented and the right hand side of my motorbike suffered significant scratches

The driver particulars is :
Name: Chew Heng Lack
HP: 96227441
Company: Proxy Express.

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190827/2094

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

3 of 4

Report No. T/20190827/2094

CONTINUATION OF REPORT

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190827/2094

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

4 of 4

Report No. T/20190827/2094

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 AMRITPAL SINGH SANDHU

A

Signature Of Informant:

Jain

Signature Of Interpreter:

Not applicable

Date/Time

27/08/2019 15:03

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp
NP168

SN 127



Signature :

A

Singapore Police Force

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 3rd September 2019

To : LKK

Attn : Bryan

Tel :

By Fax:

VEHICLE NO : FBL 671B

Gilera Runner ST200

ACCIDENT DATE: 27th August 2019

Description	Qty	Quotation \$
1 Brake Lever <i>St</i>	1	150.00 ✓
2 Handle Bar <i>NH</i>	1	265.00 X
3 Pillion Grip <i>NH</i>	1	180.00 X
4 Rear Tail Side Panel RH <i>Cut</i>	1	560.00 ✓
5 Exhaust Pipe <i>St Replaced</i>	1	800.00 500/-
6 Front RH Side Panel <i>Cut</i>	1	350.00 ✓
7 Foot Rest RH <i>Cut</i>	1	210.00 ✓
8 Shock Absorber Bitubo <i>disturbed</i>	1 Set	800.00 500/-
9 Front Panel <i>Cut</i>	1	250.00 ✓
10 Front Fender Panel <i>NH</i>	1	380.00 X
11 Front RH Guard Black <i>regr</i>	1	295.00 X
12 Rear RH Pillion Grip Bar <i>Cut</i>	1	235.00 ✓
13 Meter Top Cover <i>NH</i>	1	350.00 X
Sub-Total		2479.50
Less 10%		482.50
Sub-Total		4,342.50

VEHICLE NO : FBL 671B

Gilera Runner ST200

Nett items

1	Towing fees <i>HH</i>	40.00 X
2	Labour to remove & replace necessary parts, align & etc	250.00 180/-
3	Remove & replace Exhaust Pipe Shock Absorber	220.00 50/-
4	Putty & touch up paint work	280.00 120/-
5	Rear Runner Panel Sticker <i>huc</i>	100.00 30/-
6	Gilera Emblem <i>SVC</i>	80.00 X

Sub-Total

970.00

Nett Total

5,312.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

[Signature]
22/11/2019

03/09/2019 @ 1800m

not Actual

L/Sum 3 days

[Signature]
Yan

LKK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To be notified before/after spray painting
- To be notified during resurvey
- To be notified of any information
- To be notified of any "For office" basis
- No liability for any damage
- Supplemental work is subject to final inspection and approval

Acknowledged by Repairer

Signature:

Date:

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 3rd September 2019

To : LKK

By Fax:

Attn: Bryan

Tel :

VEHICLE NO : FBL 671B

Gilera Runner ST200

ACCIDENT DATE: 27th August 2019

Description	Qty	Quotation \$
1 Brake Lever <i>BT</i>	1 ✓	
2 Handle Bar <i>NH</i>	1 X	
3 Pillion Grip <i>NH</i>	1 X	
4 Rear Tail Side Panel RH <i>Cut</i>	1 ✓	
5 Exhaust Pipe <i>BT</i>	1 ✓	
6 Front RH Side Panel <i>Cut</i>	1 ✓	
7 Foot Rest RH <i>Cut</i>	1 ✓	
8 Shock Absorber Bitubo <i>2 distancer</i>	1 Set ✓	
9 Front Panel <i>NH</i>	1 X	
10 Front Fender Panel <i>NH</i>	1 X	
11 Front RH Guard Black <i>NH</i>	1 X	
12. <i>Rev RH Pillion grip bar cut</i>	✓	
Sub-Total		0.00
Less 10%		0.00
Sub-Total		0.00

LKK Auto Consulting hence notify
the Repairer of the following:
• To maintain relevant repair records
• To display damaged parts in a visible manner
• Parts prices are subject to local market
• Third party survey cost is without Pre-approval
• No repair work should be carried out without
• Supplier's entry for repair work should be reviewed and
is subject to final sign-off from LKK Auto Consulting Company

Acknowledged by Repairer
Signature
Date

VEHICLE NO : FBP 7959E

Honda PCX150R ABS Auto

Nett items

- | | | |
|---|---|-------------------------|
| 1 | Towing fees <i>nh</i> | 40.00 X |
| 2 | Labour to remove & replace necessary parts, align & etc | 250.00 180/- |
| 3 | Remove & replace Exhaust Pipe Shock Absorber | 220.00 60/- |
| 4 | Putty & touch up paint work | 280.00 120/- |
| 5 | Rear Runner Panel Sticker <i>hce</i> | |
| 6 | Gilera Emblem <i>svl</i> | |

Sub-Total	790.00
Nett Total	790.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

5/9/19

03/09/19 @ 180km
N/A Actual

2/smm
3 days.

yan

LKK Auto

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		30 Aug 2019 13:29 Edit Adj Rpt	S\$2,250.00 Edit Estimates	S\$2,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	PROXY EXPRESS SERVICE, Co. Reg. No.: 52311500L	
Main Claimant:	NASIRUDDIN BIN MOKHTAR, ID: S8703306F	
Vehicle Reg. No.:	FBL671B	Date of Loss: 27/08/2019 11:00 - :59 [39 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 604200	Policy/Cover Note No.: A29003359MKC (Comprehensive) Coverage: 12/08/2019 - 11/08/2020
Vehicle Reg. No. (Insured):	YN6057C	Policy No. (Claimant):
		Excess: S\$600.00
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 29/09/2019]	
Driver/Customer (Insured):	CHEW HENG LACK (59 / Male), NRIC: S1446484J, Tel: +6596227441 Email:	
Adj Asg. Remarks:	on WP. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Leena @ 6452 4898.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*FBL671B (604200)
[YN6057C]
TP
NASIRUDDIN BIN MOKHTAR
Aug 27 2019 11:00AM
[PROXY EXPRESS SERVICE]
Sg 98 Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No

Finalized On

MSIG Insurance (Singapore) Pte. Ltd. (HQ)

Thumbnail

Print

1

29/08/19 14:22

Accident Statement

From:SC - Reg. No: YN6057C, Claimant: PROXY EXPRESS SERVICE

Load HTM

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

05/09/19 15:34

Adjuster Immediate Advice

Load HTM

Photos/Images

3 per page

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

13/11/19 12:45

Front View Right

Load JPG

2

13/11/19 12:45

Front View Left

Load JPG

3

13/11/19 12:49

General View

Load JPG

4

13/11/19 12:49

General View

Load JPG

5

13/11/19 12:49

General View

Load JPG

6

13/11/19 12:49

General View

Load JPG

7

13/11/19 12:49

General View

Load JPG

8

13/11/19 12:49

General View

Load JPG

9

13/11/19 12:49

General View

Load JPG

10

13/11/19 12:49

General View

Load JPG

11

13/11/19 12:49

General View

Load JPG

12

13/11/19 12:49

General View

Load JPG

13

13/11/19 12:49

General View

Load JPG

14

13/11/19 12:49

General View

Load JPG

15

13/11/19 12:49

General View

Load JPG

16

13/11/19 12:49

General View

Load JPG

17

13/11/19 12:49

General View

Load JPG

18

13/11/19 12:49

General View

Load JPG

19

13/11/19 12:49

General View

Load JPG

20

13/11/19 12:49

General View

Load JPG

21

13/11/19 12:49

General View

Load JPG

22

13/11/19 12:49

General View

Load JPG

23

13/11/19 12:49

General View

Load JPG

24

13/11/19 12:49

General View

Load JPG

25

13/11/19 12:49

General View

Load JPG

26

13/11/19 12:49

General View

Load JPG

27

13/11/19 12:49

General View

Load JPG

28

13/11/19 12:49

General View

Load JPG

29

13/11/19 12:49

General View

Load JPG

30

13/11/19 12:49

General View

Load JPG

31

13/11/19 12:49

General View

Load JPG

32

13/11/19 12:49

General View

Load JPG

33

13/11/19 12:49

General View

Load JPG

34

13/11/19 12:49

General View

Load JPG

35

13/11/19 12:49

General View

Load JPG

36

13/11/19 12:49

Odometer Reading


























Load JPG

37

13/11/19 12:51

Reinspection Photo

Load JPG

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	13/11/19 12:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	13/11/19 12:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	13/11/19 12:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	13/11/19 12:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	13/11/19 12:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/08/19 14:22	TPD FBL671B GIA REPORT From: SC - Reg. No: YN6057C, Claimant: PROXY EXPRESS SERVICE	 Load PDF	
2	29/08/19 14:23	TPD FBL671B - PRI	 Load PDF	
3	29/08/19 14:23	TPD FBL671B - PRI (EMAIL)	 Load PDF	
4	29/08/19 16:06	Agree on SJE	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	30/08/19 09:59	email to workshop	 Load PDF	
2	30/08/19 12:19	email to outsource	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015352/DTF3E2

Date: 02/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29003359MKC
Claimant
Vehicle No : FBL671B **Insured Vehicle No :** YN6057C
Date of Loss: 27/08/2019 **Nature of Claim:** TP **Claim No:** 604200

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL671B**
 Make & Model: PIAGGIO GILERA RUNNER, 198cc ST 200 Engine No: M464M0010409
 Reg. Date: 18/05/2016 (Man. Year: 2013) Chassis No: ZAPM4640100007085
 Colour: White Odometer: 61078 km
 Engine Capacity: 198 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R14 Rear Tyre Size: 140/60 R13
 Front Left Side: Michelin 3 mm Rear Left Side: Michelin 3 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,522.50	2,509.50	2,013.00	44.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	350.00	440.00	55.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,312.50	2,859.50	2,453.00	46.17
Approved Total (Overridden) (S\$)		2,250.00		
Nett Amount (S\$)	5,312.50	2,250.00	3,062.50	57.65

INSPECTION

Date of Assignment: 30/08/2019
 Date Inspected: 03/09/2019 Inspected At: Sg 98 Motor Pte Ltd (HQ)
 BLK 4001 ANG MO KIO INDUSTRIAL
 PARK 1 #01-21
 Singapore 569622
 Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Dec 2019)	
Parts:	N/A	PIAGGIO GILERA RUNNER 198cc ST 200 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL671B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE LEVER	Bent	150.00 FL	*150.00 FL
2	1		*HANDLE BAR	Not Necessary	265.00 FL	*- FL
3	1		*PILLION GRIP	Not Necessary	180.00 FL	*- FL
4	1		*REAR TAIL SIDE PANEL RH	Cut	560.00 FL	*560.00 FL
5	1		*EXHAUST PIPE	Bent / Dented	800.00 FL	*500.00 FL
6	1		*RH SIDE PANEL	Cut	350.00 FL	*350.00 FL
7	1		*FOOT REST RH	Cut	210.00 FL	*210.00 FL
8	1		*SET SHOCK ABSORBER BITUBO	Distorted	800.00 FL	*500.00 FL
9	1		*FRONT PANEL	Cut	250.00 FL	*250.00 FL
10	1		*FRONT FENDER PANEL	Not Necessary	380.00 FL	*- FL
11	1		*FRONT RH GUARD BLACK	Repair	295.00 FL	*- FL
12	1		*REAR RH PILLION GRIP BAR	Cut	235.00 FL	*235.00 FL
13	1		*METER TOP COVER	Not Necessary	350.00 FL	*- FL
14	1		*REAR RUNNER PANEL STICKER	Necessary	100.00 FS	*30.00 FS
15	1		*GILERA EMBLEM	Serviceable	80.00 FS	*- FS
					Sub Total (S\$)	5,005.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	482.50
					Total Parts (S\$)	4,522.50
						2,785.00
						275.50
						2,509.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	40.00	0.00
2	LABOUR TO REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC	New	250.00	180.00
3	REMOVE & REPLACE EXHAUST PIPE SHOCK ABSORBER	New	220.00	50.00
4	PUTTY & TOUCH UP PAINT WORK	New	280.00	120.00
Gross Labour Cost (S\$)			790.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >