nneth	(C3/TM1 19015 529/ky f3 12 ASSIGNMENT
	N 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
From: Date:	Veh No: 3/16 5457 Yrr Regn: 12,
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD MP WS ITP RES I OD RES I EVA / INV I MV	, Truck / Trailer or
To Inspect Vehicle No:	Make: Renavit Cotitude c.c 19
at Workshop m/s Trans Cab	Colour M. White I Red A/C: Insured / Std / NI / N
of	Sp.Reading 561153 T/Radio: Insured / Std / N1/1
Insured:	Eng/No:
Policy No.	CNO: VIFIABLISAUC 2809
Claims No.	Gen. Cond: Ggod' Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Mil / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: Fouring 215/60R16
Remark: The veh had commenced its N/S	OIS BS / DUN / FYNOVA (GY / ES / LTA / MIG / GY / ES
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
ial. or Market Value: 8 42,3001	Email
DAC Accident Rport: Consistent? : Yes or No	S Dear 7
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm R/Bal. 7 mr
st. Repairs: 04 days Res.: Yes or No	28/17/10 Ubai.
um Sum: 20 % 3 Val.: Yes or No	Survey held at D.O.I. 2/9/19
A / DEL / DED / DATE	
A / REV / REP. / 24 HRS Vehicle: IN	Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or
ate: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	Body Structure affected due to collision
/ 1	
/ Fix pass to	
	27274-93, 83%)
11 Ly 8 53001 ( Red \$ SH ( 5457 - (53/ AXA 180/19	27274-93, 83%) 110 / RIC ball 12 0A - 62/09/2018
11 Sy 8 53001 ( Red \$ St. 5457 - (53/ AXA 180/19	27274-93, 83%) 110/RICHAL DOA-62/09/2018
11 Sy 8 53001 ( Red \$ St. 5457 - (53/ AXA 180/19	27274-93, 83%) 110/RICHEL 120A-62/09/2013 e Report / Estimate to tolcio,
1/2 & 5300 ( Red & St. 5457 - (55/AXA 186/10) 3/9@11:02am-gent FIA/Police	e Report lestimate to tolcio.
11 Ly & 5300 ( Red & SH C 5457 - (53/ AX A 180/10)  319@11:02am - gent GIA/POLICE  RECEIVE	e Report lestimate to tolcio.
JILY 8 5300 (Red & St. D 513Z - X  Alga II:02am - gent GIA/POLIC  RECEIVE	e Report lestimate to tolcio.  D 1 1 SEP 2019  Days Of Repair: 4
JILY 8 5300 (Red & SHO) 5457 - (SS/AXA 180/14)  RECEIVE PRES 107 : Prell. Report : Final Report	e Report lestimate to tolcio.
Viro, File Pass 10?  Illy 8 5300 (Red \$ St. 5454 - (\$5/AXA 186/10  St. 5132 - X  RECEIVE  Viro, File Pass 10?  : Prell. Report  : Final Report	Days Of Repair: 4  Resurvey No. of Trip: Survey Fee: 750
Viro, File Pass 10?  Illy 8 5300 (Red \$ St. 5454 - (\$5/AXA 186/10  St. 5132 - X  RECEIVE  Viro, File Pass 10?  : Prell. Report  : Final Report	Days Of Repair: 4  Resurvey No. of Trip: Survey Fee:  Transportation: 250  S+RS. SI 11
1/Ly 8 5300 (Red \$ St. 5454 - (\$5/AXA 186/10)  RECEIVE  Timo, File Pass 10? : Prell. Report : Final Report  11919 Typist Add 1	Days Of Repair: 4  Resurvey No. of Trip:  Survey Fee:  Transportation: 250
Viro, File Pass 10?  Illy 8 5300 (Red \$ St. 5454 - (\$5/AXA 186/10  St. 5132 - X  RECEIVE  Viro, File Pass 10?  : Prell. Report  : Final Report	Days Of Repair: 4  Resurvey No. of Trip: Survey Fee:  Transportation: 250  Site Insp (\$ )S.RSSI



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: -

Date: 9/9/2019

Our Ref: CC3/TMI19015529/Kyf3

The Motor Claims Department TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sirs/Mdm

### PRELIMINARY ADVICE OF VEHICLE NO. SHC 5457Y .

Please be informed that we had conducted the inspection of the above-mentioned vehicle on <u>2/9/2019</u> at the premises of M/s <u>Trans Cab</u> and have the following to report: -

Workshop Estimate Amount

: S\$ 32,574.93

Revised Estimate Amount

: S\$ 5,300.00(Lump Sum)

"Check" Items Amount

: S\$ 0.00

Market Value

: S\$

LTA Reimbursement Value

: S\$

Nett Value

: S\$ -

#### Description of Damage:


The vehicle sustained damages at the o/s body portion.

Repair days: 4

Comments/ Present Status:

Damages Consistent.

Yours faithfully Kenneth Automotive Assessor



#### Yvonne Wong (LKK Auto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Tuesday, September 10, 2019 2:18 PM

To:

Yvonne Wong (LKK Auto)

Cc:

'Jasmine Tan'

Subject:

RE: SHC5457Y DOA: 29/08/2019 -- AAD1908-235

Dear Yvonne

Amount confirmed \$ 5,300 (before GST).

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

\*\*\* Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



#### TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Yvonne Wong (LKK Auto) [mailto:yvonnewong@lkkauto.com]

Sent: Tuesday, 10 September, 2019 1:54 PM

To: waiyin.ng@transcab.com.sg; calvin.er@transcab.com.sg

Cc: jasminetan@transcab.com.sg Subject: SHC5457Y DOA: 29/08/2019

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$5,300/= @ 4 working days.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <a href="mailto:yvonnewong@lkkauto.com">yvonnewong@lkkauto.com</a> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

×

This email has been checked for viruses by AVG antivirus software. www.avg.com

### Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Monday, 9 September 2019 11:02 AM

To:

Motor Claims

Cc:

SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE

LTD, DOA: 29/8/2019, SHC 5457Y (TP VEHICLE), SLD 513Z (OI VEHICLE)

Attachments:

POLICE REPORT.pdf; GIA.pdf; ESTIMATE SHC 5457Y.pdf; PRELI ADVISED OF SHC

5457Y.pdf

#### Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5457Y at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Enclosed herewith a copy of TP's GIA report, Police Report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

#### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	878K
Vehicle No.:	SHC5457Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002300
Chassis No.:	VF1ABL15AUC280942
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$12,498.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount: Intended COE Rebate Details	\$9,373.00
COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$21,285.00
Total Rebate Amount: Message	\$30,658.00
Please note that the 8-year COE for this vehicle cannot	t be further renewed. The vehicle must be de-registered upon COE expiry or when the

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Aug 2019

OK

MTCS19114653 / Trans-Cab Services Pte Ltd - HQ ENTRY DATE & TIME: 30/08/2019 14:01 SUBMITTED BY: Kek ZheWei

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Contact Number

EMail Address

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available of the contract of the contract of the centre and to copies of the report being made available.

Bforesaid.	HINDS NOW AND THE CONTROL OF THE CON
A CONTRACTOR OF THE STATE OF TH	ACCIDENT STATEMENT
Date Of Report	30/08/2019 14:01
Date Of Accident	29/08/2019 22:20
Exact Location Of Accident	HANDY ROAD TOWARDS ORCHARD ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC5457Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	
Driver	
Name of Driver	YANG YOONG CHENG
NRIC No	S1382823G
Date Of Birth	19/05/1959
Occupation	OUTDOOR
Date Of Driving Pass	27/02/1979
Driving Experience	40 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97310634
Fax Number	

NOEMAIL

BLK 105A EDGEFIELD PLAINS

Address #06-23 821105

Postcode

Was driver an employee of the Insured's Company NO

OTHER - HIRER If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

SIDE SWIPE Type Of Accident CLEAR Weather Conditions

DRY Road Surface

Other Information

NO Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle) involved in the accident

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1 NAME:

GENDER: ; MALE

**Details of Police Action** 

Was the accident reported to the police? YES

If Yes, Please state which Police Station

ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE Police Station Name

2

NO

2

ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: Police Station Address

: UNKNOWN

SINGAPORE

TEL NO: 1800-4849999 - FAX NO: 62181399 Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT F/20190830/2038

Attachment(s)

YES Are accident photos available for attachment? Was there any video captured by Car Camera? NO NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLD513Z

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me,
    which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the
    external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

#### Sketch Plan #2 Pg. 1

Ochod Pl	0	r*¦	13-	Vi	l-	6	
						1	
			><	1			4
	/	A		$\rightarrow$	_		Mandy Rd & Orchard Rd A: SMC5457 Y B: SLD573Z
						0	A' SH SUSTV
6			-				R: GI D5737
19					+		J. 50 J. 50
	67	4	0	4	4		
	19	4	1	V I			
R	efer to	Blice Rop	ort F/2	2019.08.3	0 /20	38 -	
	- 4111						

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

Name: NRIC/FIN No.:

STARMC SketchPlanForm\_V3

2



# F/20190830/2038

1 of 2

Report No. F/20190830/2038

#### POLICE REPORT (NP299)

Police Station Of Origin Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No: 1800-4849999

Date/Time Report Made 30/08/2019 12:10	Vide Rep	oort No.		Station Diary No.
Name Of Informant YANG YOONG CHENG		C 105A EDC	SEFIELD PLAINS	#06-23
ID Type / ID No. NRIC NO / S1382823G	Contact Home/O		Mobile 97310634	
Nationality SINGAPORE CITIZEN	Email Ad	ddress		
Occupation Taxi driver	Sex Male	Age 60	Date of Birth 19/05/1959	Race Chinese
Institution/School Name	Languaç Chinese			
Date/Time Of Incident 29/08/2019 22:00	ORCHA		it SINGAPORE it road and Handy	road

#### Brief details.

I am a taxi driver driving vehicle bearing plate number (SHC5457Y)

ang Mo Kio North NPC 51 Ang Mo Kio Ave 9 S'pore 569784

On 29/08/2019 at about 2220hrs, I was driving along the junction of Orchard Toad and Handy road. It was a 3 lane road and I was travelling on lane 2 and there was another vehicle bearing plate number (SLD513Z) was travelling lane on 1.

Signature Of Officer Recording The Report:	Signature Of Informant:
F / Sgt 2 FOO CHUAN ZHEN	fr.
Signature Of Interpreter: Not applicable	Date/Time: 30/08/2019 12:10
Officer In-Charge Of Case: F / Ang Mo Kio North N.P.C / Sgt 2 KERK LI PING Contact No.: 62181998	Classification Of Case:

Authentication Stamp





F/20190830/2038

2 of 2

POLICE REPORT (NP299) CONTINUATION OF REPORT

Report No. F/20190830/2038

As I was driving straight towards the junction, I saw that the vehicle (SLD513Z) cut into my lane. And hence hit onto the side of my vehicle. Both of us stopped and exchanged particulars.

Subsequently on 30/08/2019 at 1130hrs, I went to my taxi company (Transcab) to inform them about the insurance, however my company informed that I should go and try for private settlement with the other party.

I then tried to call the contact number (9099383) which was missing 1 digit. However to no avail.

Hence I am lodging this report for record purposes.

Signature Of Officer Recording The Report:

F / Sgt 2 FOO CHUAN ZHEN

440

Signature Of Interpreter: Not applicable

Officer In-Charge Of Case: F / Ang Mo Kio North N.P.C / Sgt 2 KERK LI PING Contact No.: 62181998 Signature Of Informant:

Re

Date/Time: 30/08/2019 12:10

Classification Of Case:

Authentication Stamp

and

### Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

Vehicle No.:

Chassis No.:

Vehicle Make:

CO./GST Reg. No. 201019626G

SHC 5457Y

AAD1908-235

NOT Norhaises 6 12mp & 5300/

#### SHC 5457Y

VF1ABL15AUC280942

RENAULT

		Vernere maker	1	ATITU	DE
		Vehicle Model:			
		Date of Accident :		29.8.19	
		Third Party Insurer:			MARINE
		Date of Registration :		18/12/	2014
		PART			LIST
1	1	FENDER PANEL INNER TRIM REAR RH		\$	M 671.45 ★
2	1	FENDER PANEL REAR RH		\$	<b>1</b> 3,866.40 ★
3	1	WHEELARCH REAR RH		\$	543.47 X
4	1	DOOR PANEL REAR RH		\$	R 2,844.66
5	1	DOOR PANEL FRONT RH		\$	B 2,844.66 —
6	1	DOOR HANDLE OUTER FRONT RH		\$	Sh 477.76
7	1	DOOR HANDLE COVER FRONT RH		\$	Jn 13.22
8	1	DOOR HANDLE MODULE FRONT RH		\$	133.60
9	1	DOOR SEAL FRONT RH			ر 162.02
10	1	DOOR WHEATHESTRIP FRONT RH		\$	613.85 X
11	1	DOOR MIRROR ASSY RH		\$	1,483.40
12	1	ROCKER PANEL INNER GARNISH RH		\$	√s 466.51
13	1	ROCKER PANEL INNER RH		\$	n 1,024.79
14	1	ROCKER PANEL OUTER RH		\$	1,184.99
15	1	ROCKER PANEL CENTER RH		\$	990.25
16	1	DOOR HARNESS WIRE RH		\$	Sec. 2,670.00
-	ā	\$ 8.5	TOTAL	\$	19,991.03
			10%	\$	1,999.10
				\$	17,991.93
		Special Nett			
1	1SE	T FENDER WHEELARCH REAR RH CLIP		\$	ルへ 35.00 X
2	1	FENDER INNER TRIM CLIP RH		\$	~~ 28.00 ×
3	2	REAR WINDSCREEN SEALANT		\$	~~ 80.00 x
4	1			\$	マル 100.00 ×
5	1	REAR WINDSCREEN INNER SPONGE SEAL		\$	an 100.00 X
6	1	REAR RH DOOR STICKER '6555-3333'		\$	na 80.00 bosa
7	1			\$	Ma 80.00 605A
8	1	The second secon		\$	M 80.00 1552

### Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330 CO./GST Reg. No. 201019626G

SHC 5457Y

TOTAL \$  TOTAL PARTS \$  LABOUR  Putty And Spray Painting Of The Affected Portion. \$	<b>18,574.93</b> 6,000.00	66
LABOUR		66
	6,000.00	66
Putty And Spray Painting Of The Affected Portion. \$	6,000.00	66
Panel Beating, Knocking And Straightening The		
Necessary Portion, Remove And Renewal Of Parts,		_
Adjust And Realign The Same \$	6,000.00	50
To Rust-Proofing Of The Affected Areas. \$	170.00	601
To transfer of rear windscreen fittings and conduct		316
water seepage test. \$	in 170.00	X
To Check Electrical Lighting Concerned.	170.00	20
Labour charge to mount and dismount vehicle		
on jig bench, to facilitate repair.	na 380.00	X
To check steering geometry and computer wheel	مـ 220.00	<b>Y</b>
alignment \$	220.00	^
To remove and refit interior fittings, trimings,	1	V
garnish, fittings and other, to enable repair. \$	Λ <sub>λ</sub> 380.00	X
To transfer of front door fittings, attachment and		,
perform water seepage test. \$	170.00	60
To transfer of rear door fittings, attachment and		-
perform water seepage test.	170.00	60
the Repairer of the following:  To resurvey before a property of the following:	na 170.00	X
To transfer of tire, rim and on wheel balancing.  Parts prices are subject to confirm from  TOTAL \$	14,000.00	_
Parts prices are subject to confirmation     Third party survey is on a "Without Prejudice" basis     No illegal modification(s) is allowed	14,000.00	<u>-</u> 4:
Sopplementary Itam(x) munt be resurveyed and easily subject to final approval from Insurance Company  Over All Total	32,574.93	=
Acknowledged by Repairer Design (LLIMP CLIM) 20	9 DAYS	
Signatures Repair Days (LOWP SOW)	Eday,	

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI19015529/KYF3N2

Date:

18/09/2019

REFERENCE

Handling

Tokio Marine Insurance Singapore Ltd

Policy No:

MK000587

Insurer: Claimant

SHC5457Y

Insured Vehicle No:

SLD513Z

Vehicle No: Date of Loss:

29/08/2019

Nature of Claim:

TP

Claim No: M1906784

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC5457Y

Make & Model:

RENAULT LATITUDE, 2.0 D dCi (A)

M9R8839C002300 Engine No:

Reg. Date:

18/12/2014 (Man. Year: 2014) Metallic White/Red

Chassis No:

VF1ABL15AUC280942

Colour:

1995 cc

Odometer:

561153 km

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** 

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): **Pre-accident Condition:** 

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

215/60R16

Rear Tyre Size:

215/60R16

Front Tyre Size:

Front Left Side:

Touring 9 mm

Rear Left Side:

Giti 7 mm

Front Right Side:

Touring 9 mm

Rear Right Side:

Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 18,574.93 0.00	Adjuster's 5,255.39 0.00	Difference 13,319.54 0.00	Diff % 71.71
Miscellaneous Items Labour Paintwork Labour	14,000.00 0.00	1,360.00 0.00	12,640.00 0.00	90.29
Towing	0.00	0.00	0.00	
Calculated Gross Total ( Approved Total (Overridden)		6,615.39 5,300.00	25,959.54	79.69
	(\$\$) 32,574.93	5,300.00 371.00	27,274.93 1,909.25	83.73 83.73
Nett Amount		5,671.00	29,184.18	83.73

INSPECTION

Date of Assignment:

09/09/2019

Date Inspected:

02/09/2019 Inspected At:

Trans Cab Auto Services Pte Ltd - Amk

(HQ)

No 2 Ang Mo Kio St 63 Singapore 569111

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 18 Sep 2019) Part Source: MRM-SG

RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SHC5457Y) These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

10.	Qty	Part No.	ed Parts Particulars	Condition	Repairer's	Amount
200000	0 000 TO	100000-000-00	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*-FL
1	1		*FENDER PANEL REAR RH	Repair	3,866.40 FL	*-FL
2	1			Serviceable	543.47 FL	*-FL
3	1		*WHEELARCH REAR RH *DOOR PANEL REAR RH	Bent		*2,844.66 FL
4	1			Bent	2,844.66 FL	*2,844.66 FL
5	1		*DOOR PANEL FRONT RH	Serviceable	477.76 FL	*-FL
6	1		*DOOR HANDLE OUTER FRONT RH	Serviceable	13.22 FL	*-FL
7	1		*DOOR HANDLE COVER FRONT RH	Serviceable	133.60 FL	*-FL
8	1		*DOOR HANDLE MODULE FRONT RH	Serviceable	162.02 FL	*-FL
9	1		*DOOR SEAL FRONT RH *DOOR WEATHERSTRIP FRONT RH	Serviceable	613.85 FL	*-FL
10	1			Serviceable	1,483.40 FL	*-FL
11	1		*DOOR MIRROR ASSY RH *ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*-FL
12	1			Repair	1,024.79 FL	*-FL
13	1		*ROCKER PANEL INNER RH *ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
14	1			Repair	990.25 FL	
15	1		*ROCKER PANEL CENTER RH	Serviceable	2,670.00 FL	*-FL
16	1		*DOOR HARNESS WIRE RH	Not Necessary	35.00 FS	*-FS
17	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	28.00 FS	*-FS
18	1		*FENDER INNER TRIM CLIP RH	Not Necessary	80.00 FS	*-FS
19	2		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*-FS
20	1		*WINDSCREEN MOULDING  *REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
21	1		*REAR RH DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS
22	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	
23	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
24	1		cNett. L=ListItemDisc.			
F=F	ranchis	e part. S=Sp	CNEIL L-LISITERIDISC.	Sub Total (S\$)	20,574.03	5,824.32
			- List Item Discount on L Items			568.93
				Total Parts (S\$	18,574.93	5,255.39

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

AND SPRAY PAINTING OF THE AFFECTED  BEATING, KNOCKING AND STRAIGHTENING THE SARY PORTION, REMOVE AND RENEWAL OF ADJUST AND REALIGN THE SAME  ST-PROOFING OF THE AFFECTED AREAS ANSFER OF REAR WINDSCREEN FITTINGS AND BICT WATER SEEPAGE TEST ECK ELECTRICAL LIGHTING CONCERNED BIR CHARGE TO MOUNT AND DISMOUNT VEHICLE BENCH, TO FACILITATE REPAIR ECK STEERING GEOMETRY AND COMPUTER	New New New New New New	6,000.00 6,000.00 170.00 170.00 380.00	60.00 500.00 60.00 0.00 20.00
BEATING, KNOCKING AND STRAIGHTENING THE SARY PORTION, REMOVE AND RENEWAL OF ADJUST AND REALIGN THE SAME ST-PROOFING OF THE AFFECTED AREAS ANSFER OF REAR WINDSCREEN FITTINGS AND SECK ELECTRICAL LIGHTING CONCERNED IR CHARGE TO MOUNT AND DISMOUNT VEHICLE BENCH, TO FACILITATE REPAIR	New New New New	6,000.00 170.00 170.00 170.00 380.00	60.00 0.00 20.00 0.00
SARY PORTION, REMOVE AND RENEWAL OF ADJUST AND REALIGN THE SAME ST-PROOFING OF THE AFFECTED AREAS ANSFER OF REAR WINDSCREEN FITTINGS AND OCT WATER SEEPAGE TEST ECK ELECTRICAL LIGHTING CONCERNED OF CHARGE TO MOUNT AND DISMOUNT VEHICLE BENCH, TO FACILITATE REPAIR	New New New	170.00 170.00 170.00 380.00	60.00 0.00 20.00 0.00
ST-PROOFING OF THE AFFECTED AREAS ANSFER OF REAR WINDSCREEN FITTINGS AND JCT WATER SEEPAGE TEST ECK ELECTRICAL LIGHTING CONCERNED JR CHARGE TO MOUNT AND DISMOUNT VEHICLE JE BENCH, TO FACILITATE REPAIR	New New New	170.00 170.00 380.00	0.00 20.00 0.00
INSFER OF REAR WINDSCREEN FITTINGS AND ICT WATER SEEPAGE TEST ECK ELECTRICAL LIGHTING CONCERNED IR CHARGE TO MOUNT AND DISMOUNT VEHICLE BENCH,TO FACILITATE REPAIR	New New	170.00 380.00	20.00 0.00
ECK ELECTRICAL LIGHTING CONCERNED IR CHARGE TO MOUNT AND DISMOUNT VEHICLE BENCH,TO FACILITATE REPAIR	New	380.00	0.00
IR CHARGE TO MOUNT AND DISMOUNT VEHICLE BENCH, TO FACILITATE REPAIR			.745.6
FOX STEEDING GEOMETRY AND COMPUTER	Mour		
L ALIGNMENT	New	220.00	0.00
MOVE AND REFIT INTERIOR GS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO LE REPAIR	New	380.00	60.00
ANSFER OF FRONT DOOR GS,ATTACHMENT AND PERFORM WATER	New	510000FA0045.A	U.T.70280
ANSEER OF REAR DOOR FITTINGS, ATTACHMENT	New	Chromos Chromosop	60.00
ANSFER OF TIRE,RIM AND ON WHEEL NCING	New	170.00	0.00
Gross Labor	ır Cost (S\$)	14,000.00	1,360.00
1	ANSFER OF FRONT DOOR GS,ATTACHMENT AND PERFORM WATER GS TEST ANSFER OF REAR DOOR FITTINGS,ATTACHMENT ERFORM WATER SEEPAGE TEST ANSFER OF TIRE,RIM AND ON WHEEL NCING Gross Labou	ANSFER OF FRONT DOOR GS,ATTACHMENT AND PERFORM WATER GE TEST ANSFER OF REAR DOOR FITTINGS,ATTACHMENT ERFORM WATER SEEPAGE TEST ANSFER OF TIRE,RIM AND ON WHEEL NEW NCING Gross Labour Cost (S\$)	ANSFER OF FRONT DOOR GS,ATTACHMENT AND PERFORM WATER GE TEST ANSFER OF REAR DOOR FITTINGS,ATTACHMENT ERFORM WATER SEEPAGE TEST ANSFER OF TIRE,RIM AND ON WHEEL NEW 170.00 170.00

< END OF ESTIMATES >