

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052

MS16 WINNER

A16
OUT



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page

1/1

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
TAN
CHENG ANN
187A RIVERVALE DRIVE
#12-854
Singapore 541187

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
02-09-2019
5211043795
201009404M
39999
2019001892/ 1
02-09-2019
PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SKN3595B	5G13GZ	05-06-2014	WVWZZZAUZEW359494	Golf 1.4 CLBMT 90 TSI D7F	21

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,080.14	#1	1,080.14	1,155.75
5G6807568D 9B9	Rear Diffusor Satin Black	1	pcs.	277.23	#1	277.23	296.64
5G6807394	Guide Piece	1	pcs.	34.51	#1	34.51	36.93
	LABOUR	4	pcs.	800.00	#1	3,200.00	3,424.00
	Spray Painting	3	pcs.	800.00	#1	2,400.00	2,568.00

Quotation valid till 09-09-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	6,991.88	7%	542.63	7,751.88	8,294.51
Total	760.00	6,991.88		542.63	7,751.88	8,294.51

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
5 days
05/09/19 @ 1400
Resurvey after repair