

ASS. REC. BY:

REF: CS/MSG19015585/T1+d362

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

Menemen

From (Person): Muid Ashik

of

MS19

Date/Time: 3/7/19 @ 10:22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 9351K

Insured:

SCQ 9609K

at Workshop m/s

AMA Automotive

Tel:

8778 3636

of

B1K36 Joh Guan Road East # 01-36

Policy No:

27433570Q

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31/08/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:12pm @ 3/7/19

Person Contacted:

Mulvin

Vehicle IN/OUT

Date/Time

Action/Instruction

1st mtd ✓

SKG 9351K - X

SCQ 9609K - CS / AV109019230 / Rfy

DOA: 2/8/2009

11/09 @ 15

Ob sent predi advice via menemen.

Confirm Lump Sum \$1750/-

4 days Cred: 8543 51; 80%

CLASS. REC. BY: Tanplu REF: MS19

### ASSIGNMENT

From: \_\_\_\_\_ Date: 9/9/19  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV  
 To Inspect Vehicle No: SKG 9351K  
 at Workshop m/s AMA Automotive  
 of Blk 36 Joh Guan Rd East #01-36  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: After 9.30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$39K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKG 9351K Yr Regn: 2012, out.  
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /  
☐ Truck / ☐ Trailer or  
 Make: Hyundai Elantra C.C. 1591  
 Colour: Sk A/C: Insured / Std / NI / NA  
 Sp. Reading: 110656 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMH10H4CND463834  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Fallen

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 9/9/19 0300pm  
 Survey held at AMA Rth

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit \$9000</u>

RECEIVED 04 DEC 2019

Rebate \$29,389  
3/12/2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 312 typist ☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

200
11
211

Report Format: TD

Lump Sum / L.E.I: 1750

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Sep 2019		03 Sep 2019 14:13 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PRAVINCHANDRA S/O DHIRAJLAL A KOTHARY, ID: S1290271I		
Main Claimant:	MUTHURAMAN GANESAN, ID: S8265592A		
Vehicle Reg. No.:	SKG9351K	Date of Loss:	31/08/2019 18:00 - :59 [82 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	27433570QMY (Comprehensive) Coverage: 12/01/2019 - 11/01/2020
Vehicle Reg. No. (Insured):	SCQ9609K	Policy No. (Claimant):	
		Excess:	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/09/2019]		
Driver/Custodian (Insured):	HANSAKUMARI W/O PRAVINCHANDRA KOTHARY (65 / Female) , NRIC: S2186099I Email:		
Adj Asg. Remarks:	(Manual Assign). on WP. Liab: Clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Alvin @ 8778 3636 / 6200 0600.		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Tuesday, 3 September 2019 10:22 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** img-902113547.pdf; GIA Accident Report - SKG9351K.PDF

### **PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKG9351K & SCQ9609K (MSIG) ON 31/08/2019**

#### **Manual Assigned**

Dear LKK,

Refer to the email, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,  
Crystal Lee  
Admin Officer, Claims Services (In-House Survey)  
D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua  
**Sent:** Monday, 2 September, 2019 5:27 PM  
**To:** Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Subject:** FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKG9351K & SCQ9609K (MSIG) ON 31/08/2019

Have a great week ahead!

Helene Phua  
Admin Assistant, Claims Services  
D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua  
**Sent:** Monday, 2 September, 2019 5:27 PM  
**To:** AMA Automotive <[ama.claim@gmail.com](mailto:ama.claim@gmail.com)>  
**Cc:** Muhd Ashik B Madi <[ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)>  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKG9351K & SCQ9609K (MSIG) ON 31/08/2019

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

*Have a great week ahead!*

**Helene Phua**  
Admin Assistant, Claims Services  
D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** AMA Automotive [<mailto:ama.claim@gmail.com>]  
**Sent:** Monday, 2 September, 2019 3:01 PM  
**To:** Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>  
**Cc:** Muhd Ashik B Madi <[ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)>  
**Subject:** Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKG9351K & SCQ9609K (MSIG) ON 31/08/2019

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Hi,

We will choose LKK Auto Consultants Pte Ltd to be the SJE.

***Thank You and Best Regards***



**Alvin Wee**

*AMA Automotive Pte Ltd*


36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580

Hp : +65 8778 3636

Tel : +65 6200 0600

[www.amaauto.sg](http://www.amaauto.sg)



CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

On Mon, Sep 2, 2019 at 2:36 PM Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)> wrote:

Hi,

We refer to your email dated 02/09/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

\*This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Chow Bo Xiong
2) Kenneth Kong	7) E C Looi
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

**(a) \*Fast lane settlement is not applicable for cases that liability is in dispute\***

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

**We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)**

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** AMA Automotive [<mailto:ama.claim@gmail.com>]

**Sent:** Monday, 2 September 2019 11:24 AM

**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>; Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>

**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKG9351K & SCQ9609K ON 31/08/2019

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Dear Sirs/Madam

Please find the attached PRS Letter and GIA report for your perusal. Kindly let us have the Pre-Repair Surveyor Lists and advise me about the liability of this accident case.

Take note that the Repair Estimate will be ready upon the Pre-Repair Survey.

Workshop : **AMA Autocare Pte Ltd**

Address : **36 TOH GUAN ROAD EAST #01-36**



Contact Person : **Alvin Wee**  
**HP: 8778 3636 / 9017 3393 /**  
**Office: 6200 0600**

*Thank You and Best Regards*



**Alvin Wee**

*AMA Automotive Pte Ltd*


36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580

*Hp : +65 8778 3636*

*Tel : +65 6200 0600*

[www.amaauto.sg](http://www.amaauto.sg)



CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy.

This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Denise Tay (LKKAuto)


---

**From:** AMA Automotive <ama.claim@gmail.com>  
**Sent:** Tuesday, 3 December 2019 2:25 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** Re: STATUS

Dear Denise

COR \$1750, 4days. confirmed.

*Thank You and Best Regards*



**Alvin Wee**

AMA Automotive Pte Ltd

36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580

Hp : +65 8778 3636

Tel : +65 6200 0600

[www.amaauto.sg](http://www.amaauto.sg)



CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

On Mon, Dec 2, 2019 at 3:02 PM Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)> wrote:

Dear Alvin/Victor,

Can confirm?

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 11 Sep 2019

## Preliminary Advice

Insured Vehicle No : SCQ9609K

TP Vehicle No : SKG9351K

Make : HYUNDAI ELANTRA

Date of Inspection : 09/09/2019

Inspection At : AMA AUTOCARE PTE LTD (HQ)  
36 TOH GUAN ROAD EAST, #01-36  
SINGAPORE 608580

Accident Date : 31/08/2019

Assignment Date : 03/09/2019

Est. Duration of Repair : 4.00

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,293.51
Revised Amount	:S\$	3,126.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,126.56

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

( ) The vehicle is economical/not economical for repair.

( x ) The above survey was conducted on a 'without prejudice' basis.



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 592A

### Vehicle Details

Vehicle No.: SKG9351K

Vehicle to be Exported: No

Intended Deregistration Date: 11 Sep 2019

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA 1.6 AT ABS  
D/AB 2WD 4DR

Primary Colour: Silver

Manufacturing Year: 2012

Engine No.: G4FGCU632866

Chassis No.: KMHDH41CMDU638314

Maximum Power Output: 95.6 kW (128 bhp)

Open Market Value: \$11,153.00

Original Registration Date: 23 Oct 2012

First Registration Date: 23 Oct 2012

Transfer Count: 0

Actual ARF Paid: \$11,153.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Oct 2022

PARF Rebate Amount: \$7,249.00

### Intended COE Rebate Details

COE Expiry Date: 22 Oct 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$71,001.00

COE Rebate Amount: \$22,101.00

**Total Rebate Amount: \$29,350.00**

The information contained herein is correct as at 11 Sep 2019

OK



## AMA AUTOCARE PTE LTD

36 Toh Guan Road East #01-36 Enterprise Hub Singapore 608580

Email :AMA.CLAIM@GMAIL.COM

(201735370W)

Our Ref: **SKG9351K**

Your Ref: **To be advised**

**02/09/2019**

**MSIG INSURANCE (SINGAPORE) PTE LTD**  
4 Shenton Way #21-01 SGX Centre 2  
Singapore 068807


**BY EMAIL ONLY**

Dear Sir,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT MUTHURAMAN GANESAN**  
**ACCIDENT INVOLVING SKG9351K & SCQ9609K ALONG JALAN SEAVIEW**  
**ON 31/08/2019 1755HRS**  
**PRE-REPAIR SURVEY NOTICE**

- 1 We are instructed by **MUTHURAMAN GANESAN**, the owner of motor vehicle **SKG9351K** which was involved in the aforesaid accident.
- 2 As a result of the accident, Our Client's vehicle has been damaged. Before We proceed to repair the damaged vehicle, Please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. M/s AMA Autocare Pte Ltd at 36 Toh Guan road East #01-36 Singapore (608580) and kindly arrange with Mr. Alvin at 8778 3636.
- 3 If We do not receive any reply from you within the stipulated timeline, We shall proceed to repair the vehicle without further reference to you.

Yours Faithfully,



Alvin Wee

(65) 8778 3636

**AMA AUTOCARE PTE LTD**

Enterprise Hub

36 Toh Guan Road East

#01-36 S(608580)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/09/2019 09:08
Date Of Accident	31/08/2019 17:55
Exact Location Of Accident	ALONG JALAN SEAVIEW
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKG9351K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MUTHURAMAN GANESAN
NRIC No	S8265592A
Email Address	MUTHURAMAN.GANESAN@ICLOUD.COM
Mobile Phone No	(LOCAL) +65-93875098
Alternative Phone No	OFFICE-93875098
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00540938
Cover Note Number	
<b>Driver</b>	
Name of Driver	MUTHURAMAN GANESAN
NRIC No	S8265592A
Date Of Birth	26/01/1982
Occupation	INDOOR
Date Of Driving Pass	28/09/2012
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93875098
Fax Number	
Contact Number	OFFICE-93875098
EEmail Address	MUTHURAMAN.GANESAN@ICLOUD.COM

Address	26 BUKIT BATOK EAST AVENUE 2 #11-11
Postcode	659920
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please refer to the attached Sketch Plan for the accident details.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCQ9609K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HEMA KOTHARI
NRIC/Passport Number	S2186099I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time: 02-SEP-2019

09:00 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Around 5:55 PM Saturday (31-Aug-2019), My car (SKG 9351K) exited ECP on Tanjong Katong road and the turned into Jalan Seaview. I was driving straight on Jalan Seaview when another car (SCQ 9609K) driven by Hema Kothari (S21860991) turned into Jalan Seaview from Tanjong Katong road and hit my car at the back-left side. The driver of the car (SCQ 9609K) acknowledged the mistake and agreed to claim from his insurance for the damage caused.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

g. Huth  
 Policyholder's Signature  
 Date & Time: 02-SEP-2019  
 9:00 AM

g. Huth  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



AMA Autocare Pte Ltd  
Enterprise Hub 36 Toh Guan Road East #01-36  
Singapore (608580)  
E: ama.claim@gmail.com  
T: 87783636

Page No. 1

Vehicle No. SKG9351K HYUNDAI ELANTRA 1.6A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	Taillamp LH		780.00	X
1	Taillamp lower panel		349.00	X
1	Rear end panel		982.00	X
1set	Rear bumper side retainer @98.00		196.00	LH-RH ✓
1	Rear bumper		1250.00	fn ✓
1	Rear fender LHS		782.5	RY ✓
1	Rear fender inner shield LHS		272.40	fn ✓
1	Rear shock absorber LH		692.00	X
1	Rear wheel bearing LH		378.00	X
1	Rear stabilizer link LH		248.00	X
1	Rear knuckle arm LH		492.00	X
1	Rear lower control arm LH		482.00	X
			6903.90	0.00
less 10%			690.39	10% 0.00
			6213.51	0.00
<b>SPECIAL NETT ITEMS</b>				
1set	Rear bumper clips		80.00	30 ✓
1set	Inner shield clips		80.00	10 ✓
1set	Taillamp clips		70.00	X
1	Rear sports rim LH		720.00	cut ✓ 400
<b>TOTAL PARTS</b>			7163.51	0.00

X } nn  
 X } 98  
 - 1250 489.40  
 X R  
 - 272.40 175  
 X }  
 X } nn  
 X } 1620.40  
 - 20% 1296.32  
 762.40  
 20% - 609.92  
 30 ✓  
 10 ✓  
 X nn  
 - 400 440



AMA Autocare Pte Ltd  
Enterprise Hub 36 Toh Guan Road East #01-36  
Singapore (608580)  
E: ama.claim@gmail.com  
T: 87783636

Page No. 2

Vehicle No. SKG9351K HYUNDAI ELANTRA 1.6A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	500
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	180.00	30
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	150.00	X nn
5	To provide anti-rust treatment on affected areas	180.00	30
6	To conduct full computerised wheel alignment test	120.00	80
7	To remove and replace rear undercarriage parts LH	300.00	X nn
Labour Total :		3130.00	
TOTAL (PARTS & LABOUR):		10293.51	

1140

P- 1296.32  
S/N - 440  
L - 1140  

---

2876.32  
-20% 2301.05

\$2300/-

P 1670.40  
S/N 440.00  
L 1140.00  

---

2220.40

Tanpin 97495749  
wp  
Lumpsum 7/4/19 820pm  
Resing after repair  
surveillance  
4 days

609.92  
440  
1140  

---

2189.92  
1591750 # 4 days #



AMA Autocare Pte Ltd  
Enterprise Hub 36 Toh Guan Road East #01-36  
Singapore (608580)  
E: ama.claim@gmail.com  
T: 87783636

Page No. 1

Vehicle No. SKG9351K HYUNDAI ELANTRA 1.6A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	ADJUSTMENT
	<b><u>PARTS (LIST ITEMS)</u></b>			
1	Taillamp LH		780.00	X
1	Taillamp lower panel		349.00	X
1	Rear end panel		982.00	X
1set	Rear bumper side retainer @98.00		196.00	LH-de ✓
1	Rear bumper		1250.00	in ✓
1	Rear fender LHS		782.5	RY ✓
1	Rear fender inner shield LHS		272.40	in ✓
1	Rear shock absorber LH		692.00	X
1	Rear wheel bearing LH		378.00	X
1	Rear stabilizer link LH		248.00	X
1	Rear knuckle arm LH		492.00	X
1	Rear lower control arm LH		482.00	X
			6903.90	
		less 10%	690.39	10%
			6213.51	0.00
	<b>SPECIAL NETT ITEMS</b>			
1set	Rear bumper clips		80.00	30 ✓
1set	Inner shield clips		80.00	10 ✓
1set	Taillamp clips		70.00	X
1	Rear sports rim LH		720.00	cut ✓
	<b>TOTAL PARTS</b>		<b>7163.51</b>	<b>0.00</b>



AMA Autocare Pte Ltd  
Enterprise Hub 36 Toh Guan Road East #01-36  
Singapore (608580)  
E: ama.claim@gmail.com  
T: 87783636

Page No. 2

Vehicle No. **SKG9351K HYUNDAI ELANTRA 1.6A**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	500
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	180.00	30
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	150.00	X
5	To provide anti-rust treatment on affected areas	180.00	30
6	To conduct full computerised wheel alignment test	120.00	80
7	To remove and replace rear undercarriage parts LH	300.00	X
Labour Total :		3130.00	
TOTAL (PARTS & LABOUR):		10293.51	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanpin 97497449  
wp  
Lumpsum 9/4/19 @ 300pm  
Resurvey after repair  
sure 11 months  
4 days

### ...CLAIM SUBFOLDER...(Pending for Survey Report)








































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Sep 2019		03 Sep 2019 14:13 <a href="#">Edit Adj Rpt</a>	<b>S\$1,750.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>PRAVINCHANDRA S/O DHIRAJLAL A KOTHARY</b> , ID: S12902711									
Main Claimant: <b>MUTHURAMAN GANESAN</b> , ID: S8265592A									
Vehicle Reg. No.: <b>SKG9351K</b>		Date of Loss: 31/08/2019 18:00 - :59 [82 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 604731</b>		Policy/Cover Note No.: 27433570 (Comprehensive) Coverage: 12/01/2019 - 11/01/2020							
Vehicle Reg. No. (Insured): <b>SCQ9609K</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ama Autocare Pte Ltd (HQ)</b> 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 03/10/2019]									
Driver/Custodian (Insured): <b>HANSAKUMARI W/O PRAVINCHANDRA KOTHARY</b> (65 / Female) , NRIC: S2186099I Email:									
Adj Asg. Remarks: (Manual Assign). on WP. Liab: Clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Alvin @ 8778 3636 / 6200 0600.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKG9351K (604731)  
[SCQ9609K]  
TP  
MUTHURAMAN GANESAN  
Aug 31 2019 6:00PM  
[PRAVINCHANDRA S/O DHIRAJLAL A KOTHARY]  
Ama Autocare Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View <div>View in Browser</div>	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	11/09/19 15:06	Adjuster Immediate Advice					 Load HTM	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
2	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
3	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
4	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
5	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
6	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
7	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
8	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
9	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
10	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
11	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
12	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
13	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
14	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
15	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
16	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
17	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
18	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
19	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
20	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
21	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
22	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
23	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
24	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
25	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
26	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
27	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
28	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
29	05/12/19 17:40	General View					 Load JPG	<input checked="" type="checkbox"/>
30	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
31	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
32	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
33	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
34	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
35	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
36	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
37	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
38	05/12/19 17:42	Reinspection Photo					 Load JPG	<input checked="" type="checkbox"/>
39	05/12/19 17:42	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
40	05/12/19 17:42	Reinspection Photo					Load JPG	



Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			<input checked="" type="checkbox"/>
41	05/12/19 17:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	05/12/19 17:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	05/12/19 17:42	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	03/09/19 11:10	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
		PRI		Load PDF	
2	03/09/19 11:10	OI Accident Report		Load PDF	
3	03/09/19 11:10	TP GIA Accident Report - SKG9351K		Load PDF	
4	03/09/19 11:54	Agree on SJE		Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	03/09/19 14:11	email - manual assign		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015585/T1TD3E2

Date: 05/12/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27433570

Claimant SKG9351K

Insured Vehicle No : SCQ9609K

Vehicle No : SKG9351K

Date of Loss: 31/08/2019

Nature of Claim: TP

Claim No: 604731

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG9351K

Make &amp; Model: HYUNDAI ELANTRA, 1.6 (A)

Engine No: G4FGCU632866

Reg. Date: 23/10/2012 (Man. Year: 2012)

Chassis No: KMHDH41CMDU638314

Colour: Silver

Odometer: 110656 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,163.51	1,049.92	6,113.59	85.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,140.00	1,990.00	63.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,293.51</b>	<b>2,189.92</b>	<b>8,103.59</b>	<b>78.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,750.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,293.51</b>	<b>1,750.00</b>	<b>8,543.51</b>	<b>83.00</b>

### INSPECTION

Date of Assignment: 03/09/2019

Date Inspected: 09/09/2019 Inspected At:

Ama Autocare Pte Ltd (HQ)  
36 Toh Guan Road East, #01-36  
Singapore 608580

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2019)
<b>Parts:</b>	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKG9351K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP LH	Not Necessary	780.00 FL	*- FL
2	1		*TAILLAMP LOWER PANEL	Not Necessary	349.00 FL	*- FL
3	1		*REAR END PANEL	Not Necessary	982.00 FL	*- FL
4	1		*SET REAR BUMPER SIDE RETAINER	N/S Deformed	196.00 FL	*98.00 FL
5	1		*REAR BUMPER	Torn	1,250.00 FL	*489.40 FL
6	1		*REAR FENDER LHS	Repair	782.50 FL	*- FL
7	1		*REAR FENDER INNER SHIELD LHS	Torn	272.40 FL	*175.00 FL
8	1		*REAR SHOCK ABSORBER LH	Not Necessary	692.00 FL	*- FL
9	1		*REAR WHEEL BEARING LH	Not Necessary	378.00 FL	*- FL
10	1		*REAR STABILIZER LINK LH	Not Necessary	248.00 FL	*- FL
11	1		*REAR KNUCKLE ARM LH	Not Necessary	492.00 FL	*- FL
12	1		*REAR LOWER CONTROL ARM LH	Not Necessary	482.00 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
14	1		*SET INNER SHIELD CLIPS	Necessary	80.00 FS	*10.00 FS
15	1		*SET TAILLAMP CLIPS	Not Necessary	70.00 FS	*- FS
16	1		*REAR SPORTS RIM LH	Cut	720.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,853.90</b>	<b>1,202.40</b>
<b>- List Item Discount on L Items 10.00/20.00% (\$\$)</b>	<b>690.39</b>	<b>152.48</b>
<b>Total Parts (\$\$)</b>	<b>7,163.51</b>	<b>1,049.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	1,200.00	500.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,000.00	500.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	180.00	30.00
4	TO REMOVE AND REFIX / REPLACE REAR TRIMS, GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	150.00	0.00
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	30.00
6	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	80.00
7	TO REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS LH	New	300.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,130.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >