

ASS. REC'D BY:

REF:

CS/CTI 19015609 / Ftd307

Special Instruction:

Surveyor:

Rom

ASSIGNMENT (Office)

From (Person):

Chong Boon sen

of

CTI

Date/Time:

11:21am @ 3/9/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 8404

Insured:

at Workshop m/s

G.N.G Motor

Tel:

9664 8992

of

Blk 6 Defu Lane 10 #01-564

Policy No:

DMCVSN3043041901

Claim No:

SNM19D20402602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:47pm @ 3/9/19

Person Contacted:

Mr. Ong

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

Estimated ✓

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN 840 U

at Workshop m/s

of 6 Defu Lane 10 #01-564

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FBN 840 U Yr Regn: Jul / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Xmax 300

C.C 292

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 11912

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH 3SH0841JK004364

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/75 R15

R: 140/70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. mm

L/Bal. mm

D.O.A. 15/8/2019

D.O.I. 3/9/19

Survey held at

GNG motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S/Frt O/S/rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S \$1200/-

Confirm with org

(Red: 1423, 54%)

RECEIVED 27 SEP 2019

Date/Time, File Pass to?

1) 26/9 Typst

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

G + RS, SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$ 1200)

220
220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 3 September 2019 11:21 AM
To: gngmotor@singnet.com.sg
Cc: Admin-D (LKKAuto)
Subject: RE: Motor Claims Department (Pre-repair Inspection for Bike No. FBN840U) / SNM19D204026

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: gngmotor@singnet.com.sg [mailto:gngmotor@singnet.com.sg]
Sent: Sunday, 1 September, 2019 1:27 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: Motor Claims Department (Pre-repair Inspection for Bike No. FBN840U)

Dear Sir/Madam

Please send Surveyor Henry Ng to carry out the pre-repair survey.

Location of survey:
G.N.G. MOTOR TRADING CO
Blk 6 defu lane 10
#01-564
S(539187)

Thanks and Regards,
Ong
9664 8992

On Thu Aug 29 2019 08:54:16 GMT+0800 (Singapore Standard Time) Chong Boon Sen
<boonsen.chong@sg.cntaiping.com> wrote:

----- Original Message -----

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城

Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From:

Claims Dept of CTI

Sent: Wednesday, 28 August, 2019 4:53 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh
<alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;
gngmotor@singnet.com.sg

Subject: FW: Motor Claims Department (Pre-repair Inspection for Bike No. FBN840U)

Dear Boon Sen,

Please conduct PRS for FBN840U.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城
Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From:

gngmotor@singnet.com.sg [<mailto:gngmotor@singnet.com.sg>]

Sent: Wednesday, 28 August, 2019 4:04 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: Motor Claims Department (Pre-repair Inspection for Bike No. FBN840U)

Hi Shumin,

Attached is the SAS Report.

Jo

On Wed Aug 28 2019 15:56:36 GMT+0800 (Singapore Standard Time)
Claims Dept of CTI <claimsdept@sg.cntaiping.com> wrote:
----- Original Message -----

Dear Jo,

Please send us a copy of the SAS report.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:**
太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From:
gngmotor@singnet.com.sg [<mailto:gngmotor@singnet.com.sg>]
>

Sent:
Wednesday, 28 August, 2019 3:40 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
>

Subject:
Fwd: Motor Claims Department (Pre-repair Inspection for Bike No. FBN840U)

On Thu Aug 22 2019 17:11:11 GMT+0800 (Singapore Standard Time) <gngmotor@singnet.com.sg> wrote:

----- Original Message -----

Dear Sir,

We are notifying you of the captioned road traffic accident.
Kindly arrange pre-repair survey of the vehicle **FBN840U**.

The bike can be inspect at this address:

G.N.G. Motor Trading Co

**Blk 6 Defu Lane 10
#01-564
S(539187)**

Thanks and Regards,

Ong

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	925B
Vehicle Details	
Vehicle No.:	FBN840U
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2019
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	H336E0034393
Chassis No.:	MH3SH0841JK004364
Maximum Power Output:	-
Open Market Value:	\$4,317.00
Original Registration Date:	05 Jul 2018
First Registration Date:	05 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$648.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jul 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,514.00
COE Rebate Amount:	\$5,754.00
Total Rebate Amount:	\$5,754.00

The information contained herein is correct as at 04 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2019 13:42
Date Of Accident	15/08/2019 08:15
Exact Location Of Accident	KALLANG PAYA LEBAR EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN840U
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD FARDLIE BIN RAMLIE
NRIC No	S8019925B
Email Address	DANI_TORLEA@YAHOO.COM
Mobile Phone No	(LOCAL) +65-92992094
Alternative Phone No	OTHERS-92992094

Vehicle Particulars

Manufacturer	YAMAHA
Model	CZD300A / XMAX300
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	CN:72187520
Cover Note Number	CN:72187520

Driver

Name of Driver	MUHAMMAD FARDLIE BIN RAMLIE
NRIC No	S8019925B
Date Of Birth	18/07/1980
Occupation	INDOOR
Date Of Driving Pass	26/11/1998
Driving Experience	20 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92992094
Fax Number	
Contact Number	OTHERS-92992094
Email Address	DANI_TORLEA@YAHOO.COM

Address	BLK 665B PUNGGOL DRIVE #09-516
Postcode	822665
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 391 NEW BRIDGE ROAD POLICE CANTONMENT COMPLEX BLOCK A , POSTCODE: 088762 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2369999 - FAX NO: 62268438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190819/2149;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH5239E
Vehicle Make/Model/Colour	TOYOTA / DYNA 150 5MT
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD FARDLIE BIN RAMLIE
Approximate Age	39
Injuries Sustain	
Injured person in which vehicle?	FBN840U
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 665B PUNGGOL DRIVE #09-516
Postcode	822665

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

20 AUG 2019



[Signature]

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre
Name: 23 Kaki Bukit Ave 4
Singapore 415933
NRIC/Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report T/20190819/2149

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 20/08/2019 14:00

Driver's Signature

(If driver is not the policyholder)

Date & Time:

20 AUG 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signatures

Name: Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190819/2149

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

1 of 3

Report No: T/20190819/2149

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/08/2019 16:15		Vide Report No.:		Station Diary No.: 122	
Informant's Particulars					
Name of Informant: MUHAMMAD FARDLIE BIN RAMLIE			Address: APT BLK 685B PUNGGOL DRIVE #09-516 SINGAPORE 822665		
ID Type / ID No.: NRIC NO / S8019925B			Contact No.: Home/Office: Mobile: 92992094		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 18/07/1980	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: CIVIL SERVANT			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/08/2019 08:15	Type of Location: Straight Road
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY				
Along KPE towards the City, after Defu flyover, before the ERP Gantry.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Moving Vehicle Against - Others			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN840U	Motorcycle	YAMAHA	CZD300A / XMAX300	Black		0
GBH5239E	Lorry					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBN840U	MSIG INSURANCE (SINGAPORE) PTE. LTD.	72187520	05/07/2019	04/07/2020

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190819/2149

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

2 of 3

Report No: T/20190819/2149

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD FARDLIE BIN RAMLIE	ID No.	S8019925B
Related Vehicle	NIL	Contact No.	92992094
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	NUR FARHANA BINTE MOHAMED HUSSAIN	ID No.	S8603092F
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above date, time and location, I was riding my motorcycle bearing registration no. FBN840U along the said location on the left side of the 1st lane, with my wife as a pillion.


There was a lorry bearing registration no. GBH5239E with a canvass cover, travelling on my left, in the 2nd lane. The canvas at the right side of the lorry had not been secured properly. Suddenly the front lower corner of the canvas flew open and hit onto me and my handle bar, causing me to fall on the road.

My wife and I were injured and were conveyed by ambulance to Raffles Hospital. My motorcycle was also damaged.

Accident Sketch Plan



SINGAPORE
POLICE FORCE



T/20190819/2149

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

3 of 3

Report No. T/20190819/2149

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Sgt 2 ONG YAO TING

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

19/08/2019 16:15

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI

Contact No.: 65476904

Classification Of Case:

Authentication Stamp

NP168



Signature

Police Force



南藝摩哆公司 G. N. G. MOTOR TRADING CO.

REG. NO. 247124/00-A

Block 6, Defu Industrial Estate Park C, Avenue 1

Defu Lane 10, #01-564, Singapore 1953.

TEL: 2836560, 2805065

代理各種摩哆西卡及保險
AGENT FOR ALL TYPES OF MOTOR-CYCLE & INSURANCE

Your Ref: GBH5239E TOYOTA DYNA150

Our Ref: FRN840U YAMAHA X-MAX300

Date: 22/8/19

- 1pc. RIGHT EXHAUST PROTECTOR - \$75 ~~pc~~ cut ✓
- 1pc. RIGHT EXHAUST PIPE - \$750/2 DO ✓
- 1pc. RIGHT REAR SIDE COWLING - \$95 cut ✓
- 1pc. RIGHT SIDE STEP BOARD - \$125 scr ✓
- 1pc. RIGHT SIDE STEP BOARD PROTECTOR - \$38 cut ✓
- 1pc. HANDLE BAR - \$96 Xnn
- 1pc. HANDLE BALANCER - \$32 scr ✓ \$20
- 1pc. RIGHT SIDE MIRROR - \$45 scr ✓
- 1pc. FRONT WHEEL - \$365 Xnn
- 156. FRONT Fork ASSEMBLY - \$188/2 Xnn
- 1pc. FRONT RIGHT SIDE COWLING - \$89/2 cut ✓
- TOWING SERVICE - \$35
- LABOUR CHARGE - \$280

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Signature: _____
4/8/19
\$280

ParaSaram (LKK)
88622773

3/9/19 1610hrs



Q only SWB ctuan 96648992



REG. NO. 247124/00-A

南藝摩哆公司

G. N. G. MOTOR TRADING CO.

Block 6, Defu Industrial Estate Park C, Avenue 1

Defu Lane 10, #01-564, Singapore 1953.

TEL: 2836560, 2805065

代理各種摩哆西卡及保險
AGENT FOR ALL TYPES OF MOTOR-CYCLE & INSURANCE

Your Ref:

Our Ref: FBN 8404

Date: 06/9/19

1pc. RIGHT SIDE COWLING (FRONT) - \$ 75.00 ✓
1pc. FRONT RIGHT SIGNAL - \$ 55.00 ✓
1pc. SIDE COVER EMBLEM - \$ 10.00 ✓
LABOUR CHARGE - \$ 280 \$230



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

QAG ENG CHUAN
S68x S586E.

966 48992

Parasuram (LKK)
88622718

4/5
Repairs



List Items: \$ 137.7
10% : \$ 13.77
List Item: \$ 1239.30

Labour: \$ 265

Total: \$ 1504.30

20% L/S: \$ 1200.00 *

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2019		26 Sep 2019 15:54 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	0, Co. Reg. No.: 0		
Main Claimant:	CF ENGINEERING ACMV SYSTEM PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	FBN840U	Date of Loss:	15/08/2019 08:00 - :59 [13 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204026C02	Policy/Cover Note No.:	DMCVSN30430419011
Vehicle Reg. No. (Insured):	GBH5239E	Policy No. (Claimant):	DMCVSN3043041901
		Excess:	S\$0.00
Repairer:	G.N.G MOTOR TRADING CO. (HQ) BLK 6, DEFU INDUSTRIAL ESTATE PARK C, AVE 1 DEFU LANE 10 #01-564, 539187 Defu Lane - Tel: 6283 6560		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 07/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN840U (SNM19D204026C02)
[GBH5239E]
TP
CF ENGINEERING ACMV SYSTEM PTE LTD
Aug 15 2019 8:00AM
[0]
G.N.G MOTOR TRADING CO.

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

Thumbnail

Print

1

Load HTM

Photos/Images

3 per page

Thumbnail

Print

1

Load JPG

No

Finalized On

National Assessment Centre Services (Ubi)

1

20/09/19 16:53

Accident Photo

[Linked Accident Report Documents]

Thumbnail

Print

1

Load JPG

No

Finalized On

National Assessment Centre Services (Ubi)

2

20/09/19 16:53

Accident Photo

[Linked Accident Report Documents]

Thumbnail

Print

1

Load JPG

No

Finalized On

National Assessment Centre Services (Ubi)

3

20/09/19 16:53

Accident Photo

[Linked Accident Report Documents]

Thumbnail

Print

1

Load JPG

No

Finalized On

National Assessment Centre Services (Ubi)

4

20/09/19 16:53

Accident Photo

[Linked Accident Report Documents]

Thumbnail

Print

1

Load JPG

No

Finalized On

National Assessment Centre Services (Ubi)

5

20/09/19 16:53

Police Report

[Linked Accident Report Documents]

Thumbnail

Print

1

Load JPG

No

Finalized On

National Assessment Centre Services (Ubi)

6

20/09/19 16:53

Police Report

[Linked Accident Report Documents]

Thumbnail

Print

1

Load JPG

No

Finalized On

National Assessment Centre Services (Ubi)

7

20/09/19 16:53

Police Report

[Linked Accident Report Documents]

Thumbnail

Print

1

Load JPG

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

1

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

2

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

3

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

4

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

5

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

6

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

7

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

8

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

9

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

10

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

11

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

12

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

13

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

14

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

15

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

16

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

17

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

18

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

19

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

20

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

21

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

22

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

23

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

24

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

25

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

26

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

27

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

28

26/09/19 16:11

General View

Thumbnail

Print

1

Load JPG

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

29

26/09/19 16:12

























































General View

Thumbnail

Print












1

Load JPG

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
30	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/09/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/09/19 16:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
86	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	26/09/19 16:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/09/19 16:53	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 16:53	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	20/09/19 16:53	Individual Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/09/19 16:56	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/09/19 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/09/19 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/09/19 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/09/19 16:53	Police Report	 Load JPG	<input checked="" type="checkbox"/>
6	20/09/19 16:53	Police Report	 Load JPG	<input checked="" type="checkbox"/>
7	20/09/19 16:53	Police Report	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/09/19 16:53	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 16:53	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	20/09/19 16:53	Individual Statement	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19015609/FTD3E2

Date: 07/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30430419011

Claimant
Vehicle No : FBN840UInsured
Vehicle No : GBH5239E

Date of Loss: 15/08/2019

Nature of Claim: TP

Claim
No: SNM19D204026C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN840U**

Make & Model: YAMAHA X1, 111cc (M)

Engine No: H336E0034393

Reg. Date: 05/07/2018 (Man. Year: 2018)

Chassis No: MH3SH0841JK004364

Colour: Black

Odometer: 11912 km

Engine Capacity: 292 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/75R15	Rear Tyre Size:	140/70R14
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,308.00	1,239.30	1,068.70	46.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	265.00	50.00	15.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,623.00	1,504.30	1,118.70	42.65
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	2,623.00	1,200.00	1,423.00	54.25

INSPECTION

Date of Assignment: 26/09/2019
 Date Inspected: 03/09/2019 Inspected At:

G.N.G MOTOR TRADING CO. (HQ)
 BLK 6, DEFU INDUSTRIAL ESTATE
 PARK C, AVE 1 DEFU LANE 10 #01-564
 Singapore 539187

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Oct 2019)	
Parts:	N/A	YAMAHA X1 111cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN840U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT EXHAUST PROTECTOR	Cut	75.00 F	*75.00 FL
2	1		*RIGHT EXHAUST PIPE	Dented	750.00 F	*750.00 FL
3	1		*RIGHT REAR SIDE COWLING	Cut	95.00 F	*95.00 FL
4	1		*RIGHT SIDE STEP BOARD	Scratched	125.00 F	*125.00 FL
5	1		*RIGHT SIDE STEP BOARD PROTECTOR	Cut	38.00 F	*38.00 FL
6	1		*HANDLE BAR	Not Necessary	96.00 F	*- FL
7	1		*HANDLE BALANCER	Scratched	32.00 F	*20.00 FL
8	1		*RIGHT SIDE MIRROR	Scratched	45.00 F	*45.00 FL
9	1		*FRONT WHEEL	Not Necessary	365.00 F	*- FL
10	1		*FRONT RIGHT SIDE COWLING	Cut	89.00 F	*89.00 FL
11	1		*RIGHT SIDE COWLING (FRONT)	Cut	75.00 F	*75.00 FL
12	1		*FRONT RIGHT SIGNAL	Cracked	55.00 F	*55.00 FL
13	1		*SIDE COVER EMBLEM	Necessary	10.00 F	*10.00 FL
14	1		*SET FRONT FORK ASSY	Not Necessary	458.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,308.00	1,377.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	137.70
Total Parts (\$\$)	2,308.00	1,239.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING SERVICE	New	35.00	35.00
2	LABOUR CHARGE	New	280.00	230.00
Gross Labour Cost (\$\$)			315.00	265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >