

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Hafizul Fathar of SPF Date/Time: 3/9/19 @ 9.23am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 9969J Insured: OX 281C

at Workshop m/s Bluwel Automotive Tel: 67452088

of Ikaki Bukit Me 6 # 01-28 Claim No: ABMD/105/009/2019/089

Policy No: _____ Excess: _____

Sum Insured: _____ D.O.A. 26/8/2019

Make of Veh: _____ H.O.D. Endorsement: _____
(Client's Record)

CA / REV / REP. / REV 24 HRS 1up Vehicle-IN/OUT

Date/Time: 11.21am @ 3/9/19 Person Contacted: Jeromy

Date/Time | Action/Instruction | Followup | change workshop to Bluwel Automotive

SMK 9969J - X

OX 281C - X

Do Not Finalise

19/9/19 @ 9.30am check with Ram 2 weekends

19/9/19 Submit LS \$ 3800

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Thursday, 12 September 2019 2:26 PM
To: Admin-D (LKKAuto)
Cc: Hafizul Farhan RAHMAT (SPF)
Subject: RE: Pre-Repair survey of SMK9969J (vs QX281C DOA: 26/8/2019)

Your reference: SMK9969J

Our reference: AEMD/105/009/2019/089

Nivitha,

We spoke, kindly conduct the Pre-repair Inspection for vehicle SMK9969J at the address listed below:

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 3 September 2019 11:26 AM
To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: RE: Pre-Repair survey of SMK9969J (vs QX281C DOA: 26/8/2019)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

Catherine Chong (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Tuesday, 3 September, 2019 9:23 AM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF)
Subject: Pre-Repair survey of SMK9969J (vs QX281C DOA: 26/8/2019)

Our ref: AEMD/105/009/2019/089

Hi,

Kindly conduct pre-repair survey of **SMK 9969J** at:

Derrick Motor Works
Blk 9002 Tampines St 93
#01-72 Tampines Industrial Park A
Singapore 528836

Contact: Mr Jeromy, HP: 9633 3593

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.

www.avg.com

MFA319112851 / Falcon Air Auto Services Pte Ltd - Tanjines
 ENTRY DATE & TIME: 27/08/2019 11:12
 SUBMITTED BY: Joel Ng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/08/2019 11:12
 Date Of Accident 26/08/2019 13:30
 Exact Location Of Accident KAKI BUKIT ROAD 2
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK9969J
Insured/Policyholder
 Name Of Registered Owner LEONG YIK WAN
 NRIC No S7366896D
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-83889969
 Alternative Phone No OFFICE-83889969
Vehicle Particulars
 Manufacturer MERCEDES-BENZ
 Model C 200 KOMPRESSOR
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5107813691
 Cover Note Number
Driver
 Name of Driver JEREMY SOON
 NRIC No S8101455H
 Date Of Birth 18/01/1981
 Occupation INDOCR
 Date Of Driving Pass 19/12/2001
 Driving Experience 17 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-83889969
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 118A JALAN TENTERAM
 Postcode 321113
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name WHAMPOA NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: ELK 29 JALAN BAHAGIA, POSTCODE: 320229, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2507999 - FAX NO: 63554314
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN AND POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX281C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category GOVERNMENT
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be complete by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the E A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police reports

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days chosen whereby the claim must be made within the stipulated timeframe from the day of occurrence.

| |
|---------------------------------|
| Reporting Only |
| Claim OD |
| Claim TP |
| Claim OD / TP at other workshop |

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
IDOC/FIN No.:



Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20190826/2202

Police Station Of Origin:
Whampoa NPP
29 Jalan Bahagia #01-368 SINGAPORE
320029
Tel No: 1800-2507999

1 of 3

Report No. T/20190826/2202

REPORT OF A TRAFFIC ACCIDENT

| | | | | | |
|--|------------|--------------------------------------|--|--------------------------|----------------------------|
| Date/Time Report Made: 26/08/2019 21:45 | | Video Report No.: G/20190826/0099 | | Station Diary No.: 44 | |
| Informant's Particulars | | | | | |
| Name of Informant: JEREMY SOON | | | Address: APT BLK 116A JALAN TENTERAM #11-53: SINGAPORE 321: 16 | | |
| ID Type / ID No.: NRIC NO / S8101455H | | | Contact No.: Home/Office: Mobile: 83389969 | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 38 | Date of Birth: 18/01/1981 | Type of Informant: Driver | | |
| Race: Chinese | | | Language: | | Institution / School Name: |
| Occupation: SELF-EMPLOYED | | | Driving Licence Information Class: | | Date of Expiry: |

| | | | | |
|---|--------------------|---|---|--|
| General Information of the Accident | | | | |
| Type of Accident: Non-Injury Police Vehicle | Drink Drive: No | Date/Time of Accident: 26/08/2019 13:30 | Type of Location: Waiting area for the car workshop | |
| Location: Along Road 1 KAKI BUKIT ROAD 2 First East Centre | | | | |
| Weather: Clear | | Road Surface: Dry | Road Speed Limit: | |
| Traffic Flow: Two Way | | Traffic Control: Controlled by Others e.g. Workmen | Traffic Volume: | |
| Type of Collision: Moving Vehicle Against - Parked Vehicle | | | Anyone conveyed by ambulance: No | |

| Details of Vehicle Involved | | | | | | |
|------------------------------------|------------|------|-------|-------|------------------|------------------|
| Vehicle No. | Type | Make | Model | Color | Condition | No. of Passenger |
| QX281C | Police car | | | | Slightly Damaged | 1 |
| SMK9969J | Car | | | | Slightly Damaged | 0 |

| | |
|-----------------------------------|--------------------------------|
| Details of Person Involved | |
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |

Sketch Plan Pg. 4



**SINGAPORE
POLICE FORCE**



T/20190826/2202

2 of 3

Report No. T/20190826/2202

Police Station Of Origin:
Whampoa NPP
29 Jalan Bahagia #01-368 SINGAPORE
320029
Tel No. 1800-2507999

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|----------------|--|-----------------------------------|
| Driver | | | |
| Name | JEREMY SCON | ID No. | S3101455H |
| Related Vehicle | SMK9969J (Car) | Contact No. | 83889989 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On 28/08/2019 at about 1330hrs, I was at the vehicle waiting area in my car (SMK9969J) and was in a stationary position, waiting to drive into the car workshop.

While sitting in the car, I had spotted a police car (QX261C) reversing towards my car from a distance away. I then became alarmed as the said car continued to reverse nearer to my car. I had sounded my horn to alert the driver but to no avail.

The back of the police car had then collided with the front of my vehicle.

As a result of the accident, my car sustained some scratches at the front bumper. I am not injured.

After the accident, the two police officers alighted from their vehicle and I was attended to.

After investigation by traffic police, I left the scene in my own vehicle.

I am lodging this report for record and insurance purposes, and also under the instruction of Traffic Police.

Sketch Plan Pg. 5



SINGAPORE POLICE FORCE



T/20190826/2202

Police Station Of Origin:
Whampoa NPP
29 Jalan Bahagia #01-368 SINGAPORE
320029
Tel No: 1800-2507999

3 of 3

Report No. T/20190826/2202

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474685 stating the report number as reference.

| | |
|--|--------------------------------|
| Signature Of Officer Recording The Report: E / Sgt 2 CHUA CHEE PING | Signature Of Informant: |
| Signature Of Interpreter: Not applicable | Date/Time: 25/08/2019 21:46 |
| Officer In Charge Of Case: TP / DDGVT / SI NORASHIKIN BINTE DAU Contact No.: 65476439 | Classification Of Case: |
| Authentication Stamp NP198 | |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 896D

Vehicle Details

Vehicle No.: SMK9969J
Vehicle to be Exported: No
Intended Deregistration Date: 17 Sep 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: C 200 KOMPRESSOR
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: 27195031117376
Chassis No.: WDD2040412A201228
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$43,106.00
Original Registration Date: 05 Dec 2008
First Registration Date: 05 Dec 2008
Transfer Count: 2
Actual ARF Paid: \$43,106.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 04 Dec 2028
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$31,553.00
COE Rebate Amount: \$29,071.00
Total Rebate Amount: \$29,071.00

The information contained herein is correct as at 17 Sep 2019

Remains: 9 years 3 months 9 days (111.3)
Depri: \$1010/yearly \$584.16/monthly
 $111.3 \times \$584.16 = \underline{\underline{\$65017.5}}$

OK

MERCEDES BENZ C200 Price Range Depreciation Year Reg Vehicle Type

Home » Used Cars » Direct Owners » Mercedes-Benz C-Class C200K (COE till 11/2027)

Mercedes-Benz C-Class C200K (COE till 11/2027)

Overview Financial Insurance Accessories Similar Research Photos Map DIRECT

Table with car specifications: Price (\$57,500), Depreciation (\$7,010 /yr), Mileage (155,000 km), Road Tax (\$1,071 /yr), Dereg Value (\$41,179), COE (\$50,168), Engine Cap (1,796 cc), Curb Weight (1,580 kg), Type of Vehicle (Luxury Sedan), Reg Date (07-Apr-2008), Manufactured (2007), Transmission (Auto), OMV (\$39,547), ARF (\$39,547), Power (135.0 kW), No. of Owners (2).



100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER. Preferred V.

Shortlist Compare Add no Report Error More Actions

Features

Luxury German Sedan C200 1.8L Inline 4 With Suprcharged Engine. View specs of the Mercedes-Benz C-Class Saloon (2002-2006)

Accessories

Stock Components Are Kept As Spares Will Be Provided.

Description

Smooth Engine, Easy To Maintain.

Category

COE Car, Direct Owner Sale

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Seller Information

Contact Person(s) Winston Contact No. 96448080 Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

- » Indemnity form » Sales agreemen » Receipt » Hand-over form » Ownership Transfer

GET HELP WITH PAPERWORK. SGCAR MART CONNECT

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agree and we'll help with Car Loans, Insurance, Pay & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers &

Posted on: 17-Sep-2019 | Last Updated on: 17-Sep-2019

Upfront Payment

Compare

\$25

» more Financial info

Condition Codes:

(0)Good (2)Damaged (3)Discolored (4)Cracked (5)Cn (6)Scrubbed (7)Deformed
 (8)Seized (9)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn
 (14)Unassembled (15)Not Working

ACTION/AC

(1)Replace (✓) (2)Repair (N) (3)Check (Y)
 (4)Not Considered (NC)

Aug 2015

MOTOR CAR (Fr)

Vehicle No: **SMK9969J**

Front Portion

| NAC | INC | Item | CON | AC | QTY |
|------|--------|--|---------|----|-----|
| 1001 | 991886 | Fr Number Plate | | | |
| 1002 | 991887 | Fr Number Plate Base | | | |
| 1003 | 991889 | Fr Number Plate Garnish | | | |
| 1004 | 991300 | Fr Bumper | PO | | |
| 1005 | 992341 | Fr Bumper Clips | NEC | | |
| 1006 | 991325 | Fr Bumper Bracket | | | |
| 1007 | 991462 | Fr Bumper Side Retainer | | | |
| 1008 | 991433 | Fr Bumper Reinforcement | Bracket | | |
| 1009 | 991318 | Fr Bumper Beam | | | |
| 1010 | 991468 | Fr Bumper Sponge | BR | | |
| 1011 | 991427 | Fr Bumper Protector | | | |
| 1012 | 991420 | Fr Bumper Pad | | | |
| 1013 | 991363 | Fr Bumper Grille | | | |
| 1014 | 991301 | Fr Bumper Moulding | | | |
| 1015 | 991407 | Fr Bumper Lower Spoiler | | | |
| 1016 | 991438 | Fr Bumper Sensor | | | |
| 1017 | 995100 | Fr LH Bumper Fog Lamp Cover | | | |
| 1018 | 991355 | Fr RH Bumper Fog Lamp Cover | | | |
| 1019 | 995079 | Fr LH Bumper Fog Lamp | | | |
| 1020 | 995080 | Fr RH Bumper Fog Lamp | | | |
| 1021 | 991793 | Fr Grille | CP | | |
| 1022 | 991328 | Fr Grille Emblem | | | |
| 1023 | 991799 | Fr Grille Chrome Moulding | | | |
| 1024 | 991222 | Fr Apron Panel | | | |
| 1025 | 992013 | Fr Support Panel | | | |
| 1026 | 992025 | Fr Support Panel Top Garnish Cover | | | |
| 1027 | 992416 | Horn | | | |
| 1028 | 991277 | Fr Brace Panel | | | |
| 1029 | 995153 | Fr LH Headlamp Assy | PO | | |
| 1030 | 991821 | Fr RH Headlamp Assy | CP | | |
| 1031 | 995088 | Fr LH Side Lamp | | | |
| 1032 | 995089 | Fr RH Side Lamp | | | |
| 1033 | 990248 | Bonnet | | | |
| 1034 | 991328 | Bonnet Emblem | | | |
| 1035 | 990287 | Bonnet Lock | | | |
| 1036 | 990285 | Bonnet Insulator | | | |
| 1037 | 990273 | Bonnet Hinge | | | |
| 1038 | 990261 | Bonnet Damper | | | |
| 1039 | 990305 | Bonnet Rubber | | | |
| 1040 | 990252 | Bonnet Cable | | | |
| 1041 | 990311 | Bonnet Stand | | | |
| 1042 | 990119 | Air Con Condenser | | | |
| 1043 | 990122 | Air Con Fan Assy | | | |
| 1044 | 990134 | Air Con Suction Pipe (Low Pressure) | | | |
| 1045 | 990118 | Air Con Suction Hose | | | |
| 1046 | 990133 | Air Con Discharge Pipe (High Pressure) | | | |
| 1047 | 990114 | Air Con Discharge Hose | | | |
| 1048 | 990149 | Air Con Liquid Pipe | | | |
| 1049 | 995066 | Air Con Receiver Drier | | | |
| 1050 | 990111 | Air Con Compressor Assy | | | |
| 1051 | 995294 | Air Con Belt | | | |
| 1052 | 995074 | Radiator | | | |
| 1053 | 992738 | Radiator Cowling | | | |
| 1054 | 992742 | Radiator Fan Assy | | | |
| 1055 | 992745 | Radiator Fan Clutch | | | |
| 1056 | 992758 | Radiator Hose Top | | | |
| 1057 | 992757 | Radiator Hose Bottom | | | |
| 1058 | 992741 | Radiator Expansion Tank | | | |
| 1059 | 990151 | Air Duct | | | |
| 1060 | 990070 | Air Cleaner Assy | | | |
| 1061 | 990056 | Air Cleaner Hose | | | |
| 1062 | 990089 | Air Cleaner Resonator | | | |
| 1063 | 991712 | Fr Exhaust Manifold | | | |
| 1064 | 991713 | Fr Exhaust Manifold Cover | | | |
| 1065 | 991054 | Fr Exhaust Manifold Sensor (Oxygen) | | | |
| 1066 | 991714 | Front Exhaust Pipe | | | |
| 1067 | 990219 | Battery | | | |
| 1068 | 990224 | Battery Cover | | | |
| 1069 | 990223 | Battery Bracket | | | |
| 1070 | 990220 | Battery Tray | | | |

\$1365
 \$50
 \$300
 \$350
 \$485
 \$1100
 \$1100

| NAC | INC | Item | CON | AC | QTY |
|------|--------|------------------------------|-----|----|-----|
| 1071 | 992205 | Fuse Box | | | |
| 1072 | 994011 | Relay Box | | | |
| 1073 | 995053 | Wiper Washer Tank | | | |
| 1074 | 995052 | Wiper Washer Tank Motor | | | |
| 1075 | 990159 | Alternator Assy | | | |
| 1076 | 990160 | Alternator Belt | | | |
| 1077 | 992688 | Power Steering Pump | | | |
| 1078 | 992669 | Power Steering Belt | | | |
| 1079 | 994431 | Power Steering Cooler Pipe | | | |
| 1080 | 992692 | Power Steering Hose | | | |
| 1081 | 990010 | ABS Pump Control Unit | | | |
| 1082 | 990427 | Brake Master Pump Assy | | | |
| 1083 | 990403 | Brake Booster Pump Assy | | | |
| 1084 | 991005 | Engine Top Cover | | | |
| 1085 | 991011 | Engine Under Cover | | | |
| 1086 | 990946 | Engine Mounting | | | |
| 1087 | 990949 | Engine Mounting Frt | | | |
| 1088 | 990950 | Engine Mounting LH | | | |
| 1089 | 990952 | Engine Mounting RH | | | |
| 1090 | 990951 | Engine Mounting Rear | | | |
| 1091 | 992234 | Gear Box Mounting | | | |
| 1092 | 991520 | Fr LH Chassis Member | | | |
| 1093 | 991520 | Fr RH Chassis Member | | | |
| 1094 | 990728 | Fr Vertical Cross Member | | | |
| 1095 | 991863 | Fr Lower Cross Member | | | |
| 1096 | 995070 | Fr LH Fender | | | |
| 1097 | 995072 | Fr LH Fender Inner Panel | | | |
| 1098 | 995147 | Fr LH Fender Lamp | | | |
| 1099 | 995148 | Fr LH Fender Protector | | | |
| 1100 | 991740 | Fr LH Fender Inner Shield | | | |
| 1101 | 995179 | Fr LH Mudflap | | | |
| 1102 | 995170 | Fr LH Wheel Rim | | | |
| 1103 | 994025 | Fr LH Rim Cover | | | |
| 1104 | 995065 | Fr LH Tyre | | | |
| 1105 | 995071 | Fr RH Fender | | | |
| 1106 | 991739 | Fr RH Fender Inner Panel | | | |
| 1107 | 991744 | Fr RH Fender Lamp | | | |
| 1108 | 991752 | Fr RH Fender Protector | | | |
| 1109 | 991740 | Fr RH Fender Inner Shield | | | |
| 1110 | 991884 | Fr RH Mudflap | | | |
| 1111 | 992087 | Fr RH Wheel Rim | | | |
| 1112 | 994025 | Fr RH Rim Cover | | | |
| 1113 | 995065 | Fr RH Tyre | | | |
| 1114 | 992093 | Fr Windscreen Glass | | | |
| 1115 | 992117 | Fr Windscreen Rubber | | | |
| 1116 | 992108 | Fr Windscreen Moulding | | | |
| 1117 | 992098 | Fr Windscreen Sealant | | | |
| 1118 | 991019 | ERP Bracket | | | |
| 1119 | 991020 | ERP Unit | | | |
| 1120 | 992140 | Fr Wiper Arm | | | |
| 1121 | 992142 | Fr Wiper Blade | | | |
| 1122 | 995045 | Wiper Panel Garnish | | | |
| 1123 | 991126 | Firewall Panel | | | |
| 1124 | 990753 | Dashboard Assy | | | |
| 1125 | 992282 | Glove Box Cover | | | |
| 1126 | 992281 | Glove Box Compartment | | | |
| 1127 | 994483 | Steering Wheel Airbag | | | |
| 1128 | 994485 | Steering Wheel Airbag Sensor | | | |
| 1129 | 990749 | Dashboard Airbag | | | |
| 1130 | 990750 | Dashboard Airbag Sensor | | | |
| 1131 | 990029 | Airbag Control Unit | | | |
| 1132 | 990864 | Fr Driver Seat | | | |
| 1133 | 991922 | Fr RH Seat Belt Assy | | | |
| 1134 | 991899 | Fr Passenger Seat | | | |
| 1135 | 995182 | Fr LH Seat Belt Assy | | | |
| 1136 | 990247 | Sticker | | | |

No of Items: _____

Assessor: _____

original copy

(L/S)

| | |
|----------------------------------|---------|
| Frt Bumper | \$ 1365 |
| Frt Bumper clip | \$ 50 |
| Frt Bumper reinforcement bracket | \$ 300 |
| Frt Bumper sponge | \$ 350 |
| Frt grille | \$ 485 |
| Frt LH Headlamp Assy | \$ 1100 |
| Frt RH Headlamp Assy | \$ 1100 |
| <hr/> | |
| Labour | \$ 300 |
| Spray paint | \$ 200 |
| <hr/> | |

10% list item

| |
|---------|
| \$ 4750 |
| \$ 475 |
| <hr/> |
| \$ 4275 |
| <hr/> |

$\$ 4275 + \$ 500 = \underline{\$ 4775}$

L/S 20% : $\underline{\$ 3800}$ ✕

[Signature]
18/9/2019



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION
ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Ref: CS3/SPF19015611/Fvd3s2

Date: 19-09-2019



ATTN: HAFIZUL FARHAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|--------------|-----------------------|----------------|------------|
| Insured Veh. | QX 281C | Veh. Inspected | SMK 9969J |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | AEMD/105/009/2019/089 | Excess (\$) | 0.00 |
| Assign From | HAFIZUL FARHAN | Assign Date | 03/09/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|----------------------------------|--------------|------------|
| Make & Model | MERCEDES BENZ C200 KOMPRESSOR | c.c | 1796 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | WDD2040412A201228 | Colour | GREY |
| Odometer | 144570 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 235/35 R19 | YOKOHAMA | 4 mm |
| L/H Front Tyre | 235/35 R19 | YOKOHAMA | 4 mm |
| R/H Rear Tyre | 235/35 R19 | YOKOHAMA | 4 mm |
| L/H Rear Tyre | 235/35 R19 | YOKOHAMA | 4 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|--|---------------------|-------------------------|
| Accident Date | 26/08/2019 | Inspect Date / Time | 12/09/2019 (05:02 PM) |
| Survey held at | BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28 SINGAPORE 417883 | | |

5a. Remarks

| |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SMK 9969J

| Qty | Description of Parts | Condition | Recommended (\$) |
|-----|---|-----------|------------------|
| | REPLACEMENT OF PARTS | | |
| 1 | FRT BUMPER | DENTED | 1,365.00 |
| 1 | FRT BUMPER CLIPS | NECESSARY | 50.00 |
| 1 | FRT BUMPER REINFORCEMENT BRACKET | CRACKED | 300.00 |
| 1 | FRT BUMPER SPONGE | BROKEN | 350.00 |
| 1 | FRT GRILLE | CRACKED | 485.00 |
| 1 | FRT LH HEADLAMP ASSY | SCRATCHED | 1,100.00 |
| 1 | FRT RH HEADLAMP ASSY | CRACKED | 1,100.00 |
| | LESS 10% DISCOUNT | | -475.00 |
| | | | 4,275.00 |
| | LABOUR | | |
| | LABOUR. | | 300.00 |
| | SPRAY PAINT. | | 200.00 |
| | | | 500.00 |
| | GRAND TOTAL | | 4,775.00 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | 3,800.00 |

Report Ref No. CS3/SPF19015611/Fvd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800.00 - \$5,000.00

RECOMMENDED REPAIR DAYS : 4
WEEKENDS : 2
TOTAL DAYS : 6

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.