

22/03/2007

ASS. REC. BY:

REF: CS/MSG/19015622/TIT/302 Special Instruction:

Surveyor: Taukh ASSIGNMENT (Office)From (Person): IVG ch/n How of MS19 Date/Time: 3.9.19 16:53p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGF 3031B Insured: SL2 618mat Workshop m/s Anna Auto care Tel: 87783636of 36 Toh Guan Road East #01-36Policy No: 29114756 MKF Claim No: 604575

Sum Insured: Excess:

Make of Veh: D.O.A. 1-9.2019(Client's Record) 9.9.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 4.9.19 11.05a.m Person Contacted: Alvin Wu Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGF 3031B - X
	SL2 618m - (CS) LCP 17004642/ k196392 DOA - 03/03/2017
	lump sum \$4850, 5 days (Red: 7219.50; 59%)
6/12-	Confirm

Taujikh

MSIG

ASSIGNMENT

COE 2021 March

2006 April

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 915K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGF3031B

Regn: 2006

Type: M:Car / M:Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish

C.C. 1794

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading 273656

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

ENE/00288134

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

195/65R15

R: _____

BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 9/9/1903pm

Survey held at

AMA for gun

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

Put N/S, u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit 7 days.

RECEIVED 8 DEC 2019

Rebate \$7941

Signature
12/2019

Date/Time, File Pass to?

☐

Prel. Report

1) 9/12 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

200

Transportation:

\$ + P.S. \$

Fuel:

Other:

11

211

And Fee:

☐

Site Insp

\$

☐

Interview

\$

☐

Tech. Insp

\$

☐

Meal and

\$

Report to the

TP

1) 0

48507

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2019		03 Sep 2019 16:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	SURIYA KUMARY D/O RASIYAM, ID: S1344922H		
Vehicle Reg. No.:	SGF3031B	Date of Loss:	01/09/2019 15:00 - :59 [160 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 604575	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLL618M	Policy No. (Claimant):	MT/00620003
		Excess:	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/09/2019]		
Driver/Custodian (Insured):	GAN TIONG HWEE (65 / Male) , NRIC: S0013920C, Tel: +6581233119 Email:		
Adj Asg. Remarks:	on WP, OI:Grab. Liab: Dispute, Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Alvin Wee @ 8778 3636 / 9017 3393 / 6200 0600.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: AMA Automotive <ama.claim@gmail.com>
Sent: Friday, 6 December 2019 4:58 PM
To: Denise Tay (LKKAuto)
Subject: Re: SGF 3031B / MSIG / DOA:1/9/2019

Dear Denise,

COR lump sum \$4850/- 5days confirmed.

Thank You and Best Regards



Alvin Wee

AMA Automotive Pte Ltd

36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580

Hp : +65 8778 3636

Tel :+65 6200 0600

www.amaauto.sg



CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

On Thu, Dec 5, 2019 at 5:44 PM Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Sir,

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NG CHEN HOW

Date: 11 Sep 2019

Preliminary Advice

Insured Vehicle No : SLL618M

TP Vehicle No : SGF3031B

Make : TOYOTA WISH

Date of Inspection : 09/09/2019

Inspection At : AMA AUTOCARE PTE LTD (HQ)
36 TOH GUAN ROAD EAST, #01-36
SINGAPORE 608580

Accident Date : 01/09/2019

Assignment Date : 03/09/2019

Est. Duration of Repair : 5.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, n/s, undercarriage portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,189.25
Revised Amount	:S\$	5,679.00
Check Items (Estimated)	:S\$	652.50
Total	:S\$	6331.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

Soon Huat Autoserv Pte Ltd

48 Toh Guan Road East #01-136



Enterprise Hub

Singapore608586

Phone Number: 8402-5982, 9770-5782

Customer:	AMA	Date:	9/9/2019 10:22 AM
Company:		VIN	
License No:	SGF3031B	Technician:	AL HONG
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

TOYOTA, WISH, 2003-2009, ZNE10G(2WD)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3°23'	2°20'	3°49'	3°26'
		Right	3°56'	2°20'	3°49'	3°57'
	Camber	Left	-3°00'	-1°15'	0°15'	-3°08'
		Right	-1°08'	-1°15'	0°15'	-1°03'
	Toe	Left	2.8	-0.5mm	0.5mm	10.7
		Right	9.0	-0.5mm	0.5mm	1.3
Total		11.8	-1.1	1.1	12.0	
Rear	Camber	Left	-1°01'	-2°15'	-0°45'	-1°01'
		Right	-1°19'	-2°15'	-0°45'	-1°18'
	Toe	Left	1.4	-0.2mm	1.3mm	1.5
		Right	1.1	-0.2mm	1.3mm	1.1
		Total	2.5	-0.3	2.5	2.6
	Thrust Angle		-0°01'	----	----	-0°02'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	11°33'	11°20'	11°20'	11°33'
		Right	11°47'	11°20'	11°20'	11°47'
Included Angle		Left	8°33'	----	----	8°25'
		Right	10°39'	----	----	10°44'
Toe Out On Turns		Left	----	----	----	----
		Right	----	----	----	----
Maximum Turns		Left	----	----	----	----
		Right	----	----	----	----
Toe Curve Change		Left	----	----	----	----
		Right	----	----	----	----
Setback		Front	-4mm	----	----	3mm
		Rear	-5mm	----	----	-6mm
Track Width Diff.			15mm			15mm
Wheel Base Diff.			2mm			8mm
Front Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Rear Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Frame Angle						----

Thank You For Your Business



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 922H

Vehicle Details

Vehicle No.: SGF3031B
Vehicle to be Exported: Yes
Intended Deregistration Date: 11 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 A
Primary Colour: Grey
Manufacturing Year: 2006
Engine No.: 1ZZ2462143
Chassis No.: ZNE100288134
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$22,860.00
Original Registration Date: 06 Apr 2006
First Registration Date: 06 Apr 2006
Transfer Count: 2
Actual ARF Paid: \$25,146.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2021
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$25,466.00
COE Rebate Amount: \$7,913.00
Total Rebate Amount: \$7,913.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/09/2019 15:50
Date Of Accident	01/09/2019 15:10
Exact Location Of Accident	JTN OF HILL ST & COLEMAN ST TOWARDS NEW BRIDGE RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGF3031B
Insured/Policyholder	
Name Of Registered Owner	SURIYA KUMARY D/O RASIYAM
NRIC No	S1344922H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84499400
Alternative Phone No	OFFICE-84499400
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00620003
Cover Note Number	
Driver	
Name of Driver	SATHIYA SOORIAN S/O SATHIAVELU
NRIC No	S9401976A
Date Of Birth	19/01/1994
Occupation	INDOOR
Date Of Driving Pass	20/09/2012
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84499400
Fax Number	
Contact Number	
EMail Address	SATHIYASOORIAN@HOTMAIL.COM

Address	BLOCK 257 BANGKIT ROAD #08-53
Postcode	670257
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : K SATHEAVELU GENDER: : FEMALE
Passenger 2	NAME: : SATHIYA KUMARY GENDER: : FEMALE
Passenger 3	NAME: : SATHIYA SHOBHA GENDER: : FEMALE
Passenger 4	NAME: : PRITHIYANKA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attached Sketch Plan for the accident details.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL618M
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 2/9/14

1508 hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

towards new bridge road.

Junction of hill St & coleman St - 1510 hrs. on 1/9/2019

I was on the first lane when a car hit my car on the front left side.

K. Sathya Kumar - M

Sathya Kumar - F

Sathya Shobha - F

Prithi jankar - F

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 2/9/19

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 1

Vehicle No. SGF3031B TOYOTA WISH 1.8A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet		1067.00	Ry
2	Bonnet hinge @\$107.00		214.00	X nh
1	Front bumper		481.99 930.00	de
1	Front bumper center grille		397.70 413.00	one
1	Front bumper retainer LH		108.00	de
1	Front bumper undercover		189 383.00	fn
1	Fog lamp LH		340.00	dis
1	Fog lamp bracket LH		184.00	dis
1	Radiator top garnish		340.00	X jun
1	Support panel		891.00	X jun
1	Headlamp LH		886.00	one
1	Headlamp panel		568.00	part
1	Front fender LH		844 980.00	bl
1	Front fender signal light LH		143.00	X nh
1	Front fender inner shield LH		220.00	de
1	Front sport rim LH		680.00	one
1	Front shock absorber LH		468.60 692.00	X bt
1	Front wheel bearing LH		191.60 378.00	X ? bt
1	Front stabilizer link LH		248.00	X nh
1	Front knuckle arm LH		281.90 492.00	X ? bt
1	Front lower control arm LH		374 482.00	X bt
			10639.00	0.00
less 25%			2659.75	25% 0.00
			7979.25	0.00
SPECIAL NETT ITEMS				
1	Front bumper clips		60.00	30 net
1	Headlamp clips		70.00	X nh
1	Front fender inner shield clips		40.00	20 net
1	Front bumper undercover clips		40.00	X nh
TOTAL PARTS			8189.25	0.00

7254.00
- 25% 1813.50
5440.50
137
@ 1115
6214.79
4661.09
5/N 50

195/65R15 BS



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 2

Vehicle No. **SGF3031B TOYOTA WISH 1.8A**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	2000.00	600.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	700
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	200.00	30.
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	180.00	x nn
6	To provide anti-rust treatment on affected areas	210.00	30
Labour Total :		4190.00	
TOTAL (PARTS & LABOUR):		12069.50	

L 1360

P 5440.50
 S/N 50.00
 L 1360.00

 6850.50
 -20% L/S 1370.10

 5480.40

4661.09
 50
 1360

 6071.09
 1/5 \$4850*
 5 days.

Tanjun 97495745
 - WP
 9/9/19 @ 3pm
 Lungsun
 Resny after repai
 5 days

12/9/25



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 1

Vehicle No. **SGF3031B TOYOTA WISH 1.8A**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Bonnet		1067.00	Ry
1	Bonnet hinge @\$107.00		214.00	x
1	Front bumper		930.00	de
1	Front bumper center grille		413.00	una
1	Front bumper retainer LH		108.00	de
1	Front bumper undercover		383.00	tu
1	Fog lamp LH		340.00	dis
1	Fog lamp bracket LH		184.00	dis
1	Radiator top garnish		340.00	x
1	Support panel		891.00	x
1	Headlamp LH		886.00	are
1	Headlamp panel - <i>front inner panel</i>		568.00	front
1	Front fender LH		980.00	bl
1	Front fender signal light LH		143.00	x
1	Front fender inner shield LH		220.00	de
1	Front sport rim LH		680.00	out
1	Front shock absorber LH		692.00	x
1	Front wheel bearing LH		378.00	?
1	Front stabilizer link LH		248.00	x
1	Front knuckle arm LH		492.00	?
1	Front lower control arm LH		482.00	x
			10639.00	0.00
		less 25%	2659.75	25% 0.00
			7979.25	0.00
	SPECIAL NETT ITEMS			
1	Front bumper clips		60.00	30net
1	Headlamp clips		70.00	x
1	Front fender inner shield clips		40.00	20net
1	Front bumper undercover clips		40.00	x
	TOTAL PARTS		8189.25	0.00

195/65R15 BS



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 2

Vehicle No. **SGF3031B TOYOTA WISH 1.8A**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	2000.00	600.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	700
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	200.00	30.
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	180.00	x
6	To provide anti-rust treatment on affected areas	210.00	30.
Labour Total :		4190.00	
TOTAL (PARTS & LABOUR):		12069.50	

Signature
4/9/19 Taylin 97495745
- WP
9/9/19 @ 3pm
Lumpsum
Resny after repai
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2019		03 Sep 2019 16:53 Edit Adj Rpt	S\$4,850.00 Edit Estimates	S\$4,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	SURIYA KUMARY D/O RASIYAM, ID: S1344922H								
Vehicle Reg. No.:	SGF3031B	Date of Loss:	01/09/2019 15:00 - :59 [160 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 604575	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLL618M	Policy No. (Claimant):	MT/00620003						
		Excess:							
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/10/2019]								
Driver/Custodian (Insured):	GAN TIONG HWEE (65 / Male), NRIC: S0013920C, Tel: +6581233119 Email:								
Adj Asg. Remarks:	on WP. OI:Grab. Liab: Dispute. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Alvin Wee @ 8778 3636 / 9017 3393 / 6200 0600.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
































Claim Documents

*SGF3031B (604575)
[SLL618M]
TP
SURIYA KUMARY D/O RASIYAM
Sep 1 2019 3:00PM
[GRAB RENTALS PTE LTD]
Ama Autocare Pte Ltd













Upload Documents | Upload Photos | Compose New Letter


View View in Browser

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	03/09/19 14:00	Accident Statement From: SC - Reg. No: SLL618M, Claimant: GRAB RENTALS PTE LTD		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	11/09/19 14:51	Adjuster Immediate Advice		Load HTM		
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
2	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
3	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
4	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
5	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
6	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
7	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
8	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
9	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
10	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
11	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
12	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
13	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
14	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
15	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
16	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
17	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
18	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
19	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
20	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
21	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
22	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
23	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
24	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
25	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
26	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
27	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
28	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
29	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
30	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
31	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
32	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
33	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
34	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
35	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
36	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	
37	09/12/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/12/19 09:44	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	09/12/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/09/19 14:10	Agree on SJE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
1	02/09/19 16:05	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
1	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	02/09/19 16:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
1	02/09/19 16:02	Sketch Plan	 Load TIF	
2	02/09/19 16:03	Identification Card	 Load TIF	
3	02/09/19 16:03	Driving License	 Load TIF	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
4	02/09/19 16:03	Certificate of Insurance		 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015622/T1TF3E2

Date: 16/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756MKF

Claimant Vehicle No : SGF3031B

Insured Vehicle No : SLL618M

Date of Loss: 01/09/2019

Nature of Claim: TP

Claim No: 604575

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGF3031B**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2462143

Reg. Date: 06/04/2006 (Man. Year: 2006)

Chassis No: ZNE100288134

Colour: Silver

Odometer: 273656 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,189.25	4,711.09	3,478.16	42.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	1,360.00	2,830.00	67.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,379.25	6,071.09	6,308.16	50.96
Approved Total (Overridden) (S\$)		4,850.00		
Nett Amount (S\$)	12,379.25	4,850.00	7,529.25	60.82

INSPECTION

Date of Assignment: 03/09/2019

Date Inspected: 09/09/2019 Inspected At:

Ama Autocare Pte Ltd (HQ)
36 Toh Guan Road East, #01-36
Singapore 608580

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF3031B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,067.00 FL	*- FL
2	2		*BONNET HINGE	Not Necessary	214.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed	930.00 FL	*481.99 FL
4	1		*FRONT BUMPER CENTER GRILLE	Cracked	413.00 FL	*397.70 FL
5	1		*FRONT BUMPER RETAINER LH	Deformed	108.00 FL	*108.00 FL
6	1		*FRONT BUMPER UNDERCOVER	Torn	383.00 FL	*189.00 FL
7	1		*FOG LAMP LH	Distorted	340.00 FL	*340.00 FL
8	1		*FOG LAMP BRACKET LH	Distorted	184.00 FL	*184.00 FL
9	1		*RADIATOR TOP GARNISH	Not Necessary	340.00 FL	*- FL
10	1		*SUPPORT PANEL	Not Necessary	891.00 FL	*- FL
11	1		*HEADLAMP LH	Cracked	886.00 FL	*886.00 FL
12	1		*HEADLAMP PANEL	Bent	568.00 FL	*568.00 FL
13	1		*FRONT FENDER LH	Bent	980.00 FL	*844.00 FL
14	1		*FRONT FENDER SIGNAL LIGHT LH	Not Necessary	143.00 FL	*- FL
15	1		*FRONT FENDER INNER SHIELD LH	Deformed	220.00 FL	*220.00 FL
16	1		*FRONT SPORT RIM LH	Cut	680.00 FL	*680.00 FL
17	1		*FRONT SHOCK ABSORBER LH	Bent	692.00 FL	*468.60 FL
18	1		*FRONT WHEEL BEARING LH	Bent	378.00 FL	*191.60 FL
19	1		*FRONT STABILIZER LINK LH	Not Necessary	248.00 FL	*- FL
20	1		*FRONT KNUCKLE ARM LH	Bent	492.00 FL	*281.90 FL
21	1		*FRONT LOWER CONTROL ARM LH	Bent	482.00 FL	*374.00 FL
22	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*HEADLAMP CLIPS	Not Necessary	70.00 FS	*- FS
24	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FS	*20.00 FS
25	1		*FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,849.00	6,264.79
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,659.75	1,553.70
Total Parts (\$\$)	8,189.25	4,711.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	2,000.00	600.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	700.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	200.00	30.00
4	TO REMOVE AND REFIX / REPLACE REAR TRIMS, GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	180.00	0.00
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	210.00	30.00
Gross Labour Cost (\$\$)			4,190.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >