



Your Ref: CMTD1902789/SYH

Date: 09<sup>th</sup> September 2019

Our Ref: CS1/SMO19015624/Hvd3s2

**M/s Sompo Insurance Singapore Pte Ltd**

50 Raffles Place

#05-01/06

Singapore Land Tower

Singapore 048623

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YM 9319H  
INSURED VEHICLE: XB 9454U ACCIDENT DATE: 08/06/2019**

We thank you for your instruction on 02/09/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YM 9319H from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles YM 9319H and XB 9454U.
- c) Damaged vehicle photographs of YM 9319H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: YM 9319H
Make & Model	: Mitsubishi FE83BE6SRDEA
Year of Registration	: 2008
Chassis Number	: FE83BEA10796
Engine Capacity	: 2977 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.