

Man/son

ACC. REC. BY:

Conveyor: Ram

REF:

CS3/CTI19015643/Fed3

Special Instruction:

ASSIGNMENT (Office)

From (Person): Chong Ban Sen

of CTI

Date/Time: 4/9/19 @ 11:46am

Estimated Cost:

Bill to:

OD ☒ WS / ☐ TR RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV / ☐ CS

To Inspect Vehicle No:

FBD 4771L

Insured:

SLA 9383M

at Workshop m/s

All wheel Motoring

Tel:

8510 2102

of

BIK 5032 AMK Ind. Park 2 #01-307

Policy No: DMPCLN30264319033

Claim No:

SNM19D203599C02

Sum Insured:

Excess:

D.O.A. 30/7/2019

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 11:57am @ 4/9/19

Person Contacted:

Ah Seng

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	<u>Estimate (X)</u>
	<u>FBD 4771L-X</u>
	<u>SLA 9383M-NA/CTI18012133/RS</u>
	<u>Dismantle: 9/9/2019</u>

Don: 8/7/2018

ASSIGNMENT

From:

Date:

Veh No:

FBD 4771L

Yr Regn: MAR / 2009

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: FBD 4771L

Make: SUZUKI

C.C. 398

at Workshop m/s all wheel motoring

Colour Black

A/C: Insured / Std / NI / NA

of BLK 5032 AMK 1nd PARK 2 #01-307

Sp. Reading 19999

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: -

Policy No.

C/No: JS18811200108788

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 120/60 R17

R: 150/60 R17

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ROSSO

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal. 4 mm

R/Bal. 4 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. mm

L/Bal. mm

Est. Repairs:

days

Res.: Yes or No

D.O.A. 30/7/2019

D.O.I. 4/9/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

all wheel motoring

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt / O/S / Rear

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$3000-\$1000

Repair days: 5 days

MV: \$9500

PV: \$4955

NV: \$4500

12/9/2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$1

Photos

Others

TOTAL

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format: PRS

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2019		12 Sep 2019 09:16 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	MOHAMMAD HAIRIL BIN HASAN, ID: S9028177A		
Vehicle Reg. No.:	FBD4771L	Date of Loss:	30/07/2019 07:00 - :59
Claim Type:	TP / SNM19D203599C02	Policy/Cover Note No.:	DMPCSN30264319033
Vehicle Reg. No. (Insured):	SLA9383M	Policy No. (Claimant):	MSCN NO: 60837040 (TPFT)
		Excess:	S\$0.00
Repairer:	All Wheel Motoring (HQ) Blk 5032 Ang Mo Kio Industrial Park 2, #01-307, 569535 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 23/09/2019]		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 4 September 2019 11:46 AM
To: Nurhuda Bte Daud
Cc: Elaine Cheong; assignments@lkkauto.com
Subject: RE: OUR REF: SNM19D203599-SLA9383M-CML - FW: [PRI NOTICE] Your Ref: SLA 9383M ; Our Ref: 19-A38-10542-VL.jp.nh

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Nurhuda Bte Daud [mailto:nurhuda@legaloptions.biz]
Sent: Wednesday, 4 September, 2019 11:13 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D203599-SLA9383M-CML - FW: [PRI NOTICE] Your Ref: SLA 9383M ; Our Ref: 19-A38-10542-VL.jp.nh

Dear Boon Sen,

We regret to inform that our client rejected your list of surveyor.

We provide you herewith our client's list of surveyor: -

	Surveyor:	Contact Person:	Contact:
1.	OH APPRAISAL SERVICES	OH HAN CHEONG	-
2.	PAR AUTOMOTIVE CONSULTANCY	B J LOI	-
3.	UNITED APPRAISAL AND MANAGEMENT PTE LTD	MARC	-
4.	AUTO PERFORMANCE APPRAISAL	LEK BOON HWEE	-

Kindly contact our client's repairer: -

All Wheel Motoring

Blk 5032 Ang Mo Kio Industrial Park 2,
#01-307
S (569535).

Contact No. Mr Ah Seng at 8510 2102

Thanks n regards,

Murhuda

Junior Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2803 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

On Wed, Sep 4, 2019 at 9:34 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, 3 September, 2019 5:27 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; nurhuda@legaloptions.biz

Subject: OUR REF: SNM19D203599-SLA9383M-CML - FW: [PRI NOTICE] Your Ref: SLA 9383M ; Our Ref: 19-A38-10542-VL.jp.nh

Dear Boon Sen,

Please assist to conduct PRS for FBD4771L.

Note : officer in charge – Elaine Cheong 63896530.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Nurhuda Bte Daud [<mailto:nurhuda@legaloptions.biz>]

Sent: Tuesday, 3 September, 2019 3:39 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: [PRI NOTICE] Your Ref: SLA 9383M ; Our Ref: 19-A38-10542-VL.jp.nh

Dear Sirs,

PRI attached for your urgent attention.

Kindly provide us your list of surveyors in the next 2 working days.

Thanks n regards,

Nurhuda

Junior Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2803 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/08/2019 10:56
Date Of Accident 30/07/2019 07:05
Exact Location Of Accident DAIRY FARM ROAD / DAIRY FARM CRESCENT
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBD4771L

Insured/Policyholder
Name Of Registered Owner MOHAMMAD HAIRIL BIN HASAN
NRIC No S9028177A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-86615455
Alternative Phone No Office-86615455

Vehicle Particulars
Manufacturer SUZUKI
Model DRZ400SMK8
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category MOTORCYCLE

Insurance Company
Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number MSCN NO: 60837040 (TPFT)
Cover Note Number

Driver
Name of Driver MOHAMMAD HAIRIL BIN HASAN
NRIC No S9028177A
Date Of Birth 31/07/1990
Occupation INDOOR
Date Of Driving Pass 24/05/2014
Driving Experience 5 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-86615455

Fax Number	
Contact Number	OFFICE-86615455
EMail Address	NOEMAIL
Address	BLK 281 BUKIT BATOK EAST AVENUE 3 #04-307
Postcode	650281
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA9383M
Vehicle Make/Model/Colour	HONDA / VEZEL 1.5X A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KWOK MOH SHOT
NRIC/Passport Number	

Contact Number 97837043

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MOHAMMAD HAIRIL BIN HASAN

Approximate Age 29

Injuries Sustain

Injured person in which vehicle? FBD4771L

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address BLK 281 BUKIT BATOK EAST AVENUE 3 #04-307

Postcode 650281

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


19 AUG 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305

Reg. Employer's Personal's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER TP REPORT - T/20190805/2104

LATE REPORTING AS VEHICLE
WAS IN TP COMPOUND.

Note: Please note that your insurer may have 14 days time frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

19 AUG 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415931

Phone: 67416697 Fax: 67492305

Email: vockb@singnet.com.sg

NRIC/IN No:

Copyright © 2019 Singnet Ltd.

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20190805/2104

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20190805/2104

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/08/2019 16:59		Vide Report No.:		Station Diary No.: 86	
Informant's Particulars					
Name of Informant: MOHAMMAD HAIRIL BIN HASAN			Address: APT BLK 281 BUKIT BATOK EAST AVENUE 3 #04-307 SINGAPORE 650281		
ID Type / ID No.: NRIC NO / S9028177A			Contact No.: Home/Office: Mobile: 86615455		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 29	Date of Birth: 31/07/1990	Type of Informant: Rider		
Race: Javanese			Language:		Institution / School Name:
Occupation: AETOS			Driving Licence Information: Class: 2B,2A		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/07/2019 07:05	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 DAIRY FARM ROAD DAIRY FARM CRESCENT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBD4771L	Motorcycle	SUZUKI	DRZ400SMK 8	White		0
SLA9383M	Car					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBD4771L	MSIG INSURANCE (SINGAPORE) PTE. LTD.	60837040	10/01/2019	09/01/2020

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20190805/2104

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20190805/2104

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMMAD HAIRIL BIN HASAN	ID No.	S9028177A
Related Vehicle	FBD4771L (Motorcycle)	Contact No.	86615455
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A Date of Expiry: NIL
Date Treatment	30/07/2019	Date Discharge	02/08/2019
No. of Days granted Medical Leave	18	Degree of Injury	Serious
Driver			
Name	KWOK MOH SHOT	ID No.	S1331246J
Related Vehicle	NIL	Contact No.	97837043
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 30/07/2019 at around 0704hrs, I was riding my motorcycle along Dairy Farm Road towards BKE. There are 2 lanes on that particular road. There is a u-turn area towards Dairy Farm Crescent on my right hand side and as I was approaching the slip road, a red colour car suddenly turned right at the slip road. I was roughly 1 car length away from the said car. I tried to brake to avoid colliding with the car but I was unable to stop in time and thus I collided on the front left side of the car. Due to the impact, I fell to the ground. Subsequently, I got myself up and walked to the side of the road. A passerby called the ambulance. I was then conveyed to NUH for further treatment.

I suffered an ACL tear on my right knee, scratches on my chin due to broken glass fragments, a swollen left thigh and fragments of broken glasses entered both of my eyes. I was discharged on 02/08/2019 and received 18 days of medical leave.

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20190805/2104

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20190805/2104

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sr Staff Sgt SAIFULLAH BIN SUHAIMI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

05/08/2019 16:59

Officer In Charge Of Case:

TP / GIT /

SI ONG CHEE HIEN

Contact No.: 65476437

SN 114

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	177A

Vehicle Details

Vehicle No.:	FBD4771L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	SUZUKI
Vehicle Model:	DRZ400SMK8
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	K419177684
Chassis No.:	JS1B8111200108788
Maximum Power Output:	-
Open Market Value:	\$6,647.00
Original Registration Date:	24 Mar 2009
First Registration Date:	24 Mar 2009
Transfer Count:	7
Actual ARF Paid:	\$998.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Jan 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$5,910.00
COE Rebate Amount:	\$4,955.00
Total Rebate Amount:	\$4,955.00

The information contained herein is correct as at 12 Sep 2019

OK

Home > Motorbikes > Motorbikes for Sale > Class 2A



clementevo

★★★★★ 13

Chat

Make Offer

Advertisement

S\$9,900

Share

20

Suzuki DRZ400SM

📍 Bukit Batok

📍 Meetup

🔖 Used

2008 Suzuki DRZ400SM

Original Registration Date: Jul 2008

COE Expiry: Jul 2028

read more

1 month ago In Class 2A

✓ Suzuki

✓ Motard

Insurance

Meet-up

📍 Bukit Batok

Listed by clementevo

⚡ Very Responsive



Verified



Check seller profile

Reviews for clementevo



yhng1

2019 Jul

great seller, easy deal. great product, thanks bro

Read all 13 reviews

★★★★★

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2019		12 Sep 2019 09:16 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case
















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	MOHAMMAD HAIRIL BIN HASAN , ID: S9028177A								
Vehicle Reg. No.:	FBD4771L	Date of Loss:	30/07/2019 07:00 - :59 [124 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203599C02	Policy/Cover Note No.:	DMPCSN30264319033						
Vehicle Reg. No. (Insured):	SLA9383M	Policy No. (Claimant):	MSCN NO: 60837040 (TPFT)						
		Excess:	S\$0.00						
Repairer:	All Wheel Motoring (HQ) Blk 5032 Ang Mo Kio Industrial Park 2, #01-307, 569535 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 23/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									














Claim Documents

***FBD4771L (SNM19D203599C02)**
[SLA9383M]















TP
MOHAMMAD HAIRIL BIN HASAN
Jul 30 2019 7:00AM
[-]
All Wheel Motoring

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/08/19 11:13	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	19/08/19 11:10	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	16/09/19 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	16/09/19 12:52	General View	Load JPG	<input checked="" type="checkbox"/>
17	16/09/19 12:52	General View	Load JPG	<input checked="" type="checkbox"/>
18	16/09/19 12:52	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
19	16/09/19 12:52	General View	 Load JPG	✓
20	16/09/19 12:52	General View	 Load JPG	✓
21	16/09/19 12:52	General View	 Load JPG	✓
22	16/09/19 12:52	General View	 Load JPG	✓
23	16/09/19 12:52	General View	 Load JPG	✓
24	16/09/19 12:52	General View	 Load JPG	✓
25	16/09/19 12:52	General View	 Load JPG	✓
26	16/09/19 12:52	General View	 Load JPG	✓
27	16/09/19 12:52	General View	 Load JPG	✓
28	16/09/19 12:52	General View	 Load JPG	✓
29	16/09/19 12:52	General View	 Load JPG	✓
30	16/09/19 12:52	General View	 Load JPG	✓
31	16/09/19 12:52	General View	 Load JPG	✓
32	16/09/19 12:52	General View	 Load JPG	✓
33	16/09/19 12:52	General View	 Load JPG	✓
34	16/09/19 12:52	General View	 Load JPG	✓
35	16/09/19 12:52	General View	 Load JPG	✓
36	16/09/19 12:52	General View	 Load JPG	✓
37	16/09/19 12:52	General View	 Load JPG	✓
38	16/09/19 12:52	General View	 Load JPG	✓
39	16/09/19 12:52	General View	 Load JPG	✓
40	16/09/19 12:52	General View	 Load JPG	✓
41	16/09/19 12:52	General View	 Load JPG	✓
42	16/09/19 12:52	General View	 Load JPG	✓
43	16/09/19 12:52	General View	 Load JPG	✓
44	16/09/19 12:52	General View	 Load JPG	✓
45	16/09/19 12:52	General View	 Load JPG	✓
46	16/09/19 12:52	General View	 Load JPG	✓
47	16/09/19 12:52	General View	 Load JPG	✓
48	16/09/19 12:52	General View	 Load JPG	✓
49	16/09/19 12:52	General View	 Load JPG	✓
50	16/09/19 12:52	General View	 Load JPG	✓
51	16/09/19 12:52	General View	 Load JPG	✓
52	16/09/19 12:52	General View	 Load JPG	✓
53	16/09/19 12:52	General View	 Load JPG	✓
54	16/09/19 12:52	General View	 Load JPG	✓
55	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
56	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
57	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
58	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
59	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
60	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
61	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
62	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
63	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
64	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
65	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	✓
66	16/09/19 12:53	Photographs of Damaged Parts	Load JPG	✓
67	16/09/19 12:53	Photographs of Damaged Parts	Load JPG	✓
68	16/09/19 12:53	Photographs of Damaged Parts	Load JPG	✓
69	16/09/19 12:53	Photographs of Damaged Parts	Load JPG	✓
70	16/09/19 12:53	Photographs of Damaged Parts	Load JPG	✓
71	16/09/19 12:53	Photographs of Damaged Parts	Load JPG	✓

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
72	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	16/09/19 12:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/08/19 11:12	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	19/08/19 11:12	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	19/08/19 11:13	Individual Statement [Linked Accident Report Documents]	 Load TIF	
4	19/08/19 11:13	Individual Statement [Linked Accident Report Documents]	 Load TIF	
5	19/08/19 11:13	Individual Statement [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View In Browser	1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print		
1	19/08/19 11:13	Accident Statement	 Load HTM			
Photos/Images			3 per page	<input checked="" type="checkbox"/>		
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print		
1	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
2	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
3	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
4	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
5	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
6	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
7	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
8	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
9	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
10	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
11	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
12	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
13	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
14	19/08/19 11:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
Documentation			1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print		
1	19/08/19 11:12	Sketch Plan	 Load TIF			
2	19/08/19 11:12	Sketch Plan #2	 Load TIF			
3	19/08/19 11:13	Individual Statement	 Load TIF			
4	19/08/19 11:13	Individual Statement	 Load TIF			
5	19/08/19 11:13	Individual Statement	 Load TIF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI19015643/FCD3S2**Date:** 18/09/2019REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30264319033
Claimant Vehicle No :	FBD4771L	Insured Vehicle No :	SLA9383M
Date of Loss:	30/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203599C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBD4771L	Engine No:	K419177684
Make & Model:	SUZUKI DRZ400SMK8, 398cc	Chassis No:	JS1B8111200108788
Reg. Date:	24/03/2009 (Man. Year: 2008)	Odometer:	1999 km
Colour:	Black		
Engine Capacity:	398 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/60 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	ROSSO 4 mm	Rear Left Side:	ROSSO 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/09/2019	
Date Inspected:	04/09/2019	Inspected At: Blk 5032 Ang Mo Kio Industrial Park 2, #01-307 Singapore 569535 Repairer: All Wheel Motoring
Estimated Period of Repair:	5.0 days	

Adjuster: PARASURAM SHANMUGAM**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Sep 2019)	
Parts:	N/A	SUZUKI DRZ400SMK8 398cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD4771L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >