

COMFORTDELGRO ENGINEERING PTE LTD

Date: 03.09.2019

REPAIR ESTIMATE

Time: 10:55:44

Page: 1

China Taiping 4S
LKK - Calvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305329496
 REGN NO : SH 8213H
 MILEAGE : 0000000000
 MAKE : MERCEDES BENZ
 MODEL : E220CDI(E5)
 DATE OF REGN : 18.10.2013
 DATE/TIME IN : 02.09.2019 14:30
 ACCIDENT DATE : 30.08.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-0572-A	BONNET	1	2,850.60	20.00	2,280.48	✓
0002 04-01-0202-0582-A	RADIATOR GRILLE	1	1,220.00	20.00	976.00	X

SUB-TOTAL : 3,256.48

JOB NATURE

0000 PB	PANEL BEATING	300.00	20.00	240.00	✓
0001 SP	SPRAYPAINT CHARGE	300.00	20.00	240.00	✓

SUB-TOTAL : 600.00

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey

Part prices are subject to confirmation

AUTHORISED: YES/NO

- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Calvin LKK

3/9/19 1100h

2 hrs

L/s

After Repair photo