



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI19015669/Epb3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 10-12-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 1227R	Veh. Inspected	SMB 125J	
Policy No.	DMPPHQ19-004319	Coverage (\$)	0.00	
Claim No.	DM19HO02459-JG	Excess (\$)	0.00	
Assign From		Assign Date	03/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ OC500	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WEB63442021000255	Colour	GREEN	
Odometer	743341	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	CONTINENTAL	5 mm	
L/H Front Tyre	275/70 R22.5	CONTINENTAL	5 mm	
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	5/5 mm	
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/08/2019	Inspection Date	03/09/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		