

INS. CASE OWNER:

DANIEL POOI

C53 III19015670/Apa352

LKK:

IDAC:

Surveyor:

ADRIAN

DOI: 04/09/2019

Date / Time : 04/09/2019

Registered in Merimen: 04/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 8694J

Claim No. :

Name of Insured : COMFORT TRANSPORTATION PTE LTD

Policy No. :

Insured Tel No. : HP:

Make / Model : HYUNDAI I40

Excess Sec II :S\$

D.O.A : 26/08/2019 10:05

Place of Accident : JURONG EAST ST 32

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age : SIM KIM LAI

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-97222215

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

PA 7328P

INSRS:
WSP: NHT
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
SHC 8694J	Non-Reporting ltr (1st):	
PA 7328P	Non-Reporting ltr (2nd):	
NS/INC19015148/K1vf3n2; DOA:26/8/19	Non-Reporting ltr (Final):	
-NA/CT118006967/r3; DOA: 13/4/18	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :
Repair Cost:	S\$	
Loss of Rental (LOR):	S\$	(days)
Loss of Use (LOU):	S\$	(\$ x days)
Loss of Income (LOI):	S\$	(\$ x days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		[Tick only one]
GIA/LTA Search	S\$	
Medical:	S\$	
Disbursement:	S\$	(e.g. Tow/ Independent)
Legal Cost	S\$	
Total:	S\$	Global Sum S\$:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	S\$	Name 1:
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

5010760197

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 121

3) Survey fee: \$120.00

114


15670/AP

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
 Person Contacted: _____

Veh No: PA 7328P Yr Regn: 2007, Nov.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mini Bus

Make: Toyota C.C. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 83442 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFJTO2P900001113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155 R15C

R: 185 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Green Max

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>04/09/19</u> 9.18cm

Survey held at NHT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

COE Expiry: 31/10/22

MV: _____
 PV: 13.7K
 Nett: _____

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1) _____
 2) _____
 3) _____
 4) _____
 5) _____
 6) _____
 7) _____
 8) _____
 9) _____
 10) _____
 11) _____
 12) _____
 13) _____
 14) _____
 15) _____
 16) _____
 17) _____
 18) _____
 19) _____
 20) _____
 21) _____
 22) _____
 23) _____
 24) _____
 25) _____
 26) _____
 27) _____
 28) _____
 29) _____
 30) _____
 31) _____
 32) _____
 33) _____
 34) _____
 35) _____
 36) _____
 37) _____
 38) _____
 39) _____
 40) _____
 41) _____
 42) _____
 43) _____
 44) _____
 45) _____
 46) _____
 47) _____
 48) _____
 49) _____
 50) _____
 51) _____
 52) _____
 53) _____
 54) _____
 55) _____
 56) _____
 57) _____
 58) _____
 59) _____
 60) _____
 61) _____
 62) _____
 63) _____
 64) _____
 65) _____
 66) _____
 67) _____
 68) _____
 69) _____
 70) _____
 71) _____
 72) _____
 73) _____
 74) _____
 75) _____
 76) _____
 77) _____
 78) _____
 79) _____
 80) _____
 81) _____
 82) _____
 83) _____
 84) _____
 85) _____
 86) _____
 87) _____
 88) _____
 89) _____
 90) _____
 91) _____
 92) _____
 93) _____
 94) _____
 95) _____
 96) _____
 97) _____
 98) _____
 99) _____
 100) _____

Final Report

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 459C

Vehicle Details

Vehicle No.: PA7328P
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Aug 2019
Vehicle Make: TOYOTA
Vehicle Model: HIACE COMMUTER MANUAL
Primary Colour: White
Manufacturing Year: 2007
Engine No.: 1KD1669905
Chassis No.: JTFJT02P900001113
Maximum Power Output: -
Open Market Value: \$27,391.00
Original Registration Date: 09 Nov 2007
First Registration Date: 09 Nov 2007
Transfer Count: 2
Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2022
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$21,477.00
COE Rebate Amount: \$13,756.00
Total Rebate Amount: \$13,756.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 30 Aug 2019

OK

SEARCH
Hiace

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Search
View All
Advanced Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Hiace 3.0M (COE till 06/2022)



Add to Shortlist

Toyota Hiace 3.0M (COE till 08/2022)



Add to Shortlist

Toyota Hiace 3.0M (COE till 04/2023)



Add to Shortlist

Toyota Hiace 3.0M DX (COE till 05/2023)



Add to Shortlist

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$26,800	\$24,800	\$24,888	\$25,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	06-Jun-2007	17-Aug-2007	23-Apr-2008	30-May-2008
Manufactured	2007	2007	2008	2008
Mileage	-	-	-	-
Transmission	Manual	Manual	Manual	Manual
Engine Cap	2,982 cc	2,982 cc	2,982 cc	2,982 cc
Road Tax	-	-	-	-
Power	-	-	-	-
Curb Weight	1,820 kg	1,820 kg	1,800 kg	1,780 kg
Features	SRS Airbag, ABS.	One Of The Most Reliable Workhorse Van For Sale Now! Drive With No Worries! 100% Loan Available!	-	-
Accessories	CD Changer, Reverse Sensors.	DVD Player! Full Wooden Board!	-	Super Reliable Toyota Condition! New Paintw Condition Leather Seat Needed! Got Rear Airc
Description	Very Well Maintained By Previous Owner. Most Importantly, Accident-Free! Buy With No Worries As Toyota Usually Doesn't Give Many Headaches. Don't Want To Invest Too Much On A Brand New Vehicle? No Problem! This Van Is Just Right For You. Low Running Cost. Come For Viewing And Test Drive This Powerful Workhorse!	Best Selling 5 Doors Van In The Market! No Repair Needed! Handle By A Careful Driver! Door Step Viewing Can Be Arrange! Call Our Friendly Sales Person For More Information!	One Of The Most Durable And Reliable Workhorse For Sales! 5 Doors Catering Van For Your Business Needs, Very Fuel Efficient, Trade-In Are Welcomed, In-House Loan Available. Call Us Now To Arrange For A No Obligation Viewing And For An In-Depth Consultation For Your Financing Needs.	100% Loan! Selling Cf Viewing!
COE	\$18,757	\$17,920	\$18,773	\$17,865
OMV	\$24,590	\$24,590	\$24,689	\$32,585
ARF	-	-	\$1,235	\$1,630
Depreciation	\$9,730 /yr	\$8,400 /yr	\$6,850 /yr	\$6,910 /yr
No. of Owners	4	2	3	1
Type of Vehicle	Van	Van	Van	Van
Category	COE Car	COE Car	COE Car	COE Car, Premium Ad
Availability	Available	Available	Available	Available
Remarks	Fuel type Diesel COE expiry date 2023-05-29	Fuel type Diesel COE expiry date 2023-05-29	Fuel type Diesel COE expiry date 2023-05-29	Fuel type Diesel COE expiry date 2023-05-29


Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	04 Sep 2019 16:34	Clim Dtl Modified	Claimant's Name: -> AN FOO TRANSPORT SERVICE. Claimant's ID: -> 53331459C.	[A] HOW MEI KWAN
2	04 Sep 2019 16:34	Clim Veh Model Changed	(202408) TOYOTA HIACE 3.0 D Commuter (M).	[A] HOW MEI KWAN
3	04 Sep 2019 16:34	Clim Created	Reg No: PA7328P. Acct Date: 2019/08/26. Claim Type: TP. Insurer: Liberty Insurance Pte Ltd (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Works hop: New Hock Teck Motor Pte Ltd (HQ)	[A] HOW MEI KWAN
4	04 Sep 2019 16:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	04 Sep 2019 16:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/13	[A] HOW MEI KWAN
6	04 Sep 2019 16:34	Assignment 1st Accessed		[A] HOW MEI KWAN
7	04 Sep 2019 16:34	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
8	04 Sep 2019 16:37	Clim Ins Co Group Changed	[200034] Liberty Insurance Pte Ltd (HQ) -> [200033] India International Insurance Pte Ltd (HQ) Additional Remarks:	[I] Merimen Administrator
9	04 Sep 2019 16:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/13	[I] Merimen Administrator
10	04 Sep 2019 16:37	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Merimen Administrator
11	10 Sep 2019 20:50	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD. Insured ID: -> 19930382 1R.	[A] HOW MEI KWAN
12	11 Sep 2019 14:16	Adj Mandate Request	Cur.Req:0.00:PODS Liability : unclear Remarks: please request CCTV from OID	[A] VIVIAN LAU PEI FENG
13	13 Sep 2019 10:23	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/09/13. Mandate Remarks: Insured video has been uploaded.	[I] Pooi Chin Han Daniel
14	13 Sep 2019 10:23	Adj Mandate Set	Approved:0.00:Insured video has been uploaded.	[I] Pooi Chin Han Daniel
15	18 Sep 2019 16:22	Video Downloaded	Downloaded Video - Accident IV	[A] VIC ALPEH
16	18 Sep 2019 17:30	Video Downloaded	Downloaded Video - Accident IV	[A] CHEW HSIAO TONG
17	19 Sep 2019 09:28	Video Downloaded	Downloaded Video - Accident IV	[A] ADRIAN LING
18	19 Sep 2019 09:41	Video Downloaded	Downloaded Video - Accident IV	[A] DENISE TAY KWEE CHENG
19	19 Sep 2019 12:57	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 0% Remark: Seek approval to reject third party claim as third party overtook IV from the left while IV was making a left turn.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2269980	05 Sep 2019 09:11:49	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	PA7328P	SHC8694J	11.77
2278955	13 Sep 2019 10:22:10	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	PA7328P	Pool Chin Han Daniel	xx.xx

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	04 Sep 2019 16:34	Clim Dtl Modified	Claimant's Name: -> AN FOO TRANSPORT SERVICE. Claimant's ID: -> 53331459C.	[A] HOW MEI KWAN
2	04 Sep 2019 16:34	Clim Veh Model Changed	(202408) TOYOTA HIACE 3.0 D Commuter (M).	[A] HOW MEI KWAN
3	04 Sep 2019 16:34	Clim Created	Reg No: PA7328P. Acct Date: 2019/08/26. Claim Type: TP. Insurer: Liberty Insurance Pte Ltd (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: New Hock Teck Motor Pte Ltd (HQ)	[A] HOW MEI KWAN
4	04 Sep 2019 16:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	04 Sep 2019 16:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/13	[A] HOW MEI KWAN
6	04 Sep 2019 16:34	Assignment 1st Accessed		[A] HOW MEI KWAN
7	04 Sep 2019 16:34	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
8	04 Sep 2019 16:37	Clim Ins Co Group Changed	[200034] Liberty Insurance Pte Ltd (HQ) -> [200033] India International Insurance Pte Ltd (HQ) Additional Remarks:	[I] Merimen Administrator
9	04 Sep 2019 16:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/13	[I] Merimen Administrator
10	04 Sep 2019 16:37	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Merimen Administrator
11	10 Sep 2019 20:50	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD. Insured ID: -> 19930382 1R.	[A] HOW MEI KWAN
12	11 Sep 2019 14:16	Adj Mandate Request	Cur.Req:0.00:PODS Liability : unclear Remarks: please request CCTV from OJD	[A] VIVIAN LAU PEI FENG
13	13 Sep 2019 10:23	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/09/13. Mandate Remarks: Insured video has been uploaded.	[I] Pooi Chin Han Daniel
14	13 Sep 2019 10:23	Adj Mandate Set	Approved:0.00:Insured video has been uploaded.	[I] Pooi Chin Han Daniel
15	18 Sep 2019 16:22	Video Downloaded	Downloaded Video - Accident IV	[A] VIC ALPEH
16	18 Sep 2019 17:30	Video Downloaded	Downloaded Video - Accident IV	[A] CHEW HSIAO TONG
17	19 Sep 2019 09:28	Video Downloaded	Downloaded Video - Accident IV	[A] ADRIAN LING
18	19 Sep 2019 09:41	Video Downloaded	Downloaded Video - Accident IV	[A] DENISE TAY KWEE CHENG
19	19 Sep 2019 12:57	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 0% Remark: Seek approval to reject third party claim as third party overtook IV from the left while IV was making a left turn.	[A] CHEW HSIAO TONG
20	19 Sep 2019 17:27	Video Downloaded	Downloaded Video - Accident IV	[I] Pooi Chin Han Daniel
21	20 Sep 2019 14:38	Video Downloaded	Downloaded Video - Accident IV	[I] Sundari Nagarajan
22	20 Sep 2019 14:39	Adj Mandate Set	Approved:0.00.	[I] Sundari Nagarajan

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2269980	05 Sep 2019 09:11:49	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	PA7328P	SHC8694J	11.77
2278955	13 Sep 2019 10:22:10	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	PA7328P	Pooi Chin Han Daniel	xx.xx

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Friday, 20 September 2019 3:28 PM
To: Admin nht
Cc: Chloe; Admin A; Vic (LKKAUTO)
Subject: RE: PA7328P CLAIMING AGAINST SHC8694J (INDIA) ON 26.08.19 //LKK REF: CC6/III19015670/Apa3
Attachments: Statement of SHC8694J.pdf; SHC8694J_OI VIDEO.MP4

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Our insured had submitted a copy of his car video footage and based on his video footage, it shows that your client overtook our insured taxi from the left while our insured driver was making a left turn. We are of the view that our driver is not liable for the accident. Attached is a copy of our insured accident report & video for your easy reference.

In view of the above, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: Admin nht <admin@nhtmotor.com>
Sent: Friday, 20 September 2019 3:06 PM
To: Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Cc: Chloe <chloe@nhtmotor.com>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Re: PA7328P CLAIMING AGAINST SHC8694J (INDIA) ON 26.08.19

Without Prejudice - **gentle reminder**

Hi Vic

As spoken, please kindly send us your insured scene video, thanks.

Best Regards,
Sukyi Chong
New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel : 6747 9241 Fax : 6741 7276




On Thu, Sep 19, 2019 at 9:05 AM Admin nht <admin@nhtmotor.com> wrote:

Without Prejudice - **gentle reminder**

Hi Vic

As spoken, please kindly send us your insured scene video,thanks.

Best Regards,
Sukyi Chong
New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel : 6747 9241 Fax : 6741 7276



On Wed, Sep 18, 2019 at 4:24 PM Admin nht <admin@nhtmotor.com> wrote:


Without Prejudice

Hi Vic

As spoken, please kindly send us your insured scene video,thanks.

Best Regards,
Sukyi Chong

New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel : 6747 9241 Fax : 6741 7276



On Wed, Sep 18, 2019 at 11:42 AM Admin nht <admin@nhtmotor.com> wrote:

Without Prejudice - **gentle reminder**

Hi all,


Refer above mentioned, vehicle surveyed by Surveyor Adrian on 04.09.19.

Kindly provide us the video footage of the accident as your client mentioned that her car had an in-car camera.

Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel : 6747 9241 Fax : 6741 7276



On Fri, Sep 6, 2019 at 10:44 AM Admin nht <admin@nhtmotor.com> wrote:



Without Prejudice

Hi all,

Refer above mentioned, vehicle surveyed by Surveyor Adrian on 04.09.19.

Kindly provide us the video footage of the accident as your client mentioned that her car had an in-car camera.

Best Regards,
Sukyi Chong
New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel : 6747 9241 Fax : 6741 7276

	
---	---

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Sep 2019 Edit Reg		04 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	AN FOO TRANSPORT SERVICE, Co. Reg. No.: 53331459C		
Vehicle Reg. No.:	PA7328P	Date of Loss:	26/08/2019 10:00 - :59 [141 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19080651	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHC8694J	Policy No. (Claimant):	5105393829
		Excess:	
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/09/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (20/09/2019): Alert - Adj Mandate Approved (S\$0.00) - PA7328P - Claim Handler: Pooi Chin Han D...
- III_SG (13/09/2019): Alert - Adj Mandate Approved (S\$0.00) - PA7328P - Claim Handler: Pooi Chin Han D...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***PA7328P (MCT19080651)**
[SHC8694J]
TP
AN FOO TRANSPORT SERVICE
Aug 26 2019 10:00AM
[COMFORT TRANSPORTATION PTE LTD]
New Hock Teck Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/09/19 10:22	Video - Accident IV	Load MP4	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
2	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
3	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
10	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
11	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
13	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/09/19 12:56	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/19 09:08	TP GIA REPORT	Load PDF	
2	20/09/19 15:28	Email to TP_reject dd 200919	Load PDF	

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/09/19 09:11	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST
[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19015670/APA3S2
Date: 01/10/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No: PA7328P Insured Vehicle No: SHC8694J
Date of Loss: 26/08/2019 Nature of Claim: TP Claim No: MCT19080651

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA7328P
Make & Model: TOYOTA HIACE, 3.0 D Commuter (M) Engine No: 1KD1669905
Reg. Date: 09/11/2007 (Man. Year: 2007) Chassis No: JTFJT02P900001113
Colour: White Odometer: 834142 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: GREEN-MAX 6 mm Rear Left Side: GREEN-MAX 6 mm
Front Right Side: GREEN-MAX 6 mm Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/09/2019
Date Inspected: 04/09/2019 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
Singapore 417883
Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/1/2019

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Oct 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D Commuter (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA7328P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >