From (Perno	at Org Hi Hi	ol	MENT (Office)	Date/Time	49/198 2.0
estimated Co			Bill to:		
To Inspect V	STTP RES / OD RE	SMC:	CIID.	naured: Gi	3D9454U
at Workshop		yee Aut		Tel: 645	7 5768 10457
of	160 31	n Miney O	rive # 02+7		, , , , , , ,
Policy No:			Claim No:	19/19/19	1/105/0023
Sum Insured			Excess		
viaks of Vel Clinut's Recor				D.O.A	
CA / REV	/ REP. / REV 24 H	RR			112017
	2.31pm2)419/16		ed: Mr-Chan	Vehicle(IN	OUT
Date/Time	Action/Instruction	Talianda -			
	SMC2611D- 9BD 145	CSOBEIGI	069731/16/d3	6.2	DOA : 30/5/2

Surveyor Oil. REF: UPC	CANTENE
ASSI	GNMENT
rom: Date:	Veh No. SMC2610 Yr Regn. 05 Sep
Estimated Cost:	Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD / TP /WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o inspect Vehicle No:	Make: Merce Ezos co 1991
Windshoom of San Andre	Colour Grey A/C: Insured / Std / NI / N
it Workshop m/s Yee Auto	Sp.Reading 65854 T/Radio: Insured / Std / NI / N
	Eng/No:
nsured:	CNO: WDD 2120 342A 789009
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No.	Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Ingreder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / SIRim / STD A/Rim or
Make of Veh:	WE 1. 14 0 13
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF Cartinental
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6
Est. Repairs:	D.O.A. D.O.I. 05-07-
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at WS 2
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to colli
Date / Time Action / Instruction	•
lump Sum \$6500+ (Red 16	A4760 72%)
many survivation of the survivation	
5-	
Oute/Time, File Pass to? : Preli. Report	Days Of Repair: 5
22/11 Tupist Final Report	Resurvey No. of Trip: Survey Fee: 249
Date/Time, File Return to?	Transportation
2) Add Fe	ee: Site Insp (\$)S+RSSI
No.	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 6500)	: Weekend (\$
Lump sum / Lo.L. (3 Cont.)	T ARGENGIA TA

Nivitha (LKK Auto)

From:

ONG LI LI < llong@lonpac.com>

Sent:

Wednesday, 4 September 2019 2:08 PM

To:

kkrishna; assignments@lkkauto.com; Admin-D (LKKAuto)

Cc:

MT_Claim_SG

Subject:

RE: Pre-Repair Inspection of Vehicle SMC 2611D - Accident on 2.9.2019 involving SMC 2611D & GBD 9454U along Bartley Road East turning into Bedok North Road

Our Ref: 19/19/19/VC05/022324 [External General]

Attachments:

SM.PRI-YEE-SMC2611D.PDF

Lonpac External - General

Without Prejudice Save as to Costs

Dear Daphne

Thank you for your confirmation on the appointment of a Single Joint Expert.

Dear Nivitha

Please arrange Kenneth Kong to conduct TP survey.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: kkrishna [mailto:kkrishna@singnet.com.sg]
Sent: Wednesday, 4 September, 2019 1:59 PM

To: ONG LI LI

Subject: Re: Pre-Repair Inspection of Vehicle SMC 2611D - Accident on 2.9.2019 involving SMC 2611D & GBD 9454U

along Bartley Road East turning into Bedok North Road Our Ref: 19/19/19/VC05/022324 [External General]

Our Ref: SM.PRI-YEE-SMC2611D(dap)

Dear Madam,

We refer to your email dated 4 September 2019.

Our client wishes to appoint Kenneth Kong for PRI.

Kindly contact our client's workshop for PRI as soon as possible.

Regards

On 04-Sep-19 11:34 AM, ONG LI LI wrote:

Lonpac External - General

Without Prejudice Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

1	Robin Poon	
2	Nicholas Tey	
3	Jackson Quek	
4	Mohammed Rasul	
5	Adrian Ling	
6	Paul Thanapal	
7	Choo Beng Hai	
8	Saharan Bin Sharif	
9	Aw Po Huat (Andrew)	
10	Kenneth Kong	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards, Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: kkrishna [mailto:kkrishna@singnet.com.sg] Sent: Wednesday, 4 September, 2019 10:44 AM

To: MT_Claim_SG

Cc: yeeautopteltd@gmail.com

Subject: Pre-Repair Inspection of Vehicle SMC 2611D - Accident on 2.9.2019 involving SMC 2611D & GBD 9454U along Bartley Road East turning into Bedok

North Road

Our Ref: SM.PRI-YEE-SMC2611D(dap)

Dear Sirs

We attached herewith our letter dated 4 September 2019 for your attention.

Please arrange for PRI as soon as possible.

Regards

Daphne on behalf of K. Krishna & Partners

Lonpac External - General data is for internal / external use.

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Friday, 6 September 2019 2:27 PM

To:

Admin-D (LKKAuto); 'ONG LI LI'; assignments

Cc:

'MT Claim SG'; SUR

Subject:

RE: Pre-Repair Inspection of Vehicle SMC 2611D - Accident on 2.9.2019 involving SMC 2611D & GBD 9454U along Bartley Road East turning into Bedok North Road

Our Ref: 19/19/VC05/022324 [External General]

Attachments:

PRELI ADVISED OF SMC 2611D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMC 2611D

Number of days (estimated): 4 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com> Sent: Wednesday, 4 September 2019 5:20 PM

To: 'ONG LI LI' < llong@lonpac.com>; assignments < assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>

Subject: RE: Pre-Repair Inspection of Vehicle SMC 2611D - Accident on 2.9.2019 involving SMC 2611D & GBD 9454U

along Bartley Road East turning into Bedok North Road Our Ref: 19/19/19/VC05/022324 [External General]

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 05/09/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Wednesday, 4 September 2019 2:08 PM

Denise Tay (LKKAuto)

From: Gent: Fo: Subject:	yeeauto pteltd <yeeautopteltd@gmail.com> Saturday, 23 November 2019 11:04 AM Guo Qiang (LKKAuto) Re: SMC2611D Airbag Photo</yeeautopteltd@gmail.com>	•
Hi Sir,		
We accept amount S\$6500/-	(before GST) & 05 working days.	
Thanks & Regards		
Ms Phang		
Yee Auto Pte Ltd 160 Sin Ming Drive #02-17 Sin Ming AutoCi Singapore 575722 ROC & GST No.: 201719251W email: yeeautopteltd@g		
On Thu, 14 Nov 2019 at 17:1	2, Guo Qiang (LKKAuto) < Guo Qiang@lkkauto.com	<u>n</u> > wrote:
Hi,		
Finalize COR \$6500 before	GST @ 5 working days.	
Regards,		
Guo Qiang		
From: yeeauto pteltd [mail Sent: Thursday, 31 Octobe To: Guo Qiang (LKKAuto) Subject: Re: SMC2611D Ai		
Good day Sir,		
As per attached for your re	ference and action.	



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: CS/LPC19015689/Gtd3

Date: 6/9/2019

Our Ref: CS/MSG19014800/R1td3

The Motor Claims Department LONPAC INSURANCE BHD Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SMC 2611D .

Please be informed that we had conducted the inspection of the above mentioned vehicle on _____5/9/2019___ at the premises of M/s _Yee Auto_ and have the following to report:-

Workshop Estimate Amount	: S\$	20,011.70
Revised Estimate Amount	: S\$	6,645.90
"Check" Items Amount	: S\$	4,269.90
Market Value	: S\$	-
LTA Reimbursement Value	: SS	
Nett Value	: <u>S\$</u>	-

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully Guo Qiang Automotive Assessor

K. KRISHNA & PARTNERS

Advocates & Solicitors Commissioner for Oaths/Notary Public (UEN No. 53131210X) GST Registration No. M90371530C

101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533 Fax: 6323 2120 (not for service of Court documents) Tel: 6323 3038

E-mail: kkrishna@singnet.com.sg

K. Krishnamoorthi LLB (Hons) (London) Barrister-at-Law (Gray's Inn) B.Sc (Hons) (Est. Man) (S'pore)

S. Manohar LLB (Hons) (S'pore)

. A.

Vengadesh s/o Kumaravelu LLB (Hons)

Our Ref :

SM.PRI-YEE- SMC2611D (dap)

4th September 2019

LONPAC INSURANCE BHD

IMMEDIATE ATTENTION PRE-REPAIR INSPECTION

Email: mt_claim@lonpac.com

Attention: Motor Claims Department

Dear Sirs

PRE-REPAIR INSPECTION OF VEHICLE SMC 2611D ACCIDENT ON 02.09.2019 INVOLVING SMC 2611D & GBD 9454U ALONG BARTLEY ROAD EAST TURNING INTO BEDOK NORTH ROAD

We act for Mr. Boey Siong Fatt, the owner of motor vehicle no. SMC 2611D which was involved in the above captioned accident.

We are instructed that the accident was caused by the negligence of the driver of motor vehicle no. GBD 9454U. Our search shows that you are the insurers of motor vehicle no. GBD 9454U.

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address :-

M/S YEE AUTO PTE LTD 160 Sin Ming Drive #02-17 Sin Ming AutoCity

Singapore 575722

Tel: 64575768 Fax: 6252 8459

K. KRISHNA & PARTNERS

Advocates & Solicitors

4th September 2019 LONPAC INSURANCE BHD

Please request your assessor to contact Mr Chan Kal Yee of M/s Yee Auto Services at his mobile no. 96874031 within forty-eight (48) hours from receipt of this letter to arrange for the inspection.

Yours faithfully

cc. workshop - (by email)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

2011

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- E. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

A. 新自己 "明·春日表》可以及10年10年10日	ACCIDENT STATEMENT
Date Of Report	03/09/2019 11:20
Date Of Accident	02/09/2019 16:20
Exact Location Of Accident	ALONG BARTLEY RD EAST TURNING INTO BEDOK NORTH RD
Country/State of Loss	SINGAPORE
A CHARLES WAR TO BE THE DESIGNATION OF THE PARTY OF THE P	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SMC2611D
Insured/Policyholder	
Name Of Registered Owner	BOEY SIONG FATT
NRIC No	S0040620A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92287655
Alternative Phone No	OTHERS-92287655
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Palicy Number	Z/18/VP05/019684-001
Cover Note Number	
Driver	
Name of Driver	BOEY LIH HAN (MEI LIHAN)
NRIC No	S7705583E
Date Of Birth	25/02/1977
Occupation	INDOOR
Date Of Driving Pass	27/11/2002
Driving Experience	16 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92287655
Fax Number	
Contact Number	

ADRIANBOEYLH@GMAIL.COM

BLK 240 SERANGOON AVENUE 2 Address

#08-73

Postcode 550240

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) 2

involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

NO

NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

NO

If Yes Please state which Police Station

Police Station Name

SERANGOON NEIGHBOURHOOD POLICE CENTRE

ROAD: 50 SERANGOON AVE 2 #01-02 , POSTCODE: 556129 , COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 1800-4880999 - FAX NO: 64883561

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20190903/2011.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD9454U

NO

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Line Coll gasserides furnishing misself	
	DETAILS OF INJURED PERSON 1
Name	BOEY LIH HAN
Approximate Age	42
Injuries Sustain	
Injured person in which vehicle?	SMC2611D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 240 SERANGOON AVEMUE 2 #08-73
Postcode	550240

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgment of this report to the insurers, you becely consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this [form] and any other personal information. provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes"
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: - 3 SEP 2019

Driver 1 Signature

Oate & Time: 3 SEP 7019 Reporting Centre Personnel's Signature

NRIC/FIN No.:

KETCH PLAN	A) SMC2611	D (15) 6	GBD9454 U Bedok North Road
		A B	Bartley Road East
DESCRIBE CIRCUM	ASTANCES OF THE ACCIDENT		
Refer to	Police Report		
/			
DECLARATION I/We declare the fo	rregaing particulars are true in ev	Prespect.	80
Policyholder's Signi Date & Time: 3 SE	Driver's Sign (If driver is a Date & Time	nature not the policyholder) =-3 SEP 2019	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

parts, s---

POLICE REPORT Pg. 1





Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE 556129

1 of 3 Report No. T/20190903/2011

Tel No: 1800-4880999

REPORT OF A TRAFFIC ACCIDENT

Date/Tir 03/09/2	me Report I 019 03:05	Made:	Vide Report No.	Station Diary No.:
Informa	int's Partic	ulars	是是数据的第三人称单数	The state of the s
	f Informant IH HAN		Address APT BLK 240 SERANGO 550240	ON AVENUE 2 #08-73 SINGAPORE
	/ ID No.: 0 / S77055	83E	Contact No.: Home/Office:	Mobile: 92287655
National SINGAP	ity: ORE CITIZ	EN	Email	WOONE, 32207033
Sex: Male	Age: 42	Date of Birth: 25/02/1977	Type of Informant: Driver	
Race: Chinese	1		Language:	Institution / School Name:
Occupat SELF EN	ion: MPLOYED		Driving Licence Information Class: 3A	Date of Expiry:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/09/2019 16:2	Type of Location
BARTLEY RO	OAD EAST			
Weather: Clear	COOK WOITH ROAD	Road Surface Dry		Road Speed Limit
Traffic Flow: One Way		Traffic Control Traffic Light - Wor	king	Traffic Volume:
Olio Tital	on:			

venicle Not	Hyper	Make	Model	Color	Condition	No of Passange
GBD9454U	Van				Slightly Damaged	1
SMC2611D	Car	MERCEDES BENZ	SEDAN (R17)	Grey	Slightly Damaged	0

The state of the s
surance No Effective Expiry Date

POLICE REPORT Pg. 2





Report No. T/20190903/2011

Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE

Tel No: 1800-4880999

CONTINUATION OF REPORT

Die ralle : DIN	hicle insurance	TOTAL STREET,	A CHANGE SALES	PARTY NAMED IN COLUMN
Vehicle Now	Insurance Company	Insurance No.	Effective	Expiry Date
SMC2611D	LONPAC INSURANCE BHD.	Z/18/VP05/019684- 001	03/08/2019	04/09/2019

No. of Pedestrian	Use of Per	Use of Pedestrian Crossing: NA				
Driver,	described to the	ART CONTRACTOR	E SECTION S	1	0.00	Mark Commencer
Name	BOEY LIH HAN			ID No		S7705583E
Related Vehicle	SMC2611D (Car)			Conta	ct No.	92287655
Hospital/Clinic	MOUNT ALVERNIA	HOSPITAL	2	Class Drivin Licens Expiry	g	Class: 3A Date of Expiry: NIL
Date Treatment	03/09/2019		Date Disc	harge	03/09	/2019
No. of Days gran	ted Medical Leave	05	Degree of	Injury	Sligh	

On 02/09/2019 at about 1620hrs, while I was travelling in my car SMC2611D on Bartley Road East turning into Bedok North Road and wanted to do a U-turn, I stopped at the red traffic light. After about 2 minutes, I felt a huge impact from the back. I then got down from vehicle and talk to the driver of the van GBD9454U who informed that he could not apply his brakes when approaching my car. We exchanged particulars and took some photos. After the accident, my car could not start and I have to engage tow truck to assist me. I then felt pain at my neck, back, arm and fingers due to the accident and decided to see a doctor at Mount Alvernia Hospital and was given 5 days MC. My in car camera managed to capture the whole accident. That is all

POLICE REPORT Pg. 3





Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE 556129

3 of 3 Report No. T/20190903/2011

Tel No: 1800-4880999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgl 2 FDWIN CHAU YEW FEI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/09/2019 03:05
Officer In Charge Of Case:	Classification Of Case
SI MOHAMAD ZULFAZDLI, BIN ABDULLAH Contact No.: 65476204	791 454
Authentication Stamp	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	620A	
Vehicle No.:	SMC2611D	
Vehicle to be Exported;	No	
Intended Deregistration Date:	05 Sep 2019	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	E200 SEDAN (R17)	
Primary Colour:	Grey	
Manufacturing Year:	2013	
Engine No.:	27492030055625	
Chassis No.:	WDD2120342A789009	
Maximum Power Output:	135.0 kW (181 bhp)	
Open Market Value:	\$42.967.00	
Original Registration Date:	05 Sep 2013	
First Registration Date:	05 Sep 2013	
Transfer Count:	1	
Actual ARF Paid:	\$47,154.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	04 Sep 2023	
PARF Rebate Amount:	\$30,650.00	
COE Expiry Date:	04 Sep 2023	_
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$77.600.00	
COE Rebate Amount:	\$31,021.00	
Total Rebate Amount	\$61,671.00	

OK



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com Registration No. 201719251W GST No. 201719251W

M/S: LONPAC INSURANCE BHD

300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No:

ES1900074

Date:

04 Sep 2019

Policy No:

TEL: 62507388

FAX: 62933767

Veh Reg No:

SMC2611D

ATTN: Motor Claim Department

Make/Model:

MERCEDES BEN E200

SEDAN (R17)

Your Ref No: Claim Type:

Third Party

Chassis No: Engine No: WDD2120342A789009 27492030055625

Accident Date:

02/09/2019

Reg. Date:

05/09/2013

TP Veh Reg No:

GBD9454U

Estimate Repair Cost to Vehicle No :SMC2611D

	Description	U/Price	Quantity	List Price	Amount
	N. C. W. S.			<u>SS</u>	SS
	Net Price	CALACTEC	100000000000000000000000000000000000000	Catholic decision	
. !	REAR NUMBER PLATE X	80.00	1 PC	80,00	
2	REAR NUMBER PLATE LAMP	65,00	2 PC	130.00	
3	REVERSE SENSOR CENTRE - LH X NW	465.00	1 PC	465.00	200/54.
4		465.00	1 PC	/ 465.00	200 (SN)
5	REVERSE SIDE SENSOR - LH 💢	465.00	1 PC	465.00	
6	REVERSE SIDE SENSOR - RH X REAR REVERSE SENSOR WIRE X	465.00	1 PC	465.00	
7	RESIDENCE SELECTION WINE	395.00	ESET	395.00	
8	REAR BOOT LID CAMERA X	400.00	1 PC	400.00	
				2,865.00	2,865.00
	Spare Parts				Part Company
9	REAR BOOT LID / 07 .	2,630.00	1 PC	2.638.00	2150
10	REAR BOOT LID CHROME MOULDING X	380,00	1 PC	380.00	
11	REAR BOOT LID HANDLE LOCK X /	180.00	1 PC	180.00	
12	REAR BOOT LID HINGE COVER CLIPS X	100.00	1 SET	100,00	
13	REAR LID HINGE COVER-LH X	180.00	1 PC	180,00	
14	REAR LID HINGE COVER - RH X	180,00	1 PC	180,00	
15	REAR BOOT LID HINGE - LH	420.00	1 PC	420.00	
16	REAR BOOT LID HINGE - RH X	420.00	1 PC	420.00	
17	REAR BOOT LID EMBLEM - 7G-TRONIC / SHC	120.00	1 PC	/ 120.00	
18	REAR BOOT LID MERCEDES STAR	120.00	LPC	/ 120.00	
19	REAR BOOT LID LAMP - LH X NN	781.90	1 PC	781.90	contract and
20	REAR BOOT LID LAMP - RH REAR BOOT LID LAMP - RH REAR EMBLEM 'E200'	781.90	1 PC	/ 781/50	450.8
21	REAR EMBLEM 'E200'	120.00	1 PC	× 120:00	32
22	REAR BOOT LID WEATHERSTRIP V TW	265.00	1 PC	265.00	1335 (-51%
23	REAR BUMPER / LE	2,080.00	1 PC	2,080,00	1630
24	REAR BUMPER CLIPS (NEC	80.00	1 SET	/ 80,00	30
25	REAR END PANEL & MYON	610.10	1 PC	610.10	
26	REAR END PANEL GARNISH 7 NIV	240.00	1 PC	240.00	
27	REAR TAILLAMP - LH X NN	913,90	1 PC	913.90	100
28	REAR TAILLAMP - RH V COA	913.90	1 PC	91890	698
29	REAR HE SUPER INSTRUCTORS	350.00	1 PC	350.00	
30	REAR BUMPER INNER IMPACT BRACKET X /	Λ/ 62.00	LPC	62.00	
31	REAR BUMPER OUTER IMPACT BRACKET K	62.00	1 PC	62.00	
32	REAR BUMPER BOTTOM BRACKET - LH X	85.00	1 PC	85.00	
33	REAR BUMPER BOTTOM BRACKET-RH 3 / (N	85.00	1 PC	/ 85:00	48
34	REAR BUMPER TOWING COVER	80.00	1 PC	8000	67



E AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No. 201719251W

M/S: LONPAC INSURANCE BHD

300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No:

ES1900074

Date:

04 Sep 2019

Policy No:

TEL:

62507388

FAX: 62933767

Veh Reg No:

SMC2611D

ATTN: Motor Claim Department

Make/Model:

MERCEDES BEN E200 SEDAN (R17)

Chassis No:

WDD2120342A789009

Third Party

Engine No:

27492030055625

Claim Type: Accident Date:

Your Ref No:

02/09/2019

Reg. Date:

05/09/2013

TP Veh Reg No:

GBD9454U

Estimate Repair Cost to Vehicle No :SMC2611D

	Description	U/Price	Quantity	List Price	Amount
35	REAR BUMPER LOWER PAD / CAT	385.90	† PC	385,90	280.9 SS
36	BOOT LID LOCK (KEY) X NN 675.2	340.10	LPC	340.10	1.5
	70.0	1-1-60		12,966.70	12,966,70
	Labour 1 0% : 55	51.00			500
37	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,600,00	1 JOB	1,600.00	(Doe
38	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE	1,600.00	LJOB	1,600.00	600
39	TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL	200,00	LJOB	200.00	×NN
40	COMPUTER DIAGNOSTIC	480,00	1 PC	480.00	X NN
41	TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	30 -
42	TO TOW VEHICLE TO WORSHOP.	150.00	LJOB	150.00	× X
				4,180.00	4,180.00
				Total	\$\$ 20,011.70
			Add GS	T @ 7%	1,400.82
			Total Amount	Payable	S\$ 21,412.52

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND FOUR HUNDRED TWELVE AND CENTS FIFTY TWO ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LRIX Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(a) duning resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" bank
- . No Blegat modification(s) is allowed
- Supplementary item(x) must be resurveyed and is subject to final approval from Insurance Company

Admostedged by Repairer

Standary:

Date:

17447 60

Whom report photos.

Guo Q: ag -82880282 05/9/19.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Registration No. 201719251W GST No. 201719251W Tel 6457 5768 Fax: 6252 8459 Mobile 9687 4031 Email yeeautopteltd@gmail.com

M/S: LONPAC INSURANCE BHD

Estimate No: 300, BEACH ROAD #17-04/07, THE CONCOURSE

06 Sep 2019 ES1900074

Veh Reg No: Policy No:

FAX: 62933767

ATTN: Motor Claim Department

62507388

MERCEDES BEN E200 SMC2611D Make/Model:

WDD2120342A789009 SEDAN (R17) Chassis No:

27492030055625 Engine No:

05/09/2013 Reg. Date:

GBD9454U 02/09/2019 Third Party

TP Veh Reg No:

Accident Date:

Your Ref No: Claim Type: Description

Spare Parts

Estimate Repair Cost to Vehicle No :SMC2611D

Amount

List Price

U/Price Quantity

Supplementary Parts to Repair

1 9 MC. REAR BUMPER SIDE MOULDING - LH REAR BUMPER SIDE MOULDING - RH

REAR BUMPER REINFORCEMENT

1 PC 1 PC 185.50 185.50 764.50

88

764.50 1.135.50

SS 1.135.50 SS 79.49

1,135.50

GST Amount

(one long. 10%, 1959 49 Total Amount Payable

85 1214.99

For Yee Auto Pte Ltd

AUTHORISMD/SIGNATURE

27447.60



E AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031 Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No.: 201719251W

M/S:

LONPAC INSURANCE BHD

300, BEACH ROAD #17-04/07, THE CONCOURSE

Estimate No:

ES1900074

Date:

31 Oct 2019

Policy No:

SMC2611D

FAX: 62933767 62507388 TEL: ATTN: Motor Claim Department

Veh Reg No: Make/Model:

MERCEDES BEN E200

SEDAN (R17)

Your Ref No:

Third Party

Chassis No:

WDD2120342A789009

Claim Type: Accident Date:

02/09/2019

Engine No: Reg. Date:

27492030055625 05/09/2013

TP Veh Reg No:

GBD9454U

Estimate Repair Cost to Vehicle No :SMC2611D

	Description	*3	U/Price	Quantity	List Price	Amount
	Description				SS	55
		Supplement	ary Parts to Repo	ür		
	Spare Parts AIRBAGREST- LH	(Geal)	R 1,150.20	1 PC	1,150.20	150 SIN
2	AIRBAGREST - RH	2 seminar	1,150.20	1 PC	1,150.20	150 SIN
-	AIRDAOREST - REF	200 (SN)	S	1000000	2,300.40	2,300.40
		100 (314)		GST A	Total	S\$ 2,300.40 S\$ 161.03
		, Act		Total Amount Po	iyable	S\$ 2,461.43

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Sell I din L	Affiliated to Federation Internation	onale Des Experts En Automob	pile
ON.	PAC INSURANCE	BHD	Ref : CS/LPC19015689	9/Gtd3e2
	BEACH ROAD 04/07 THE CONC	DURSESINGAPORE 199555	Date: 09-12-2019 Code: LPC2	
		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	GBD 9454U	Veh. Inspected	SMC 2611D
	Policy No.		Coverage (\$)	0.00
	Claim No.	19/19/19/VC05/022324	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	04/09/2019
!.		Vehicle Parti	culars & Condition	
	Make & Model	MERCEDES BENZ E200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD2120342A789009	Colour	GREY
	Odometer	105854	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condit	ions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
	L/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm
i.		Descripti	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR PORTION.	
	DAMAGES SEE D	ETAILS.		
5,		Genera	I Information	Table 1
	Accident Date	02/09/2019	Inspection Date	05/09/2019
	Survey held at	160 SIN MING DRIVE# 02-17		
	Repairer	YEE AUTO SERVICE		
ā.		R	emarks	
		N WAS CONDUCTED ON A"WIT		
5b.	IB)IN ACCORDANG	E TO YOUR INSTRUCTIONS, V	Days of Repair	U REPAIRS.
u.	ECTIMATED NOD	MAL PERIOD FOR REPAIR:	5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 2611D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	DENTED	2,630.00	2,150.00
1	REAR BOOT LID CHROME MOULDING	NOT NECESSARY	380.00	
1	REAR BOOT LID HANDLE LOCK	NOT NECESSARY	180.00	
- 1	SET REAR BOOT LID HINGE COVER CLIPS	NOT NECESSARY	100.00	
1	REAR LID HINGE COVER - LH	NOT NECESSARY	180.00	
1	REAR LID HINGE COVER - RH	NOT NECESSARY	180.00	
1	REAR BOOT LID HINGE - LH	NOT NECESSARY	420.00	
- 1	REAR BOOT LID HINGE - RH	NOT NECESSARY	420.00	
1	REAR BOOT LID EMBLEM - 7G - TRONIC	NECESSARY	120.00	120.00
1	REAR BOOT LID MERCEDES STAR	NECESSARY	120.00	120.00
1	REAR BOOT LID LAMP - LH	NOT NECESSARY	781.90	
1	RERA BOOT LID LAMP - RH	CRACKED	781.90	450.80
1	REAR EMBLEM 'E200'	NECESSARY	120.00	98.00
1	REAR BOOT LID WEATHERSTRIP (50%)	TWISTED	265.00	132.50
1	REAR BUMPER	DEFORMED	2,080.00	1,630.00
1	SET REAR BUMPER CLIPS	NECESSARY	80.00	30.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	610.10	
1	REAR END PANEL GARNISH	NOT NECESSARY	240.00	
1	REAR TAILLAMP - LH	NOT NECESSARY	913.90	
1	REAR TAILLAMP - RH	CRACKED	913.90	698.00
1	REAR BUMPER INNER GARNISH	CRACKED	350.00	350.00
1	REAR BUMPER INNER IMPACT BRACKET	NOT NECESSARY	62.00	
1	REAR BUMPER OUTER IMPACT BRACKET	NOT NECESSARY	62.00	
1	REAR BUMPER BOTTOM BRACKET - LH	NOT NECESSARY	85.00	
1	REAR BUMPER BOTTOM BRACKET - RH	CRACKED	85.00	48.00
1	REAR BUMPER TOWING COVER	MISSING	80.00	67.00
1	REAR BUMPER LOWER PAD	CUT	385.90	280.90
1	BOOT LID LOCK (KEY)	NOT NECESSARY	340.10	
	REAR BUMPER SIDE MOULDING - LH (ADDITIONAL)	NECESSARY	185.50	150.80
1	REAR BUMPER SIDE MOULDING - RH (ADDITIONAL)	NECESSARY	185.50	150.80
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	BENT	764.50	764.50
	LESS 10% DISCOUNT		12	-724.13
			14,102.20	6,517.17

Report Ref No. CS/LPC19015689/Gtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
-1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	- 12
2	REAR NUMBER PLATE LAMP @\$65.00 (SN)	NOT NECESSARY	130.00	13
1	REVERSE SENSOR CENTRE - LH (SN)	NOT NECESSARY	465.00	
1	REVERSE SENSOR CENTRE - RH (SN)	NOT WORKING	465.00	200.00
1	REVERSE SIDE SENSOR - LH (SN)	NOT NECESSARY	465.00	
-1	REVERSE SIDE SENSOR - RH (SN)	NOT NECESSARY	465.00	
4	SET REAR REVERSE SENSOR WIRE (SN)	NOT NECESSARY	395.00	
- 1	REAR BOOT LID CAMERA (SN)	NOT NECESSARY	400.00	1
1	AIRBAGREST - LH (SN) (ADDITIONAL) (LOCAL REPAIR)	ACTIVATED	1,150.20	150.00
	AIRBAGREST - RH (SN) (ADDITIONAL) (LOCAL REPAIR)	ACTIVATED	1,150.20	150.00
	M 50% 500		5,165.40	500.00
	LABOUR		201000000000000000000000000000000000000	20,000
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY, INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,600.00	500.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,600.00	600.00
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	NOT NECESSARY	200.00	-
	COMPUTER DIAGNOSTIC.	NOT NECESSARY	480.00	-
	TO CHECK WIRING FUNCTIONS.		150.00	30.00
	TO TOW VEHICLE TO WORKSHOP.	NOT NECESSARY	150.00	
			4,180.00	1,130.00
	GRAND TOTAL		23,447.60	8,147.17
	RECOMMENDED COST OF LUMP SUM REPAIRS			6,500.00

Report Ref No. CS/LPC19015689/Gtd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

(TO ITS PRE-ACCIDENT CONDITION)

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own tisk.