

S. REC. BY:

REF: A19

## ASSIGNMENT

From: \_\_\_\_\_ Date: 6/9/19

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 8620C

at Workshop m/s Supreme Auto

of 176 Sn Ming Drive # 02-01

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: After 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKS 8620C Yr Regn: 1

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 730Li C.C.

Colour: M. P. White A/C: Insured / Std / NI / NA

Sp. Reading: 228566 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAKB22010C274288

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 245/50ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 1/119

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 6/9/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

M N/S down mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

GIA not ready

~~L/S = \$140.00  
 CHANGED ITEM = \$1,500.40  
 R = \$1,500.70 / 38.59%~~

L/S = \$750.00

R = \$1,193.70 / 38.59%

CHECK ITEM : \$826.50

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / L.B.E. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL