



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

20 September 2019

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SMH8610R & SHC8135G ON 02/09/2019 ALONG TANJONG KATONG ROAD AT ABOUT 1210 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SMH8610R
Vehicle Make : HONDA
Vehicle Model : SHUTTLE HYBRID 1.5 AUTO
Vehicle Chassis No. : GP72003393
Policy No. : 5087272209-03
Date of Accident : 02/09/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Side Mirror (LH) Complete <i>(cover & glass only) / BR</i>		\$ 527.50
2	1	Front Door Glass (LH) / <i>CUT</i>		\$ 450.00
				\$ 977.50
			Less 20%	\$ 195.50
				\$ 782.00
		To dismantle front LH door trim to change LH side mirror & change front LH door glass		\$ 250.00 <i>100/50</i>
		To perform wire checking		\$ 20.00 <i>/</i>
		To spray LH side mirror cover		\$ 100.00 <i>80</i>
				\$ 1,152.00
			7% GST	\$ 80.64
			Total	\$ 1,232.64

Steve (LKK) wml mml 30/9/19, 2:00 pm

1 dg

P/P

By #L sy



Authorised by Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey, before/after spray painting
- Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: QUOT201909-000039
Date: HHTPCLAIMS19-174