

2/20/2002

ASS. REC. BY:

REF: CS3/C7219011388

Ctd3-1

Special Instruction:

Survivor

EQ

ASSIGNMENT (Office)

From (Person):

Alfred Toh

of

CT1

Date/Time:

28/8/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 65603

Insured:

GBD 8482V

at Workshop m/s

AF motorworkz

Tel:

632 49431

of 66 kerk

Dutli Ave 6 me (W) B

Policy No:

DMCVSN30549618022

Claim No:

SIVM191202798C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16-6-19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

27.6.19 12:10 pm

Person Contacted:

Jia Yun

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKW 65603 - ✓

Issue a reinspection Report
(see email)


GBD 8482V - ✓

Dismantle: 26/6/2019

After repair: 28/6/2019

\$5800, 5 Days.
(Red: 1580; 21%)

16/9- Filepass to typast.


16/9/2019

PRS
Gul.

REF: CTi

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt.:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKW6560J Yr Regn: 11 Nov 2015

Type: M/Cas / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry 2.5 c.c 2494

Colour:

Grey

A/C Insured / Std / Nil / NA

Sp Reading:

82/51

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

MR053 AK 500 40/0074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F: 215/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6 mm

R/Bal:

6 mm

L/Bal:

6 mm

L/Bal:

6 mm

D.O.A.

D.O.I.

25-06-19

Survey held at

w/s

19pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

\$ 4000 - \$ 5000

21/6/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) \$ + RS. \$1

) Photos

) Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I. (\$

Add Fee:

☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Nitha (LKK Auto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Wednesday, 28 August 2019 6:53 PM
To: assignments; SUR
Cc: Irene Tay; Alfred Toh
Subject: RE: ACCIDENT INVOLVING GBD8482U & SKW6560JK ON 16 JUNE 2019 (SNM19D202798C02/2(thp))
Attachments: REPORT FROM PROMINENT APPRAISER SERVICES PTE LTD.pdf

LKK REF: CC3/CTI19011388/GCD3S2
CTPIS REF: SNM19D202798C02/2(thp)

ATTN: MR XING GUO AING/MS CELINE FONG

Dear Sirs

We refer to your pre-repair report (without estimates provided by the third party workshop).

Please assist to issue a **RE-INSPECTION report** (not paper survey) based on M/s Prominent Appraiser Services Pte Ltd report and let us have your findings and bill at your earliest convenience.

Aside to Irene, please assist to keep track on the matter.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, 28 August, 2019 5:07 PM
To: jackieng1973@gmail.com
Cc: Vitesse Insurance <sales@vitesseinsurance.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Sally Chua <sally.chua@sg.cntaiping.com>; Chai Chui Ai <chui.ai.chai@sg.cntaiping.com>
Subject: ACCIDENT INVOLVING GBD8482U & SKW6560JK ON 16 JUNE 2019 (SNM19D202798C02/2(thp))

Policy No: DMCVSN3054961802
From 17 June 2018 to 16 June 2019
Date of Accident: 16 June 2019 11.10 hours
Vehicle No: GBD8482U
Claim Ref: SNM19D202798C02/2(thp)

M/s SP Campers Pte Ltd
Attn: Mr Jackie Ng Chee Kang

Hi Mr Jackie Ng

We refer to the telephone conversation you had with our Irene Tay yesterday and our telephone conversation a while ago pertaining to the above matter.

Please file the SAS (accident) report at any of China TaiPing Insurance's Authorized Workshop (Reporting Centre) IMMEDIATELY to enable us to handle the incoming claim/s against your Motor Insurance Policy.

Aside to Irene, please assist to keep track on the matter.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID : (65) 6389 6183
FAX: (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

MSME16078A17 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 17/06/2019 16:16
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/06/2019 16:16
Date Of Accident 16/06/2019 11:10
Exact Location Of Accident BLK 404B FERNVALE LANE LOADING/ UNLOADING BAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKW6560J
Insured/Policyholder
Name Of Registered Owner TAY LENG WHATT
NRIC No S0488993B
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96654252
Alternative Phone No OFFICE-96654252

Vehicle Particulars

Manufacturer TOYOTA
Model CAMRY-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 2100436690-03
Cover Note Number

Driver

Name of Driver TAY LENG WHATT
NRIC No S0488993B
Date Of Birth 18/12/1951
Occupation INDOOR
Date Of Driving Pass 23/06/1970
Driving Experience 48 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96654252
Fax Number
Contact Number OFFICE-96654252
Email Address NOEMAIL

Address BLK 301 TAMPINES ST 32 #08-14^A
 Postcode 520301
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : TAY LEE YEN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TAMPINES NORTH NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7818999 - FAX NO: 67838603
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20190616/2058.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD8462U
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAY LEE YEN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKW6560J

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

i. Understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

17/6/19 11:55am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:


NRIC/ID No.:

Printed Name and No.

AF MOTOR

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer police report No: T/20190616/2058

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

17/6/19 11:55am

OUTSIDE THE POLICE STATION 1/3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190616/2058

1 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20190616/2058

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/06/2019 15:20		Vide Report No.:		Station Diary No.: 14	
Informant's Particulars					
Name of Informant: TAY LENG WHATT			Address: APT BLK 301 TAMPINES STREET 32 #08-14 SINGAPORE 520301		
ID Type / ID No.: NRIC NO / S0488993B			Contact No.: Home/Office: Mobile: 96654252		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 67	Date of Birth: 18/12/1951	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Self-employed			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident					
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 16/06/2019 11:10	Type of Location: Service Road	
Location: FERNVALE LANE Blk 404B Fernvale Lane loading/unloading bay					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD8482U	Van	SSANGYONG	ACTYON SPORTS D/CAB 2.0 5AT ABS D/AB 2WD	Brown		0
SKW6560J	Car	TOYOTA	CAMRY 2.5 AUTO	Grey		0

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190616/2058

2 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20190616/2058

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SKW6560J	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100436690-03	11/11/2018	10/11/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	JACKIE NG CHEE KANG	ID No.	NIL
Related Vehicle	GBD8482U (Van)	Contact No.	96530343
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAY LENG WHATT	ID No.	S0488993B
Related Vehicle	SKW6560J (Car)	Contact No.	96654252
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	TAY LEE YEN	ID No.	S8735300A
Related Vehicle	SKW6560J (Car)	Contact No.	96876203
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	16/06/2019	Date Discharge	16/06/2019
No. of Days granted Medical Leave	02	Degree of Injury	NIL

Sketch Plan #5 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20190616/2058

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

3 of 4

Report No. T/20190616/2058

CONTINUATION OF REPORT

Brief Details.

On 16/06/2019 at about 1110hrs, I wanted to drop-off my daughter namely Tay Lee Yen at Blk 404B Fernvale Lane. I parked my car (SKW6560J) at the loading/unloading bay as she wanted to unload somethings from the car boot. I alighted from my car to help unload the stuffs from the car boot.

Out of sudden, there was a vehicle (GBB8482U) reversing towards my car and hit on the front bumper of my car which resulted to damage. The strong impact also resulted my car to move backwards and hit on my daughter's right hand which caused internal injury. I was away when the accident occurred hence I was not injured.

I have in-car CCTV installed which captured the accident footage. I exchanged particulars with the driver.

I brought my daughter to the Sengkang General Hospital and she was given 2 days of outpatient sick leave from 16/06/2019 to 17/06/2019. The doctor informed she is required to go for the follow-up consultation.

Sketch Plan #6 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20190616/2058

4 of 4

Police Station Of Origin:

Tampines North NPP

461 Tampines Street 44 #01-56 SINGAPORE

520461

Tel No: 1800-7818999

Report No. T/20190616/2058

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 MUHAMMAD ISA BIN MD RASHID

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/06/2019 15:20

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP166



SIGNATURE



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0520619

Date of Report : 19/07/2019

To : Mr Tay Leng Whatt
C/o. 66 Kaki Bukit Ave 6
ARK @ KB
Singapore 417895

Date of Assignment : 25/06/2019
Report requested by : Mr Tay Leng Whatt
Date of Accident : 16/06/2019
Date of Inspection : 25/06/2019
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.	: SKW6560J	Engine Capacity (cc)	: 2494cc
Make & Model	: Toyota Camry	Mileage (km)	: 82151km
Date of Registration	: 11/11/2015	Chassis / Frame No.	: MR053AK5004010074
Colour	: Met. Grey	Engine No.	: 2ARU271124

TYRE CONDITION

Front LH	: 7 mm	Front RH	: 7 mm
Make	: Yokohama	Make	: Yokohama
Rear LH	: 7 mm	Rear RH	: 7 mm
Make	: Yokohama	Make	: Yokohama

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent Engine Modification	: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. AF Motorworkz Pte Ltd
66, Kaki Bukit Ave 6, ARK @ KB, Singapore 417895

ASSESSMENT

Repairer's Estimate	: \$ 10,335.88
Revised Amount	: \$ 9,230.13
Less Excess	: \$ -
Recommended Reserve	: \$ 7,380.00 (Lump Sum)

Estimated Normal Period of Repairs : 5 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SKW6560J

Report No. : PAS/TP/0520619

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. AF Motorworkz Pte Ltd, 66, Kaki Bukit Ave 6, ARK @ KB, Singapore 417895.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The bonnet, front bumper, front support panel, front chassis members, front fenders, headlamps, front grilles, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$9,230.13.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$7,380.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKW6560J

Report No. : PAS/TP/0520619

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Bonnet	Dented/Distorted	\$ 1,520.30	1261.4 \$ 1,520.30 /
2	1 pc	Bonnet moulding	Broken/Dislodged	\$ 283.70	168.8 \$ 283.70 /
3	2 pcs	Headlamp R/L	Cracked/Broken	\$ 5,865.20	4887.6 \$ 5,865.20 /
4	1 pc	Frt grille assy	Dented/Broken	\$ 496.80	439.52 \$ 496.80 /
5	1 pc	Frt grille emblem	Necessary	\$ 71.60	59.6 \$ 71.60 /
6	1 pc	Frt bumper	Dented	\$ 589.70	521.1 \$ 589.70 /
7	1 pc	Frt bumper lower grille assy	Dented/Cracked	\$ 725.60	115.1 \$ 725.60 /
8	6 pcs	Frt bumper clip	Necessary	\$ 19.20	\$ 19.20 /
9	2 pcs	Frt bumper retainer R/L	Cracked/Necessary	\$ 117.40	\$ 117.40 /
10	1 pc	Frt bumper absorber	Dented/Cracked	\$ 100.80	\$ 100.80 /
11	1 pc	Frt bumper reinforcement	Dented	\$ 393.90	\$ 393.90 SVC
12	1 pc	Frt support assy	Dented/Repair	\$ 631.70	\$ -
13	2 pcs	Frt radiator side deflector	LH Cracked	\$ 218.60	98.1 \$ 109.30 /
14	1 pc	Frt fender LH	Dented/Repair		(Refer labour no. 2 & 3)
15	1 pc	Frt support assy	Dented/Repair		(Refer labour no. 2 & 3)
16	2 pcs	Frt chassis member R/L	Dented/Repair		(Refer labour no. 2 & 3)
				\$ 11,034.50	\$ 10,293.50
Less Discount : 25%				\$ 2,758.63	25% \$ 2,573.38
List Parts Sub-Total :				\$ 8,275.88	\$ 7,720.13
Parts Total :				\$ 8,275.88	\$ 7,720.13

7794.62

25%: 5845.96



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKW6560J

Report No. : PAS/TP/0520619

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check electrical system and calibrate/focus headlamp.	\$ 60.00	\$ 50.00 30
2	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 660.00 600
3	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 800.00 ✓
Labour Total :		\$ 2,060.00	\$ 1,510.00
Total (Parts & Labour) :		\$ 10,335.88	\$ 9,230.13

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 7,380.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 5 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

60 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

7275.96
20%: 5800




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS3/CTI19011388/Gtd3s2-1	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 17-09-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	GBD 8482U	Veh. Inspected	SKW 6560J	
Policy No.	DMCVSN30549618022	Coverage (\$)	0.00	
Claim No.	SNM19D202798C02	Excess (\$)	0.00	
Assign From	ALFRED TOH	Assign Date	28/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.5	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053AK5004010074	Colour	GREY	
Odometer	82151	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	16/06/2019	Inspection Date	25/06/2019	
Survey held at	AF MOTORWORKZ PTE LTD 66 KAKI BUKIT AVENUE 6 SINGAPORE 417895			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 6560J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	REPLACED	1,520.30	1,267.40
1	BONNET MOULDING	REPLACED	283.70	168.80
2	HEADLAMP R/L @ \$2932.60	REPLACED	5,865.20	4,887.60
1	FRT GRILLE ASSY	REPLACED	496.80	439.52
1	FRT GRILLE EMBLEM	REPLACED	71.60	59.60
1	FRT BUMPER	REPLACED	589.70	521.10
1	FRT BUMPER LOWER GRILLE ASSY	REPLACED	725.60	115.10
6	FRT BUMPER CLIP @ \$3.20	REPLACED	19.20	19.20
2	FRT BUMPER RETAINER R/L @ \$58.70	REPLACED	117.40	117.40
1	FRT BUMPER ABSORBER	REPLACED	100.80	100.80
1	FRT BUMPER REINFORCEMENT	SERVICEABLE	393.90	-
1	FRT SUPPORT ASSY	REPAIRED SEE LABOUR	631.70	-
2	FRT RADIATOR SIDE DEFLECTOR @ \$109.30	N/S REPLACED	218.60	98.10
1	FRT FENDER LH (NPA)	REPAIRED SEE LABOUR	-	-
1	FRT SUPPORT ASSY (NPA)	REPAIRED SEE LABOUR	-	-
2	FRT CHASSIS MEMBER R/L (NPA)	REPAIRED SEE LABOUR	-	-
	LESS 25% DISCOUNT		-2,758.62	-1,948.66
			8,275.88	5,845.96
LABOUR				
	TO CHECK ELECTRICAL SYSTEM AND CALIBRATE / FOCUS HEADLAMP.		60.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN, ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT SUPPORT ASSY, FRT FENDER LH AND FRT CHASSIS MEMBER R/L.		1,000.00	600.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	800.00
			2,060.00	1,430.00
GRAND TOTAL			10,335.88	7,275.96



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,800.00
---	--	--	----------

Report Ref No. CS3/CT119011388/Gtd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.