

ASS. REC. BY:

REF:

CTI19015733/710302

Special Instruction:

Surveyor: Tauhid

ASSIGNMENT (Office)

From (Person): Tan Kah Leongof CTIDate/Time: 4.9.19 16.04p.m

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 62365

Insured:

SKA 447J

at Workshop m/s

NGE NGE & Motor

Tel:

67775382

of

Blk 1 No. 22 Pender Loop

Policy No:

DMPCSN18411318000

Claim No:

SNM19D20340202

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5.9.19 @ 10.33am

Person Contacted:

Jessie

Vehicle

IN/OUT

Date/Time	Action/Instruction
	(X) Estimate
	SLL 62365 -X
	SKA 447J-NA/CTI19012828/24
	Diamond: 9/9/2019

DOA: 20/09/2019

ASS. REC. BY:

Tanghe

REF:

CTI

ASSIGNMENT

From:

Date:

5/9/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLL 62365

at Workshop m/s

Ngee Ngee Motor

of

Blk K No. 22 Penden Loop

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No,

CA / REV / REP. / 24 HRS

up - PRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLL 62365

Yr Regn:

2017, March

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hilux

C.C

1986

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

5603

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

2546000 92010

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

Ngee Ngee Motor

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / ☒ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range - 5,000 - 6,000

Repair days - 5 days

12/9/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

140

Transportation:

S + RS, SI

Photos

Others

TOTAL

140

Report Format:

PRC

Lump Sum / L.B.I. (%)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2019		04 Sep 2019 16:04 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	EDMUND VEHICLE PTE LTD		
Vehicle Reg. No.:	SLL6236S	Date of Loss:	20/07/2019 08:00 - :59
Claim Type:	TP / SNM19D203402C02	Policy/Cover Note No.:	DMPCSN18411318000
Vehicle Reg. No. (Insured):	SKA447J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ngee Ngee Motor (HQ) BLK 1 NO 22 PANDAN LOOP (WEST COAST ROAD),JURONG TOWN, 128219 West Coast - Tel: 67775382		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/09/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Yvonne

From: Yvonne
Sent: Wednesday, 4 September 2019 9:17 AM
To: 'Claims Dept of CTI'; Tan Kah Leong; Alfred Toh; Chee So Chow; Irene Tay
Subject: [PRI] OUR REF: SNM19D203402-SKA447J-TKL - FW: China Taiping insured SKA447J - 2019.6442.MK.ya - SLL6236S

Our ref : 2019.6442.SLL6236S.MK.ya
Your ref : SKA447J

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

China Taiping Insurance (Singapore) Pte. Ltd.
No. 3 Anson Road,
#16-00 Springleaf Tower,
Singapore 079909
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s China Taiping Insurance (Singapore) Pte. Ltd.
Vehicle **SLL6236S** inspected as follows by Name:

Before repair	Parts removed	After repair
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: EDMUND VEHICLE RENTAL PTE LTD

ACCIDENT INVOLVING SLL6236S & SKA447J ON 20 JULY 2019 ALONG CTE(CITY) AT ABOUT 0845 HOURS

We refer to the above matter wherein we are instructed to act for **EDMUND VEHICLE RENTAL PTE LTD**, the owner of vehicle no. **SLL6236S**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SLL6236S** is available as follows, **please call prior appointment** for the pre-repair inspection:

M/s Ngee Ngee Motor
Blk K, No. 22 Pandan Loop
(West Coast Road, Jurong Town),
Singapore 128219
Tel: 67775382 (Ms Jessie)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	244G

Vehicle Details

Vehicle No.:	SLL6236S
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 CVT SF
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	3ZRB910367
Chassis No.:	ZSU600092010
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$31,466.00
Original Registration Date:	01 Mar 2017
First Registration Date:	01 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$31,053.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2027
PARF Rebate Amount:	\$23,289.00

Intended COE Rebate Details

COE Expiry Date:	28 Feb 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$37,875.00
Total Rebate Amount:	\$61,164.00

The information contained herein is correct as at 06 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/08/2019 16:57
Date Of Accident	20/07/2019 08:45
Exact Location Of Accident	ALONG CTE (CITY)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6236S
Insured/Policyholder	
Name Of Registered Owner	EDMUND VEHICLE RENTAL PTE LTD
Co Reg No	201625244G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94504393

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086598106-02
Cover Note Number	

Driver

Name of Driver	RUBABA ISLAM SABED
NRIC No	S2637794C
Date Of Birth	24/10/1956
Occupation	INDOOR
Date Of Driving Pass	25/02/1994
Driving Experience	25 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94504393
Fax Number	
Contact Number	OFFICE-94504393
Email Address	NOEMAIL

Address	23 CHUAN TERRACE SINGAPORE
Postcode	558491
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA447J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JASON
NRIC/Passport Number	
Contact Number	91289652
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 20/07/19 @ 8:45AM AROUND 9 WAS DRIVING MY VEHICLE SLL6236S
 ALONG CTE (CTE CITY), 9 SLOWLY DROVE MY VEHICLE THEN SUDDENLY
 ONE VEHICLE PLATE NO. SKA447J HIT MY VEHICLE BEHIND.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2019		04 Sep 2019 16:04 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case









































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: EDMUND VEHICLE PTE LTD									
Vehicle Reg. No.: SLL6236S		Date of Loss: 20/07/2019 08:00 - :59 [28 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D203402C02		Policy/Cover Note No.: DMPCSN18411318000							
Vehicle Reg. No. (Insured): SKA447J		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Ngee Ngee Motor (HQ) BLK 1 NO 22 PANDAN LOOP (WEST COAST ROAD), JURONG TOWN, 128219 West Coast - Tel: 67775382									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/09/2019]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL6236S (SNM19D203402C02)
[SKA447J]
TP
EDMUND VEHICLE PTE LTD
Jul 20 2019 8:00AM
[-]
Ngee Ngee Motor

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/09/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	16/09/19 16:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19015733/T1CD3E2

Date: 20/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN18411318000

Claimant
Vehicle No : SLL6236SInsured
Vehicle No : SKA447J

Date of Loss: 20/07/2019

Nature of Claim: TP

Claim
No: SNM19D203402C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL6236S

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZRB910367

Reg. Date: 01/03/2017 (Man. Year: 2016)

Chassis No: ZSU600092010

Colour: Silver

Odometer: 56103 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/09/2019

Date Inspected: 05/09/2019 Inspected At:

Ngee Ngee Motor (HQ)
BLK 1 NO 22 PANDAN LOOP (WEST
COAST ROAD), JURONG TOWN
Singapore 128219

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL6236S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >