

ASS. REC. BY:

REF:

CS/AIG/9015734/T1sd302

Special Instructions:

Senior: TAN Fik

ASSIGNMENT (Office)

Mei Men

From (Person): Chin Lee Ying

of AIG

Date/Time: 5/9/2019 @ 9:29 am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBP 1493X

Insured:

at Workshop m/s: Bike Production

Tel: 62995177

610 Serangoon Road

Policy No: 1900016376

Claim No:

Sum Insured:

Excess:

600

Make of Veh:

D.O.A. 01/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:23 am @ 5/9/19

Person Contacted:

Wendy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	FBP 1493X - X
06/09/19 @ 11:33 am	revised IA to Chen Yoke Shw via me-men.
06/09/19 @ 11:34 am	mandate requested authorize repair to A.D. via me-men

Taufer

AIG

ASSIGNMENT

From

Date

5/9/19

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBP 1493X

at Workshop m/s

Bike production

of

610 Seungoun Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

75A \$600/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$9500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

FBP1493X

Yr Regd:

20/9 Feb.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Flender, CB150

C.C. 149

Colour

Black

AC:

Insured / Std / NI / NA

Sp Reading

8279

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MLHKC282JS030348

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/70K 17

R:

150/60K 17

BS/DUX / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

45

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

5/1/19 530/-

Survey held at

Bike Production

Des. of Damages:

Fr / Rear /

O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

08/09/19 @ 17:48 pm mandate approved by Thaddeus Ng via memo.

09/09/19 @ 09:09 am inform C/A to Kwan S.H. Cooper via email

11/9/19 Pending supplementary approval

23/09/19 Confirmed HS \$2,350/- @ 5 days with Taufer (\$4,479.30 Red - 61%)

RECEIVED 10 SEP 2019

23/9/2019

Date/Time, File Path (if)

30/09/19

1)

Typ. 34

Date/Time, File Path (if)

2)

Report Form (if)

Stamp (if)

(ID):

2,350/- 45

☐

: Prel. Report

☒

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Workshop (\$

Survey Fee:

Transportation

S + P.S. 34

Photos

Other:

211

200

11

211

Your password will expire in 10 days. Click here to change it.

**FBP1493X OD CLAIM**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 8/5/2019 9:29:44 AM  
Attachments:  20190905\_085553.jpg  FBP1493X DQA01092019 AIG ODOWS.pdf

---

Hi LKE,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #88-16 Singapore 079128  
Tel +(65) 6419 1847  
Lee-Ying.Chin@aig.com | www.aig.sg

-----Original Message-----

From: Sbk E [mailto:sbk5643e@yahoo.com]  
Sent: Thursday, September 05, 2019 9:03 AM  
To: AIG SGP, Claims-Survey  
Subject: [EXTERNAL] RE: FBP1493X OD CLAIM

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Good Day. Please refer to the attached file. Please contact us at 62995177 for pre-repair inspection appointment. Thank you very much for your attention.

Regards,

Kwan S. H.  
Director  
Bike Production Pte Ltd

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If y



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 263D

Vehicle Details

Vehicle No.: FBP1493X  
Vehicle to be Exported: No  
Intended Deregistration Date: 06 Sep 2019  
Vehicle Make: HONDA  
Vehicle Model: CB150R MANUAL  
Primary Colour: Black  
Manufacturing Year: 2018  
Engine No.: KC32E0030348  
Chassis No.: MLHKC2882J5030348  
Maximum Power Output: -  
Open Market Value: \$3,784.00  
Original Registration Date: 11 Feb 2019  
First Registration Date: 11 Feb 2019  
Transfer Count: 1  
Actual ARF Paid: \$568.00

Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Feb 2029  
COE Category: D - Motorcycle  
COE Period(Years): 10  
QP Paid: \$3,709.00  
COE Rebate Amount: \$3,497.00  
Total Rebate Amount: \$3,497.00

The information contained herein is correct as at 06 Sep 2019

OK

**Re: UNCONFIRMED AND SUPPLEMENTARY ITEMS, Re: FBP1493X AUTHORIZATION TO REPAIR - Mandate Approved & Labour Consistency**

Shirley Hiew (LKK Auto)

Thu 12/9/2019 9:48 AM

To: Ng, Thaddaeus-HC &lt;Thaddaeus-HC.Ng@aig.com&gt;

Cc: SUR &lt;sur@lkkauto.com&gt;; Fong, Andy-SY &lt;Andy-SY.Fong@aig.com&gt;; Koh, Victor-CK &lt;Victor-CK.Koh@aig.com&gt;

Dear Thaddaeus,

Resurvey photo re-uploaded.

Kindly approved on the supplementary.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>**Sent:** Wednesday, 11 September 2019 11:52 AM**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Cc:** SUR <sur@lkkauto.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Koh, Victor-CK <Victor-CK.Koh@aig.com>**Subject:** RE: UNCONFIRMED AND SUPPLEMENTARY ITEMS, Re: FBP1493X AUTHORIZATION TO REPAIR - Mandate Approved & Labour Consistency

Hi,

You end have uploaded FBP 1493X &amp; FBN 4881A photos onto the same document. Is FBN 4881A relate with the claims?

Please check.

**Regards,****Thaddaeus Ng****AIG**

Motor Claims Surveyor

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel: +(65) 6419 1929 | Fax: +(65) 6835 7416 Hp: +(65) 8876 5433

[Thaddaeus-HC.Ng@AIG.com](mailto:Thaddaeus-HC.Ng@AIG.com) | [www.AIG.com.sg](http://www.AIG.com.sg)

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>**Sent:** Wednesday, September 11, 2019 11:34 AM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>**Cc:** SUR <sur@lkkauto.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>**Subject:** [EXTERNAL] RE: UNCONFIRMED AND SUPPLEMENTARY ITEMS, Re: FBP1493X AUTHORIZATION TO REPAIR - Mandate Approved & Labour Consistency**This message is from an external sender; be cautious with links and attachments.**

Dear Thaddaeus,

We have submitted supplementary in merimen.

Kindly approved on the supplementary.

**Re: FBP1493X AUTHORIZATION TO REPAIR - Mandate Approved & Labour Consistency**

Shirley Hiew (LKK Auto)

Mon 9/9/2019 9:09 AM

To: Sbk E &lt;sbk5643e@yahoo.com&gt;

Cc: SUR &lt;sur@lkkauto.com&gt;

Hi Kwan S.H,

Kindly refer to the below email above matter given by AIG.

As instructed by our client, please proceed to repair the insured vehicle **FBP 1493X** (Excess S 600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>**Sent:** Sunday, 8 September 2019 5:47 PM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Sbk E <sbk5643e@yahoo.com>**Cc:** Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>**Subject:** RE: FBP1493X AUTHORIZATION TO REPAIR - Mandate Approved & Labour Consistency

Hi Both,

Mandate approved. Revise estimate are to be the tally with accident statement and parts given for labour to confirm.

Resurvey for check, supplementary and after paint require.

- Rider ride back home after the accident. Towing Charges to be remove
- Labour To Remove/ Refit, Replace (if damaged) Check And straighten Front Sport Rims not require unless the parts changed or removed
- Labour Spray Painting to indicate which body panel require

Thanks

*Regards,***Thaddaeus Ng****AIG**

Motor Claims Surveyor

Claims|AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1929|Fax +(65) 6835 7416 Hp +(65) 8876 5433

[Thaddaeus-HC.Ng@AIG.com](mailto:Thaddaeus-HC.Ng@AIG.com) | [www.AIG.com.sg](http://www.AIG.com.sg)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Sent:** Friday, September 6, 2019 5:33 PM

To: Sbk E <sbk5643e@yahoo.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>; SUR <sur@lkkauto.com>

Subject: [EXTERNAL] Re: FBP1493X AUTHORIZATION TO REPAIR

This message is from an external sender; be cautious with links and attachments.

Hi Kwan S.H.

Kindly refer below email.

## FBP 1493X OD / 22140191855G



Shirley Hiew (LKK Auto)

Fri 6/9/2019 4:16 PM

Thaddaeus-HC.Ng@aig.com; SUR; 'Fong, Andy-SY' <Andy-SY.Fong@aig.com>

Dear Thaddaeus,

Kindly let us have your authorization approval.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>

Sent: Friday, 6 September 2019 4:44 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>; SUR <sur@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>

Subject: RE: FBP1493X AUTHORIZATION TO REPAIR

Dear Sur

Please seek permission from AIG to authorise for FBP1493X. I have include Thadd from AIG in this email. Thank you very much for your attention.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



## View Received Message

This mail is associated with :

**\*FBP1493X (2214019185SG)**

OO

Sep 1 2019 10:00AM

[HSU WEN XIONG]

Bike Production

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 08/09/2019 17:48 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$3200.60) - FBP1493X - Claim Handler: Chan, Yoke Shi

Approved:3200.60:To resurvey for check, supplementary & after repair.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199807198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chan, Yoke Shi

Date: 11 Sep 2019

**Preliminary Advice**

Vehicle No	: FBP1493X	Accident Date	: 01/09/2019
Make	: HONDA CB150R	Policy No.	: 1900016376
Assignment Date	: 05/09/2019	Excess	: S\$600.00
Date of Inspection	: 5/9/2019	Est. Duration of Repair	: 5
Inspection At	: BIKE PRODUCTION PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,329.30 (incl.supplementary \$331.20)
Revised Amount	:S\$	3,564.30 (incl.supplementary \$331.20)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,564.30

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,500.00
COE / PARF Rebate	:S\$	3,497.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,003.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chan, Yoke Shi

Date: 06 Sep 2019

## Preliminary Advice

Vehicle No	: FBP1493X	Accident Date	: 01/09/2019
Make	: HONDA CB150R	Policy No.	: 1900016376
Assignment Date	: 05/09/2019	Excess	: S\$0.00
Date of Inspection	: 05/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Bike Production (HQ) No 610 Serangoon Road Singapore 218216		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,998.10
Revised Amount	:S\$	2,551.60
Check Items (Estimated)	:S\$	649.00
Total	:S\$	3,200.60

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,500.00
COE / PARF Rebate	:S\$	3,497.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,003.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2019 16:08
Date Of Accident	01/09/2019 10:35
Exact Location Of Accident	SEA AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP1493X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HSU WEN XIONG
NRIC No	S9318263D
Email Address	XDAILO221@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81183353
Alternative Phone No	OFFICE-81183353

### Vehicle Particulars

Manufacturer	HONDA
Model	CB150R-149CC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900016376
Cover Note Number	

### Driver

Name of Driver	HSU WEN XIONG
NRIC No	S9318263D
Date Of Birth	17/05/1993
Occupation	OUTDOOR
Date Of Driving Pass	21/09/2017
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81183353
Fax Number	
Contact Number	OFFICE-81183353
E-Mail Address	XDAILO221@GMAIL.COM

Address BLK 623 BEDOK RESERVOIR ROAD #07-1526  
 Postcode 470623  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLOUDLY  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 1  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? NO  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO STATEMENT ———SELF SKID

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF INJURED PERSON 1

Name  
 Approximate Age  
 Injuries Sustain  
 Injured person in which vehicle? FBP1493X  
 Were seat belts worn?  
 Was this injured conveyed to hospital by ambulance?  
 Address  
 Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 1 SEP 2019 I WAS ON MY WAY HOME I WAS ABOUT TO CHANGE  
 lane — a white BMW WAS INFRONT OF ME WHEN I WAS ABOUT  
 TO CHANGE LANE TO CUT THE DRIVER SUDDENLY ~~THE~~ THE DRIVER TURN  
 and I SKIDDED and fell down because there was no room way out other  
 than to jam break then the bike flip over me and I fell down  
 after that I drove back home and I didn't know what to do  
 so I didn't report it till I brought my bike to my bike shop  
 then they advice me on what to do next

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2019 16:08
Date Of Accident	01/09/2019 10:35
Exact Location Of Accident	SEA AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP1493X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HSU WEN XIONG
NRIC No	S9318263D
Email Address	XDAILO221@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81183353
Alternative Phone No	OFFICE-81183353

### Vehicle Particulars

Manufacturer	HONDA
Model	CB150R-149CC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900016376
Cover Note Number	

### Driver

Name of Driver	HSU WEN XIONG
NRIC No	S9318263D
Date Of Birth	17/05/1993
Occupation	OUTDOOR
Date Of Driving Pass	21/09/2017
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81183353
Fax Number	
Contact Number	OFFICE-81183353
Email Address	XDAILO221@GMAIL.COM



Address	BLK 623 BEDOK RESERVOIR ROAD #07-1526
Postcode	470623
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLOUDLY
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT -----SELF SKID

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF INJURED PERSON 1

Name	
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBP1493X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

\_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 1 SEP 2019 I WAS ON MY WAY HOME I WAS ABOUT TO CHANGE  
 lane — a white bus WAS INFRONT OF ME WHEN I WAS ABOUT  
 TO CHANGE LANE TO CUT THE DRIVER SUDDENLY ~~THE~~ THE DRIVER TURN  
 and I Skidded and fell down because there was a car way out there  
 then I jam break then the bike flip over me and I fall down  
 after that I drove back home and I didn't know what to do  
 so I didn't report ... till I brought my bike to my bike shop  
 then they advice me on what to do next

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



# CERTIFICATE OF INSURANCE

## MOTORCYCLE AUTOVANTAGE MOTORCYCLE

Name of Policyholder : HSU WEN XIONG  
 Period of Insurance : 13 Feb 2019 To 12 Feb 2020  
 Engine No. : KC32ED030348  
 Chassis No. : MLHKC2882J5030348

Vehicle No. : FBP1493X  
 Policy No. : 1900016376  
 Endorsement No. :  
 Issued Date : 13 Feb 2019

### ABOUT THE COVER

Make/Model : HONDA CB150R  
 Engine Capacity/Tonnage : 149.00 CC  
 Driver Restriction : Named Driver Basis  
 Person or Classes of Persons Entitled to Drive\* :

Sum Insured : Market Value  
 Off Peak Car : No

First Year of Registration : 2019  
 Insuring with COE/PAFF : Yes

- a) The Policyholder  
 b) Any person who is named as a "named driver" under this Policy.

Age Condition : Not Applicable

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- 1) use for hire or reward;
- 2) use for driving tuition, driving test, racing, pace-making, reliability trial or speed-testing;
- 3) use for the carriage of goods (other than samples) in connection with any trade or business; and
- 4) use for any purpose in connection with Motor Trade.

\* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

Section 1  
 Fire - \$0 Own Damage - \$600 Theft - \$0

Section 2  
 Property Damage - \$0

Windscreen : NA

Named Driver and Excess (where applicable)

HSU WEN XIONG - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.  
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: BIKE PRODUCTION PTE LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).

Please note that this vehicle  
 is under hire purchase with  
**Bike Production Pte Ltd**  
 No transfer or endorsement is allowed  
 unless with our written consent

**BIKE PRODUCTION PTE LTD**  
 Co Reg No: 200007407G  
 610 Serangoon Road  
 Singapore 218216  
 Tel: 63922555 Fax: 62975400

0500656016

COWELL - BIKE PRODUCTION

8 BURN ROAD #09-09 TRIVEX

SINGAPORE 369977 ANSP-NONLIFE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
 AUTHORISED REPRESENTATIVE

**BIKE PRODUCTION PTE LTD**  
 610, Serangoon Road S(218216)  
 Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

Date: 3 Sept 2019

**ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBP1493X**


Chassis No.: MLHKC2882J5030348

Engine No.: KC32E0030348

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$180.00 <i>cut</i>
1 pc	Headlamp	\$230.00 <i>cut</i>
1 pc	Front disk brake	\$165.00 x
1 pc	Front wheel axle	\$75.00 x
1 pc	Front left fork assy	\$480.00 <i>Rx</i>
1 pc	Front right fork assy	\$480.00 <i>Rx</i>
1 pc	Steering stem	\$220.00 x
1 pc	Steering bridge	\$195.00 x
2 pcs	Steering bearings	\$90.00 x
1 set	Steering bridge holder	\$150.00 x
1 pc	Front right signal	\$145.00 <i>cut</i>
1 pc	Headlamp black cover	\$145.00 <i>cut</i>
1 pc	Right view mirror	\$105.00 <i>cut</i>
1 pc	Left view mirror	\$105.00 <i>cut</i>
1 pc	Right balancer	\$40.00 <i>cut</i>
1 pc	Right handle grips	\$40.00 ?
1 pc	Headlamp bracket	\$195.00 ?
1 pc	Handle bar	\$150.00 ?
1 pc	Centre tank cover amblem	\$29.00 <i>cut</i>
1 pc	Centre tank cover	\$145.00 <i>cut</i>
1 pc	Brake lever	\$75.00 <i>cut</i>
1 pc	Right switch	\$175.00 ?
1 pc	IU bracket	\$45.00 x
1 pc	Fuel tank right cover	\$295.00 <i>Rx</i>
1 pc	Right cover label	\$35.00 x
1 pc	Right cover silver	\$195.00 x
1 pc	Meter assy	\$395.00 <i>cut</i>
1 pc	Brake pedal	\$105.00 <i>cut</i>
1 pc	Right front footrest	\$75.00 <i>cut</i>
1 pc	Right front footrest holder	\$145.00 x
1 pc	Right rear footrest	\$75.00 <i>cut</i>
		<hr/>
		\$4,979.00
	Less discount 10%	\$497.90
		<hr/>
		\$4,481.10
	<b><u>Special nett items</u></b>	
1 pc	ERP IU	\$157.00 <i>cut</i>
1 pc	Front number plate	\$20.00 <i>cut</i>
1 pc	Box rack	\$145.00 ?
1 pc	Top case	\$205.00 <i>cut</i>
1)	Towing charges	\$100.00 <i>50 x</i>
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$800.00 <i>250</i>
	To knock, straighten chassis & body	
3)	balancing	\$380.00 x

4)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00	120
4)	To remove/refit, replace (if damage) check and straighten front sport rims.	\$150.00	30x
6)	Spray painting <i>Fit fender, Fuel tank cover, Rear side fair cover</i>	\$380.00	150
	<b>Total Estimate</b>	<b>\$6,998.10</b>	

Note: The above estimate is subjected to the prevailing GST of 7%

*[Signature]*  
  
 For Bike Production Pte Ltd

*[Signature]*  
 9/9/19

Tanpik 97495749  
 Not Authorise  
 Ex: to be advise -  
 Bounney after repair  
 5 days  
 sure@lukaauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To reserved all materials every editing
- To disuse all materials every recovery
- Parts and accessories
- Third party insurance on "No Prejudice" basis
- No illegal activities allowed
- Supplementary work must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**BIKE PRODUCTION PTE LTD**  
 610, Serangoon Road S(218216)  
 Tel: 63922555, 62995177 Fax: 62975400  
 ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2019

**ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBP1493X**

Chassis No.: MLHKC2882J5030348


Engine No.: KC32E0030348

Qty	Description	Estimate
1 pc	Front fender	\$180.00 <i>wt</i>
1 pc	Headlamp	\$230.00 <i>wt</i>
1 pc	Front disk brake	<del>\$165.00</del> <i>x nn</i>
1 pc	Front wheel axle	<del>\$75.00</del> <i>x nn</i>
1 pc	Front left fork assy	\$480.00 <i>Rv</i>
1 pc	Front right fork assy	<del>\$480.00</del> <i>Rv</i>
1 pc	Steering stem	<del>\$220.00</del> <i>x nn</i>
1 pc	Steering bridge	<del>\$195.00</del> <i>x nn</i>
2 pcs	Steering bearings	<del>\$90.00</del> <i>x nn</i>
1 set	Steering bridge holder	\$150.00 <i>bt</i>
1 pc	Front right signal	\$145.00 <i>cut</i>
1 pc	Headlamp black cover	\$145.00 <i>cut</i>
1 pc	Right view mirror	\$105.00 <i>cut</i>
1 pc	Left view mirror	\$105.00 <i>cut</i>
1 pc	Right balancer	\$40.00 <i>cut</i>
1 pc	Right handle grips	\$40.00 <i>?dis</i>
1 pc	Headlamp bracket	\$195.00 <i>?bt</i>
1 pc	Handle bar	\$150.00 <i>?bt</i>
1 pc	Centre tank cover amblem	\$29.00 <i>at</i>
1 pc	Centre tank cover	\$145.00 <i>at</i>
1 pc	Brake lever	\$75.00 <i>at</i>
1 pc	Right switch	<del>\$175.00</del> <i>? x nn</i>
1 pc	IU bracket	\$45.00 <i>x bt</i>
1 pc	Fuel tank right cover	<del>\$295.00</del> <i>Rv</i>
1 pc	Right cover label	<del>\$35.00</del> <i>x nn</i>
1 pc	Right cover silver	<del>\$195.00</del> <i>x nn</i>
1 pc	Meter assy	\$395.00 <i>cut x nn</i>
1 pc	Brake pedal	\$105.00 <i>del</i>
1 pc	Right front footrest	\$75.00 <i>cut</i>
1 pc	Right front footrest holder	<del>\$145.00</del> <i>x nn</i>
1 pc	Right rear footrest	\$75.00 <i>cut</i>
		<hr/>
		\$4,979.00      2429
	Less discount 10%	\$497.90
		<hr/>
		\$4,481.10      2186.10
	<b>Special nett items</b>	
1 pc	ERP IU	\$157.00 <i>at</i>
1 pc	Front number plate	\$20.00 <i>del</i>
1 pc	Box rack	\$145.00 <i>? -bt</i>
1 pc	Top case	\$205.00 <i>cut</i> 527
		<hr/>
1)	Towing charges	\$100.00 <i>50 x nn</i>
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$800.00      250
	To knock, straighten chassis & body	
3)	balancing	<del>\$380.00</del> <i>x nn</i>

- 4) To remove/refit, replace (if damage) check and straighten front fork tubes.  
 4) To remove/refit, replace (if damage) check and straighten front sport rims.  
 6) Spray painting  
**Total Estimate**

\$180.00 120.  
 \$150.00 ~~20~~ X nh  
 \$380.00 150  
 \$6,998.10 520

**Note: The above estimate is subjected to the prevailing GST of 7%**

  
 For Bike Production Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repairs being
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjil 97995719  
 Not Authorise  
 EX: to be advise.  
 Resurvey after repair  
 5 days  
 sur@lkkauto.com

7719 40



**BIKE PRODUCTION PTE LTD**

610, Serangoon Road S(218216)

**BIKE PRODUCTION PTE LTD**

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 6 Sept 2019

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBP1493X

Chassis No.: MLHKC2882J5030348

Engine No.: KC32E0030348

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Meter cover	\$98.00 <i>art-</i>
1 pc	Honda chrome label	\$40.00 <i>art-</i>
1 pc	Side cover right	\$95.00 <i>cut-</i>
1 pc	Rear side tail cover	\$135.00 <i>art-</i>
		<hr/>
		\$368.00
	Less discount: 10%	\$36.80
		<hr/>
		\$331.20

**Note: The above estimate is subjected to the prevailing GST of 7%**

For Bike Production Pte Ltd

2186.10

527

520

331.20

3564.30

1/5 \$ 2850

5 days

*Anglin*  
9/9/19

Hsu Wen Xiong  
Blk 623 Bedok Reservoir Road  
#07-1526  
Singapore 470623

Date: 4 Sept 2019

To: Mr Kwan Say Hwee  
Bike Production Pte Ltd  
610, Serangoon Road  
Singapore 218216

Dear Sir,

**RE: LETTER OF UNDERTAKING FOR LUMP SUM REPAIR UNDER VEHICLE  
NO.: FBP1493X**

I, Hsu Wen Xiong, NRIC No.: 263D, authorise Bike Production Pte Ltd to repair my motorcycle, Honda CB150R Manual – FBP1493X back to road worthy condition on a lump sum basis.

I understand and acknowledge that a lump sum repair takes into consideration repairs and/or replacements with the use of reconditioned and ex-stock parts wherever possible.

Thank you very much for your attention.

Yours faithfully,



Hsu Wen Xiong

# BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216

Tel: 6392 2555 Fax: 6297 5400

## TAX INVOICE

Co. Registration No. 200007407G

GST Reg. No: 200007407G

GST Inclusive

No: 6108

Name: AIG ASIA PACIFIC INSURANCE PTE LTD Date: 26/09/2019

Address: 78 SHENTON WAY #07-16 AIG BUILDING SE 079120

I/C No: \_\_\_\_\_ Occupation: \_\_\_\_\_ DOB: \_\_\_\_\_

Tel: (H)61493000 (F)64153723 Driving Licence: \_\_\_\_\_

Particulars		Amount
Reg. No: <u>FBP/493X</u>	Selling Price	\$ 2,407.50
Make & Model: <u>HONDA CB150R MANUAL</u>	+ Insurance	\$ 0
Engine No: <u>KC32E 0030348</u>	+ Retention	\$ 0
Chassis No: <u>MLHKC 2882J 5030348</u>	TOTAL PRICE	\$ 2,407.50
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire Theft <input type="checkbox"/> Third Party Only		
Colour: <u>BLACK</u>	LUMP SUM REPAIRS Downpayment	\$2,850.00
	LESS EXCESS	\$ 600.00
Loan Amount _____	Interest rates _____ p.a.	\$2,250.00
Terms: ( _____	Monthly Instalments of \$ <u>GST 7%</u> )	\$ 157.50
N/R: _____	TEL: _____	\$ 2,407.50
GTR: _____	TEL: _____	
COE NO: _____	TR	

### Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid.
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have fullrights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions. If the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For **Bike Production Pte Ltd**

I accept the above terms and conditions

Hsu Wen Xiong  
Blk 623 Bedok Reservoir Road  
#07-1526  
Singapore 470623

Date: 11 Sept 2019

To: Mr Kwan Say Hwee  
Bike Production Pte Ltd  
610, Serangoon Road  
Singapore 218216

Dear Sir,

**RE: AKNOWLEDGEMENT OF THE ACCIDENT REPAIR AND COLLECTION  
OF HONDA CB150R MANUAL VEHICLE NO.: FBP1493X**

I, Hsu Wen Xiong, NRIC No.: 263D, have inspected the repair done by Bike Production Pte Ltd and the repair is in accordance to the repair quotation and/or surveyor report.

I have collected the above mentioned vehicle on 11 / 9 / 19 at 1535.

Thank you very much for your attention.

Yours faithfully,



Hsu Wen Xiong

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2019		05 Sep 2019 14:14 <a href="#">Edit Adj Rpt</a>	<b>S\$2,850.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,850.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>HSU WEN XIONG</b> , ID: S9318263D, Tel: +6581183353, Email: xdailo221@gmail.com									
Vehicle Reg. No.: <b>FBP1493X</b>		Date of Loss: 01/09/2019 10:00 - :59 [6 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>OD / 2214019185SG</b>		Policy/Cover Note No.: 1900016376 (Comprehensive)							
		Excess: S\$600.00							
Repairer: <b>Bike Production (HQ)</b> No 610 Serangoon Road, 218216 Serangoon - Tel: 6299-5177									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Yoke Shi</b> ] yokeshi.chan@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 16/09/2019]									
Driver/Custodian: <b>HSU WEN XIONG (26 / Male)</b> , NRIC: S9318263D, Tel: +6581183353 Email: xdailo221@gmail.com									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (12/09/2019): Alert - Adj Mandate Approved (S\$3564.30) - FBP1493X - Claim Handler: Chan, Yoke ...</li> <li>AIG_SG (08/09/2019): Alert - Adj Mandate Approved (S\$3200.60) - FBP1493X - Claim Handler: Chan, Yoke ...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBP1493X (2214019185SG)


OD









































Sep 1 2019 10:00AM

























































[HSU WEN XIONG]

Bike Production































[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#) | [Upload Video](#) | [Upload Audio](#)
View [View in Browser](#) 

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/19 11:33	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
2	11/09/19 11:10	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>














Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/09/19 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
42	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
43	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
44	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
45	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
46	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
47	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
48	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
49	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
50	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
51	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
52	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
53	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
54	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
55	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
56	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
57	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
58	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
59	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
60	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
61	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
62	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
63	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
64	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
65	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
66	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
67	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
68	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
69	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
70	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
71	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
72	06/09/19 11:29	General View		<input checked="" type="checkbox"/>
73	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
74	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
75	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
76	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
77	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
78	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
79	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
80	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
81	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
82	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
83	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
84	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
85	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
86	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
87	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
88	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
89	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
90	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
91	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
92	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
93	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
94	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
95	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>
96	12/09/19 09:45	Reinspection Photo		<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
97	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	12/09/19 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/19 11:27	CI.pdf	 Load PDF	
2	06/09/19 11:27	DRIVING & IC.pdf	 Load PDF	
3	06/09/19 11:27	ESTIMATE.pdf	 Load PDF	
4	06/09/19 11:27	FBP 1493X GIA.pdf	 Load PDF	
5	11/09/19 10:59	1ST MARKING	 Load PDF	
6	11/09/19 10:59	SUPPLEMENTARY	 Load PDF	
7	23/09/19 13:14	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
8	14/10/19 09:31	Workshop Invoice	 Load PDF	
9	14/10/19 09:31	Discharge Voucher	 Load PDF	

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	03/09/19 16:44	Accident Statement	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	03/09/19 16:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	03/09/19 16:34	Sketch Plan	 Load TIF	



## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CS/AIG19015734/T1SD3E2

Date: 14/10/2019

### REFERENCE

Insured/Claimant: HSU WEN XIONG Policy No: 1900016376  
Date of Loss: 01/09/2019 Nature of Claim: OD Claim No: 2214019185SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP1493X**  
Make & Model: HONDA CB150R, 149cc Engine No: KC32E0030348  
Reg. Date: 11/02/2019 (Man. Year: 2018) Chassis No: MLHKC2882J5030348  
Colour: Black Odometer: 8279 km  
Engine Capacity: 149 cc  
Market Value/New Car Price: S\$9,500.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 150/60 R17  
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,339.30	3,044.30	2,295.00	42.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,990.00	520.00	1,470.00	73.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,329.30</b>	<b>3,564.30</b>	<b>3,765.00</b>	<b>51.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,850.00</b>		
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	6,729.30	2,250.00	4,479.30	66.56
<b>+ GST 7.00/7.00% (S\$)</b>	471.05	157.50	313.55	66.56
<b>Nett Amount (S\$)</b>	<b>7,200.35</b>	<b>2,407.50</b>	<b>4,792.85</b>	<b>66.56</b>

### INSPECTION

Date of Assignment: 05/09/2019  
Date Inspected: 05/09/2019 Inspected At: Bike Production (HQ)  
No 610 Serangoon Road  
Singapore 218218  
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	180.00 FL	*180.00 FL
2	1		*HEADLAMP	Cut	230.00 FL	*230.00 FL
3	1		*FRONT DISK BRAKE	Not Necessary	165.00 FL	*- FL
4	1		*FRONT WHEEL AXLE	Not Necessary	75.00 FL	*- FL
5	1		*FRONT LEFT FORK ASSY	Repair	480.00 FL	*- FL
6	1		*FRONT RIGHT FORK ASSY	Repair	480.00 FL	*- FL
7	1		*STEERING STEM	Not Necessary	220.00 FL	*- FL
8	1		*STEERING BRIDGE	Not Necessary	195.00 FL	*- FL
9	2		*STEERING BEARINGS	Not Necessary	90.00 FL	*- FL
10	1		*STEERING BRIDGE HOLDER	Bent	150.00 FL	*150.00 FL
11	1		*FRONT RIGHT SIGNAL	Cut	145.00 FL	*145.00 FL
12	1		*HEADLAMP BLACK COVER	Cut	145.00 FL	*145.00 FL
13	1		*RIGHT VIEW MIRROR	Cut	105.00 FL	*105.00 FL
14	1		*LEFT VIEW MIRROR	Cut	105.00 FL	*105.00 FL
15	1		*RIGHT BALANCER	Cut	40.00 FL	*40.00 FL
16	1		*RIGHT HANDLE GRIPS	Distorted	40.00 FL	*40.00 FL
17	1		*HEADLAMP BRACKET	Bent	195.00 FL	*195.00 FL
18	1		*HANDLE BAR	Bent	150.00 FL	*150.00 FL
19	1		*CENTRE TANK COVER EMBLEM	Cut	29.00 FL	*29.00 FL
20	1		*CENTRE TANK COVER	Cut	145.00 FL	*145.00 FL
21	1		*BRAKE LEVER	Cut	75.00 FL	*75.00 FL
22	1		*RIGHT SWITCH	Not Necessary	175.00 FL	*- FL
23	1		*IU BRACKET	Bent	45.00 FL	*45.00 FL
24	1		*FUEL TANK RIGHT COVER	Repair	295.00 FL	*- FL
25	1		*RIGHT COVER LABEL	Not Necessary	35.00 FL	*- FL
26	1		*RIGHT COVER SILVER	Not Necessary	195.00 FL	*- FL
27	1		*METER ASSY	Cracked	395.00 FL	*395.00 FL
28	1		*BRAKE PEDAL	Dented	105.00 FL	*105.00 FL
29	1		*RIGHT FRONT FOOTREST	Cut	75.00 FL	*75.00 FL
30	1		*RIGHT FRONT FOOTREST HOLDER	Not Necessary	145.00 FL	*- FL
31	1		*RIGHT REAR FOOTREST	Cut	75.00 FL	*75.00 FL
32	1		*ERP IU	Cut	157.00 FS	*157.00 FS
33	1		*FRONT NUMBER PLATE	Dented	20.00 FS	*20.00 FS
34	1		*BOX RACK	Bent	145.00 FS	*145.00 FS
35	1		*TOP CASE	Cut	205.00 FS	*205.00 FS
36	1		*METER COVER	Cut	98.00 FL	*98.00 FL
37	1		*HONDA CHROME LABEL	Cut	40.00 FL	*40.00 FL
38	1		*SIDE COVER RIGHT	Cut	95.00 FL	*95.00 FL
39	1		*REAR SIDE TAIL COVER	Cut	135.00 FL	*135.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,874.00</b>	<b>3,324.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>534.70</b>	<b>279.70</b>
<b>Total Parts (\$\$)</b>	<b>5,339.30</b>	<b>3,044.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGES	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	800.00	250.00
3	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	120.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT SPORT RIMS	New	150.00	0.00
6	SPRAY PAINTING	New	380.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>1,990.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >