From (Person): Philis	ASSIGNMENT (Office	Date/Time: 5/9/2019	
Estimated Cost:	Bill to:		
OD CP/WS/TP RES/OD RE			
	A CONTRACTOR OF THE PARTY OF TH	Insured: GBB 8377	
at Workshop m/s	sty tech	Tel: 9605 8843	
of 2 kaki	Bulit Ave 2 # 02-30	AufoHub	
Policy No: DHOMII0169	17 41 900 Claim N	0:	
Sum Insured:	Excess	3.	
Make of Veh:(Client's Record)		D.O.A. 3/9/2019	
CA / REV / REP. / REV 241	ERS	H.O.D. Endorsement:	
Date/Time: 2.55pmg slal	Person Contacted: Wins	Vehicle (IN) OUT	14
Date/Time Action/Instruction	Dalamala (		
GBF 688			
	7- NA/40114015645/2	24: DOA: 3/9/2019	
- 1900 997			

(08/11/13) wef ASS. REC. BY: MCreus	no,/	3.01 X
	ASSIGNMENT	
From: Date:	Veh No: GBF6 F84	Yr Regn: 217
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Va	n / Lorry / Taxi / Prime Mover /
OD TP/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or M	)
To Inspect Vehicle No: 657645	Make: NISSON	V V 200 c.c 146/
at Workshop m/s StyleeC	Colour Mile	A/C: Insured / Std / NI / NA
of	Sp.Reading 485/8	T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:	
Policy No.	C/No: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	BAM 20:20 (37273
Claims No.	Gen. Cond; Good / Fair / Poor / B	
Sum Insured: Excess:	Steering: Inorder / Jammed / Lea	aked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Lea	aked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Ri	im or
and the Engineer	Tyre Size: F:	N
(Policy Condition)	R:	178/7000
Remark: The veh had commenced its		LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or	
Bal. or Market Value:	Front	Rear
	/	R/Bal. mm
IDAC Accident Rport: Consistent? : Yes or GIA PR Seen: Consistent? : Yes or	The state of the s	L/Bal. mm
· · · · · · · · · · · · · · · · · · ·	_ / /	D.O.I. (-/9/19
2/	2/1/1	
Zum oum. /4/1 ~		O/S / N/S / U/C / Rooftop or
OA / KET / KET / ZTIKO	Des. of Damages : Frt / Rear /	Old I NIG I Old I Roollop of
Date: Person Contacted:		Body Structure affected due to collision.
Date / Time Action / Instruction		
11/9/19 confund fine / f	\$6340.60 ml n.	nsten.
(\$ 2,799.63 R	red - 31%).	1 2 SEP 2019
	N L V L I V L L	1 1 2 311 2010
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 4	
1) 12/69/15 Date/Time, File Return to?	Resurvey No. of Trip:	3 Survey Fee: 250 Transportation: 60
2)	Add Fee: : Site Insp (\$	)_s+Rs_s  80+80+80
	: Interview (\$	) Photos 93
Report Format :	: Tech. Invs (\$	) Others
Lump Sum/ 1.B.1) (\$ 6,340.60 P/P		) KLD
1370.00 111		TOTAL ALA 642

## SGEARMART.COM

Login 5

**New Cars** 

Used Cars

Sell My Car

Directory

Products

Insurance

Articles



AVIVA

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Lexus LC500 Limited Edition



Direct Owner StarAd



Post an Ad

Advertiser Login

٠

Ways of Selling

Browse by Category

Nissan NV200

Sort by Date Posted

Model

Depreciation

Red Date

Eng Cap

Mileage

Search Selection

13 vehicles

Nissan NV200

Any

Price

2017

Any Any

26-Jul-2017

49,600 km

Nissan NV200 1.6A

\$42,888

\$5,440 /yr

1,597 cc

Fuel Type: Petrol

1 Owner, New Battery, Inspection Done For Peace Of Mind, Free 6 Months Roadtax. Fully Serviced And Maintenance By Tan Chong Niss Agent. No Repairs Needed. Call For Viewing Appointment.

Posted: 05-Sep-2019

Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used



Nissan NV200 1.5M

\$44,800

\$5,790 /yr

31-May-2017

1,461 cc

Fuel Type: Diesel

Cheapest In The Market Nissan NV200, 1 Owner Only! Low Mileage, Original Paintwork, Accident Free, Tip Top Condition, High Loan An High Trade In Available. Drive Off With No Worries! DoorStep Viewing Can Be Arrange!

ABWIN (1994) Pte Ltd

Posted: 05-Sep-2019

Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used



Nissan NV200 1.5M

\$45,800

\$5,750 /yr

22-Aug-2017

1,461 cc

35,000 km

We Provide Door Steps Viewing, 1 Owner Only, Agent Model Euro 5 Engine, Low Mileage Done, Well Maintained, No Repairs Needed, 100% Accident-Free, Reserve Camera, Easy Financing, High Trade In, Don't Miss! Call Us Now! See To Believel

Posted: 04-Sep-2019

Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used

Nissan



Nissan NV200 1.5M

\$48,800

\$5,870 /yr

29-Dec-2017

1,461 cc

Fuel Type: Diesel

Owner Consignment Well Taken Care By 1 Owner, Diesel / Manual - 5 Door Mid Size Van. In House Loan OK! Fast Approval And Deliver Call Now For Appointment.

Posted: 02-Sep-2019

Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan

Car Buying

Car Selling

Car Ownership

> Buy Tyres Online!

Car Aftermarket

On The Move

Lifestyle

> Latest Special Offers fr

Nissan NV200 1.5M

\$43,800

\$5,850 /yr

04-Mar-2017

1.461 cc

26,000 km

ge, Accident-Free, Regularly Serviced, Currently Parked In Sheltered Car Park. Van Was Bought By The Company Brand New er) From The Car Company (1st Owner).

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	270X
Vehicle Details	
/ehicle No.:	GBF6885T
/ehicle to be Exported:	No
ntended Deregistration Date:	06 Sep 2019
/ehicle Make:	NISSAN
/ehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR ES W/RC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	K9KC400D056214
Chassis No.:	VSKYBAM20Z0137273
Maximum Power Output:	
Open Market Value:	\$20,261.00
Original Registration Date:	17 Feb 2017
First Registration Date:	17 Feb 2017
Transfer Count:	0
Actual ARF Paid: ntended PARF Rebate Details	\$1,014.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: ntended COE Rebate Details	\$0.00
COE Expiry Date:	16 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$47,489.00
COE Rebate Amount:	\$35,362.00
Total Rebate Amount:	\$35,362.00

The information contained herein is correct as at 06 Sep 2019

ОК

### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	04/09/2019 11:17
Date Of Accident	03/09/2019 19:15
Exact Location Of Accident	AYE TOWARDS JURONG
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBF6885T
Insured/Policyholder	
Name Of Registered Owner	KRYSGMAN VINCE
Co Reg No	5XXXX270X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90052480
Vehicle Particulars	
Manufacturer	NISSAN
Model	UV200
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107097106
Cover Note Number	
Driver	
Name of Driver	ONG CHEE HWA
NRIC No	SXXXX545C
Date Of Birth	30/06/1963
Occupation	OUTDOOR
Date Of Driving Pass	16/05/1981
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90052480

NOEMAIL

Address

BLK 70 REDHILL CLOSE

#28-88

Postcode

150070

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: NA

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBB837T

Vehicle Make/Model/Colour

Details Of Properties

REFER ATTACHED

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

KARUPPLAH KARUVA PANDI

NRIC/Passport Number

GXXXX054R

Contact Number

82422762

Address

Postcode

Insurance Company Name

Nature Of Damage

REFER ATTACHED

# No. Of Passenger (Including Driver)

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLX2246B

Vehicle Make/Model/Colour

**Details Of Properties** 

REFER ATTACHED

Vehicle Category

PRIVATE CAR

Name of Driver

LI CHENGYU

NRIC/Passport Number

LICILIVOIO

Contact Number

SXXXX986D

50,....

Address

Postcode


Insurance Company Name

Nature Of Damage

REFER ATTACHED

No. Of Passenger (Including Driver)

# Sketch Plan Pg. 1



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along ATE at the 3rd Lane from the wat the direction towards surang in between North Buona Vista and Clementi, there was heavy traffic and all vehicles were moving at Slow Speed. The forry (GBB 85 Suddenly band into the back of my vehicle (GBF 6885 Causing badly damage to the back of my vehicle.	
at the direction towards surang in between North Buona Vista and Clementi, there was heavy traffic and all vehicles were moving at Slow Speed. The Horry (GBB 85 Suddenly band into the back of my vehicle (GBF 6885 causing badly damage to the back of my vehicle.	ng along ATE at the 3rd Lane from the lef-
Vista and Clementi, there was heavy traffic and all vehicles were moving at Slow Speed. The torry (GBB 83 Suddenly band into the back of my vehicle (GBF 6885 causing badly damage to the back of my vehicle.	on towards Jurang in between North Buona
Vehicles were moving at slow speed. The torry (GBB 85 Suddenly band into the back of my vehicle (GBF 6885 Causing badly damage to the back of my vehicle.	lementi, there was heavy traffic and all
Suddenly band into the back of my vehicle (GBF 6885 causing badly damage to the back of my vehicle.	moving at Slow Speed. The torry (GBB SETT
causing badly damage to the back of my vehicle.	I into the back of my vehicle (GBF 6885T
	damage to the back of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GIARMC SkerchPlanForm\_V3

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  Interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Vehicle:

GBF6885T

Not Authorian

Mare 6340.60 Make & Model: Nissan NV200

Chassis No: VSKYBAM20Z0137273

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Tailgate (Left)			1381.10N	30Gm -
2	Rear Tailgate (Right) 960.60			1,160.90N	5019 20 -
3	Rear Tailgate Hinge (Right)			125.00N	a1X
4	Rear Left Tailgate Inner Lock (Lower)			135.00N	1w1 -
5	Rear Right Tailgate Inner Lock (Lower)			135.00N	7~1
6	Rear Tailgate Left center Rubber			102.00N	cu1/
7	Rear Tailgate weather strip			125.00N	17 X
8	Rear Tailgate Left Handle Moulding			185.00N	17 X
9	Nissan Emblem			95.60N	ru /
10	"NV200" Plate 7 9.9 )			90:50N	su -
11	"dCi" Plate			70.90N	m/
12	"70KM/H" Sticker		+	10.00SN	ner / s. n nu / s
13	"5 Pax" Sticker		*	10.00SN	m/s.
14	Number Plate With Casing			45.00SN	su x
15	Right Rear Tail Lamp 25 2-10			\$ 282.10	cre/
16	Rear Bumper 624. F			684.80N	m/se/
17	Rear Bumper Retainer	2	90.40N	180.80N	11 %
18	Rear Bumper Clip		*	30.00SN	m/s.
19	Reverse Sensor	1set	*	200.00SN	shell s.
20	Rear Bumper Reflector (Right)			62.00N	CA9/
21	Rear Glass Sealant (Left)		A	40.00SN	M / 5. N
22	Rear Glass Sealant (Right)		*	40.00SN	m / s.n
23	Rear Glass Sealant (Left & Right)			100.00SN	Repeated

24	Rear End Panel			284.00N	RX
25	Rear Bumper Inner Sponge			165.00N	RX 7011
26	Rear End Panel Garnish			160.00N	nnx
27	Wiper Arm		107	135.00N	su -
28	Wiper Motor	1	6	350.00N	11 X  54 -  54/5m -  7m -  11 X
29	Left Rear Tailgate Lock Mechanism			285.00N	Jm /
30	Rear Tailgate Inner Trim Board Chips			40.00SN	11X
31	Rear Right Tailgate Sport Plate			30.00SN	лел /s
32	Hello Kitty Emblem			30.00SN	11 X
33	Left & Right Tailgate Chrome Moulding	2		30.00SN	M - S.A
34	Rear Right Taillamp Chrome Garnish			80.00SN	11 ×
7					
					P-4734
					102
					P 4260.60 N 390.00
				, . L	1690.00
					6340.60

		Labour			
1	Transfer Tailgate Fitting	2	\$ 100.00	\$ 200.00	100
2	Tranfer Tailgate Glass	2	\$ 120.00	\$ 240.00	160
3	Interior Upholstery			\$ 120.00	111
4	Check Wiring			\$ 100.00	20
5	Anti Rust Proofing			\$ 120.00	60
6	Paint Work			\$ 1,200.00	750
7	Panel Beating			\$ 900.00	600
8					1690

9140,23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- » To display damaged part(s) during resurvey
- » Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

1000		A Part of the Control	nationale Des Experts En Autom	
UNIT	ED OVERSEAS I	NSURANCE LTD	Ref : CS/UOI190157	40/Usd3n2
	SON ROAD #28-0 NGLEAF TOWER	01 R SINGAPORE 079909	Date: 16-09-2019 Code: UOI2	
1.		Policy Particula	ars :- THIRD PARTY CLAI	M
	Insured Veh.	GBB 837T	Veh. Inspected	GBF 6885T
	Policy No.	DHOM110169741900	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	PHILIS	Assign Date	05/09/2019
2.		Vehicle Pa	articulars & Condition	The state of the s
	Make & Model	NISSAN NV200 (M)	c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	VSKYBAM20Z0137273	Colour	WHITE
	Odometer	58519	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	DUNLOP	6 mm
	L/H Front Tyre	175/70 R14	DUNLOP	6 mm
	R/H Rear Tyre	175/70 R14	DUNLOP	6 mm
	L/H Rear Tyre	175/70 R14	DUNLOP	6 mm
4.	A DESCRIPTION OF THE PERSON NAMED IN	Descr	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	NEW WALLES
	Accident Date	03/09/2019	Inspection Date	05/09/2019
	Survey held at	STYTECH AUTO PTE LTD		
		2 KAKI BUKIT AVENUE 2 #0 KAKI BUKIT AUTOHUB SINGAPORE 417921	02-30	
5a.			Remarks	
		ON WAS CONDUCTED ON A"		
5b.			ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Day	18



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 6885T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS		1	
1	REAR TAILGATE (LEFT)(N)	BADLY DENTED	1,381.10	1,281.10
1	REAR TAILGATE (RIGHT)(N)	BADLY DENTED	1,160.90	960.60
- 1	REAR TAILGATE HINGE (RIGHT)(N)	NOT NECESSARY	125.00	
1	REAR LEFT TAILGATE INNER LOCK (LOWER)(N)	TWISTED	135.00	135.00
1	REAR RIGHT TAILGATE INNER LOCK (LOWER)(N)	TWISTED	135.00	135.00
1	REAR TAILGATE LEFT CENTEE RUBBER (N)	CUT	102.00	102.00
1	REAR TAILGATE WEATHER STRIP (N)	NOT NECESSARY	125.00	0.
1	REAR TAILGATE LEFT HANDLE MOULDING (N)	NOT NECESSARY	185.00	
1	NISSAN EMBLEM (N)	NECESSARY	95.60	95.60
1	"NV200" PLATE (N)	NECESSARY	90.50	79.90
1	"DCI" PLATE (N)	NECESSARY	70.90	70.90
1	RIGHT REAR TAIL LAMP (N)	CRACKED	282.10	252.10
1	REAR BUMPER (N)	DENTED / DEFORMED	684.80	624.80
2	REAR BUMPER RETAINER @\$90.40 (N)	NOT NECESSARY	180.80	
1	REAR BUMPER REFLECTOR (RIGHT)(N)	CRACKED	62.00	62.00
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	284.00	3
1	REAR BUMPER INNER SPONGE (N)	TORN	165.00	165.00
1	REAR END PANEL GARNISH (N)	NOT NECESSARY	160.00	10-
1	WIPER ARM (N)	BENT	135.00	135.00
1	WIPER MOTOR (N)	BENT / JAMMED	350.00	350.00
1	LEFT REAR TAILGATE LOCK MECHANISM (N)	JAMMED	285.00	285.00
	LESS 10% DISCOUNT	294.700.47 most = 3	-619.47	-473.40
			5,575.23	4,260.60
	SPECIAL NETT ITEMS			31.30.00
1	NUMBER PLATE WITH CASING (SN)	SERVICEABLE	45.00	
1	"70KM/H" STICKER (SN)	NECESSARY	10.00	10.00
	"5PAX" STICKER (SN)	NECESSARY	10.00	1,000
	REAR BUMPER CLIP (SN)	NECESSARY	30.00	
	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
	REAR GLASS SEALANT (LEFT)(SN)	NECESSARY	40.00	40.00
	REAR GLASS SEALANT (RIGHT)(SN)	NECESSARY	40.00	
	REAR GLASS SEALANT (LEFT & RIGHT)(SN)	REPEATED	100.00	N-583737.83

Report Ref No. CS/UOI19015740/Usd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE INNER TRIM BOARD CHIPS (SN)	NOT NECESSARY	40.00	-
1	REAR RIGHT TAILGATE SPORT PLATE (SN)	NECESSARY	30.00	30.00
1	HELLO KITTY EMBLEM (SN)	NOT NECESSARY	30.00	-
2	LEFT & RIGHT TAILGATE CHROME MOULDING (SN)	NECESSARY	30.00	30.00
1	REAR RIGHT TAILLAMP CHROME GARNISH (SN)	NOT NECESSARY	80.00	-
	× e		685.00	390.00
	LABOUR			
	TRANSFER TAILGATE FITTING.		200.00	100.00
	TRANSFER TAILGATE GLASS.		240.00	160.00
	INTERIOR UPHOLSTERY.	NOT NECESSARY	120.00	
	CHECK WIRING.		100.00	20.00
	ANTI RUST PROOFING.		120.00	60.00
	PAINT WORK.		1,200.00	750.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		900.00	600.00
			2,880.00	1,690.00
	GRAND TOTAL		9,140.23	6,340.60
867	RECOMMENDED COST OF REPAIRS		SAMPLE PARTY	6,340.60

Report Ref No. CS/UOI19015740/Usd3n2

CHUA KANG SENG

Licensed Appraiser