



Your Ref: 2790074781SG-003

Date: 02nd October 2019

Our Ref: CS1/AIG19015750/Htd3s2

M/s AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16
Chartis Building
Singapore 079120

Attn: Bennie Tan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJF 770K
INSURED VEHICLE: SDT 1088M ACCIDENT DATE: 26/06/2018**

We thank you for your instruction on 04/09/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJF 770K from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles SJF 770K and SDT 1088M.
- c) Damaged vehicle photographs of SJF 770K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJF 770K
Make & Model	: Mercedes Benz C200
Year of Registration	: 2008
Chassis Number	: WDD2040412A114195
Engine Capacity	: 1796 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.