



Your Ref: SNM18D03364C02

Date: 10th Sep 2019

Our Ref: CS1/CTI19015776/Esd3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLN 4203P
INSURED VEHICLE: SKA 519K
ACCIDENT DATE: 05/07/2018**

We thank you for your instruction on 04/09/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLN 4203P from M/s Sincere Appraisal Services Pte Ltd.
- b) Final Repair Bill of SLN 4203P from M/s Horizon Auto Tuners Pte Ltd.
- c) Singapore Accident Statement of Vehicles SLN 4203P, SKA 519K and GBG 316D.
- d) Police Report of Vehicles SLN 4203P.
- e) Colour damaged vehicle photographs of SLN 4203P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLN 4203P
Make & Model	: Volkswagen Polo GTI 1.4 A
Year of Registration	: 2012
Chassis Number	: WWZZZ6RZCY541720
Engine Capacity	: 1390 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.