

22/03/2002

A.S. REC. BY:

REF:

CS/MSG19015797/GCF302

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person):

Paulin Tham

of

MSG

Date/Time:

5.9.19 16.58p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 7333Y

Insured:

SDG 362

at Workshop m/s

D'S Graffiti Concept

Tel:

8 6083456

of

25 Kaki Bukit Road 4 #06-26

Policy No:

605183

Claim No:

287988053MF

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4-9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

6.9.19 10.30am

Person Contacted:

stori

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SDG 362 : X
	SKV 7333Y : X
09/09/19	@ 14:35 pm checked with Steve, no estimate
	Dismantle: 9/9/2019
	After repair: 17/9/2019.

PRS
bul.

REF: MSIG

ASSIGNMENT

C-2022)
26 Apr 2007

From: Date 6.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 7333Y
at Workshop m/s D's Grafty Concept
of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 86083456

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COB: 13213

\$ 7000 - \$ 8000

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: PRS

Lump Sum / I.B.I: (\$

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

120

11

131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019 16:07		05 Sep 2019 16:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by insurer]																					
Insured:	TAN BEE HOON WINNIE, ID: S1423757G																							
Main Claimant:	AKA ZEN, Co. Reg. No.: 53321846B																							
Vehicle Reg. No.:	SKV7333Y	Date of Loss:	04/09/2019 00:00 - :59 [148 Months and 9 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP	Policy/Cover Note No.:	28798825SMF (Comprehensive) Coverage: 20/07/2019 - 19/07/2020																					
Vehicle Reg. No. (Insured):	SDE36Z	Policy No. (Claimant):																						
		Excess:																						
Repairer:	D's Graffiti Concepts (HQ) 25 Kaki bt Road 4 #06-26 Synergy @ KB, 417800 Kaki Bukit - Tel:																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/09/2019]																							
Adj Asg. Remarks:	on WP. Liab: NR. Disagree on SJE. Contact: Mr Dave @ 8608 3456. Address of Workshop: Block C Kaki Bukit Avenue 6 #01-59 Kaki Bukit Autobay, Singapore 417883.																							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
There are no mail for this case.																								
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> View All Search Tasks Create New Task Complete </div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Business
Owner ID:	846B
Vehicle No.:	SKV7333Y
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	3ZZ4633826
Chassis No.:	MR053ZEC107142321
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	26 Apr 2007
First Registration Date:	26 Apr 2007
Transfer Count:	2
Actual ARF Paid:	\$16,891.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	25 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,115.00
COE Rebate Amount:	\$13,213.00
Total Rebate Amount:	\$13,213.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Sep 2019

OK

▶ Altis Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Corolla Altis 1.6A (COE till 07/2022)	\$19,900	\$7,000 /yr	13-Jul-2007	1,598 cc	104,241 km	Swee Watt Motor Trading	Available
(We Assure 100% Genuine Mileage), Very Good Condition, Low Depreciation, New Road Tax Till 12/01/2020. Office No. - 63441932 Ms Ivy - 97370832 Mr Ang - 98320832							
Toyota Corolla Altis 1.6A (COE till 10/2022)	\$17,500	\$5,670 /yr	10-Oct-2007	1,598 cc	-	Boeki Auto Pte Ltd	Available
Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only. Office No. - 67555005 Boeki - 82180500							
Toyota Corolla Altis 1.6A Elegance (COE till 04/2023)	\$26,800	\$7,480 /yr	08-Apr-2008	1,598 cc	148,000 km	Creative Auto	Available
1 Owner Only Through Out 11 Years! Meticulously Well Maintained Unit Assured! Low Mileage Done! Guaranteed Accident Free! With Most Wear And Tear Parts Replaced! Buy With Assurance On This Market Most... Office No. - - Jeff Huang - 88180344 Alex Tan - 97556887 Terence Leow - 90290899							
Toyota Corolla Altis 1.6A (COE till 04/2023)	\$26,800	\$7,470 /yr	11-Apr-2008	1,598 cc	138,565 km	Happy Motoring Pte Ltd	Available
100% Loan Available, Unbelievably Good Condition Inside Out! Excellent Fuel Efficiency, Easy Maintenance, Reliable Built, Car Available In Showroom For Viewing Now. Contact For More Details Before It!... Office No. - 68442228 Sham - 84228768 Toh - 81388352 Khoo - 96803004							
Toyota Corolla Altis 1.6A (COE till 11/2027)	\$42,800	\$5,200 /yr	17-Apr-2008	1,598 cc	95,000 km		Available
The Condition Of The Car Is Very Good As I Have Serviced It Regularly. The Mileage Is Only 95000km Because It Is Seldom Used. Office No. - - Chng Song Beng - 82686542							
Toyota Corolla Altis 1.6A (COE till 04/2023)	\$24,500	\$6,770 /yr	22-Apr-2008	1,598 cc	-	Corsica Trading	Available
Excellent Condition, No Repairs Needed, Sports Rims, Leather Seats, Pioneer DVD Player With Reverse Camera And Sensor, In House Loan Available. Office No. - 67775005 Woo Kok Wah - 90086666 Kelvin Goh - 96786666							
Toyota Corolla Altis 1.6A (COE till 04/2023)	\$23,800	\$6,540 /yr	29-Apr-2008	1,598 cc	88,257 km	Bz Carz Pte Ltd	Available
Guaranteed You This The Best Condition You Can Find In The Market! All Time Favourite Toyota Sedan! One Of The Top Class Of Its Category! Not A Single Scratch On The Outside! Spectacular Shiny Origina... Office No. - - Mr Ang - 92233102 Mr Liang - 88768886							
Toyota Corolla Altis 1.6A (COE till 05/2023)	\$25,000	\$6,760 /yr	20-May-2008	1,598 cc	154,000 km	360 VR Cars	Available
Low Mileage Unit, Interior Leather Seats Rewrapped! As Good As New! All Wear And Tear Done Up, No Repairs Needed. Very Well Maintained. Trade In, Flexible Loan Available, Call Now! Viewing By Appointm... Office No. - 69310005 Pauline - 96211963 James Tan - 90700005							
Toyota Corolla Altis 1.6A (COE till 06/2023)	\$28,800	\$7,580 /yr	27-Jun-2008	1,598 cc	190,000 km	Otua Auto Pte Ltd	Available
Consignment Code: A205. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please D... Office No. - - Stedtsen Koh - 97869900 Francis Chen - 87539539							

Toyota Corolla Altis 1.6A (COE till 10/2023)	\$26,800	\$6,570 /yr	07-Oct-2008	1,598 cc	105,753 km	Creative Auto	Available
Loan Amount Stated! Showroom Condition With Beautiful Paintwork/Well Kept Interior. Low Mileage Done! Guaranteed Accident Free With Smooth Running Engine And Transmission. Reliable Yet Easy To Maintai...							
Office No. - -							
Francis Yao - 93275727 Alex Tan - 97556887 Terence Leow - 90290899							
Toyota Corolla Altis 1.6A (COE till 10/2023)	\$29,800	\$7,270 /yr	14-Oct-2008	1,598 cc	116,000 km	FredLink Auto Trading	Available
Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.							
Office No. - 67788997 / 67788995							
Daniel Loh - 83938889 Mohammad - 81121493 Freddy Lee - 96923373							
Toyota Corolla Altis 1.6A (COE till 12/2023)	\$26,888	\$6,310 /yr	12-Dec-2008	1,598 cc	-	ABWIN (1994) Pte Ltd	Available
100% Loan And Trade In Welcome! New Paintwork! No Repairs Needed At All! Guaranteed Satisfaction! Excellence Condition! PHV Welcome! Don't Wait! Contact Our Friendly Sales Representative For Viewing N...							
Office No. - 68416666							
Tony Lee - 90065775 Ah Hwee - 86663444							
Toyota Corolla Altis 1.6A (COE till 02/2029)	\$46,800	\$4,970 /yr	03-Feb-2009	1,598 cc	-	Mandai Motor Trading	Available
Reliable, Economical, Low Maintenance And Easy On Fuel. Well Known For Family Car. Low Maintenance And Easy On Fuel. Flexible Loan Arrangement! Trade In Welcomed. Hurry Call Our Friendly Sales Today T...							
Office No. - 67775585							
Mr Chong - 93513956 Heng Heng - 90058812 Sharon Toh - 81395235 Mr Ee - 96275585							
Toyota Corolla Altis 1.6A (COE till 03/2024)	\$28,500	\$6,320 /yr	13-Mar-2009	1,598 cc	-	Precise Auto Trading Pte Ltd	Available
Full Loan Available At \$640 Monthly, Interest From 3.18%. Bank Loan And In House Loan Available. Vehicle Checked By In House Workshop. Trade In Welcome.							
Office No. - -							
Wei Quan - 97713559 Marcus Ong - 94897930 Feng - 91153492							
Toyota Corolla Altis 1.6A (COE till 03/2029)	\$59,000	\$6,170 /yr	01-Apr-2009	1,598 cc	142,000 km	Otua Auto Pte Ltd	Available
Consignment Code: A346. Flexible And Attractive Loan Available. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact...							
Office No. - -							
Stedtson Koh - 97869900 Francis Chen - 87539539							
Toyota Corolla Altis 1.8A (COE till 02/2029)	\$44,800	\$4,720 /yr	06-Apr-2009	1,794 cc	-	Karz Enterprise	Available
Rare 1.8L In The Market.100% Loan Available. No Repair Required As Previous Retired Lady Owner Changed All The Under Carriage Parts Also Change Aircond Compressor & Condenser And Many More.Road Tax Ti...							
Office No. - -							
Alan - 82778188 Kelvin - 82000108							
Toyota Corolla Altis 1.6A (COE till 04/2024)	\$30,200	\$6,510 /yr	28-Apr-2009	1,598 cc	134,440 km	EU Automobile Pte Ltd	Available
COE Up Trend, Buy Now Or Pay More For The Same Car Next Month! Full Restored New Parts With Proven Receipts. New Paintwork. Trade In, Loan Available. Call/text Now For More Info!							
Office No. - 67771515							
Dalton - 86008130 Louis - 86282886 Patrick - 98593180							
Toyota Corolla Altis 1.6A (COE till 04/2024)	\$33,800	\$7,270 /yr	06-May-2009	1,598 cc	85,000 km	Victory Cars Trading Pte Ltd	Available
Well Maintained, Low Genuine Mileage Done. Well Maintained, Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emerg...							
Office No. - 63854916							
Mr Quek - 90096473 Mr Lee - 86885879 Mr Tan - 90999505							
Toyota Corolla Altis 1.6A (COE till 05/2024)	\$31,000	\$6,600 /yr	19-May-2009	1,598 cc	160,000 km	Inchcape Pre-Owned	Available
Low Risk Purchase, An Ideal Option For Daily Commute. Call Our Sales Consultants For A Viewing Now!							

Office No. - 63036303

Jj Chua - 90037428 | Kelvin Kee - 98719789 | Jason Tan - 98882000 | Chris Tang - 81683557

Toyota Corolla Altis 1.6A (COE till 05/2024)	\$30,800	\$6,550 /yr	21-May-2009	1,598 cc	144,820 km	Inchcape Pre-Owned	Available
---	-----------------	--------------------	--------------------	-----------------	-------------------	---------------------------	------------------

Well Maintained Unit. Low Mileage To Go With! Spacious And Fuel Eco Unit In The Market! Please Call Our Sales Consultant For More Enquiries Now!

Office No. - 63036303

Jj Chua - 90037428 | Kelvin Kee - 98719789 | Chris Tang - 81683557 | Jason Tan - 98882000

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please read the following information carefully before completing this form.
2. This form is to be filled out by the driver of the vehicle involved in the accident.
3. Information on this form will be used by the police and insurance companies.
4. Any false reporting may be referred to the police for investigation.
5. This form is to be filled out by the driver of the vehicle involved in the accident.
6. This form is to be filled out by the driver of the vehicle involved in the accident.
7. This form is to be filled out by the driver of the vehicle involved in the accident.

ACCIDENT STATEMENT

Date (DD/MM/YYYY) 01/09/2019 11:11
 Date of Accident 01/09/2019 09:00
 Exact Location of Accident LAMPOH 1, LESTER ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number RMV 7311Y
Insured/Policyholder
 Name of Registered Owner AKA ZEN
 Tel. No. 533218460
 Email Address NOEMAIL
 Mobile No. 98300189
 Office No. 98300189
Vehicle Particulars
 Manufacturer TOYOTA
 Model COROLLA ALTIS 1.6 AUTO
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5990659774-02
 Driver Note Number
Driver
 Name of Driver LEE LIN PYNG
 NRIC No. 984072152
 Date Of Birth 11/03/1984
 Occupation OUTDOOR
 Date Of Driving Pass 12/01/2005
 Driving Experience 14 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98300189
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 432A #08-603 SENGKANG WEST WAY FERNVALE PALMS
 Postcode 791432
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - OWN COMPANY
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting offering accident claims assistance. NO
 Number of Passengers (including Driver) 2
 Passenger 1
 NAME: GRAB PASSENGER
 GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TAMPINES NORTH NPP
 Police Station Address ROAD: 461 TAMPINES ST 44 #01-55 POSTCODE: 520461, COUNTRY SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT NO.T/20190904/2068;

Attachments

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH DRIVER-CAPTURE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDE36Z
 Vehicle Make/Model/Colour AUDI / A8 AVANT 1.8 TFSI (PI) (17" WHEELS)
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLM2814U
Vehicle Make/Model/Colour TOYOTA/VIOS 1.5E CVT
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LEE LIN PYNG
Approximate Age 35
Injuries Sustain
Injured person in which vehicle? SKV7333Y
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address BLK 432A #08-503 SENGKANG WEST WAY FERNVALE PALMS
Postcode 791432

Accident Sketch Plan

SKETCH PLAN



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to question policy validity.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that exist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time


04 SEP 2019

IDAC KAKE BUKIT (YAG)

Supporting Centre for Insurance Claims
Name: Singapore 412933
MUC/Hub: 67414697 Fax: 67492305
Email: yachib@insnet.com.sg

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Police Officer's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

04 SEP 2019

IDAC KAKI BUKIT (VAC)

33 Jalan Bukit Timah

SINGAPORE 259333

Phone: 67416497 Fax: 67492305

Email: enquiry@idac.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Sep 2019 16:07		05 Sep 2019 16:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN BEE HOON WINNIE , ID: S1423757G									
Main Claimant: AKA ZEN , Co. Reg. No.: 53321846B									
Vehicle Reg. No.: SKV7333Y		Date of Loss: 04/09/2019 08:00 - :59 [148 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 605183		Policy/Cover Note No.: 28798805SMF (Comprehensive) Coverage: 20/07/2019 - 19/07/2020							
Vehicle Reg. No. (Insured): SDE36Z		Policy No. (Claimant):							
		Excess: S\$1,500.00							
Repairer: D's Graffiti Concepts (HQ) 25 Kaki bt Road 4 #06-26 Synergy @ KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 06/09/2019]									
Adj Asg. Remarks: on WP. Liab: NR. Disagree on SJE. Contact: Mr Dave @ 8608 3456. Address of Workshop: Block C Kaki Bukit Avenue 6 #01-59 Kaki Bukit Autobay, Singapore 417883.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents























































*SKV7333Y (605183)
[SDE36Z]
TP
AKA ZEN
Sep 4 2019 8:00AM
[TAN BEE HOON WINNIE]
D's Graffiti Concepts




















































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print
1	10/09/19 19:19	Accident Statement <small>From:OD - Reg. No: SDE36Z, Claimant: WINNIE TAN BEE HOON</small>	 Load HTM	1	<input type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
2	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
3	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
4	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
5	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
6	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
7	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
8	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
9	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
10	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
11	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
12	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
13	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
14	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
15	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
16	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
17	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
18	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
19	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
20	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
21	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
22	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
23	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
24	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
25	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
26	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
27	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
28	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
29	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
30	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
31	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
32	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
33	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
34	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
35	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
36	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
37	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
38	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>
39	16/09/19 13:40	General View	 Load JPG	1	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
40	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
64	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
65	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
66	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
67	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
68	16/09/19 13:40	General View	 Load JPG	<input checked="" type="checkbox"/>
69	16/09/19 13:41	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
70	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	16/09/19 13:41	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
95	16/09/19 13:41	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
96	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
121	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
122	16/09/19 13:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
123	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
138	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
141	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
142	19/09/19 12:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/09/19 16:26	TP SKV7333Y GIA REPORT	 Load PDF	
2	04/09/19 16:29	PRI	 Load PDF	
3	05/09/19 14:53	Disagree on SJE	 Load PDF	
4	05/09/19 14:53	Noted that workshop address different from Merimen System	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19015797/GCF3E2

Date: 20/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28798805SMF

Claimant**Vehicle No :** SKV7333Y**Insured Vehicle No :** SDE36Z

Date of Loss: 04/09/2019

Nature of Claim: TP

Claim No: 605183

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKV7333Y**

Make & Model: TOYOTA COROLLA, 1.6 (A)

Engine No: 3ZZ4633826

Reg. Date: 26/04/2007 (Man. Year: 2006)

Chassis No: MR053ZEC107142321

Colour: Black

Odometer: 300408 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/09/2019

Date Inspected: 06/09/2019 Inspected At:

D's Graffiti Concepts (HQ)

25 Kaki bt Road 4 #06-26 Synergy @

KB

Singapore 417800

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2019)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV7333Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >