

22/03/2019

ASS. REC. BY:

REF:

CS/SMO/19015799/KLF302

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Tholma Choo

of

SMO

Date/Time:

6.9.19 11.54a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8891D

Insured:

FBP 9119A

at Workshop m/s:

Chew Goon Motor (AMK)

Tel:

64441626

64841976

of Blk 10 Ang Mo Kio Industrial Park 2A #10-15/16 & 17

Policy No:

D19MTMCO1006261

Claim No:

CMTD1904215

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/08/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

6.9.19 1.53p.m

Person Contacted:

Kelly

H.O.D. Endorsement:

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

FBP 9119A: X

SLD 8891D: CCE/AIG/MOB37R/KND392 D.O.A. 25/07/2019

9/9-

Revised via messenger.

10/10

61 Lm @ 56501 email unconfirm

ASS. REC. BY:

REF:

Jmo/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8686

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLD 88910 Yr Regn: 04, 13
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or A Wagon
Make: Volkswagen Sharan cc 1984

Colour: M. Brown A/C: Insured / Std / NI / NA

Sp. Reading: 87021 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WLV 222 7NBDV 026205

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 8 mm

Rear R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 30/8/19

D.O.I. 6/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear n/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

26/2- check with Kelly they not accept. Submit own figure.

RECEIVED 2 MAR 2020

Date/Time, File Pass to?

213 Typist

Date/Time, File Return to?

☐ : Prell. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 350

Transportation: S + RS. \$

Fuel

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 5650

361

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 09 Sep 2019

Preliminary Advice

Insured Vehicle No	: FBP9119A		
TP Vehicle No	: SLD8891D	Accident Date	: 30/08/2019
Make	: VOLKSWAGEN SHARAN	Assignment Date	: 06/09/2019
Date of Inspection	: 06/09/2019	Est. Duration of Repair	: 4.00
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,553.30
Revised Amount	:S\$	9,535.90
Check Items (Estimated)	:S\$	529.20
Total	:S\$	10,065.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Twisted	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Auth'd	Status
Main	05 Sep 2019		06 Sep 2019 11:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AMEERUL NA'LM BIN AMIRUDEEN ALIAS SABARUDIN, ID: T0030531B, Tel: +6587985367, Email: AMEERULNAIM0030@GMAIL.COM								
Main Claimant:	LEONG DARYL NOEL, ID: S8851053D								
Vehicle Reg. No.:	SLD8891D	Date of Loss:	30/08/2019 09:00 - :59						
Claim Type:	TP / CMTD1904215	Policy/Cover Note No.:	D19MTMC01006261 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBP9119A	Policy No. (Claimant):							
		Excess:							
Repairer:	Chew Goon Motor (AMK) Bldg 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2019]								
Driver/Custodian (Insured):	AMEERUL NA'LM BIN AMIRUDEEN ALIAS SABARUDIN (18 / Male), NRIC: T0030531B, Tel: +6587985367 Email: AMEERULNAIM0030@GMAIL.COM								
Adj Asg. Remarks:	KELLY 64841626								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Kenneth Kong (LKKAUTO)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Thursday, 7 November, 2019 2:30 PM
To: Kenneth Kong (LKKAUTO)
Subject: RE: Veh No: SLD8891D ; Acc date: 30.08.2019

Dear Kenneth,

We propose lumpsum \$ 8,050.00.

Thanks & Regards,
Kelly

Chew Goon Motor

Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Sent from Mail for Windows 10

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Wednesday, October 23, 2019 10:59:18 AM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: RE: Veh No: SLD8891D ; Acc date: 30.08.2019

Dear Kenneth,

We have reaffirm the listed price with Kian Hua.
Attached for your persusal.

We propose lumpsum \$ 8,050.00.

Thanks & Regards,
Kelly

Chew Goon Motor

Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Sent from Mail for Windows 10

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 053D

Vehicle Details

Vehicle No.: SLD8891D
Vehicle to be Exported: No
Intended Deregistration Date: 10 Sep 2019
Vehicle Make: VOLKSWAGEN
Vehicle Model: SHARAN 2.0 TSI AT 7N14H3
Primary Colour: Brown
Manufacturing Year: 2013
Engine No.: CCZ349235
Chassis No.: VVVZZZ7NZDV026205
Maximum Power Output: 147.0 kW (197 bhp)
Open Market Value: \$40,035.00
Original Registration Date: 16 Apr 2013
First Registration Date: 16 Apr 2013
Transfer Count: 1
Actual ARF Paid: \$48,049.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Apr 2023
PARF Rebate Amount: \$31,231.00

Intended COE Rebate Details

COE Expiry Date: 15 Apr 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$73,900.00
COE Rebate Amount: \$26,583.00
Total Rebate Amount: \$57,814.00

The information contained herein is correct as at 10 Sep 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 053D

Vehicle Details

Vehicle No.: SLD8891D
Vehicle to be Exported: No
Intended Deregistration Date: 30 Aug 2019
Vehicle Make: VOLKSWAGEN
Vehicle Model: SHARAN 2.0 TSI AT 7N14H3
Primary Colour: Brown
Manufacturing Year: 2013
Engine No.: CCZ349235
Chassis No.: WVVZZZ7NZDV026205
Maximum Power Output: 147.0 kW (197 bhp)
Open Market Value: \$40,035.00
Original Registration Date: 16 Apr 2013
First Registration Date: 16 Apr 2013
Transfer Count: 1
Actual ARF Paid: \$48,049.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Apr 2023
PARF Rebate Amount: \$31,231.00

Intended COE Rebate Details

COE Expiry Date: 15 Apr 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$73,900.00
COE Rebate Amount: \$26,808.00
Total Rebate Amount: \$58,039.00

The information contained herein is correct as at 30 Aug 2019

OK

(S)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/08/2019 16:52
Date Of Accident	30/08/2019 09:20
Exact Location Of Accident	TAMPINES EXPRESSWAY TPE (PIE) BEFORE EXIT 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD8891D
Insured/Policyholder	
Name Of Registered Owner	LEONG DARYL NOEL
NRIC No	S8851053D
Email Address	L.DARYLNOEL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97760987
Alternative Phone No	OTHERS-97760987
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	SHARAN 2.0 TSI AT 7N14H3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102784391
Cover Note Number	
Driver	
Name of Driver	LEONG DARYL NOEL
NRIC No	S8851053D
Date Of Birth	21/12/1988
Occupation	INDOOR
Date Of Driving Pass	09/03/2011
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97760987
Fax Number	
Contact Number	OTHERS-97760987
EEmail Address	L.DARYLNOEL@GMAIL.COM

Address	BLK 984B BUANGKOK LINK #18-19
Postcode	532984
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHANGI N.P.C
Police Station Address	ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT NO: T/20190830/2050.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBP9119A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBP9119A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature:
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
KIRIC/PID No.: _____



SINGAPORE POLICE FORCE



T/20190830/2050

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

1 of 4

Report No. T/20190830/2050

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/08/2019 11:35		Vide Report No.: G/20190830/0087		Station Diary No.: 43	
Informant's Particulars					
Name of Informant: LEONG DARYL NOEL			Address: APT BLK 984B BUANGKOK LINK #18-19 SINGAPORE 532984		
ID Type / ID No.: NRIC NO / S8851053D			Contact No.: Home/Office: Mobile: 97760987		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 30	Date of Birth: 21/12/1988	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Account Manager			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 30/08/2019 09:20	Type of Location: Expressway
Location: Along Road 1 TAMPINES EXPRESSWAY TPE (PIE) before exit 1, lamppost 19 Lamp Post Number: 19				
Weather: Cloudy		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBP9119A	Motorcycle	YAMAHA	R15	Red		0
SLD8891D	Car	VOLKSWAGO N	SHARAN 2.0 TSI AT 7N14H3	Brown	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20190830/2050

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

2 of 4

Report No. T/20190830/2050

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SLD8891D	NTUC Income Insurance Co-Operative Limited	5102784391	01/08/2018	15/10/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEONG DARYL NOEL		ID No. S8851053D
Related Vehicle	SLD8891D (Car)		Contact No. 97760987
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3A Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 30/08/2019 at 0920hrs, I was driving my brown colored Volkswagon car bearing the registration plate number SLD8891D along TPE towards PIE exiting TPE near to exit 1. At that point of time, there was a silver colored Mercedes car that was travelling ahead of my car.

Suddenly, the silver colored Mercedes car swerved his car to the left side, I then applied brake immediately and managed to stop my car on time to avoid collision with the silver mercedes. Subsequently, I felt an impact from the rear of my car. I then alighted and make a check and found out that a red and black colored Yamaha R15 (FBP9119A) had collided onto my car rear left portion with his motorcycle front portion. The motorcyclist was already lying on the road behind my car.

I have an in car camera installed in my car and was recording at that point of time.

I also make a check and found out that there was an accident that took place between a red colored Audi car (SMC2030E) and a blue motorcycle (FBP7953X) just in front of the silver mercedes car.

The other driver that was involved in another accident then called for police assistance and a passerby called for ambulance assistance.

Later traffic police came to the accident scene and recorded our particulars and also took the in car camera footage from my car. Amulance also came and attended to the 2 motorcyclists involved in the accident and both of them was conveyed conscious to the nearest hospital.

Due to the collision, my car left rear portion suffered scratches and the rear left lights were broken and there was slight dent.



**SINGAPORE
POLICE FORCE**



T/20190830/2050

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

3 of 4

Report No. T/20190830/2050

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190830/2050

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

4 of 4

Report No. T/20190830/2050

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 2 ALVIN TAY MING WEI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI
Contact No.: 65476904

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
30/08/2019 11:35

Classification Of Case:

SIGNATURE

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: S102784391

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SLO8891D**
Chassis Number : **WVWZZZ7NZDV02620S**
2. Name of Policyholder : **LEONG DARYL NOEL**
3. Effective Date of Insurance : **01 Aug 2018**
4. Expiry Date of Insurance : **15 Oct 2019**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: LEONG DARYL NOEL
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: HL BANK
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Agency : THIS MARKETING INSURANCE AGENCY (00000572208)
Date of Issue : 01 Aug 2018 11:49 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
61 Day @ \$650k
Recovery After Pain
4 days Third Party

To: Sompo Insurance Singapore Pte Ltd

Policy No: _____

06.09.2019

Date: _____

ACCIDENT DATE : 30.08.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Volkswagen Sharan" Reg. No. SLD8891D Claiming Against Your Insured Veh. No. FBP9119A			
1pc	Rear Bumper <i>1024.10</i>	<i>9</i> 18.00	1,850.00 ✓
10pcs	Rear Bumper Clips		180.00 ✓
1pc	Rear Bumper Bracket LH		68.00 X
1pc	Rear Bumper Sponge <i>199.60</i>		210.00 X
1pc	Rear Bumper Reflector LH <i>72.00</i>		390.00 ✓
1pc	Rear Bumper Core LH		440.00 X
2pcs	Rear Bumper Reverse Sensors	<i>Car</i> 320.00	640.00 ✓
6pcs	Rear Bumper Reverse Sensor Holders <i>@ 55.00</i>	98.00	588.00 ✓
1pc	Rear Bumper Lower Diffuser Cover <i>328.35</i>		1,550.00 ✓
1pc	Rear Bumper Reinforcement		750.00 X
1pc	Taillamp LH <i>526.89</i>		670.00 ✓
1pc	Taillamp Gasket		48.00 ✓
1pc	Tailgate <i>2346.64</i>		2,780.00 ✓
1pc	Tailgate Emblem		170.00 ✓
1pc	Tailgate Badge "Sharan"		140.00 ✓
1pc	Tailgate Badge "2.0"		110.00 ✓
1pc	Tailgate Badge "TSI"		95.00 ✓
1pc	Tailgate Lamp LH		490.00 ✓
1pc	Tailgate Lamp Gasket		38.00 ✓
1pc	Tailgate Auto Lift Sensor		520.00 X
1pc	Rear Wiper Arm Cover		110.00 X
			11,837.00
			1,183.70
			10,653.30
	Less 10%		
1pc	Tailgate Glass Sealant		50.00 SN
1pc	Tailgate Glass Fastener		50.00 SN
			30.00
			150.00
	To Conduct Electrical Check, Replace Reverse Sensors & Reprogram System.		
	To Transfer Tailgate Fitting & Accessories		
		CIF	10,933.30

LKK Auto Consultants hereby notify the Repairer of the following:

- To remedy before/after spray painting
- To display damaged parts during survey
- Part prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No legal modification is allowed
- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 06.09.2019

ACCIDENT DATE : 30.08.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Volkswagen Sharan" Reg. No. SLD8891D Claiming Against Your Insured Veh. No. FBP9119A		
		B/F	10,933.30
	To Dismantle / Refit Tailgate Glass		1201 160.00
	To Reseal Tuff Coating		301 60.00
	Labour Charge - Panel Beating, Repairing Of Taillamp Panel, End Panel Rear N/S Fender & Parts Replacement		4001 600.00
	To Spray Painting Affected Areas		6001 800.00
		Total :	12,553.30

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2019		06 Sep 2019 11:54 Edit Adj Rpt	S\$5,650.00 Edit Estimates	S\$5,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	AMEERUL NA'LM BIN AMIRUDEEN ALIAS SABARUDIN, ID: T0030531B, Tel: +6587985367, Email: AMEERULNAIM0030@GMAIL.COM								
Main Claimant:	LEONG DARYL NOEL, ID: S8851053D								
Vehicle Reg. No.:	SLD8891D	Date of Loss:	30/08/2019 09:00 - :59 [76 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904215	Policy/Cover Note No.:	D19MTMC01006261 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	F8P9119A	Policy No. (Claimant):							
		Excess:							
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/09/2019]								
Driver/Custodian (Insured):	AMEERUL NA'LM BIN AMIRUDEEN ALIAS SABARUDIN (18 / Male), NRIC: T0030531B, Tel: +6587985367 Email: AMEERULNAIM0030@GMAIL.COM								
Adj Asg. Remarks:	KELLY 64841626								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD8891D (CMTD1904215)

[FBP9119A]

TP

LEONG DARYL NOEL

Aug 30 2019 9:00AM

[AMEERUL NA'LM BIN AMIRUDEEN ALIAS SABARUDIN]

Chew Goon Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/09/19 11:20	Adjuster Immediate Advice	Load HTML	
Photos/Images				
			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
2	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
3	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
4	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
5	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
6	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
7	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
15	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
16	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
17	03/03/20 11:22	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page <input type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/19 11:02	Third Party E-filed GIA report(M)	Load PDF	
2	06/09/19 11:55	Pre-Repair Survey - AGREED LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015799/KTF3E2

Date: 03/03/2020

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTMC01006261

Claimant Vehicle No: SLD8891D Insured Vehicle No: FBP9119A

Date of Loss: 30/08/2019 Nature of Claim: TP Claim No: CMTD1904215

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD8891D
 Make & Model: VOLKSWAGEN SHARAN, 2.0 TSI AT 7N14H3 (A) Engine No: CCZ349235
 Reg. Date: 16/04/2013 (Man. Year: 2013) Chassis No: WWWZZZ7NZDV026205
 Colour: Metallic Brown Odometer: 87021 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm
 Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,753.30	5,874.08	4,879.22	45.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,230.00	570.00	31.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,553.30	7,104.08	5,449.22	43.41
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	12,553.30	5,650.00	6,903.30	54.99
+ GST 7.00/7.00% (S\$)	878.73	395.50	483.23	54.99
Nett Amount (S\$)	13,432.03	6,045.50	7,386.53	54.99

INSPECTION

Date of Assignment: 06/09/2019
 Date Inspected: 06/09/2019 Inspected At:

Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2020)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD8891D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	1,850.00 FL	*1,024.10 FL
2	10		*REAR BUMPER CLIPS	Necessary	180.00 FL	*90.00 FL
3	1		*REAR BUMPER BRACKET LH	Serviceable	68.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	210.00 FL	-
5	1		*REAR BUMPER REFLECTOR LH	Cut	390.00 FL	*72.00 FL
6	1		*REAR BUMPER CORE LH	Serviceable	440.00 FL	*- FL
7	2		*REAR BUMPER REVERSE SENSORS	Cut	640.00 FL	*640.00 FL
8	6		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	588.00 FL	*330.00 FL
9	1		*REAR BUMPER LOWER DIFFUSER COVER	Dented/Cut	1,550.00 FL	*328.35 FL
10	1		*REAR BUMPER REINFORCEMENT	Repair	750.00 FL	*- FL
11	1		*TAILLAMP LH	Broken	670.00 FL	*526.89 FL
12	1		*TAILLAMP GASKET	Necessary	48.00 FL	*48.00 FL
13	1		*TAILGATE	Bent	2,780.00 FL	*2,346.64 FL
14	1		*TAILGATE EMBLEM	Necessary	170.00 FL	*170.00 FL
15	1		*TAILGATE BADGE SHARAN	Necessary	140.00 FL	*140.00 FL
16	1		*TAILGATE BADGE 2.0	Necessary	110.00 FL	*110.00 FL
17	1		*TAILGATE BADGE TSI	Necessary	95.00 FL	*95.00 FL
18	1		*TAILGATE LAMP LH	Cracked	490.00 FL	*490.00 FL
19	1		*TAILGATE LAMP GASKET	Necessary	38.00 FL	*38.00 FL
20	1		*TAILGATE AUTO LIFT SENSOR	Serviceable	520.00 FL	*- FL
21	1		*REAR WIPER ARM COVER (MISSING)	Not Consistent With The Impact	110.00 FL	*- FL
22	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
23	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,937.00	6,518.98
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,183.70	644.90
Total Parts (\$\$)	10,753.30	5,874.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK,REPLACE REVERSE SENSORS & REPROGRAM SYSTEM	New	30.00	20.00
2	TO TRANSFER TAILGATE FITTING & ACCESSARIES	New	150.00	60.00
3	TO DISMANTLE/REFIT TAILGATE GLASS	New	160.00	120.00
4	TO RESEAL TUFF COATING	New	60.00	30.00
5	LABOUR CHARGE-PANEL BEATING,REPAIRING OF TAILLAMP PANEL,END PANEL REAR N/S FENDER & PARTS REPLACEMENT	New	600.00	400.00
6	TO SPRAY PAINTING AFFECTED AREAS	New	800.00	600.00
Gross Labour Cost (S\$)			1,800.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >