

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTI Date/Time: 06/09/2019

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJG 4656B Insured: YP 1046Gat Workshop m/s Charn's Customcraft Tel: 6271 7054of BLK 1010 Bukit Merah Lane 3 #01-105Policy No: DMCVSN30001219000 Claim No: SNM19020401+C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

10/09/2019

H.O.D. Endorsement:

Date/Time: 6/09/2019 @ 03:14pm Person Contacted: _____ Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	YP 1046G: X
	SJG 4656B: NS/INC10067906/H1V012 D.O.A: 26/04/2016
14/09/2019	2.26pm checked with Esther (wsp), they still pending liability & the vehicle have not yet repair.
26/9/20 @ 11.08am	sharon lee informed that the vehicle has not repair due to liability not clear.

Signature: *Rasul*

REF: CT1

7722

ASSIGNMENT

WT K/144: 2028/Jan

From: _____ Date: 10-9-2019

Estimated Cost: _____

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SJG 4656B

at Workshop m/s Charn's Customcraft
of Block 1010 Bukit Merah Lane 3 #01-105

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 11:00a.m Owner wahy

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJG 4656B Yr Regn: 2008 / July

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS A C.C. 1497

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 78420 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKRB204503436679

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195 / 55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/08/19 D.O.I. 10/09/19

Survey held at CHARN'S CUSTOMCRAFT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rasul,

Pls check parts prices.

26/3/20 Submit Prelim. report.

RECEIVED 26 MAR 2020

[Signature]
12/9

Date/Time, File Pass to?

☒ Prelim. Report

1) 26/3/2020

☐ Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee: 220

Transportation: _____

\$ + RS. \$

Photos

Others

TOTAL

220

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019		06 Sep 2019 15:05 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	[Created by insurer]		
Main Claimant:	CHIA HOCK TECK, ID: S01637722		
Vehicle Reg. No.:	SJG4656B	Date of Loss:	23/08/2019 12:00 - :59
Claim Type:	TP / SNM19D204014C02	Policy/Cover Note No.:	DMCVSN30001219000
Vehicle Reg. No. (Insured):	YP1046G	Policy No. (Claimant):	5109422787
		Excess:	S\$500.00
Repairer:	Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Rasul (LKKAuto)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Thursday, 26 March, 2020 11:08 AM
To: Rasul (LKKAuto)
Cc: reporting@charnscustomcraft.com.sg
Subject: RE: SJG 4656B DOA : 23/08/19

Hi Rasul,

As mentioned, vehicle not repair as liability not clear.

Kindly close at your end.

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg No: M90367863L
Bus. Reg No: 25151300M

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, March 26, 2020 11:05 AM
To: Charn's Customcraft <charns@singnet.com.sg>
Subject: RE: SJG 4656B DOA : 23/08/19

Hi Esther,

Kindly acknowledge

Best Regards,
Rasul | Assessor

NTUC / China Taping

MN1819111155 / NTUC Income Insurance Co-operative Ltd - HQ
ENTRY DATE & TIME: 23/08/2019 15:34
SUBMITTED BY: Eric Woo

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/08/2019 15:34
Date Of Accident	23/08/2019 12:00
Exact Location Of Accident	BUILDMATE BUILDING - JOO YEE ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJG4656B
Insured/Policyholder	
Name Of Registered Owner	CHIA HOCK TECK
NRIC No	S0163772Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97619646
Alternative Phone No	OTHERS-97619646
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109422787
Cover Note Number	DRIVO PREMIUM
Driver	
Name of Driver	ONG BIAUW KIAT
NRIC No	S2006749G
Date Of Birth	08/12/1954
Occupation	INDOOR
Date Of Driving Pass	26/07/1975
Driving Experience	44 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96896444
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 14 QUEEN ASTRID PARK
Postcode 266806

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : PASSENGER
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I REVERSED MY VEHICLE WHEN VEHICLE B WAS STATIONARY. AS I CONTINUED TO REVERSE, VEHICLE B STARTED TO REVERSE AS WELL. I STOPPED MY VEHICLE IMMEDIATELY AND HORN AT HIM BUT VEHICLE B STILL CONTINUE TO REVERSE AND HIT INTO THE LEFT PASSENGER DOOR OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP1046G
Vehicle Make/Model/Colour
Details Of Properties REAR PORTION
Vehicle Category COMMERCIAL VEHICLE
Name of Driver CHUA TECK CHYE
NRIC/Passport Number
Contact Number 93698543
Address
Postcode
Insurance Company Name

China Taiping

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

N.T.U. Income Motor Service Centre

Vehicle No.

Report Date: 23/8/2019 Start Time: 3:45 PM

Report No. M1

D.O.A.

Make

Model

Reporting Type

End Time

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.

23/8/2019 15:45

23/8/2019 15:45


Policyholder's Signature
Date & Time

Driver's Signature (if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: Eric Woon Jun Kiat
NRIC/ Pin No: S992751

Sketch Plan Pg. 2

SKETCH PLAN



VEHICLE B REVERSE

VEHICLE A REVERSE

BUILD MATE BUILDING - JOO YEE ROAD

Vehicle A: SJG4656B Vehicle B: NP1046G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I REVERSED MY VEHICLE WHEN VEHICLE B WAS STATIONARY. AS I CONTINUED TO REVERSE, VEHICLE B STARTED TO REVERSE AS WELL. I STOPPED MY VEHICLE IMMEDIATELY AND HORN AT HIM BUT VEHICLE B STILL CONTINUE TO REVERSE AND HIT INTO THE LEFT PASSENGER DOOR OF MY VEHICLE.

DECLARATION

We declare the foregoing particulars are true in every respect.


23/8/2019 15:45

Policyholder's Signature
Date & Time



Driver's Signature (If driver is not the policyholder)
Date & Time

23/8/2019 15:45


Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	772Z
Vehicle Details	
Vehicle No.:	SJG4656B
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS AUTO
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1NZ5097427
Chassis No.:	JTDKB20U503436679
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$32,311.00
Original Registration Date:	01 Jul 2008
First Registration Date:	01 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$19,387.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$38,214.00
COE Rebate Amount:	\$33,766.00
Total Rebate Amount:	\$33,766.00

The information contained herein is correct as at 29 Aug 2019

OK

THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	: 5109422787
The Policyholder	: CHIA HOCK TECK 14 QUEEN ASTRID PARK SINGAPORE 266806

Period of Insurance	: 27 Jun 2019 To 30 Jun 2020
Sum Insured	: Market Value of Insured Vehicle less Residual COE/PARF Value at Time of Loss
Premium (inclusive GST)	: S\$1,168.56

Interest Insured

Cover Type	: drive PREMIUM	Capacity	: 1500cc
Primary Driver	: CHIA HOCK TECK	Registration Year	: 2008
Named Driver (1)	: ONG BIAUW KIAT	Off-peak Car	: No
Named Driver (2)	: CHIA PEI XIAN	Insure with COE	: No
Make/Model	: TOYOTA/PRIUS	NCD Entitlement	: 50%
Registration Number	: SIG4656B	NCD Protection	: Yes(Free)
Chassis Number	: JTDKB20U503436679	Loyalty Discount	: 5%
Repair at Owner's Preferred Workshop	: Yes		
Excess (Section 1)	: S\$600		
Excess (Section 2)	: N/A		
Windscreen Excess	: S\$100		
Additional Excess	: N/A		
Unnamed Driver Excess	: Please refer to Terms and Conditions		
Hire Purchase Company	: N/A		

Optional Cover

Transport Allowance	: No
Excess Waiver	: No

Memo A : N/A

Endorsement Operative : M3, M4, M7

Agency	: PHUA KAH KENG, THOMAS (00000529154)
Date of Issue	: 22 May 2019 22:13 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L ESTEER

YP 1046G
NTUC/CHINA TAIPING (SJC 4656 B)-
DOA: 23/08/2019@1200

CHINA TAIPING INSURANCE (S) PTE LTD

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJC 4656 B - TOYOTA PRIUS AUTO

CHASSIS: JTDKB20U503436679 (07/2008)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" Basis
- No illegal modification and
- Supplementary item(s) must be removed and is subject to final approval from Insurance Company

04/09/2019

Acknowledged by Repairer

Signature:

Date:

1 pc	Rear door LH 4 ✓	Rasul	\$ 1,063.00	954
1 pc	Rear door outer handle LH X svc	Hp 90010068	\$ 355.00	X
1 pc	Rear door outer handle inner bracket LH 7 Xsvc	4 days	\$ 285.00	X
4 pcs	Rear LH door frame sticker @ \$98 rec @38		\$ 392.00	152
1 pc	Rear door inner lock LH 7 Xsvc		\$ 498.70	X
1 pc	Rear door glass outer moulding LH rec ✓	4/5	\$ 89.70	-
1 pc	Rear rim LH (Cap) cm ✓	10/09/19 @ 1100	\$ 989.00	price? 132
			\$ 3,672.40	
			\$ 918.10	
		Resurvey after repair	\$ 2,754.30	
			\$ 70.00	60
	Alignment		\$ 700.00	400
	Remove necessary parts: jacking, panel beating, repair and straighten rear fender inner panel, rear fender LH and rear door LH.		\$ 500.00	400
	Putty and respray rear fender inner panel LH, rear fender LH and rear door LH.		\$ 4,024.30	910
			\$ 281.70	
			\$ 4,306.00	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

* Rim respray - \$80 50

995.77

910.00

1905.77

20%

1524.61

45-1,500

4 days

4104.30

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019		06 Sep 2019 15:05 Edit Adj Rpt	S\$2,810.27 Edit Estimates	S\$2,810.27 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: CHIA HOCK TECK , ID: S0163772Z									
Vehicle Reg. No.: SJG4656B		Date of Loss: 23/08/2019 12:00 - :59 [133 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D204014C02		Policy/Cover Note No.: DMCVSN30001219000							
Vehicle Reg. No. (Insured): YP1046G		Policy No. (Claimant): 5109422787							
		Excess: S\$500.00							
Repairer: Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJG4656B (SNM19D204014C02)
 [YP1046G]
 TP
 CHIA HOCK TECK
 Aug 23 2019 12:00PM
 [-]
 Charn's Customcraft

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)					Thumbnail	Print	
1	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
2	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
3	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
4	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
5	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
6	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
7	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
8	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
9	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
10	23/08/19 15:40	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	26/03/20 14:20	Odometer Reading					Load JPG	<input checked="" type="checkbox"/>	
2	26/03/20 14:20	Chassis Number					Load JPG	<input checked="" type="checkbox"/>	
3	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
4	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
5	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
6	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
7	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
8	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
9	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
10	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
11	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
12	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
13	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
14	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
15	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
16	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
17	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
18	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
19	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
20	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
21	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
22	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	
23	26/03/20 14:20	General View					Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
24	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
25	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
26	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
27	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
28	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
29	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
30	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
31	26/03/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/19 15:06	PRS - SJG46568	Load PDF	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	23/08/19 16:01	Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/20 14:29	Certificate of Insurance	Load PDF	
2	26/03/20 14:29	Driver's Driving License	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	04/09/19 02:38	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	23/08/19 15:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	23/08/19 16:01	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19015812/R1QF3E2

Date: 02/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30001219000

Claimant Vehicle
No: SJG4656BInsured Vehicle
No: YP1046G

Date of Loss: 23/08/2019

Nature of Claim: TP

Claim
No: SNM19D204014C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJG4656B

Make & Model: TOYOTA PRIUS, 1.5 HYBRID (A)

Engine No: 1NZ5097427

Reg. Date: 01/07/2008 (Man. Year: 2008)

Chassis No: JTDKB20U503436679

Colour: White

Odometer: 78420 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R16

Rear Tyre Size: 195/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,754.30	1,900.27	854.03	31.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	910.00	440.00	32.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,104.30	2,810.27	1,294.03	31.53
+ GST 7.00/7.00% (S\$)	287.30	196.72	90.58	31.53
Nett Amount (S\$)	4,391.60	3,006.99	1,384.61	31.53

INSPECTION

Date of Assignment: 06/09/2019

Date Inspected: 10/09/2019 Inspected At:

Charn's Customcraft (HQ)

Block 1010 Bukit Merah Lane 3, #01-105

Singapore 159724

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)
Parts:	144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG4656B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent	1,063.00 FL	*1,063.00 FL
2	1		*REAR DOOR OUTER HANDLE LH	Serviceable	355.00 FL	*- FL
3	1		*REAR DOOR OUTER HANDLE INNER BRACKET LH	Serviceable	285.00 FL	*- FL
4	4		*REAR LH DOOR FRAME STICKER	Necessary	392.00 FL	*392.00 FL
5	1		*REAR DOOR INNER LOCK LH	Serviceable	498.70 FL	*- FL
6	1		*REAR DOOR GLASS OUTER MOULDING LH	Necessary	89.70 FL	*89.70 FL
7	1		*REAR RIM LH (CAP)	Cracked	989.00 FL	*989.00 FL
					Sub Total (\$\$)	3,672.40 2,533.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	918.10 633.43
					Total Parts (\$\$)	2,754.30 1,900.27

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ALIGNMENT	New	70.00	60.00
2	REMOVE NECESSARY PARTS: JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR FENDER INNER PANEL, REAR FENDER LH AND REAR DOOR LH	New	700.00	400.00
3	PUTTY AND RESPRAY REAR FENDER INNER PANEL LH, REAR FENDER LH AND REAR DOOR LH	New	500.00	400.00
4	RIM RESPRAY	New	80.00	50.00
Gross Labour Cost (S\$)			1,350.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >