### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

	ACCIDENT STATEMENT
Date Of Report	09/09/2019 09:56
Date Of Accident	23/08/2019 14:55
Exact Location Of Accident	BLK 149 BEDOK RESERVOIR RD OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE
-	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBJ62U
Insured/Policyholder	
Name Of Registered Owner	BM BEST RENOVATION PTE LTD
Co Reg No	200700026N
Email Address	NOEMAIL
Mobile Phone No	NO LIVINIE
Alternative Phone No	OFFICE-64812933
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150 5MT
Exact Purpose for which vehicle was being used at ime of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800136706
Cover Note Number	
Driver	
Name of Driver	NG THIAM LAI
NRIC No	S1642011E

Name of Driver

NG THIAM LA

NRIC No

S1642011E

Date Of Birth

27/09/1964

Occupation

OUTDOOR

Date Of Driving Pass

12/11/1986

Driving Experience 32 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-86711267

Fax Number

Contact Number OFFICE-86711267

EMail Address NOEMAIL

**BLK 322B SUMANG WALK** Address

#09-883

Postcode 822322

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

2

**General Information of the Accident** 

SIDE SWIPE Type Of Accident Weather Conditions **CLEAR** 

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

YES Was any other material or property damaged? NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

**Details of Police Action** 

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name HOUGANG NEIGHBOURHOOD POLICE POST

**ROAD**: BLK 357 HOUGANG AVENUE 7 #01-805, **POSTCODE**: 530357,

Police Station Address **COUNTRY: SINGAPORE** 

Police Station Contact TEL NO: 1800-2869999 - FAX NO: 63822066

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident** 

REFER TO POLICE REPORT - T/20190904/2107.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number SHC4070K

Vehicle Make/Model/Colour

**Details Of Properties** 

TAXI Vehicle Category

Name of Driver

NRIC/Passport Number

**Contact Number** 

Address

Postcode

Insurance Company Name

Page 2 of 15

#### Accident Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

## **Accident Sketch Plan**

	ak wa		Pel .
		abili their white	
			A: 60362U
		<u></u>	8: ZHCYORAK .
		(B) T	
CRIBE CIRCUMSTANCE			
efor to potice	report - 1/20 1900	. हिला भवन	
			1975
	rticulars are true in every re	spect.	7/2
(a) (w)	rticulars are true in every re		eporting Centre Persophely Signature

## **Police Report**





1 of 3

Report No. T/20190904/2107

Police Station Of Origin: Hougang NPP 357 Hougang Avenue 7 #01-805 SINGAPORE 530357 Tel No: 1800-2869999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
04/09/2019 15:18		10

Informa	nt's Partic	ulars		
Name of Informant: NG THIAM LAI			Address: APT BLK 322B SUMA 822322	NG WALK #09-883 SINGAPORE
ID Type / ID No.: NRIC NO / S1642011E		Contact No.: Home/Office:	Mobile: 86711267	
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 54	Date of Birth: 27/09/1964	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name	
Occupation: Lorry driver		Driving Licence Inform Class: 3	nation: Date of Expiry:	

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 23/08/2019 14:55	Type of Location Car Park	
	ERVOIR ROAD	park (lot number: 942) Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic	
Two Way	Type of Collision: Moving Vehicle Against - Parked Vehicle				

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
GBJ62U	Lorry					0
SHC4070K	Car					0

#### **Police Report**





Police Station Of Origin: Hougang NPP 357 Hougang Avenue 7 #01-805 SINGAPORE 530357 Tel No: 1800-2869999 2 of 3 Report No. T/20190904/2107

#### CONTINUATION OF REPORT

## Brief Details.

On 23/08/2019 at about 1455hrs while parking my lorry bearing registration number GBJ62U at Blk 149 Bedok Reservoir Open carpark (lot number: 942), I noticed that there was a taxi bearing registration number SHC4070K parked to my right lot (Number: 943).

During that instant, the said taxi driver namely Riduan Bun Rahim (S8119990F) was washing his taxi. While I was reversing my rear portion of vehicle got collided onto the said taxi driver's door as it was not closed.

Soon I then stop to make a check. The taxi driver's doors suffered a slight dent and minor scratches. Thus both drivers then exchange particular s and agreed to pursue insurance claim.

No one was injured. There is no Traffic Police or Ambulance attended to scene. There is no in-built CCTV installed in my lorry.

Hence I was then advised by my company to make this report for my insurance claim purposes.

### **Police Report**





Police Station Of Origin: Hougang NPP 357 Hougang Avenue 7 #01-805 SINGAPORE 530357 Tel No: 1800-2869999 3 of 3 Report No. T/20190904/2107

CONTINUATION OF REPORT

## Sketch Plan

NP168

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

A DE
e/Time: 9/2019 15:18
sification Of Case:
) !













