

REF: A19 CC3/A191905871/ G543

ASSIGNMENT

File No. 612

From Minim Date 6/9/19

Veh No: SMD6885Z or Regn: 30 Aug 2018
Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
Truck / Trailer or

Estimated Cost:
☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
To inspect Vehicle No: 382 1482
at Workshop n/s premium
of 55 ubi Road 1

Make: Audi Q2 C.C. 979
Colour: yellow A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
Sp Reading 10580 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
Eng/No:

Insured:
Policy No.
Claims No.
Sum Insured: Excess: 0
(Client's Record)
Make of Veh: +30pm

C/No: WAU282GA0JA071739
Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Modi: ☐ Nil / ☐ S/Rim / ☒ STD A/Rim or

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 245/60 R16
R: 11
☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Bal. or Market Value: \$106K
IDAC Accident Report: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 06-09-19
Survey held at w/s 3pm
Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

CA / ☒ REV / REP. / 24 HRS
Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMD 6885 Z - NA / TMS / 901941 / r3 ROA - 05/09/2019
10/9@15:47	Mandate Request all in \$52,000
11/9@11:41	mandate Approval -
11/9@11:48am	email premium authorise repair, not exceeding 52,000 PIP
	luggage compartment cover, Pillar C trim, luggage compartment trim damage photo required.

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation:
3 x RS, \$
Photos
Others
TOTAL

Report Format:
Lump Sum / L.R. (\$)