

72/0013002

ASS. REC. BY:

REF:

CS/EG219015916/Agf302

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Pauline soh

of

EG1

Date/Time: 9/9/19 @ 11:34am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 792S

Insured:

YQ 1473B

at Workshop m/s

Modern Automotive

Tel:

6748 4422

of

Blk 3023A Ubi Road 1 #01-61

Policy No:

Claim No:

CDMC919001632

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:15pm @ 9/9/18

Person Contacted:

Aimee

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ✓

YQ 1473B : X

GBF 792S : X

27/9/19 @ 9.24am revised to Pauline Soh by email.

US \$4150, 4 days (incl \$5698.23, 58%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBF792S Yr Regn: 2016 / JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading 87903 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA T35Y10K20 G354Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 155/75R15R: 155R12 C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/09/19Survey held at Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ergo

RECEIVED 27 SEP 2019

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) 29/9 14:54

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

290290

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 9 September 2019 11:34 AM
To: assignments
Subject: FW: Claims ref no. (P) CDMCG19001632 TP Claim GBF792S & YQ1473B

Hi

Kindly assist.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pauline Soh <pauline.soh@ergo.com.sg>
Sent: Monday, 9 September, 2019 11:32 AM
To: Chin <chin@modernautomotive.com.sg>; Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Subject: RE: Claims ref no. (P) CDMCG19001632 TP Claim GBF792S & YQ1473B

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only)

Kindly contact us if you are not able to make it.

*** NOTE: Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Date Classification Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group) one of the world's leading risk carriers



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd, will not be liable for any loss or damage thereby caused.

From: Chin [<mailto:chin@modernautomotive.com.sg>]
Sent: Monday, September 09, 2019 9:41 AM
To: Pauline Soh; Ivy Yong; Phoebe Xie
Subject: RE: Claims ref no. (P) CDMCG19001632 TP Claim GBF792S & YQ1473B

Dear Pauline

We choose LKK Auto Consultancy to survey our client's vehicle and by the way please advise case officer for liability.

Thank you

Regards,
Grace Chin
Modern Automotive Pte Ltd
Blk 3023-A, Ubi Road 1 #01-61
Singapore 408717

Tel: 6748 4422
Fax: 6747 6720

From: Pauline Soh [<mailto:pauline.soh@ergo.com.sg>]
Sent: Monday, September 9, 2019 9:33 AM
To: Chin <chin@modernautomotive.com.sg>; Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>; Pauline Soh <pauline.soh@ergo.com.sg>
Subject: RE: Claims ref no. (P) CDMCG19001632 TP Claim GBF792S & YQ1473B

Dear Chin,

Please refer to our list of surveyors

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Chin [<mailto:chin@modernautomotive.com.sg>]
Sent: Friday, September 06, 2019 5:29 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Pauline Soh
Subject: Re: TP Claim GBF792S & YQ1473B

Dear Sir

We refer to the above matter.

Kindly advise liability and arrange survey our client vehicle as follow:

Your Insured: YQ1473B
Our Insured: GBF792S
DOA: 06.09.2019

We enclosed herewith our client report for your perusal and revert asap.

Thank you

Regards,
Grace Chin
Modern Automotive Pte Ltd

Blk 3023-A, Ubi Road 1 #01-61
Singapore 408717

Tel: 6748 4422
Fax: 6747 6720

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 27 September 2019 9:24 AM
To: 'Pauline Soh'; 'Ivy Yong'; assignments
Cc: 'Phoebe Xie'; SUR
Subject: RE: Claims ref no. (P) CDMCG19001632 TP Claim GBF792S & YQ1473B
Attachments: CSEGI19015916Aqf3.pdf

Dear Pauline,

Enclosed herewith preliminary advice of GBF 792S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 9 September 2019 12:17 PM
To: 'Pauline Soh' <pauline.soh@ergo.com.sg>; 'Ivy Yong' <ivy.yong@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Phoebe Xie' <phoebe.xie@ergo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Claims ref no. (P) CDMCG19001632 TP Claim GBF792S & YQ1473B

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pauline Soh [<mailto:pauline.soh@ergo.com.sg>]
Sent: Monday, 9 September 2019 11:32 AM
To: Chin <chin@modernautomotive.com.sg>; Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>; Admin-D (LKKAUTO) (admin-d@lkkauto.com) <admin-d@lkkauto.com>; Admin A (admin-a@lkkauto.com) <admin-a@lkkauto.com>; Mei Kwan (LKKAUTO) (Meikwan@lkkauto.com) <Meikwan@lkkauto.com>
Subject: RE: Claims ref no. (P) CDMCG19001632 TP Claim GBF792S & YQ1473B



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CDMCG19001632

Date: 27th September 2019

Our Ref: CS/EGI19015916/Aqf3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBF 792S.


We thank you for the instruction on 09/09/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/09/2019 at the premises of M/s MODERN AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,848.23</u>
Revised Estimate Amount	: S\$ <u>4,150.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have NOT authorise repair.

Yours faithfully

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/09/2019 15:00
Date Of Accident	06/09/2019 09:30
Exact Location Of Accident	LORONG 15 GEYLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF792S
Insured/Policyholder	
Name Of Registered Owner	TECK HOE AIRCONDITIONING PARTS PTE LTD
Co Reg No	197801697R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98226300
Alternative Phone No	OFFICE-67478096

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109247257
Cover Note Number	

Driver

Name of Driver	LAI NAM FATT
NRIC No	S1168032A
Date Of Birth	24/03/1956
Occupation	INDOOR
Date Of Driving Pass	16/08/1978
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98226300
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 632 VEERASAMY ROAD #13-100
Postcode	200632
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHER N.P.C
Police Station Address	ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2949999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO.T/20190906/2049

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	UNKNOWN
Phone Number	83108867
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ1473B
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 06/9/19



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS per police report no: T/2019 0906 / 2049

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 06/11/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190906/2049

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

1 of 3

Report No. T/20190906/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/09/2019 12:18		Vide Report No.:		Station Diary No.: 94	
Informant's Particulars					
Name of Informant: LAI NAM FATT			Address: APT BLK 632 VEERASAMY ROAD #13-100 SINGAPORE 200632		
ID Type / ID No.: NRIC NO / S1168032A			Contact No.: Home/Office: Mobile: 98226300		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 24/03/1956	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: SHOP ASSISTANT		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:			

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 06/09/2019 09:30	Type of Location: Straight Road
Location: Along Road 1 LORONG 15 GEYLANG				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF792S	Lorry				Seriously Damaged	0
YQ1473B	Lorry					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190906/2049

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

2 of 3

Report No. T/20190906/2049

CONTINUATION OF REPORT

Driver			
Name	LAI NAM FATT	ID No.	S1168032A
Related Vehicle	GBF792S (Lorry)	Contact No.	98226300
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 06/09/2019 at about 0800hrs, I park my vehicle, GBF792S along Geylang Lorong 15, Lot 16.

At about 0930hrs, I heard a loud band and I went outside to make a check and I spotted my vehicle was damaged on the driver's side. Both the headlight and bumper was damaged.

I was informed by a member of public that the vehicle that hit my lorry was YQ1473B.



SINGAPORE
POLICE FORCE



T/20190906/2049

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

3 of 3

Report No: T/20190906/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Sgt 1 LIM HUI YI KLARISSA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Insp GOH GEOK LYE

Contact No.: 65476148

Authentication Stamp

NP168



SINGAPORE
POLICE FORCE

Signature Of Informant:

Date/Time:

06/09/2019 12:18

Classification Of Case:

SIGNATURE

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 6829 - 9170
Fax : 6829 - 9247

Xiao Chen.

Quotation
DATE : 10.09.2019
VEH NO : GBF792S
MODEL : Toyota Dyna
D O A : 06.09.2019
YR REF : YQ1473B

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBF792S (TOYOTA DYNA)

Item	Description	Qty	Amt
<u>NO</u>	<u>LIST ITEMS</u>		
1	Front Bumper <i>Repair</i>	1	788.20 X
2	Front Grille <i>crushed</i>	1	481.30 ✓
3	Front Grille Logo <i>new</i>	1	75.30 ✓
4	Front Grille Clips <i>new</i>	1set	20.00 ✓
5	Head Lamp - RH <i>crushed</i>	1	1,015.00 ✓
6	Front Corner Panel - RH <i>dented</i>	1	396.50 ✓
7	Front Corner Panel Top Protector - RH <i>missing</i>	1	101.90 ✓
8	Wiper Panel Side Cover - RH <i>crushed</i>	1	386.90 ✓
9	Front Door - RH <i>dented</i>	1	1,568.30 ✓
10	Front Door Hinges - RH (upper & Lower) <i>Best</i>	1	157.80 ✓
11	Front Door Catch - RH <i>new</i>	1	65.40 X
12	Front Door Inner Trim Board - RH <i>new</i>	1	645.10 X
13	Front Door Inner Trim Board Clips - RH <i>new</i>	1	30.00 X
14	Front Door Wing Mirror - RH <i>crushed</i>	1	359.30 ✓
15	Front Door Glass Regulator Gear - RH <i>new</i>	1	393.10 X
16	Front Door Pillar - RH <i>Repair</i>	1	711.50 X
17	Front Windscreen Moulding <i>new</i>	1	268.70 X
			\$ 7,464.30
Less 25%			(1,866.08)
			\$ 5,598.23
<u>S/ NET ITEMS</u>			
1	Front Door Company Address Sticker - RH <i>new</i>	1	30.00 ✓
2	Front Door Advertisement Sticker - RH <i>new</i>	1	280.00 200.
3	Front Windscreen Sealant <i>new</i>	1	60.00 X
			\$ 370.00
Total			\$ 5,968.23

RE : ESTIMATE FOR ACCIDENT REPAIR GBF792S (TOYOTA DYNA)

LABOUR CHARGE

1	To knocking & pull out front RH side portion & renew above parts	\$	1,600.00 600
2	To putty & spray up paint works	\$	1,400.00 800
3	To check wiring system	\$	50.00 30
4	To transfer door fittings	\$	150.00 80
5	To underseal	\$	150.00 50
6	To remove front windscreen	\$	180.00 X
7	To remove dashboard	\$	350.00 X
		\$	3,880.00
Grand Total		\$	9,848.23

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5211.72
L/s: 4150
04 Days.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG19015916/Aqf3e2		
5 TEMASEK BOULEVARD #04-05 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 08-10-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 1473B	Veh. Inspected	GBF 792S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CDMCG19001632	Excess (\$)	0.00	
Assign From	PAULINE SOH	Assign Date	09/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFAT35Y10K206354	Colour	SILVER	
Odometer	87903	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/75 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	155 R12C	YOKOHAMA	6 mm	
L/H Rear Tyre	155 R12C	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2019	Inspection Date	10/09/2019	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 792S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	788.20	-
1	FRONT GRILLE	CRACKED	481.30	481.30
1	FRONT GRILLE LOGO	NECESSARY	75.30	75.30
1	SET FRONT GRILLE CLIPS	NECESSARY	20.00	20.00
1	HEAD LAMP - RH	CRACKED	1,015.00	1,015.00
1	FRONT CORNER PANEL - RH	DENTED	396.50	396.50
1	FRONT CORNER PANEL TOP PROTECTOR - RH	MISSING	101.90	101.90
1	WIPER PANEL SIDE COVER - RH	CRACKED	386.90	386.90
1	FRONT DOOR - RH	DENTED	1,568.30	1,568.30
1	FRONT DOOR HINGES - RH (UPPER & LOWER)	BENT	157.80	157.80
1	FRONT DOOR CATCH - RH	NOT NECESSARY	65.40	-
1	FRONT DOOR INNER TRIM BOARD - RH	NOT NECESSARY	645.10	-
1	FRONT DOOR INNER TRIM BOARD CLIPS - RH	NOT NECESSARY	30.00	-
1	FRONT DOOR WING MIRROR - RH	CRACKED	359.30	359.30
1	FRONT DOOR GLASS REGULATOR GEAR - RH	NOT NECESSARY	393.10	-
1	FRONT DOOR PILLAR - RH	TO REPAIR SEE LABOUR	711.50	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	268.70	-
	LESS 25% DISCOUNT		-1,866.08	-1,140.58
			5,598.22	3,421.72
SPECIAL NETT ITEMS				
1	FRONT DOOR COMPANY ADDRESS STICKER - RH (SN)	NECESSARY	30.00	30.00
1	FRONT DOOR ADVERTISEMENT STICKER - RH (SN)	NECESSARY	280.00	200.00
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			370.00	230.00
LABOUR				
	TO KNOCKING & PULL OUT FRONT RH SIDE PORTION & RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT DOOR PILLAR - RH.		1,600.00	600.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,400.00	800.00

Report Ref No. CS/EGI19015916/Aqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO TRANSFER DOOR FITTINGS.		150.00	80.00
	TO UNDERSEAL.		150.00	50.00
	TO REMOVE FRONT WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE DASHBOARD.	NOT NECESSARY	350.00	-
			3,880.00	1,560.00
GRAND TOTAL			9,848.22	5,211.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CS/EGI19015916/Aqf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.