

7/03/2003

ASS. REC. BY:

REF:

CS3/ALG190159 44/Fcd32

Special Instruction:

Surveyor: Ram

## ASSIGNMENT (Office)

Mentimen

From (Person): chin lee ying

of AIG

Date/Time: 16/9/19 @ 11:15am

Estimated Cost:

Bill to:

OD - TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 6868C

Insured:

SLW 4620X

at Workshop in/s

Mcwell Ventures

Tel:

9389 3004.

of

8 kaki Bukit Ave 4 # 01-47 premier

Policy No:

1800051187

Claim No:

50812040955G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:54pm @ 16/9/19

Person Contacted:

Man

Vehicle IN OUT

Date/Time

Action/Instruction

Valid? X

SKV 6868C - X

SLW 4620X - X

Dismantle: 11/9/2019

After repair: 16/9/2019

PRS

## ASSIGNMENT

From:

Date:

10/9/2019

Veh No:

SKV 6868C

Yr Regn: OCT / 2011

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SKV 6868C

Make:

BMW 535i

c.c 2979

at Workshop m/s

McWell Ventures

Colour:

white

A/C: Insured / Std / NI / NA

of

8 kaki Bukit Ave 4 # 01-47/48

Sp. Reading

152166

T/Radio: Insured / Std / NI / NA

Insured:

premier

Eng/No:

C/No:

WBAFR72030C957904

Policy No.

Gen. Cond: Good / Fair / Poor / Burnt

Claims No.

Steering: Inorder / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Alan @ 9389 3004

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Tyre Size:

P: 255 / 30 R 20

R: 285 / 30 R 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A. 05/09/2019

D.O.I. 11/09/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

MCWELL VENTURES

CA / REV / REP. / 24 HRS

iup

Des. of Damages: Frt / (Rear) O/S / N/S / U/C / Rooftop or

rear.

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction   |
|-------------|------------------------|
|             | Range: \$5000 - \$6000 |
|             | Repair days: 5 days    |
|             | <i>[Signature]</i>     |
|             | 12/9/2019              |
|             | MV: \$20000            |
|             | PV: \$53081            |
|             | NV: \$26006            |

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

5

1)

☐

Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Wheel end (\$)

Survey Fee:

180

Transportation:

3 + RS, 31

Photos:

Other:

Report Format:

DAR

Lump Sum / L.R.I. (\$)

TOTAL

191

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt | Adj Submitted | Ins Auth'ed | Status  |
|------|---|---------------|---|---------|---------------|-------------|---|
| Main | 06 Sep 2019<br><a href="#">Edit Reg</a> |               | 10 Sep 2019 00:00<br><a href="#">Edit Adj Rpt</a> |         |               |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

|                             |  |                        |                            |
|-----------------------------|--|------------------------|----------------------------|
| Insured:                    | SCREEN SPE SINGAPORE PTE LTD, Co. Reg. No.: 197902488E   |                        |                            |
| Main Claimant:              | TEO CHI WEI, ID: S7722839Z   |                        |                            |
| Vehicle Reg. No.:           | SKV6868C   | Date of Loss:          | 05/09/2019 10:00 - :59     |
| Claim Type:                 | TP / 5081204095SG  | Policy/Cover Note No.: | 1800051187 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SLW4620X   | Policy No. (Claimant): |                            |
|                             |  | Excess:                |                            |
| Repairer:                   | Mcwell Ventures Pte Ltd (HQ) 8 Kakui Bukit Ave 4, #01-47/48 Premier@Kaki Bukit, 415875 Kaki Bukit - Tel:               |                        |                            |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com  |                        |                            |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/09/2019] |                        |                            |
| Claimant's Solicitor:       | Ap Law Practice  |                        |                            |

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (11/09/2019): TP GIA REPORT

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

Your password will expire in 5 days. [Click here to change it.](#)

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 9/10/2019 11:15:40 AM

Attachments:  LETTER TO 3P AND AIG.PDF  GIA REPORT SKV6868C.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** sengtat@aplp.com.sg [mailto:sengtat@aplp.com.sg]

**Sent:** Monday, September 09, 2019 9:08 AM

**To:** Subramaniam, Divyashni

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Hor, Yinrul; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; sengtat@aplp.com.sg

**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLW4620X AND SKV6868C ON 05/09/2019

**WITHOUT PREJUDICE**

Dear Sir,

We refer to your mail of even date.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Sincere Appraiser
- g. Seah Kwang Boon
- h. L H Teo
- i. Mr Willy Goh
- j. Nicky Seah
- k. Jayson Liaw

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

In the event you are not agreeable to our list of surveyor, please note that our client's vehicle can be inspected at:

**McWell Ventures Pte Ltd**

8 Kaki Bukit Ave 4

#01-47/48 Premier@Kaki Bukit

S415875

**Contact: Alan (93893004)**

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                   |
|-------------------------------|-----------------------------------|
| Owner ID Type:                | Singapore NRIC                    |
| Owner ID:                     | 839Z                              |
| Vehicle Details               |                                   |
| Vehicle No.:                  | SKV6868C                          |
| Vehicle to be Exported:       | No                                |
| Intended Deregistration Date: | 12 Sep 2019                       |
| Vehicle Make:                 | B.M.W.                            |
| Vehicle Model:                | 535i A                            |
| Primary Colour:               | Black                             |
| Manufacturing Year:           | 2011                              |
| Engine No.:                   | 09417805N55B30A                   |
| Chassis No.:                  | WBAFR72030C957904                 |
| Maximum Power Output:         | 225.0 kW (301 bhp)                |
| Open Market Value:            | \$66,126.00                       |
| Original Registration Date:   | 07 Oct 2011                       |
| First Registration Date:      | 07 Oct 2011                       |
| Transfer Count:               | 1                                 |
| Actual ARF Paid:              | $\$66,126.00 \times 50\% = 33063$ |
| Intended PARF Rebate Details  |                                   |
| PARF Eligibility:             | Yes                               |
| PARF Eligibility Expiry Date: | 06 Oct 2021                       |
| PARF Rebate Amount:           | \$39,675.00                       |
| Intended COE Rebate Details   |                                   |
| COE Expiry Date:              | 06 Oct 2021                       |
| COE Category:                 | B - Car (1601cc & above)          |
| COE Period(Years):            | 10                                |
| QP Paid:                      | \$64,889.00                       |
| COE Rebate Amount:            | \$13,406.00                       |
| Total Rebate Amount:          | \$53,081.00                       |

The information contained herein is correct as at 12 Sep 2019

Remaining : 2 years 1 month 1 day (25.03) OK

Depr : \$22300/yearly    \$1858.33/monthly

$25.03 \times \$1858.33 = \$47015.74$

$\$47015.74 + \$33063 = \$80078.74$

## Need Items for Your Car?

We have thousands of car parts & accessories to explore.

The best online platform to sell and buy car parts & accessories - Marketplace

bmw 535i

Price Range ▼

Depreciation ▼

2011 ▼

Vehicle Type ▼

Advanced  
Search[Home](#) » [Used Cars](#) » [SG Car Consign Pte Ltd](#) » BMW 5 Series 535i

### BMW 5 Series 535i

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

|                        |  |                        |                                       |
|------------------------|--|------------------------|---------------------------------------|
| <b>Price</b>           | \$75,900                                       |                        |                                       |
| <b>Depreciation</b> ⓘ  | \$22,300 /yr<br>View models with similar depre | <b>Reg Date</b>        | 27-Sep-2011<br>(2yrs 14days COE left) |
| <b>Mileage</b>         | 80,000 km (10k /yr)                            | <b>Manufactured</b> ⓘ  | 2011                                  |
| <b>Road Tax</b> ⓘ      | \$2,362 /yr                                    | <b>Transmission</b>    | Auto                                  |
| <b>Dereg Value</b> ⓘ   | \$49,330 as of today (change)                  | <b>OMV</b> ⓘ           | \$60,785                              |
| <b>COE</b> ⓘ           | \$63,002                                       | <b>ARF</b> ⓘ           | \$60,785                              |
| <b>Engine Cap</b>      | 2,979 cc                                       | <b>Power</b>           | 225.0 kW (301 bhp)                    |
| <b>Curb Weight</b> ⓘ   | 1,775 kg                                       | <b>No. of Owners</b> ⓘ | 2                                     |
| <b>Type of Vehicle</b> | Luxury Sedan                                   |                        |                                       |

#### Features

Grey. View specs of the BMW 5 Series Sedan (2010-2017)

#### Accessories

As Per Factory Fittings.

#### Description

Best Value For Your Money. Direct Owner's Beautiful Metallic Grey, Apr '2007' B.M.W. 535i A. Selling Due To Upgrading To New Car. Low Fuel Consumption, Low Maintenance. Original Paintwork Condition And Well Taken Care By 2nd Owner. Fully Modified With Exhaust, Wide Body Kit, Tuning Stage 2, Rim And Brake. Trade In And Loan Available. No Obligation! Must Call To Arrange For Viewing!

#### Category

ⓂARF Car, Low Mileage Car

#### Status

Available

#### Resources



##### Car Valuation - Free

Find out the market value of your existing car for free. Get started



##### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

[Shortlist](#)[Compare](#)[Add note](#)[Report Error](#)[More Actions](#)

#### Seller Information

|                          |   |                               |
|--------------------------|---|-------------------------------|
| <b>Company</b>           | <b>SG Car Consign Pte Ltd</b><br>» dealer's pricelist<br>» 25 vehs sold   42 vehs available |                               |
| <b>Address</b>           | 170 Upper Bukit Timah Road #01-28<br>Search cars nearby this location                       |                               |
| <b>Location</b>          | Bukit Timah Shopping Centre   |                               |
| <b>Office No</b>         | 61000200  |                               |
| <b>Contact Person(s)</b> | Danny Loh<br>Joey Kwan<br>Andy Tay  | 9762287<br>8715805<br>9489103 |

ited on: 24-Jul-2019 | Last Updated on: 29-Jul-2019

Upfront Payment

» more Financial info

Transf

\$25

Insurance

\$1,222 onwards

Not at fault? No upfront payment required! (Get a quote)

Quote assumes a standard profile. "Get a quote" for exact figure.

Powered by

AVIVA

Total Upfront Payment

\$26,363

Check with seller for exact figure

Products and Services

» View All

Reliable Service. Competitive Rates.

Ispiri FFR X2 20" Rim Selling @ \$2800

3D Royal MAXpider Car Mat

Boot Lip To Improve Aerodynamic Structure

Daytime Running Light

Bidded Carplate for Sale

View all 55 suitable items for BMW 535i

igs: BMW 535i, bmw 535i, 2011 BMW 535i, 2011 bmw 535i, BMW, 535i, Used BMW

Recommended for you

1-6 of 18

What is VEP and how do you register for it

BMW launches the all new 1 Series here

Performance every day with Yokohama V105

Exclusive editions for BMW's i lineup

Get rid of your 3-5 years old cars now!

Share Your Car Fuel Consumption



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 06/09/2019 16:03 |
| Date Of Accident           | 05/09/2019 10:10 |
| Exact Location Of Accident | KAKI BUKIT VIEW  |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKV6868C             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | TEO CHI WEI          |
| NRIC No                     | S7722839Z            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-98771899 |
| Alternative Phone No        | OTHERS-98771899      |

### Vehicle Particulars

|  |             |
|--|-------------|
| Manufacturer   | BMW         |
| Model  | 535I A      |
| Exact Purpose for which vehicle was being used at time of accident           |             |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO          |
| If No, Please state action to be taken                                       | THIRD PARTY |
| Vehicle Category   | PRIVATE CAR |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5088595318-02                          |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | TEO KAI JIE           |
| NRIC No              | S8208716H             |
| Date Of Birth        | 31/03/1982            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 02/04/2003            |
| Driving Experience   | 16 YEARS AND 5 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-91093723  |
| Fax Number           |                       |
| Contact Number       |                       |
| Email Address        | NOEMAIL               |

|   |                          |
|---|--------------------------|
| Address   | 2E GREEN LOANE           |
| Postcode  | 438897                   |
| Was driver an employee of the Insured's Company   | NO                       |
| If No, Relationship of the Driver with the Insured  | SIBLING                  |
| Vehicle Registration Number of Driver's Own Vehicle   | -                        |
|   | -                        |
|   | -                        |
| Insurance Company of Driver's Own Vehicle   | -                        |
|   | -                        |
|   | -                        |
| <b>General Information of the Accident</b>  |                          |
| Type Of Accident  | COLLISION - HEAD TO REAR |
| Weather Conditions  | CLEAR                    |
| Road Surface  | DRY                      |
| <b>Other Information</b>  |                          |
| Was any foreign vehicle involved in this accident?  | NO                       |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                        |
| Was any body injured in the Accident?   | NO                       |
| Was any injured conveyed to hospital by ambulance?  | NO                       |
| Was any other material or property damaged?   | YES                      |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                       |
| Number of Passengers (Including Driver)   | 2                        |
| Passenger 1   | NAME: : FABIAN SEOW      |
|   | GENDER: : MALE           |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of Intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN ;

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |   |
|-------------------------------------|---|
| Vehicle Registration Number         | SLW4620X                                      |
| Vehicle Make/Model/Colour           | MAZDA / MAZDA2 SEDAN 1.5 AT STANDARD PLUS EU6 |
| Details Of Properties               |   |
| Vehicle Category                    | PRIVATE CAR                                   |
| Name of Driver                      |   |
| NRIC/Passport Number                |   |
| Contact Number                      |   |
| Address                             |   |
| Postcode                            |   |
| Insurance Company Name              |   |
| Nature Of Damage                    |   |
| No. Of Passenger (Including Driver) |   |

## Accident Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC KAKI BUKIT (VAC)**

Reporting Office: **23 Kaki Bukit Avenue 4**  
Name: **Singapore 415933**  
Tel: **67416697** Fax: **67492305**  
Email: **vackb@singnet.com.sg**

### Accident Sketch Plan

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving out from Bukit Bukit View towards Kak. Bukit Ave 3  
I was stationary at the stop line and the car behind just drove into my car's  
rear.  
We got down and exchanged details and went off.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date & Time:

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Center: Singapore 415933

Tel: 67416697 Fax: 67492305

NRIC/Fin No:   
 Email: [vockb@singnet.com.sg](mailto:vockb@singnet.com.sg)

# MOTORCAR (Rear)

## Rear Portion

| NAC  | INC    | Item                        | CON | AC | Qty |
|------|--------|-----------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate           |     |    |     |
| 1138 | 993627 | Rear Number Plate Base      |     |    |     |
| 1139 | 993630 | Rear Number Plate Garnish   |     |    |     |
| 1140 | 993632 | Rear Number Plate Lamp      |     |    |     |
| 1141 | 992958 | Rear Bumper                 | DD  | ✓  |     |
| 1142 | 993085 | Rear Bumper Upper           |     |    |     |
| 1143 | 993017 | Rear Bumper Lower           | ERA | ✓  |     |
| 1144 | 993054 | Rear Bumper Side            |     |    |     |
| 1145 | 993103 | Rear Bumper Tow Cover       | MIS | ✓  |     |
| 1146 | 992341 | Rear Bumper Clips           | MC  | ✓  |     |
| 1147 | 992976 | Rear Bumper Bracket         |     |    |     |
| 1148 | 993068 | Rear Bumper Side Retainer   |     |    |     |
| 1149 | 993045 | Rear Bumper Reinforcement   | CU  | ✓  |     |
| 1150 | 992970 | Rear Bumper Beam            |     |    |     |
| 1151 | 993077 | Rear Bumper Sponge          |     |    |     |
| 1152 | 992999 | Rear Bumper Damper          |     |    |     |
| 1153 | 993040 | Rear Bumper Protector       | CU  | ✓  |     |
| 1154 | 993036 | Rear Bumper Pad             |     |    |     |
| 1155 | 993026 | Rear Bumper Moulding        |     |    |     |
| 1156 | 993044 | Rear Bumper Reflector       |     |    |     |
| 1157 | 993023 | Rear Bumper Lower cover     | ERA | ✓  |     |
| 1158 | 994023 | Reverse Sensor              | SC  | ✓  |     |
| 1159 | 993327 | Rear End Panel              | DD  | ✓  |     |
| 1160 | 993339 | Rear End Panel Top Garnish  |     |    |     |
| 1161 | 993333 | Rear End Panel Inner Trim   |     |    |     |
| 1162 | 990333 | Boot Compartment Inner Trim |     |    |     |
| 1163 | 993851 | Rear LH Taillamp            |     |    |     |
| 1164 | 993853 | Rear LH Taillamp Garnish    |     |    |     |
| 1165 | 993859 | Rear LH Taillamp Panel      |     |    |     |
| 1166 | 995116 | Rear RH Taillamp            |     |    |     |
| 1167 | 993853 | Rear RH Taillamp Garnish    |     |    |     |
| 1168 | 993859 | Rear RH Taillamp Panel      |     |    |     |
| 1169 | 993554 | Rear Apron Panel            |     |    |     |
| 1170 | 992895 | Bootlid                     | SC  | ✓  |     |
| 1171 | 991328 | Bootlid Emblem              |     |    |     |
| 1172 | 990356 | Bootlid Handle              |     |    |     |
| 1173 | 995250 | Bootlid Moulding            |     |    |     |
| 1174 | 990376 | Bootlid Reflector           |     |    |     |
| 1175 | 995222 | Bootlid Lamp LH             |     |    |     |
| 1176 | 992899 | Bootlid Lamp RH             |     |    |     |
| 1177 | 995243 | Bootlid Lock                | SC  | ✓  |     |
| 1178 | 990377 | Bootlid Rubber              |     |    |     |
| 1179 | 990382 | Bootlid Hinge               |     |    |     |
| 1180 | 993877 | Bootlid Spoiler             |     |    |     |
| 1181 | 994543 | Tailgate                    |     |    |     |
| 1182 | 991328 | Tailgate Emblem             |     |    |     |
| 1183 | 994643 | Tailgate Outer Handle       |     |    |     |
| 1184 | 994640 | Tailgate Moulding           |     |    |     |
| 1185 | 994545 | Tailgate Garnish            |     |    |     |
| 1186 | 994648 | Tailgate Reflector          |     |    |     |
| 1187 | 994549 | Tailgate Lamp               |     |    |     |
| 1188 | 994646 | Tailgate Protector          |     |    |     |
| 1189 | 994676 | Tailgate Wiper Arm          |     |    |     |
| 1190 | 994677 | Tailgate Wiper Blade        |     |    |     |
| 1191 | 994679 | Tailgate Wiper Nozzle       |     |    |     |
| 1192 | 994555 | Tailgate Wiper Motor        |     |    |     |
| 1193 | 994602 | Tailgate Glass              |     |    |     |
| 1194 | 994606 | Tailgate Glass Rubber       |     |    |     |
| 1195 | 994604 | Tailgate Glass Moulding     |     |    |     |
| 1196 | 994607 | Tailgate Glass Sealant      |     |    |     |
| 1197 | 994629 | Tailgate Lock               |     |    |     |
| 1198 | 994651 | Tailgate Rubber             |     |    |     |
| 1199 | 994611 | Tailgate Hinge              |     |    |     |
| 1200 | 994594 | Tailgate Damper             |     |    |     |
| 1201 | 994613 | Tailgate Inner Board        |     |    |     |

Vehicle No: SKV 6868C

| NAC  | INC    | Item                           | CON | A |
|------|--------|--------------------------------|-----|---|
| 1202 | 993784 | Spare Tyre Board               |     |   |
| 1203 | 994328 | Spare Tyre Panel               |     |   |
| 1204 | 995065 | Spare Tyre                     |     |   |
| 1205 | 994326 | Spare Tyre Lock Screw          |     |   |
| 1206 | 993787 | Spare Tyre Cover               |     |   |
| 1207 | 995323 | Triangle Breakdown Sign        |     |   |
| 1208 | 990507 | CD Changer Assy                |     |   |
| 1209 | 990164 | Antenna                        |     |   |
| 1210 | 990534 | Centre Exhaust Pipe Assy       |     |   |
| 1211 | 990532 | Centre Exhaust Mounting        |     |   |
| 1212 | 993364 | Rear Exhaust Pipe              |     |   |
| 1213 | 993357 | Rear Exhaust Chrome Pipe       |     |   |
| 1214 | 993361 | Rear Exhaust Mounting          |     |   |
| 1215 | 993358 | Rear Exhaust Heat Shield       |     |   |
| 1216 | 995223 | Rear LH Chassis Member         |     |   |
| 1217 | 993165 | Rear RH Chassis Member         |     |   |
| 1218 | 993436 | Rear LH Fender                 |     |   |
| 1219 | 993449 | Rear LH Fender Protector       |     |   |
| 1220 | 993420 | Rear LH Fender Inner Panel     |     |   |
| 1221 | 993431 | Rear LH Fender Inner Trim      |     |   |
| 1222 | 993415 | Rear LH Fender Inner Garnish   |     |   |
| 1223 | 993425 | Rear LH Fender Inner Shield    |     |   |
| 1224 | 993621 | Rear LH Mudflap                |     |   |
| 1225 | 993933 | Rear LH Wheel Rim              |     |   |
| 1226 | 994025 | Rear LH Rim Cover              |     |   |
| 1227 | 995065 | Rear LH Tyre                   |     |   |
| 1228 | 993456 | Rear RH Fender                 |     |   |
| 1229 | 993450 | Rear RH Fender Protector       |     |   |
| 1230 | 993420 | Rear RH Fender Inner Panel     |     |   |
| 1231 | 993431 | Rear RH Fender Inner Trim      |     |   |
| 1232 | 993415 | Rear RH Fender Inner Garnish   |     |   |
| 1233 | 993425 | Rear RH Fender Inner Shield    |     |   |
| 1234 | 993622 | Rear RH Mudflap                |     |   |
| 1235 | 993934 | Rear RH Wheel Rim              |     |   |
| 1236 | 994025 | Rear RH Rim Cover              |     |   |
| 1237 | 995065 | Rear RH Tyre                   |     |   |
| 1238 | 995162 | Rear Fender Extension Panel LH |     |   |
| 1239 | 993401 | Rear Fender Extension Panel RH |     |   |
| 1240 | 993430 | Rear Fender Inner Top Garnish  |     |   |
| 1241 | 993673 | Rear Fender 1/4 Glass          |     |   |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber   |     |   |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant  |     |   |
| 1244 | 993949 | Rear Windscreen Glass          |     |   |
| 1245 | 993976 | Rear Windscreen Rubber         |     |   |
| 1246 | 993961 | Rear Windscreen Moulding       |     |   |
| 1247 | 993955 | Rear Windscreen Sealant        |     |   |
| 1248 | 994729 | Third Brake Light              |     |   |
| 1249 | 993385 | Rear Fender Air Grille         |     |   |
| 1250 | 992167 | Fuel Lid                       |     |   |
| 1251 | 992168 | Fuel Neck                      |     |   |
| 1252 | 992179 | Fuel Tank                      |     |   |
| 1253 | 992184 | Fuel Tank Bracket              |     |   |
| 1254 | 992191 | Fuel Tank Float                |     |   |
| 1255 | 990247 | Sticker                        |     |   |

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING









































| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt   | Adj Submitted                             | Ins Auth'ed | Status  |
|------|---|---------------|---|---|---|-------------|---|
| Main | 06 Sep 2019<br><a href="#">Edit Reg</a> |               | 10 Sep 2019 00:00<br><a href="#">Edit Adj Rpt</a> | <b>\$0.00</b><br><a href="#">Edit Estimates</a> | <b>\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|















































| CLAIM SUBFOLDER DETAILS  |  | [Created by adjuster]  |  |         |         |             |              |            |       |
|--|--|------------------------|--|---------|---------|-------------|--------------|------------|-------|
| Insured:   | SCREEN SPE SINGAPORE PTE LTD, Co. Reg. No.: 197902488E   |                        |  |         |         |             |              |            |       |
| Main Claimant:   | TEO CHI WEI, ID: S7722839Z   |                        |  |         |         |             |              |            |       |
| Vehicle Reg. No.:  | SKV6868C   | Date of Loss:          | 05/09/2019 10:00 - :59<br>[94 Months and 29 Days From LTA Reg Date (Man Yr)] |         |         |             |              |            |       |
| Claim Type:  | TP / 5081204095SG  | Policy/Cover Note No.: | 1800051187 (Comprehensive)   |         |         |             |              |            |       |
| Vehicle Reg. No. (Insured):  | SLW4620X   | Policy No. (Claimant): |  |         |         |             |              |            |       |
|  |  | Excess:                |  |         |         |             |              |            |       |
| Repairer:  | Mcwell Ventures Pte Ltd (HQ) 8 Kakui Bukit Ave 4, #01-47/48 Premier@Kaki Bukit, 415875 Kaki Bukit - Tel:               |                        |  |         |         |             |              |            |       |
| Handling Insurer:  | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com  |                        |  |         |         |             |              |            |       |
| Adjuster:  | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/09/2019] |                        |  |         |         |             |              |            |       |
| Claimant's Solicitor:  | Ap Law Practice  |                        |  |         |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>   |  |                        |  |         |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (11/09/2019): TP GIA REPORT</li> </ul>   |  |                        |  |         |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |  |                        |  |         |         |             |              |            |       |
| Due Date   | Priority   | Type                   | Task Group   | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results.  |  |                        |  |         |         |             |              |            |       |

## Claim Documents

\*SKV6868C (5081204095SG)  
[SLW4620X]  
TP  
TEO CHI WEI  
Sep 5 2019 10:00AM  
[SCREEN SPE SINGAPORE PTE LTD]  
Mcwell Ventures Pte Ltd

| <a href="#">Upload Documents</a> |                 | <a href="#">Upload Photos</a>   | <a href="#">Compose New Letter</a> | <a href="#">Upload Video</a>   | <a href="#">Upload Audio</a>        | <b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/> |                                     |
|----------------------------------|-----------------|---|------------------------------------|--|-------------------------------------|--|-------------------------------------|
| <b>Assessment Reports</b>        |                 |   |                                    |  |                                     | 1 per page <input type="button" value="v"/>                                  | <input checked="" type="checkbox"/> |
| No                               | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)   |                                    | Thumbnail  | Print                               |  |                                     |
| 1                                | 11/09/19 17:17  | <b>Accident Statement</b><br>From: SC - Reg. No: SLW4620X, Claimant: SCREEN SPE SINGAPORE PTE LTD |                                    |  Load HTM   |                                     |  |                                     |
| <b>Photos/Images</b>             |                 |   |                                    |  |                                     | 3 per page <input type="button" value="v"/>                                  | <input checked="" type="checkbox"/> |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)   |                                    | Thumbnail  | Print                               |  |                                     |
| 1                                | 17/09/19 12:15  | General View  |                                    |  Load JPG   | <input checked="" type="checkbox"/> |  |                                     |
| 2                                | 17/09/19 12:15  | General View  |                                    |  Load JPG   | <input checked="" type="checkbox"/> |  |                                     |
| 3                                | 17/09/19 12:15  | General View  |                                    |  Load JPG   | <input checked="" type="checkbox"/> |  |                                     |
| 4                                | 17/09/19 12:15  | General View  |                                    |  Load JPG   | <input checked="" type="checkbox"/> |  |                                     |
| 5                                | 17/09/19 12:15  | General View  |                                    |  Load JPG   | <input checked="" type="checkbox"/> |  |                                     |
| 6                                | 17/09/19 12:15  | General View  |                                    |  Load JPG   | <input checked="" type="checkbox"/> |  |                                     |
| 7                                | 17/09/19 12:15  | General View  |                                    |  Load JPG  | <input checked="" type="checkbox"/> |  |                                     |
| 8                                | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 9                                | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 10                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 11                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 12                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 13                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 14                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 15                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 16                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 17                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 18                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 19                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 20                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 21                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 22                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 23                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 24                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 25                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 26                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 27                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 28                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 29                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 30                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 31                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 32                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 33                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 34                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 35                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 36                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 37                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 38                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |
| 39                               | 17/09/19 12:15  | General View  |                                    |  Load JPG | <input checked="" type="checkbox"/> |  |                                     |



| Assessment Reports |                |   | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No                 | Finalized On   | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail  | Print                               |
| 40                 | 17/09/19 12:15 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 17/09/19 12:15 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 17/09/19 12:15 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 57                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 58                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 59                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 60                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 61                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 62                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG  | <input checked="" type="checkbox"/> |
| 63                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 17/09/19 12:15 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 81                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 82                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 83                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 84                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 85                 | 17/09/19 12:16 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 86                 | 20/09/19 09:21 | After Repair Photo                        |  Load JPG | <input checked="" type="checkbox"/> |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |



**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19015944/FCD3E2

Date: 23/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800051187

## Claimant

Vehicle No : SKV6868C

Insured Vehicle No : SLW4620X

Date of Loss: 05/09/2019

Nature of Claim: TP

Claim No: 5081204095SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKV6868C

Make &amp; Model: BMW 535i, 3.0 (A)

Engine No: 09417805N55B30A

Reg. Date: 07/10/2011 (Man. Year: 2011)

Chassis No: WBAFR72030C957904

Colour: White

Odometer: 152166 km

Engine Capacity: 2979 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 255/30 R20

Rear Tyre Size: 285/30 R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 11/09/2019 Inspected At:

Mcwell Ventures Pte Ltd (HQ)

8 Kaki Bukit Ave 4, #01-47/48

Premier@Kaki Bukit

Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No.                      | Qty | Part No. | Particulars                | Condition     | Repairer's  | Amount      |
|--------------------------|-----|----------|----------------------------|---------------|-------------|-------------|
| 1                        | 1   |          | *REAR BUMPER               | Dented        | 0.00 F      | *- F        |
| 2                        | 1   |          | *REAR BUMPER LOWER         | Cracked       | 0.00 F      | *- F        |
| 3                        | 1   |          | *REAR BUMPER TOW COVER     | Missing       | 0.00 F      | *- F        |
| 4                        | 1   |          | *REAR BUMPER CLIPS         | Necessary     | 0.00 F      | *- F        |
| 5                        | 1   |          | *REAR BUMPER REINFORCEMENT | Cut           | 0.00 F      | *- F        |
| 6                        | 1   |          | *REAR BUMPER PROTECTOR     | Cut           | 0.00 F      | *- F        |
| 7                        | 1   |          | *REAR BUMPER LOWER COVER   | Cracked       | 0.00 F      | *- F        |
| 8                        | 1   |          | *REVERSE SENSOR            | Short Circuit | 0.00 F      | *- F        |
| 9                        | 1   |          | *REAR END PANEL            | Repair        | 0.00 F      | *- F        |
| 10                       | 1   |          | *BOOTLID                   | Repair        | 0.00 F      | *- F        |
| 11                       | 1   |          | *BOOTLID LOCK              | Short Circuit | 0.00 F      | *- F        |
| F=Franchise part.        |     |          |                            |               |             |             |
| <b>Total Parts (S\$)</b> |     |          |                            |               | <b>0.00</b> | <b>0.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >