



SMRT Accident Vehicle Repair Estimates

m116

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/09/2019

User ID : GohKK2

Section A - Accident Details

Registration Number	SG1713H
Case Reference Number	BUS/09/19/7005
Registration Date	4/5/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Rabu Bin Sunaidi
Type of Accident	Side Swipe
Accident Date and Time	5/9/2019 7:55 AM
Accident Reported Date and Time	5/9/2019 12:01 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1713H - RIGHT REAR PORTION SLH5251A (TP) - INSURED WITH MSIG
Prepared Date and Time	8/9/2019 2:42 PM
Chassis Number	WMAA22ZZ8F7002884
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$772.00	\$0.00
Total Spare Part Cost	\$200.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,297.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	08/09/2019 2:52 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve (LKK)
WRC Majidi
9/9/19, 11.22 am

2 days
LKK Auto Consultancy
The Repairer of the following:
• To remedy defect after spray repair
• To replace damaged body panels during repair
• Parts prices are subject to confirmation
• Third party costs are subject to confirmation
• No legal action will be taken
• Supplemental claims must be reviewed and
is subject to approval from Insurance Company
Acknowledged by Repairer
Signature: _____
Date: _____



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/09/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	1060
Total Labour	\$1,325.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$772.00	528
Total Spray Painting & Panel Beating	\$772.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009987	BODY RH	A01001-CW568	PANEL SIDE:R6, FOR MAN A22 BUS	1.00	\$1,776.80	100.00	\$0.00	Repair	X
6009988	BODY RH	A01001-CW567	PANEL SIDE:R7, FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	X
6009989	BODY RH	A01001-CW566	PANEL SIDE:R8, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	X
6009990	BODY RH	A01001-CW565	PANEL SIDE:R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	X
6010330	Body	5029	TRIM, WHEELARCH, FOR MB OC500 LE BUS	1.00	\$124.20	100.00	\$0.00	Repair	X
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00		
Total					\$4,027.90		\$200.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: