

ASS. REC. BY:

REF: CS3/III19016022/Fcd3021 Special Instruction:

Signature: RamASSIGNMENT (Office)From (Person): Gabriel wee

of

IIIDate/Time: 10/9/19 @ 1:58pm

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FW4593L

Insured:

SH 8625C

at Workshop m/s

My Car Consultant

Tel:

88668832

of

53 ubi Avenue 1 # 01-33

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:12pm @ 10/9/19

Person Contacted:

Hui QinVehicle IN / OUT

Date/Time	Action/Instruction
	<u>Estimate (X) Insp: Tuck Life: 25 kaki Bukit Rd 4</u>
	<u>FW4593L - NA / PWD 19015478 / 24</u>
	<u>SH 8625C - NA / PWD 19015978 / 24</u>
	<u>Dismantle: 18/9/2019 0200pm</u>

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FW 4593L

at Workshop m/s

TUCK LIFE

of 25 KAKI BUKIT RD #01-68

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

FW 4593L

Yr Regn: MAR, 2003

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda VFR800

C.C. 782

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

1096

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH2RC46C62M 404611

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 120/70 R17

R: 180/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

-

mm

L/Bal.

mm

D.O.A.

07/09/2019

D.O.I.

10/09/2019 0349pm

Survey held at

Tuck life

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear / O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$3000-\$4000

Repair days: 5 days

13/9/2019

MV \$4000

PV \$608

NV \$8000

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair:

1)

☐: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐: Site Insp (\$☐: Interview (\$☐: Tech. Invs (\$☐: Weekend (\$

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Report Format: PRS.

Lump Sum / I.B.I.: (\$

170
11
171

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) Edit Reg		10 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	GAN EE ZHONG JEREMY, ID: S8811361F		
Vehicle Reg. No.:	FW4593L	Date of Loss:	07/09/2019 16:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SH8625C	Policy No. (Claimant):	
		Excess:	
Repairer:	My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/09/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 10 September 2019 1:58 PM
To: admin@mycar.sg; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: OUR REF: FW4593L YOUR REF: SH8625C PRE-REPAIR INSPECTION FORFW4593L
Attachments: FW4593L_07092019.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : FW4593L
III INSURED VEHICLE NO. : SH8625C
DATE OF LOSS : 07.09.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Priya**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: My Car Consultant [mailto:admin@mycar.sg]
Sent: 10 September, 2019 1:52 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: OUR REF: FW4593L YOUR REF: SH8625C PRE-REPAIR INSPECTION FORFW4593L

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to your email on even date.

We disagree to your list of surveyor and propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Lee Kok Weng
- g. Seah Kwang Boon
- h. Lee K.W.
- i. Nicky Seah
- j. Winson Goh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd

- ☐ [+65 88668832](tel:+6588668832)
- ☐ Admin@mycar.sg
- ☐ Mycar.sg
- ☐ 53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "Motor Claim - III" <motorclaim@iii.com.sg>

Sent: Tuesday, September 10, 2019 1:47 PM

To: "admin@mycar.sg" <admin@mycar.sg>

Subject: RE: OUR REF: FW4593L YOUR REF: SH8625C PRE-REPAIR INSPECTION FORFW4593L

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: My Car Consultant [mailto:admin@mycar.sg]
Sent: 10 September, 2019 11:05 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: OUR REF: FW4593L YOUR REF: SH8625C PRE-REPAIR INSPECTION FOR FW4593L

WITHOUT PREJUDICE

OUR REF: FW4593L
YOUR REF: SH8625C

Dear Sir/Madam,

RE-REPAIR INSPECTION FOR FW4593L
ACCIDENT INVOLVING FW4593L vAND SH8625C

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Warm Regards,
Kai Ling

My Car Consultant Pte Ltd
53 Ubi Avenue 1
Paya Ubi Industrial Park
#01-33 S(408934)

Tel: +65 9868 6000 / Fax: 6925 5219

CONFIDENTIALITY NOTICE: This message (including any attachments) is confidential and may be privileged. It may be read, copied and used only by the intended recipient. If you have received it in error please contact the sender (by return e-mail) immediately and delete this message. Any unauthorized use or dissemination of this message in whole or in parts is strictly prohibited.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	361F

Vehicle Details

Vehicle No.:	FW4593L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	VFR800A2
Primary Colour:	Silver
Manufacturing Year:	2002
Engine No.:	RC46E2418176
Chassis No.:	JH2RC46C62M404611
Maximum Power Output:	-
Open Market Value:	\$13,980.00
Original Registration Date:	26 Mar 2003
First Registration Date:	26 Mar 2003
Transfer Count:	10
Actual ARF Paid:	\$2,097.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	25 Mar 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,721.00
COE Rebate Amount:	\$608.00
Total Rebate Amount:	\$608.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

The information contained herein is correct as at 12 Sep 2019

+ NEA rebate \$3500

OK

depr: \$130/monthly (roughly)

* Remaining months: 42.5 months

1.5 x \$130 = \$538

\$538 + \$3500 (NEA Rebate) = \$9000



(1)

Bike model

More Search Options

Type

Any

Price From

Any

Price To

Any

Class

Any

Q SEARCH [VIEW ALL \(/LISTING/USED/BIKES/LISTING/\)](#)



Honda VFR800

Listing Type	Free Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda VFR800 (/listing/usedbike/model/honda-vfr800/)
Engine Capacity	782cc
Classification	Class 2 (/listing/usedbike/model/motorcycle-for-sale/class/class-2/)
Registration Date	11/01/2006
COE Expiry Date	31/12/2025 (6 years 3 months left)
Mileage	10700km
No. of owners	7
Type of Vehicle	Sport Tourers (/listing/usedbike/model/motorcycle-for-sale/sport-tourers/)

SELLER INFORMATION

Name	Contact
Ng	+65 97334967


FORMS TO DOWNLOAD

- Agreement Form (/static/forms/agreement.pdf) [Handing Over Form \(/static/forms/agreement.pdf\)/forms/handling_over.pdf\)](#)
- Deposit Receipt (/static/forms/deposit_receipt.pdf) [LTA Transfer Form \(/static/forms/deposit_receipt.pdf\)/forms/M01.pdf\)](#)
- Private Settlement Form (/static/forms/private-settlement-agreement.pdf)

REPORT ERROR (/LISTING/LISTING/ERROR/USED/BIKE/13952/)

ADD TO SHORTLIST [Like 0](#) [Share](#)

SHARE (WHATSAPP//SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USED/BIKE/HONDA-HONDA-VFR800F-INTERCEPTOR/13952/)



Price: SGD \$10000

The Official Distributor of Honda Motorcycles

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 21:03
Date Of Accident	07/09/2019 16:40
Exact Location Of Accident	BUKIT BATOK RD TWDS CHOA CHU KANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FW4593L
Insured/Policyholder	
Name Of Registered Owner	GAN EE ZHONG JEREMY
NRIC No	S8811361F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92348738
Alternative Phone No	OFFICE-92348738

Vehicle Particulars

Manufacturer	HONDA
Model	VFR800A2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNMC2018-00003944
Cover Note Number	

Driver

Name of Driver	GAN EE ZHONG, JEREMY (YAN YIZONG)
NRIC No	S8811361F
Date Of Birth	02/04/1988
Occupation	INDOOR
Date Of Driving Pass	13/07/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92348738
Fax Number	
Contact Number	OFFICE-92348738
EEmail Address	NOEMAIL

Address	BLK 293D BUKIT BATOK STREET 21 #20-532
Postcode	654293
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190907/7023.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH8625C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GAN EE ZHONG, JEREMY (YAN YIZONG)

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? FW4593L

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7 September 2019, at about 16:40 hrs, I was travelling along Bukit Botok Road towards CCK. At the junction before Brickland Road, I stop my bike bearing (FW4593L) as the traffic light was red. Suddenly, I felt an impact from my back which send me flying forward to the ground. I saw that a taxi bearing (SH8625C) had collided into the rear of my bike. An ambulance came to assist my injuries. I then exchange particulars with the taxi driver and decide to proceed with insurance claims.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Form 10-1 (Rev. 1/2018)

Police Report



**SINGAPORE
POLICE FORCE**



T/20190907/7023

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190907/7023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/09/2019 20:05		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: GAN EE ZHONG, JEREMY			Address: APT BLK 293D BUKIT BATOK STREET 21 #20-532 SINGAPORE 654293		
ID Type / ID No.: NRIC NO / S8811361F			Contact No.: Home/Office: Mobile: 92348738		
Nationality: SINGAPORE CITIZEN			Email: jeremy_7754@hotmail.sg		
Sex: Male	Age: 31	Date of Birth: 02/04/1988	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: WAREHOUSE ASSISTANT			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/09/2019 16:40	Type of Location: X-Junction
Location: BUKIT BATOK ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FW4593L	Motorcycle	HONDA	VFR800A2	Silver		0
SH8625C	Taxi					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FW4593L	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	PNMC2018-00003944	15/09/2018	25/09/2019

Police Report



**SINGAPORE
POLICE FORCE**



T/20190907/7023

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190907/7023

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	GAN EE ZHONG, JEREMY	ID No.	S8811361F
Related Vehicle	FW4593L (Motorcycle)	Contact No.	92348738
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	07/09/2019	Date Discharge	07/09/2019
No. of Days granted Medical Leave	05	Degree of Injury	Serious

Brief Details.

On stated time and date, I was travelling in my motorcycle along bukit batok road. I stop at the traffic junction as it was red light. Suddenly a taxi hit me from the rear. An ambulance came to assist and I exchange particulars with the driver and we decide to proceed with insurance claims. I went to see a doctor for my injuries and receive 5 days mc

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190907/7023

3 of 3

Report No. T/20190907/7023

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG CHEE HIEN
Contact No.: 65476437

Authentication Stamp
NP158

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
07/09/2019 20:05

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2019 08:39 Edit Reg		10 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	GAN EE ZHONG JEREMY, ID: S8811361F		
Vehicle Reg. No.:	FW4593L	Date of Loss:	07/09/2019 16:00 - :59 [197 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SH8625C	Policy No. (Claimant):	
		Excess:	
Repairer:	My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/09/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS























































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FW4593L
[SH8625C]
TP
GAN EE ZHONG JEREMY
Sep 7 2019 4:00PM
[-]
My Car Consultant - Ubi

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
3	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
4	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
5	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
6	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
7	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
8	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
9	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
10	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
11	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
12	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
13	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
14	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
15	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
16	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
17	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
18	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
19	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
20	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
21	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
22	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
23	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
24	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
25	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
26	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
27	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
28	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
29	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
30	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
31	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
32	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
33	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
34	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
35	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
36	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
37	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
38	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
39	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
40	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
41	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
42	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
43	20/09/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
55	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/09/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
57	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	20/09/19 09:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	20/09/19 09:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
99	20/09/19 09:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
100	20/09/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
101	20/09/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
102	20/09/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
103	20/09/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
104	20/09/19 09:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	11/09/19 08:53	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19016022/FCD3E2

Date: 23/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : FW4593L

Insured Vehicle No : SH8625C

Date of Loss: 07/09/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FW4593L

Make & Model: HONDA VFR800, 782cc

Engine No: RC46E2418176

Reg. Date: 26/03/2003 (Man. Year: 2003)

Chassis No: JH2RC46C62M404611

Colour: Silver

Odometer: 1096 km

Engine Capacity: 782 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17

Rear Tyre Size: 180/55 R17

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 10/09/2019 Inspected At:

Tuck Life; 25 Kaki Bukit Rd 4
Repairer : My Car Consultant - Ubi
(HQ)

Estimated Period of Repair: 0.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Sep 2019)	
Parts:	N/A	HONDA VFR800 782cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FW4593L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >