

23/02/2009

ASS. REC. BY:

REF:

CS3/AIG19016026/Fcd301

Special Instruction:

Surveyor:

Raim

ASSIGNMENT (Office)

From (Person):

Naimen chin lee ring

of

AIG

Date/Time:

10/9/2019 11:16am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJQ 9175L

Insured:

SKT 5089B

(Audi Q3)

at Workshop m/s

Kent Auto

Tel:

6741 2539

of

2 keli Bukit Ave 2 # 01-21

Policy No:

1800062133

Claim No:

5875722771SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:33am 10/9/19

Person Contacted:

Serene

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

Voluntary (X)

SJQ 9175L - X

SKT 5089B - X

Dismantle: 11/9/2019

After repair: 13/9/2019

ASS. REC. BY:

REF: **A1G**

N

PRS

## ASSIGNMENT

From

Date:

10/9/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJQ 9175L

at Workshop m/s

Kent Auto

of

2 Kaki Bukit Ave 2 #01-21

Insured:

Autohub

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJQ 9175L

Yr Regn:

May 1 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Corolla altis cc 1598

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

190119

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

M0053ZEE10614538

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 / rossve mm

R/Bal. 4 / NEXEN mm

L/Bal. 4 / YOKOHAMA mm

L/Bal. 4 / MICHELIN mm

D.O.A. 06/09/2019

D.O.I. 10/09/19


Survey held at

Kent auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

Range: \$3000-\$4000

Repair days: 5 days

MV: \$30000

PV: \$13148

NV: \$16000

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format:

DAR

Lump Sum / LBK (\$)

180

11

191

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2019 <a href="#">Edit Reg</a>		10 Sep 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN HUI SZE ALICE, ID: S7210729B, Tel: +6591765001		
Main Claimant:	KENT AUTO SERVICES, Co. Reg. No.: 52974332M		
Vehicle Reg. No.:	SJQ9175L	Date of Loss:	06/09/2019 09:00 - :59
Claim Type:	TP / 5875722771SG	Policy/Cover Note No.:	1800062133 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT5089B	Policy No. (Claimant):	
		Excess:	
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/09/2019]		
Claimant's Solicitor:	C YOGARAJAH LLC - Tel: 62925838		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (11/09/2019): TP GIA REPORT

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date    Priority    Type    Task Group    Subject    Handler    Assigned By    Completed On    Created On    Done?

No results.

Your password will expire in 5 days. [Click here to change it.](#)

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 9/10/2019 11:16:41 AM  
Attachments:  20190909144723.pdf

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Pamela Pamela [mailto:pamela@yoga-legal.com]

**Sent:** Monday, September 09, 2019 3:45 PM

**To:** Hor, Yinrul

**Cc:** winnie (winnie@yoga-legal.com); Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

**Subject:** [EXTERNAL] Re: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKT5089B AND SJQ9175L ON 06/09/2019

**This message is from an external sender; be cautious with links and attachments.**

Dear Sirs,

Please be informed that the said vehicle can be inspected at:

Name of workshop	:	M/s. Kent Auto Services
Address	:	2 Kaki Bukit Ave 2
		#01 – 21 Kaki Bukit Auto Hub
		Singapore 417921
Contact Person	:	Mr Kent Tan
Telephone no.	:	9754 7573 / 6741 2539
Fax no.	:	6741 2539

Regards,

Pamela

**M/s C. YOGARAJAH LLC**

883 North Bridge Road

#11-03 Southbank

Singapore 198785

Tel : (65) 6292 5838

Fax : (65) 6292 5938

(UEN No. 201333127N) (GST Reg No. 201333127N)

**Important Note:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

On Mon, Sep 9, 2019 at 3:41 PM Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)> wrote:



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่าน  
มันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려  
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,  
membuka attachment.

[Click here](#) by 2019-09-16 15:41 +08 to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref : CY.SJQ9175L.19.KA(HW).wp(PT)

Your Ref : Your insured vehicle SKT 5089B

09 September 2019

**Tan Hui Sze Alice**  
**c/o AIG Asia Pacific Insurance Pte Ltd**  
The Motor Claims Department  
78 Shenton Way #07-16  
Singapore 079120

**By Email**

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SJQ 9175L & SKT 5089B ON 06.09.2019 @ 09:45HRS ALONG BUKIT TIMAH ROAD**


We are instructed by Kent Auto Services to notify you of a road traffic accident on 06.09.2019 @09:45hrs along Bukit Timah Road involving our client's vehicle registration number SJQ 9175L and vehicle registration number SKT 5089B driven by you at the material time. A copy of the Singapore accident statement is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent
4. Alan Chong

Yours faithfully,

  
**C. Yogarajah LLC**  
Enc

cc: M/s Kent Auto Services  
2 Kaki Bukit Ave 2  
#01 – 21 Kaki Bukit Auto Hub  
Singapore 417921  
Mr. Kent Tan (9754 7573 / 6741 2539)  
By fax 6741 2539

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Business
Owner ID:	332M

### Vehicle Details

Vehicle No.:	SJQ9175L
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4889501
Chassis No.:	MR053ZEE106145393
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,500.00
Original Registration Date:	29 May 2009
First Registration Date:	29 May 2009
Transfer Count:	2
Actual ARF Paid:	\$17,500.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	28 May 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,943.00
COE Rebate Amount:	\$13,148.00
Total Rebate Amount:	\$13,148.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Sep 2019

Remaining : 4 years 8 months 22 days (56.7)

OK

Depri: \$6500/yearly) \$541.66 (monthly)

$56.7 \times \$541.66 = \$30712.12$



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

May 2018 Mazda 3



Immaculate Condition And  
Lightly Driven Mazda 3. Mileage  
Still Less Than 10k km  
Direct Owner *Sarah*



View our cars

Browse by Category

« Back ( 1 2 3 4 5 6 7 8 9 10 ) Next »

Sort by Date Posted

20 results/page

187 vehicles

Toyota Corolla

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Toyota Corolla		Any	Any	2009	Any	Any	Any	Available

Search Selection



**Toyota Corolla Altis 1.6A (New 5-yr COE)**

\$30,800

\$6,150 /yr

30-Nov-2009

1,598 cc

-

Sedan

Available

2.88% Per Annum. \$538 Monthly. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. In House Finance, In House Workshop And Paint Shop All Under One Roof. Buy With Assurance. Warranty Booklet And STA Report Will Be Given.

2.88% P.A. \$0 Admin,\$0 Down,Monthly Frm \$468, Sta "B" 2 Yr Warranty Engine,gear  
GV Credit Pte Ltd

Posted: 10-Sep-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



**Toyota Corolla Altis 1.6A (COE till 09/2024)**

\$33,800

\$6,770 /yr

07-Sep-2009

1,598 cc

152,000 km

Sedan

Available

Genuine Low Mileage! New Paintwork! Fully Groomed Interior/Exterior! Immaculate Condition With No Repairs Needed! One Of The Best Condition In Market! Just Serviced! Flexible Loan Scheme, Full Cash Welcome! Monthly \$560 Only! The Most Reliable Vehicle, Definitely...

Car (S) Pte Ltd

Posted: 10-Sep-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



**Toyota Corolla Altis 1.6A (COE till 05/2024)**

\$33,800

\$7,150 /yr

15-Jul-2009

1,598 cc

83,000 km

Sedan

Available

1 Owner Low Mileage! Well Maintained, Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loans, Trade In, Insurance And Scrap Services With Flexibility...

Posted: 10-Sep-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



**Toyota Corolla Axio 1.5A X (New 5-yr COE)**

\$29,800

\$5,950 /yr

24-Nov-2009

1,496 cc

-

Sedan

Available

Take This Chance And Give Us A Call To Drive Home This Great Condition Toyota Axio Today. Great Drive With Low Fuel Consumption. Call Us Now For This Fantastic Deal Today.

Swee Seng Motors

Posted: 10-Sep-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**GET YOUR  
COE  
RENEWAL  
LOAN**

**Is your COE expiring? Let us help you renew it!**

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



**Toyota Corolla Altis 1.6A (New 5-yr COE)**

\$33,800

\$6,750 /yr

07-Sep-2009

1,598 cc

87,000 km

Sedan

Available

2 Owner Low Mileage! Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loans, Trade In, Insurance And Scrap Services With Flexibility. Kindly Call Us N...

Posted: 10-Sep-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



**Toyota Corolla Altis 1.6A (New 5-yr COE)**

\$30,800

\$6,150 /yr

29-Sep-2009

1,598 cc

-

Sedan

Available

B by STA

PREMIUM AD



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/09/2019 15:14
Date Of Accident	06/09/2019 09:45
Exact Location Of Accident	BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ9175L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KENT AUTO SERVICES
Co Reg No	52974332M
Email Address	KENTKH530@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97547573
Alternative Phone No	OFFICE-67412539

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	P2204317
Cover Note Number	

### Driver

Name of Driver	ANT THEE HOCK LAI
NRIC No	S1742018F
Date Of Birth	04/12/1966
Occupation	OUTDOOR
Date Of Driving Pass	26/03/1996
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97371267
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	504 BUKIT BATOK STREET 52 #02-29
Postcode	650504
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG UBI NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7479999 - FAX NO: 67453410
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT5089B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**



Name	ANT THEE HOCK LAI
Approximate Age	
Injuries Sustain	NECK AND SHOULDER INJURY - 5 DAYS MC
Injured person in which vehicle?	SJQ9175L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

### Accident Sketch Plan

### SKETCH PLAN

Vehicle	
A-SJA 9175	
B-JKT 5089 B	

Legend	
	
Vehicle	Motorcycle

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Refer to police Report : T/20190906/2074.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your contract may have a fourteen (14) day clause whereby the claim against our policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature \_\_\_\_\_

**Date & Time:**

**Driver's Signature**

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name: \_\_\_\_\_

NRIC/FIN No.:

06/09/19 Date &  
1450 hrs.

Day 1

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

06/09/19  
1450hrs.



Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.:

# MOTORCAR (Rear)

## Rear Portion

NAC	INC	Item	CON	AC	Qb
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish	cra		
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	cra		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	rec		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	rec		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	cra		
1152	992999	Rear Bumper Damper	DD		
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	cra		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	cra		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD		
1171	991328	Bootlid Emblem	rec		
1172	990356	Bootlid Handle	DD		
1173	995250	Bootlid Moulding	DD		
1174	990376	Bootlid Reflector	DD		
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BR		
1178	990377	Bootlid Rubber	DD		
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJR 0175L

NAC	INC	Item	CON	A
1202	993784	Spare Tyre Board	cra	
1203	994328	Spare Tyre Panel	DD	R
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim		
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender		
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim		
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993401	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		

No of Items:

Assessor:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2019 <a href="#">Edit Reg</a>		10 Sep 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN HUI SIZE ALICE, ID: S7210729B, Tel: +6591765001		
Main Claimant:	KENT AUTO SERVICES, Co. Reg. No.: 52974332M		
Vehicle Reg. No.:	SJQ9175L	Date of Loss:	06/09/2019 09:00 - :59 [123 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5875722771SG	Policy/Cover Note No.:	1800062133 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT5089B	Policy No. (Claimant):	
		Excess:	
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/09/2019]		
Claimant's Solicitor:	C YOGARAJAH LLC - Tel: 62925838		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (11/09/2019): TP GIA REPORT

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJQ9175L (5875722771SG)**

**[SKT5089B]**









































**TP**

**KENT AUTO SERVICES**

























































**Sep 6 2019 9:00AM**














**[TAN HUI SZE ALICE]**

**Kent Auto Services - Kaki Bukit**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Assessment Reports</b>						1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	11/09/19 17:26	<b>Accident Statement</b> <small>From: SC - Reg. No: SKT5089B, Claimant: TAN HUI SZE ALICE</small>		Load HTM	<input type="checkbox"/>		
<b>Photos/Images</b>						3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
2	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
3	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
4	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
5	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
6	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
7	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
8	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
9	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
10	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
11	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
12	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
13	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
14	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
15	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
16	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
17	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
18	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
19	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
20	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
21	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
22	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
23	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
24	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
25	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
26	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
27	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
28	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
29	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
30	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
31	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
32	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
33	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
34	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
35	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
36	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
37	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
38	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
39	17/09/19 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
40	17/09/19 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/09/19 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/09/19 12:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	17/09/19 12:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
96	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
99	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
100	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	17/09/19 12:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	17/09/19 12:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	17/09/19 12:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	17/09/19 12:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	17/09/19 12:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	17/09/19 12:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	17/09/19 12:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19016026/FCD3E2

Date: 23/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800062133  
**Claimant**  
**Vehicle No :** SJQ9175L **Insured Vehicle No :** SKT5089B  
**Date of Loss:** 06/09/2019 **Nature of Claim:** TP **Claim No:** 5875722771SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

**Reg No:** SJQ9175L  
**Make & Model:** TOYOTA COROLLA ALTIS, 1.6 (A) **Engine No:** 3ZZ4889501  
**Reg. Date:** 29/05/2009 (Man. Year: 2009) **Chassis No:** MR053ZEE106145393  
**Colour:** Silver **Odometer:** 190119 km  
**Engine Capacity:** 1598 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

## CONDITION OF TYRES

**Front Tyre Size:** 195/65 R15 **Rear Tyre Size:** 195/65 R15  
**Front Left Side:** Yokohama 4 mm **Rear Left Side:** Michelin 4 mm  
**Front Right Side:** Rasser 4 mm **Rear Right Side:** Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

**Date of Assignment:** 10/09/2019  
**Date Inspected:** 10/09/2019 **Inspected At:** Kent Auto Services - Kaki Bukit (HQ)  
 BLOCK 2 KAKI BUKIT AVE 2, #01-21  
 KAKI BUKIT AUTOHUB  
 Singapore 417921  
**Estimated Period of Repair:** 5.0 days

**Adjuster:** PARASURAM SHANMUGAM**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE GARNISH	Cracked	0.00 F	*- F
2	1		*REAR BUMPER	Cracked	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
6	1		*REAR BUMPER DAMPER	Dented	0.00 F	*- F
7	1		*REVERSE SENSOR	* Check	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Dented	0.00 F	*- F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID HANLDE	Scratched	0.00 F	*- F
14	1		*BOOTLID MOULDING	Broken	0.00 F	*- F
15	1		*BOOTLID LOCK	Broken	0.00 F	*- F
16	1		*BOOTLID RUBBER	Deformed	0.00 F	*- F
17	1		*SPARE TYRE BOARD	Cracked	0.00 F	*- F
18	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >