

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/1

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Ms.
CUI
SHULI
356 CLEMENTI AVENUE 2
#19-281
Singapore 120356

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
09-09-2019
5211000972
198703792K
39999
2019001951/ 1
09-09-2019
EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SKS5241H	5G13GZ	21-04-2015	WVWZZZAUZEW391607	Golf 1.4 CLBMT 90 TSI D7F	47,703

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G6807417APGRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,080.14	#1	1,080.14	1,155.75
5G6807568D 9B9	Rear Diffusor Satin Black <i>?</i>	1	pcs.	277.23	#1	277.23	296.64
5G0807305D	Bumper (BUMPER REINFORCEMENT) <i>?</i>	1	pcs.	572.31	#1	572.31	612.37
5G6807863C	Attachment Strip	1	pcs.	59.89	#1	59.89	64.08
5G6807393A	Guide Piece <i>?</i> (BUMPER GUIDE LH) <i>.</i>	1	pcs.	34.51	#1	34.51	36.93
5G6807394A	Guide Piece <i>?</i> (BUMPER GUIDE RH) <i>.</i>	1	pcs.	34.51	#1	34.51	36.93
5G6807393	Guide Piece <i>?</i> (BUMPER BRACKET LH) <i>?</i>	1	pcs.	34.51	#1	34.51	36.93
5G6807394	Guide Piece <i>?</i> (BUMPER BRACKET RH) <i>?</i>	1	pcs.	34.51	#1	34.51	36.93
	LABOUR	3	pcs.	840.00	#1 <i>840</i>	2,520.00	2,696.40
	Spray Painting	3	pcs.	800.00	#1 <i>800</i>	2,400.00	2,568.00
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	REVERSE SENSORS <i>?</i>	1	pcs.	400.00	#1	400.00	428.00

Quotation valid till 16-09-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	7,527.61	7%	580.13	8,287.61	8,867.74
Total	760.00	7,527.61		580.13	8,287.61	8,867.74

Customer

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

Acknowledged by Repairer

Signature:

Date:

Service Advisor

Raul
Hp 90010068
3 days
12/09/12 @ 1035

Raul before paint