

ASS. REC. BY:

REF:

CS31SM019016045/VcP352

Special Instruction:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Jane James Henry of SNODate/Time: 10.9.19 15.29p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 1138KInsured: SJT 2676Mat Workshop m/s Blunell AutomotiveTel: 67452082of 1 Kaki Buti + MK C 101-28Policy No: 018MTP 01014494Claim No: CHT12 1904271

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10.9.19 3.40p.m

Person Contacted:

Sally

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SJT 2676M : X
	SMC 1138K : X
	Dismantle: 13/9/2019
	After repair: 17/9/2019

marinun

108/11/13) wef

ASS. REC. BY: *Marcus*

REF:

smc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time Action / Instruction

*PRS d1A 47007 6yrs. full
resurvey done 17-9-19**6500 - 7500*

RECEIVED 27 SEP 2019

Veh No:

SMC 1138K

Yr Regn:

*5 16*Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *(A)*

Make:

Volkswagen Golf

C.O.

1395

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

60816

T/Radio: Insured / Std / NI / NA

Eng/No:

WVWZZZAUZGW 27K713

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/40 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front:

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear:

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages:

The U/C / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Data/Time, File Return to?

Days Of Repair: *6*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS \$

) Photos

) Others

Report Format: *PRG*

Lump Sum / I.B.I. (\$

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019		10 Sep 2019 15:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AHMAD SAIFUL RIJAL BIN HASSAN , ID: S8615726H								
Main Claimant:	ONG KAR CHYE , ID: S1542185A								
Vehicle Reg. No.:	SMC1138K	Date of Loss:	07/09/2019 23:00 - :59						
Claim Type:	TP / CMTD1904271	Policy/Cover Note No.:	D18MTPV01014494 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJT2676M	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by IRENE JAMES HENRY - 6322 4618]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/09/2019]								
Driver/Custodian (Insured):	MUHAMMAD SIDDIQ MASHKUR BIN HASSAN () , NRIC: S9349711B, Tel: +6596170725 Email:								
Adj Asg. Remarks:	WS: SALLY 67452088								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCPS1011021143 / Kan Pook Sing Motor Workshop - Defu
 ENTRY DATE & TIME: 08/09/2019 13:33
 SUBMITTED BY: Lucy Ng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/09/2019 13:33
 Date Of Accident 07/09/2019 23:30
 Exact Location Of Accident BENDEMEER ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC1138K
 Insured/Policyholder
 Name Of Registered Owner ONG KAR CHYE
 NRIC No S1542185A
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96278198
 Alternative Phone No OFFICE-96278198

Vehicle Particulars

Manufacturer VOLKSWAGEN
 Model GOLF

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company EQ INSURANCE COMPANY LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number DMPPHQ19-003545
 Cover Note Number

Driver

Name of Driver ONG YONG HAO ADRIAN
 NRIC No S9600825B
 Date Of Birth 06/01/1996
 Occupation INDOOR
 Date Of Driving Pass 22/08/2014
 Driving Experience 5 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number +65-82018681
 Fax Number
 Contact Number
 EMail Address A.DRIAN_@HOTMAIL.COM

Address 75 PASIR RIS GROVE #01-31
 Postcode 518207
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 2
 Passenger 1 NAME: : ANGIE SEE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH OWNER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJT7276M
 Vehicle Make/Model/Colour 2636
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver MUHAMMAD SIDDIQ MASHKUR BIN HASSAN
 NRIC/Passport Number S9349711B
 Contact Number NA
 Address NA
 Postcode NA
 Insurance Company Name

Nature Of Damage

NA

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 9/9/19, 12:00pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 9/9/19, 12:00pm


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT (Geylang Bahru)

On 07/09/19 at about 1130pm, I was driving along Bendemeer Road on the right lane when suddenly a car came out from Geylang Bahru. Immediately I honked at the driver and I could not stop and hit the rear of the car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 9/9/19, 12:20pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 9/9/19, 12:20pm

Reporting Centre Personnel's Signature

Name:

NRAC/FBI No.:

NRAC Sketch Form Ver. 1.2

Addendum Sheet Pg. 1

11-09-19;11:49

;68412088

1/ 2



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #118-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours: Monday to Friday, 09:00 - 17:00
 VISA 5663061235 / GST Reg. #14 M68812285

Ann: Lucy

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: UKF S19119211 Vehicle Registration No: SMC113&K
 Name (as shown in NRIC): Ong Yong Hao Adrian NRIC/FIN/Passport No: S9600825B
 ("Vehicle Driver / Vehicle Owner") (*) Please delete as appropriate
 Address: 76 Pasir Ris Grove #01-31 Singapore ()
 Contact (Tel): 8201 8681 Mobile No.: 8201 8681
 Email Address: a.drian_@hotmail.com
 Date of Accident: 07/09/2019 Time of Accident: 1130 PM
 Place of Accident: Bendemeer Road
 Insurance Company: EQ Insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I would like to amend the sketch Plan.

Policyholder / Driver's Signature
 Date: 11/09/2019

Reporting Centre Personnel's Signature
 Name: _____
 NRIC/FIN No.: _____
 Date: _____


Accident Sketch Plan Pg. 1

11-09-19;11:49 ;

:68412088

2/ 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(Gaylang Bahr)

Vehicle A - SMC 1158 K

Vehicle B - SJT 7276 M.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11/09/2019

Reporting Centre Personnel's Signature
Name:
NRIC/PIH No.:

G:\MISC (SketchPlan)\omh_173

2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	185A
Vehicle Details	
Vehicle No.:	SMC1138K
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI R-LINE AT SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CZD512309
Chassis No.:	WVWZZZAUZGW274713
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$25,070.00
Original Registration Date:	25 May 2016
First Registration Date:	25 May 2016
Transfer Count:	1
Actual ARF Paid:	\$17,098.00 <i>8549</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2026
PARF Rebate Amount:	\$12,823.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$34,184.00
Total Rebate Amount:	\$47,007.00

The information contained herein is correct as at 11 Sep 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New Toyota Hiace Agent @ \$67800



100% Loan! Ready Stock! Agent

Unit! Call Fast!

Net Link Partners StarAd


[Browse by Category](#)
[Sort by Date Posted](#)

16 vehicles

Volkswagen Golf

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Volkswagen Golf		Any	Any	2016	Any	Any	
	Volkswagen Golf	Volkswagen Golf 1.4A TSI	\$60,800	\$8,860 /yr	12-Jan-2016	1,395 cc	62,888 km	
1 Owner Only, One Of The Lowest Depreciation In The Market! Great Fuel Consumption Of 18 Km/L! Immaculate Condition. Grooming Done. Knockdown Rear Seats Provide Large Boot Space For Your Luggage's Shopping Trips! Trade In Welcome. Flexible In House/Bank!								
SKL Automobile Pte Ltd								
Posted: 10-Sep-2019 Tags: 2016 Volkswagen Golf, 2016 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								
	Volkswagen Golf	Volkswagen Golf 1.4A TSI EQP Sunroof	\$76,800	\$10,020 /yr	05-Aug-2016	1,395 cc	78,800 km	
1 Owner! Full Volkswagen Agent Serviced And Maintained. Come With Sunroof/GPS/Bluetooth/Keyless/LED Headlight. 100% Accident Free, Superb Well Maintained. Loan Interest At Promotion 2.28%, Full Loan Available. Call Us Now Before It's Gone.								
Hua Yang Credit Pte Ltd								
Posted: 10-Sep-2019 Tags: 2016 Volkswagen Golf, 2016 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								
	Volkswagen Golf	Volkswagen Golf 1.4A TSI	\$69,800	\$9,820 /yr	04-Apr-2016	1,395 cc	46,402 km	
Comes With 12 Months Select Approved Warranty. Most Popular Hatchback Equipped With A 1.4L Turbo And Mated To A Dual Clutch Gearbox And With Drive Mode Selection Ensuring You A Zippy Yet Fuel Efficient Drive! Spacious Cabin For Small Families! Knockdown R								
Select By Performance Premium Selection								
Posted: 10-Sep-2019 Tags: 2016 Volkswagen Golf, 2016 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								
	Volkswagen Golf	Volkswagen Golf 1.4A TSI (OPC)	\$58,800	\$7,590 /yr	30-Sep-2016	1,395 cc	24,192 km	
1 Owner, Almost Like New, Flawless Paint, Super Clean And Smoke Free Cabin, 100% Accident-free, Still Under Agent Warranty, Flexibl								
Loan Package Available, Kindly Contact Sales Person For Viewing Please. Thanks.								
Henly Enterprises Co								
Posted: 10-Sep-2019 Tags: 2016 Volkswagen Golf, 2016 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								

Rainbow IL-C6.2 VW Golf 6 Component Speakers

Rainbow IL-C6.2 2-way 6.5 inch Max. 150 Watts Component Speakers for VW Golf 6

[More info about this product](#)

[Compare](#)

swagen Golf Variant 1.4A \$73,800 \$9,710 /yr 23-Mar-2016 1,395 cc 65,000 km S

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019		10 Sep 2019 15:29 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: AHMAD SAIFUL RIJAL BIN HASSAN , ID: S8615726H									
Main Claimant: ONG KAR CHYE , ID: S1542185A									
Vehicle Reg. No.:	SMC1138K	Date of Loss:	07/09/2019 23:00 - :59 [39 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904271	Policy/Cover Note No.:	D18MTPV01014494 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJT2676M	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/09/2019]								
Driver/Custodian (Insured):	MUHAMMAD SIDDIQ MASHKUR BIN HASSAN (), NRIC: S9349711B, Tel: +6596170725 Email:								
Adj Asg. Remarks:	WS: SALLY 67452088								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC1138K (CMTD1904271)**
[SJT2676M]
TP
ONG KAR CHYE
Sep 7 2019 11:00PM
[AHMAD SAIFUL RIJAL BIN HASSAN]
Bluwel Automotive Service Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports				1 per page ▼	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print	
1	10/09/19 15:27	Accident Statement From:SC - Reg. No: SJT2676M, Claimant: AHMAD SAIFUL RIJAL BIN HASSAN	 Load HTM		

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	27/09/19 08:55	General View	 Load JPG	☒	
2	27/09/19 08:55	General View	 Load JPG	☒	
3	27/09/19 08:55	General View	 Load JPG	☒	
4	27/09/19 08:55	General View	 Load JPG	☒	
5	27/09/19 08:55	General View	 Load JPG	☒	
6	27/09/19 08:55	General View	 Load JPG	☒	
7	27/09/19 08:55	General View	 Load JPG	☒	
8	27/09/19 08:55	General View	 Load JPG	☒	
9	27/09/19 08:55	General View	 Load JPG	☒	
10	27/09/19 08:55	General View	 Load JPG	☒	
11	27/09/19 08:55	General View	 Load JPG	☒	
12	27/09/19 08:55	General View	 Load JPG	☒	
13	27/09/19 08:55	General View	 Load JPG	☒	
14	27/09/19 08:55	General View	 Load JPG	☒	
15	27/09/19 08:55	General View	 Load JPG	☒	
16	27/09/19 08:55	General View	 Load JPG	☒	
17	27/09/19 08:55	General View	 Load JPG	☒	
18	27/09/19 08:55	General View	 Load JPG	☒	
19	27/09/19 08:55	General View	 Load JPG	☒	
20	27/09/19 08:55	General View	 Load JPG	☒	
21	27/09/19 08:55	General View	 Load JPG	☒	
22	27/09/19 08:55	General View	 Load JPG	☒	
23	27/09/19 08:55	General View	 Load JPG	☒	
24	27/09/19 08:55	General View	 Load JPG	☒	
25	27/09/19 08:55	General View	 Load JPG	☒	
26	27/09/19 08:55	General View	 Load JPG	☒	
27	27/09/19 08:55	General View	 Load JPG	☒	
28	27/09/19 08:55	General View	 Load JPG	☒	
29	27/09/19 08:55	General View	 Load JPG	☒	
30	27/09/19 08:55	General View	 Load JPG	☒	
31	27/09/19 08:55	General View	 Load JPG	☒	
32	27/09/19 08:55	General View	 Load JPG	☒	
33	27/09/19 08:55	General View	 Load JPG	☒	
34	27/09/19 08:55	General View	 Load JPG	☒	
35	27/09/19 08:55	General View	 Load JPG	☒	
36	27/09/19 08:55	General View	 Load JPG	☒	

Assessment Reports			1 per page ▼	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
37	27/09/19 08:55	General View	 Load JPG	☒
38	27/09/19 08:55	General View	 Load JPG	☒
39	27/09/19 08:55	General View	 Load JPG	☒
40	27/09/19 08:55	General View	 Load JPG	☒
41	27/09/19 08:55	General View	 Load JPG	☒
42	27/09/19 08:55	General View	 Load JPG	☒
43	27/09/19 08:55	General View	 Load JPG	☒
44	27/09/19 08:55	General View	 Load JPG	☒
45	27/09/19 08:55	General View	 Load JPG	☒
46	27/09/19 08:55	General View	 Load JPG	☒
47	27/09/19 08:55	General View	 Load JPG	☒
48	27/09/19 08:55	General View	 Load JPG	☒
49	27/09/19 08:55	General View	 Load JPG	☒
50	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
51	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
52	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
53	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
54	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
55	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
56	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
57	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
58	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
59	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
60	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
61	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
62	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
63	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
64	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
65	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
66	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
67	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
68	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
69	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
70	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
71	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
72	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
73	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
74	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
75	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
76	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
77	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
78	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
79	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
80	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
81	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
82	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
83	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
84	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
85	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
86	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
87	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
88	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒
89	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
90	27/09/19 08:56	Photographs of Damaged Parts		☒
91	27/09/19 08:56	Photographs of Damaged Parts		☒
92	27/09/19 08:56	Photographs of Damaged Parts		☒
93	27/09/19 08:56	Photographs of Damaged Parts		☒
94	27/09/19 08:56	Photographs of Damaged Parts		☒
95	27/09/19 08:57	Photo After Spray		☒
96	27/09/19 08:57	Photo After Spray		☒
97	27/09/19 08:57	Photo After Spray		☒
98	27/09/19 08:57	Photo After Spray		☒
99	27/09/19 08:57	Photo After Spray		☒
100	27/09/19 08:57	Photo After Spray		☒
101	27/09/19 08:57	Photo After Spray		☒
102	27/09/19 08:57	Photo After Spray		☒
103	27/09/19 08:57	Photo After Spray		☒
104	27/09/19 08:57	Photo After Spray		☒
105	27/09/19 08:57	Photo After Spray		☒
106	27/09/19 08:57	Photo After Spray		☒
Documentation			1 per page ▼	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/09/19 15:26	Pre-Repair Survey		☒
2	10/09/19 15:26	Third Party E-filed GIA report(M)		☒
3	10/09/19 15:26	Pre-Repair Survey - ASSIGN LKK		☒
4	27/09/19 13:55	PD LOD W ENCLS DT 26.09.19 FR M NEDUMARAN & CO - SMC1138K PD LOD W ENCLS DT 26.09.19 FR M NEDUMARAN & CO - SMC1138K		☒

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19016045/UCF3S2
Date: 03/10/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01014494
Claimant Vehicle No : SMC1138K **Insured Vehicle No :** SGT2676M
Date of Loss: 07/09/2019 **Nature of Claim:** TP **Claim No:** CMTD1904271

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC1138K **Engine No:** CZD512309
Make & Model: VOLKSWAGEN GOLF, 1.4 (A) **Chassis No:** WWWZZZAUZGW274713
Reg. Date: 25/05/2016 (Man. Year: 2016) **Odometer:** 60816 km
Colour: White
Engine Capacity: 1395 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 235/40 R15 **Rear Tyre Size:** 235/40 R15
Front Left Side: Yokohama 6 mm **Rear Left Side:** Yokohama 6 mm
Front Right Side: Yokohama 6 mm **Rear Right Side:** Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION**Date of Assignment:** 10/09/2019**Date Inspected:** 11/09/2019 **Inspected At:**

Bluwel Automotive Service Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 6.0 days**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/3/2019

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500.00 - \$7,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2019)
Parts:	144	VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC1138K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >