

ASS. REC. BY:

REF: es/INC19016050/RlgBnz | Special Instruction:

Surveyor: Rasul

## ASSIGNMENT (Office)

From (Person): Annie Koh of INC Date/Time: 12:24pm @ 10/9/19

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 9876K Insured: XE 4372P

at Workshop m/s: Sene You Motor Tel: 92343188

of: SA Julien Poupin

Policy No: Claim No: MT/1061679-001

Sum Insured: Excess:

Make of Veh: D.O.A. 6/9/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 12:28pm @ 10/9/19 Person Contacted: Guine Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Johnnie ✓
	PA 9876K - CC6 / CTI / 6015371 / KygBnz
	XE 4372P - X.
	RA: 11/8/2016
	Rasul finalised LS \$2090, 3 days.
	(Red \$3760, 65%.)

*Rame*

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐  
 To Inspect Vehicle No: PA 9876K  
 at Workshop m/s 8 JALAN PAPAN  
 of \_\_\_\_\_  
 Insured: NML  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	1

Bal. or Market Value: 24K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: PA 9876K Yr Regn: 2010 / NOV  
 Type: M.Car / M.Cycle ☒ Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: HILUX KLAB 1.8 c.c. 6692  
 Colour: MULTI A/C: Insured / Std / NI / NA  
 Sp. Reading: 649338 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: LKLRIFSE4AC545219  
 Gen. Cond: Good ☒ Fair / Poor / Burnt  
 Steering: ☒ In order / Jammed / Leaked / Burnt or  
 Brake: ☒ In order / Jammed / Leaked / Burnt or  
 Modi: ☒ Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 10R 22-5  
 R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or DOUBLE COIN

Front		Rear
R/Bal. <u>8</u> mm		R/Bal. <u>8/8</u> mm
L/Bal. <u>8</u> mm		L/Bal. <u>8/8</u> mm
D.O.A. <u>06/09/19</u>		D.O.I. <u>10/09/19</u>
Survey held at <u>8, JALAN PAPAN</u>		<u>2.23pm</u>

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 OCT 2019

*[Signature]*  
4/10/2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 07/10 2019

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

250

Report Format:

TP

Lump Sum / Hourly

2000

TOTAL

## **Nivitha (LKK Auto)**

**From:** Annie Koh <[annie.koh@income.com.sg](mailto:annie.koh@income.com.sg)>  
**Sent:** Tuesday, 10 September 2019 12:24 PM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto)  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

**From:** Annie Koh  
**Sent:** Tuesday, 10 September 2019 11:58 AM  
**To:** 'assignments@lkkauto.com' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; 'Admin-D (LKKAuto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Re-send

Warmest Regards

**Annie Koh**  
Senior Admin,  
Motor Insurance  
T +65 64307899  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



**From:** Annie Koh  
**Sent:** Tuesday, 10 September 2019 9:24 AM  
**To:** 'assignments@lkkauto.com' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; 'Admin-D (LKKAuto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>; Teng Ken Leong <[kenleong.teng@income.com.sg](mailto:kenleong.teng@income.com.sg)>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	Workshop Name	Workshop Address	Workshop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Charlotte Chew	MT/1060673-002	SGJ6583J	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	celia lai / 92740999		SJT2613U	31/8/19	
2	Juliana Lee	MT/1061610-001	SGR3518B	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	celia lai / 92740999		SJM2951E	7/9/19	
3	Charlotte Chew	MT/1060994-002	SKT3638E	EUROKARS HABITAT PTE LTD	NO.27A TANJONG PENJURU SINGAPORE 609042	JOB THOMAS / 63310682	14:00-16:00	SHB8048E	4/9/19	
4	Serene Lim	MT/1061249-002	SLE1509A	HITACHI CAPITAL (S) PTE LTD	8 FOURTH LOK YANG ROAD SINGAPORE 629705	ng jiong how / 68336282	14:00-16:00	GBE3833T	5/9/19	
5	Helena Tan	MT/1059976-001	SMD2338M	KAH MOTOR CO SDN BHD	255 ALEXANDRA ROAD BODY REPAIR & PAINT CENTRE SINGAPORE 159937	jack ng / 82886309	10:00-12:00	FBE481U	28/8/19	
6	Azhari	MT/1053928-001	SMD518Z	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	caroline / 63190174	10:00-12:00	SMH5415H	17/7/19	
7	Alice Low	MT/1061272-002	SLW9079B	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	GEORGE WONG / 63662323	10:00-12:00	SLM6686X	5/9/19	

8	Jared Liu	MT/1061679-001	PA9876K	SERVE YOU MOTOR SERVICE	8 # JALAN PAPAN SINGAPORE 619418	ELAINE CHIA / 92393188	XE4372P	6/9/19	
9		To be advise	XD8408A	VFIX AUTO PTE LTD	26 CHIA PING ROAD SINGAPORE 619977	weng sheng / 64552957		14:00-16:00	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

[www.income.com.sg](http://www.income.com.sg)



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	917G
Vehicle Details	
Vehicle No.:	PA9876K
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	HIGER
Vehicle Model:	KLQ6108GQ 6.7 M/T ABS TURBO
Primary Colour:	Multicolor
Manufacturing Year:	2010
Engine No.:	ISBE4250B21950922
Chassis No.:	LKLR1FSE4AC545219
Maximum Power Output:	-
Open Market Value:	\$68,741.00
Original Registration Date:	26 Nov 2010
First Registration Date:	26 Nov 2010
Transfer Count:	1
Actual ARF Paid:	\$3,438.00
Intender PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intender COE Rebate Details	
COE Expiry Date:	25 Nov 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,002.00
COE Rebate Amount:	\$3,608.00
Total Rebate Amount:	\$3,608.00

The information contained herein is correct as at 12 Sep 2019

OK

24,000  
3,608  
20,392

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/09/2019 18:03
Date Of Accident	06/09/2019 15:50
Exact Location Of Accident	OLD JURONG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA9876K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	A&S TRANSIT PTE. LTD
Co Reg No	201216917G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63831111

### Vehicle Particulars

Manufacturer	HIGER
Model	KLQ6108GQ
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095393771-01
Cover Note Number	

### Driver

Name of Driver	HAMID BIN E MD ALI
Passport No/FIN	G6610627L
Date Of Birth	14/11/1979
Occupation	OUTDOOR
Date Of Driving Pass	28/11/2018
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91665876
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	11 WOODLANDS CLOSE #08-46/47
Postcode	737853
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED; REMARKS: TYPE OF ACCIDENT PLEASE REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE4372P
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED WITH TRD1926M
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHONG GEOK CHUAN
NRIC/Passport Number	G8024378U
Contact Number	81121177
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	



SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time: 

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 9/9/19

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER ATTACHED MY STATEMENT

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 9/9/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident involved: vehicle A) PA 9876 K (41 pax bus) /

Vehicle B) XE 4372 P / TRD 1926 M / Along: Old Jurong Road

Accident date: 06.09.19, time 1550 hours

I'm driving my vehicle A) PA 9876 K at along Old Jurong Road. On that time, there was only two lanes available and I'm on the extreme left lane and I noticed right side opposite direction an "oversized vehicle" XE 4372 P / TRD 1926 M was passing by towards my direction so I stopped and stationary to give way as the road is slightly bending.

Well, the vehicle passed by halfway, note that the heavy vehicle crane step board panel is too near and caused to my bus rear right side body pillar to damage along with the window glass to shatter.

Third party details: XE 4372 P / TRD 1926 M

Driver name: Chong Geok Chuan / FIN number: G8024378U

Contact number: 81121177

The above-mentioned driver initially wants to mutual settle and I will asked the driver to contact my boss, well, today, the reason for late reporting is that I received a call from the company (09.09.2019) mentioned third party at because there is insufficient settlement amount for my vehicle damage. Instead, third party

XE 4372 P / TRD 1926 M inform us to file a report to claim from the insurance company.

Nobody was injured on that time and I have accident scene photos for support.



Hamid Bin E MD ALI / G6610627L / 09.09.19

# SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2  
#01-265, SINGAPORE 569536  
TEL. NO: 64810555 / FAX NO. 64831654  
E-MAIL: elainesyms@gmail.com

INS: NTUC INCOME INSURANCE CO-OP LTD  
COMPANY: A & S TRANSIT PTE LTD

Registration no. : PA 9876 K / HIGER KLQ6108GQ 6.7 M/T ABS TURBO  
Acc/date: 6.9.2019

Date : 9-Sep-19

Quotation No. : CM190902

S/N	Qty	Item	Amount
-----	-----	------	--------

## SPECIAL NETT ITEMS

1	1	Rear RH tinted window glass <i>bro ✓</i>	1200 1680.00
2	1	Rear RH tinted window glass moulding <i>nee ✓</i>	250 380.00
3	1	Rear RH section body panel	repair
4	1	Rear RH tinted window glass sealant <i>nee</i>	150 300.00
			<u>2360.00</u>

## LABOUR & MISC CHARGES

1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	150 1500.00
2	To remove and refit window glass for replacement.	650 200 450.00
3	Supply spray paint material and necessary items to respray multi-layered on rear RH affected area.	300 1200.00
4	To special vacuum the interior passenger seats to remove the glass debris	nn X 250.00
<b>TOTAL</b>		<u>3400.00</u>

**Total Parts and Labour Cost of Repair**

**\$5,760.00**

*Rasm*  
*Hp 90010068*  
*3 days*  
*4/3*  
*10/09/19 @ 1420*  
*Resurvey after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Page 1 of 1

*1600*  
*650*  
*2250*  
*10%*  
*2025*  
*45-2000*  
*3 days*

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19016050/R1qd3n2

73 BRAS BASAH ROAD

Date: 10-10-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

ATTN: JARED LIU

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	XE 4372P	Veh. Inspected	PA 9876K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1061679-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	10/09/2019

**2. Vehicle Particulars & Condition**

Make & Model	HIGER KLQ6108GQ 6.7	c.c	6692
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	LKLR1FSE4AC545219	Colour	MULTI
Odometer	649338 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	10 R22.5	DOUBLE COIN	8 mm
L/H Front Tyre	10 R22.5	DOUBLE COIN	8 mm
R/H Rear Tyre	10 R22.5 (D)	DOUBLE COIN	8/8 mm
L/H Rear Tyre	10 R22.5 (D)	DOUBLE COIN	8/8 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	06/09/2019	Inspect Date / Time	10/09/2019 ( 02:23 PM )
Survey held at	8A JALAN PAPAN		
Repairer	SERVE YOU MOTOR SERVICE		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 9876K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR RH TINTED WINDOW GLASS (SN)	BROKEN	1,680.00	1,200.00
1	REAR RH TINTED WINDOW GLASS MOULDING (SN)	NECESSARY	380.00	250.00
1	REAR RH SECTION BODY PANEL (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	REAR RH TINTED WINDOW GLASS SEALANT (SN)	NECESSARY	300.00	150.00
			2,360.00	1,600.00
	<b>LABOUR</b>			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR RH SECTION BODY PANEL.		1,500.00	150.00
	TO REMOVE AND REFIT WINDOW GLASS FOR REPLACEMENT.		450.00	200.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY MULTI-LAYERED ON REAR RH AFFECTED AREA.		1,200.00	300.00
	TO SPECIAL VACUUM THE INTERIOR PASSENGER SEATS TO REMOVE THE GLASS DEBRIS.	NOT NECESSARY	250.00	-
			3,400.00	650.00
	<b>GRAND TOTAL</b>		<b>5,760.00</b>	<b>2,250.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,000.00</b>

Report Ref No. CS/INC19016050/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS  
Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.