

ASS. REC. BY:

REF: CS/INC19016064/71vd321 Special Instruction:

Surveyor: TaufikhASSIGNMENT (Office)From (Person): Annie Koh

of

INCDate/Time: 12:24pm @ 10/9/19

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SQR 3518B

Insured:

SJM 2951E

at Workshop in/s

Accord Auto

Tel:

92740999

of

Blk 1009 Blct merch lane 3 # 01-80

Policy No:

Claim No:

MT/1061610-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:43pm @ 10/9/19

Person Contacted:

CelicaVehicle IN OUT

Date/Time

Action/Instruction

Taufikh ✓SQR 3518B - CS/SMO1901594/f3DUA: 7/9/2019SJM 2951E - CS/SMO1901594/f3DUA: 7/9/201925/9/19Taufikh Said part prices - OK25/9/19LS \$ 5650 Confirmed by email (Red 6636.51, 5410)

Taylor
Ginn

REF:

INC

ASSIGNMENT

LOE 2022 Feb

2007 Feb

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$20K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGR3518R Yr Regn: 2007 Feb
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Wish c.c. 1797
Colour: Blue A/C: Insured / Std / NI / NA
Sp.Reading: 334549 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ENE100335477
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 10/9/19 0445pm

Survey held at Accord Hub
Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Regru limit \$7K, inform n/s

note: \$12,523

RECEIVED 20 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

1)

Date/Time, File Return to?

2) 26/9 - typist

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : TP

Lump Sum / I.B.I. (\$) 5650 1/2

290

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 10 September 2019 12:24 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

From: Annie Koh
Sent: Tuesday, 10 September 2019 11:58 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg

income
mode different



From: Annie Koh
Sent: Tuesday, 10 September 2019 9:24 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Charlotte Chew	MT/1060673-002	SGJ6583J	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	celia lai / 92740999		SJT2613U	31/8/19	
2	Juliana Lee	MT/1061610-001	SGR3518B	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	celia lai / 92740999		SJM2951E	7/9/19	
3	Charlotte Chew	MT/1060994-002	SKT3638E	EUROKARS HABITAT PTE LTD	NO.27A TANJONG PENJURU SINGAPORE 609042	JOB THOMAS / 63310682	14:00-16:00	SHB8048E	4/9/19	
4	Serene Lim	MT/1061249-002	SLE1509A	HITACHI CAPITAL (S) PTE LTD	8 FOURTH LOK YANG ROAD SINGAPORE 629705	ng jiong how / 68336282	14:00-16:00	GBE3833T	5/9/19	
5	Helena Tan	MT/1059976-001	SMD2338M	KAH MOTOR CO SDN BHD	255 ALEXANDRA ROAD BODY REPAIR & PAINT CENTRE SINGAPORE 159937	jack ng / 82886309	10:00-12:00	FBE481U	28/8/19	
6	Azhari	MT/1053928-001	SMD518Z	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	caroline / 63190174	10:00-12:00	SMH5415H	17/7/19	
7	Alice Low	MT/1061272-002	SLW9079B	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	GEORGE WONG / 63662323	10:00-12:00	SLM6686X	5/9/19	

8	Jared Liu	MT/1061679-001	PA9876K	SERVE YOU MOTOR SERVICE	8 # JALAN PAPAN SINGAPORE 619418	ELAINE CHIA / 92393188	XE4372P	6/9/19	
9		To be advise	XD8408A	VFIX AUTO PTE LTD	26 CHIA PING ROAD SINGAPORE 619977	weng sheng / 64552957		14:00-16:00	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 664I

Vehicle Details

Vehicle No.: SGR3518B
Vehicle to be Exported: No
Intended Deregistration Date: 11 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 A
Primary Colour: Blue
Manufacturing Year: 2006
Engine No.: 1ZZ2741626
Chassis No.: ZNE100335477
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$17,928.00
Original Registration Date: 06 Feb 2007
First Registration Date: 06 Feb 2007
Transfer Count: 1
Actual ARF Paid: \$19,721.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 05 Feb 2022
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$26,039.00
COE Rebate Amount: \$12,509.00
Total Rebate Amount: \$12,509.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.
The information contained herein is correct as at 11 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 11:03
Date Of Accident	07/09/2019 15:45
Exact Location Of Accident	YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGR3518B
Insured/Policyholder	
Name Of Registered Owner	DING TEO GOD
NRIC No	S7172664I
Email Address	MOSESNDOROTHY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91398709
Alternative Phone No	OTHERS-63570484

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01001347
Cover Note Number	

Driver

Name of Driver	EVANGELYN DING XIN YU
NRIC No	T0005758J
Date Of Birth	27/02/2000
Occupation	INDOOR
Date Of Driving Pass	31/01/2019
Driving Experience	0 YEAR AND 7 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-98646332
Fax Number	
Contact Number	
Email Address	EVANGELYNDING.XY@GMAIL.COM

Address	BLK 352C CANBERRA ROAD #13-241
Postcode	753352
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

While I travelling along Yishun Ave 1 at lane 1. Suddenly Vehicle B cut into my lane and we collided.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM2951E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

Veh A: SGR 3518 B

Veh B: SJM 2951E


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders

I AM AWARE THAT MY INSURER (AND/OR MY WORKSHOP) WILL SUBMIT AN AUTO DAMAGE CLAIM UNDER MY OWN POLICY (I WILL CHECK MY POLICY FOR MORE DETAILS)


Policyholder's Signature: 9/9/19
Date & Time: 9:30am


Driver's Signature
(If driver is not the policyholder)
Date & Time: 9:50 am



Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No: _____

Sketch Plan #2

SKETCH PLAN

Veh A: SGR 3518 B

Veh B: SJM 2951 E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While i traveling along Yishun Ave 1 at lane 1. Suddenly Vehicle B Cut into my lane and we collided.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature] 9/9/19
Policyholder's Signature

Date & Time: 09:50 am

[Signature] 9/9/19
Driver's Signature

(If driver is not the policyholder)

Date & Time: 9:52 am



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 / 62717433 FAX: 62745715

ESTIMATE REPAIR

Pg1

NTUC Income Ins Co-Op Ltd

Date: 9.9.2019

Owner's Name : Ding Teo God

Vehicle No : SGR3518B

Vehicle Make & Model : Toyota Wish 1.8 A

Registration Date : 6 Feb 2007 (YOM 2006) COE Expiry Date 5 Feb 2022

Claim Type: Third Party Claim

Chassis No: ZNE100335477

DOA: 7.9.2019

No	Description	Unit	List (\$)
1	FRONT BONNET	1	\$ <i>bt</i> 880.00
2	FRONT BONNET LOGO (WITH CHORME)	1	\$ <i>aw</i> 85.00
3	FRONT BONNET LOCK	1	\$ <i>bt</i> 115.00
4	FRONT BONNET HINGE - <i>photo</i>	2	\$ <i>bt</i> 160 160.00
5	FRONT BONNET SEAL	1	\$ <i>aw</i> 65.00
6	FRONT BONNET BRACE PANEL	1	\$ <i>bt</i> 85.00
7	FRONT BONNET INSULATOR	1	\$ <i>de</i> 220.00
8	FRONT BONNET INSULATOR CLIPS	Set	\$ <i>aw</i> 35.00
9	FRONT BONNET RUBBER	1	\$ <i>aw</i> 95.00
10	FRONT BONNET STAND CLIP	1	\$ <i>x un</i> 18.00
11	FRONT BONNET CABLE	1	\$ <i>x un</i> 95.00
12	FRONT HEADLAMP LH	1	\$ <i>aw</i> 620.00
13	FRONT HEADLAMP RH	1	\$ <i>aw</i> 620.00
14	FRONT HEADLAMP BRACKET LH & RH	2	\$ <i>x un</i> 150.00
15	FRONT BUMPER	1	\$ <i>de</i> 780.00
16	FRONT BUMPER SIDE RETAINER LH & RH <i>65</i>	2	\$ <i>LH-X, RH-de</i> 130.00
17	FRONT BUMPER SPONGE	1	\$ <i>aw</i> 115.00
18	FRONT BUMPER CLIPS	SET	\$ <i>aw</i> 35.00
19	FRONT BUMPER LOWER FRILLE	1	\$ <i>de</i> 155.00
20	FRONT BUMPER GRILLE (CENTRE)	1	\$ <i>? aw x un</i> 155.00
21	FRONT GRILLE ASSY	1	\$ <i>aw</i> 265.98
22	FRONT LH FOGLAMP GARNISH	1	\$ <i>x un</i> 105.65
23	FRONT RH FOGLAMP GARNISH	1	\$ <i>x un</i> 105.65
24	FRONT FENDER SHIELD LH & RH	2	\$ <i>LH-X, RH-X un</i> 230.00
25	FRONT FENDER SHIELD CLIPS	2 SET	\$ <i>x un</i> 70.00
26	WASHER WHISPER TANK	1	\$ <i>x</i> 128.98
27	WASHER WHISPER PIPE	1	\$ <i>x un</i> 166.00
28	WINDSHIELD WASHER PUMP MOTOR	1	\$ <i>x</i> 168.52
Total (A) :			\$ 5,853.78
Less 25%			\$ 1,463.45
Grand Total:			\$ 4,390.34

TEL:62715133/ 62717433 FAX:62745715

ESTIMATE REPAIR

Pg2

NTUC Income Ins Co-Op Ltd

Date: 9.9.2019

Owner's Name : Ding Teo God

Vehicle No : SGR3518B

Claim Type: Third Party Claim

Vehicle Make & Model : Toyota Wish 1.8 A

Chassis No: ZNE100335477

Registration Date : 6 Feb 2007 (YOM 2006) COE Expiry Date 5 Feb 2022

DOA: 7.9.2019

No	Description	Unit	List (\$)
29	RADIATOR	1	\$? cra ✓ 722.25
30	RADIATOR AUTO FAN MOTOR	1	\$? cra ✓ 240.00
31	RADIATOR AUTO FAN COWLING	1	\$? cra ✓ 173.34
32	RADIATOR TANK	1	\$ X nn . 154.45
33	AIRCON CONDENSER	1	\$ bt - 808.92
34	AIRCON CONDENSER HOSE	1	\$? } 220.00
35	AIRCON PIPE	1	\$? } X 225.00
36	RADIATOR FAN BLADE	1	\$? } nn 177.65
37	AIR CLEANER BOX	1	\$ X 162.50
38	AIR CLEANER HOSE	1	\$ Y 88.00
39	BATTERY BRACKET	1	\$ X 65.00
40	BATTERY TRAY	1	\$ X 55.00
41	UNDER ENGINE COVER	1	\$? 231.12
42	UNDER ENGINE COVER CLIPS	SET	\$! 35.00
43	RADIATOR SIDE AIR DUCT	2	\$ X 60.00
44	FRONT FENDER LH	1	\$ X 420.00
45	FRONT FENDER RH	1	\$ X 420.00
46	FRONT SUPPORT PANEL	1	\$ bt - 420.00
47	FRONT REINFORCEMENT BAR	1	\$ bt - 280.00
48	FRONT REINFORCEMENT ARM LH & RH	2	\$ X nn 250.00
49	HORN	1	\$ X nn 80.00
		Total (B) :	\$ 5,288.23
		Less 25%	\$ 1,322.06
		Grand Total:	\$ 3,966.17

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/ 62717433 FAX:62745715

ESTIMATE REPAIR

Pg3

NTUC Income Ins Co-Op Ltd

Date: 9.9.2019

Owner's Name : Ding Teo Gōd

Vehicle No : SGR3518B

Vehicle Make & Model : Toyota Wish 1.8 A

Registration Date : 6 Feb 2007 (YOM 2006) COE Expiry Date 5 Feb 2022

Claim Type: Third Party Claim

Chassis No: ZNE100335477

DOA: 7.9.2019

No	Description	Unit	List (\$)
	Special Nett		
1	CAR PLATE NUMBER WITH HOLDER	1	\$ 50.00 45 50.00
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
	Acknowledged by Repairer Signature: Date:		
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 1,200.00 730 1,200.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 1,600.00 800 1,600.00
3	Check Wiring System & Light	1	\$ 100.00 30 100.00
4	Anti Rust Treatment	1	\$ 120.00 40 120.00
5	To Check & Adjust Front Wheel Aligment	1	\$ 120.00 X nm. 120.00
6	To Remove / Refix Air-con Condensor (Top up Gas, Pipe & Etc...)	1	\$ 180.00 100 180.00
7	To Remove / Replace/Refix Radiator (piping/hose ,top up radiator coolant & etc...)	1	\$ 180.00 120 180.00
8	To Realign & Straight Main Chassis Frame	1	\$ 380.00 nm. X 380.00
	Tanpin 9749549 'wp' 10/9/19 Lumpy Repair after repair 6 days To check repair limit. sure / want. am		
Total (C) :			\$ 3,930.00
Grand Total:			\$ 12,286.51

Veron Chen (LKKAUTO)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Wednesday, 25 September 2019 6:15 PM
To: Veron Chen (LKKAUTO)
Cc: Taufikh (LKKAUTO); SUR
Subject: Re: Photos After Photos SGR3518B-DOA:7/9/2019

Dear Veron,

Accept with thanks!

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Wed, Sep 25, 2019 at 2:45 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Celia,

WITHOUT PREJUDICE

Offer Lump Sum \$5650 @ 6 working days

PARTS-\$7155.49 (less 25%)=\$5,366.62

SN-\$45

LABOUR-\$1690

TOTAL-\$7,101.62 (less 20%)=\$5681.29

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>

Sent: Monday, 23 September 2019 5:14 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: Photos After Photos SGR3518B

Dear Taufikh,

Kindly refer photos after repair as attached and please finalize.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19016064/T1vd3e2
73 BRAS BASAH ROAD Date: 01-10-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN : JULIANA LEE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 2951E	Veh. Inspected	SGR 3518B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1061610-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	10/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ZNE100335477	Colour	BLUE
Odometer	334549 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2019	Inspect Date / Time	10/09/2019 (04:35 PM)
Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 3518B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	BENT	880.00	880.00
1	FRONT BONNET LOGO (WITH CHROME)	CRACKED	85.00	85.00
1	FRONT BONNET LOCK	BENT	115.00	115.00
2	FRONT BONNET HINGE	BENT	160.00	160.00
1	FRONT BONNET SEAL	NECESSARY	65.00	65.00
1	FRONT BONNET BRACE PANEL	BENT	85.00	85.00
1	FRONT BONNET INSULATOR	DEFORMED	220.00	220.00
1	SET FRONT BONNET INSULATOR CLIPS	NECESSARY	35.00	35.00
1	FRONT BONNET RUBBER	CUT	95.00	95.00
1	FRONT BONNET STAND CLIP	NOT NECESSARY	18.00	-
1	FRONT BONNET CABLE	NOT NECESSARY	95.00	-
1	FRONT HEADLAMP LH	CRACKED	620.00	620.00
1	FRONT HEADLAMP RH	CRACKED	620.00	620.00
2	FRONT HEADLAMP BRACKET LH & RH	NOT NECESSARY	150.00	-
1	FRONT BUMPER	DEFORMED	780.00	780.00
2	FRONT BUMPER SIDE RETAINER LH & RH	N/S NOT NECESSARY / O/S DEFORMED	130.00	65.00
1	FRONT BUMPER SPONGE	CRACKED	115.00	115.00
1	SET FRONT BUMPER CLIPS	NECESSARY	35.00	35.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	155.00	155.00
1	FRONT BUMPER GRILLE (CENTRE)	NOT NECESSARY	155.00	-
1	FRONT GRILLE ASSY	CRACKED	265.98	265.98
1	FRONT LH FOGLAMP GARNISH	NOT NECESSARY	105.65	-
1	FRONT RH FOGLAMP GARNISH	NOT NECESSARY	105.65	-
2	FRONT FENDER SHIELD LH & RH	NOT NECESSARY	230.00	-
2	SET FRONT FENDER SHIELD CLIPS	NOT NECESSARY	70.00	-
1	WASHER WHISPER TANK	NOT NECESSARY	128.98	-
1	WASHER WHISPER TANK	NOT NECESSARY	166.00	-
1	WINDSHIELD WASHER PUMP MOTOR	NOT NECESSARY	168.52	-
1	RADIATOR	CRACKED	722.25	722.25

Report Ref No. CS/INC19016064/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR AUTO FAN MOTOR	CRACKED	240.00	240.00
1	RADIATOR AUTO FAN COWLING	CRACKED	173.34	173.34
1	RADIATOR TANK	NOT NECESSARY	154.45	-
1	AIRCON CONDENSER	BENT	808.92	808.92
1	AIRCON CONDENSER HOSE	NOT NECESSARY	220.00	-
1	AIRCON PIPE	NOT NECESSARY	225.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	177.65	-
1	AIR CLEANER BOX	NOT NECESSARY	162.50	-
1	AIR CLEANER HOSE	NOT NECESSARY	88.00	-
1	BATTERY BRACKET	NOT NECESSARY	65.00	-
1	BATTERY TRAY	NOT NECESSARY	55.00	-
1	UNDER ENGINE COVER	NOT NECESSARY	231.12	-
1	SET UNDER ENGINE COVER CLIPS	NOT NECESSARY	35.00	-
2	RADIATOR SIDE AIR DUCT	NOT NECESSARY	60.00	-
1	FRONT FENDER LH	NOT NECESSARY	420.00	-
1	FRONT FENDER RH	NOT NECESSARY	420.00	-
1	FRONT SUPPORT PANEL	BENT	420.00	420.00
1	FRONT REINFORCEMENT BAR	BENT	280.00	280.00
2	FRONT REINFORCEMENT ARM LH & RH	NOT NECESSARY	250.00	-
1	HORN	NOT NECESSARY	80.00	-
	LESS 25% DISCOUNT		-2,785.50	-1,760.12
			8,356.51	5,280.37
	<u>SPECIAL NETT ITEMS</u>			
1	CAR PLATE NUMBER WITH HOLDER (SN)	CRACKED	50.00	45.00
			50.00	45.00
	<u>LABOUR</u>			
	SPRAY PAINTING TO ALL AFFECTED AREAS.		1,200.00	750.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.		1,600.00	700.00
	CHECK WIRING SYSTEM & LIGHT.		100.00	30.00
	ANTI RUST TREATMENT.		120.00	40.00
	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-

Report Ref No. CS/INC19016064/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIX AIR-CON CONDENSOR (TOP UP GAS, PIPE & ETC...)		180.00	100.00
	TO REMOVE / REPLACE / REFIX RADIATOR (PIPING / HOSE, TOP UP RADIATOR COOLANT & ETC...)		180.00	120.00
	TO REALIGN & STRAIGHT MAIN CHASSIS FRAME.	NOT NECESSARY	380.00	-
			3,880.00	1,740.00
GRAND TOTAL			12,286.51	7,065.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				5,650.00

Report Ref No. CS/INC19016064/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.