

ASS. REC. BY:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong

of SMD

Date/Time: 10.9.19 17.30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 5577J

Insured: XD 5732H

at Workshop m/s Guan Auto

Tel: 93884210

of Blk 7 Sin Ming Industrial Estate Sector C #01-80

Policy No: DIGMTH (VE 00305)

Claim No: CMTD1904277

Sum Insured:

Excess:

D.O.A. 9.9.2019

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement:

Date/Time: 11.9.19 10.23am

Person Contacted: Jacky

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKA 5577J - CS/INC 1507/197/TIVX2 DOA - 05/09/2019
	XD 5732H - X
	Dismantle: 12/9/2019
	After repair: 20/9/2019

REF: SMD

PRS

ASSIGNMENT

From: _____ Date: **11.9.2019**

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKA 5577J**

at Workshop n/s **Guan Auto**

of **Blk 7 Sheng Industrial Estate Sec 6**

Insured **C #01-80**

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **ny'**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKA 5577J** Yr Regn: **NOV / 2010**

Type: (M) Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Toyota altis** cc **1598**

Colour: **Beige** A/C: Insured / Std / NI / NA

Sp. Reading: **148256** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **MT053ZFE106176703**

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or _____

Brake: (Inorder) / Jammed / Leaked / Burnt or _____

Modi: Nil / (S/Rim) / STD A/Rim or _____

Tyre Size: F: **195/65 R15**

R: **195/65 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **FALKEN**


Front	Rear
R/Bal. 4 / RUN mm	R/Bal. 4 mm
L/Bal. 4 mm	L/Bal. 4 mm
D.O.A. 09/09/2019	D.O.I. 11/09/19

Survey held at **Guan auto**

Des. of Damages: (Frt) / Rear / O/S / (N/S) / U/C / Rooftop or

Frt O/S N/S / Rear O/S / N/S / O/S

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	Repair days: 12 days Range \$11000-\$12000
	MU: \$21000 PV: \$13402 NV: \$7000*
	24/9/2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : **PRG.**

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: **12**

Resurvey No. of Trip: **2**

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS, SI _____

Photos _____

Others _____

TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2019		10 Sep 2019 17:32 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SENG GUAN CONTAINER SERVICE, Co. Reg. No.: 52287700A		
Main Claimant:	CHUAH TAIK SIM, ID: S01236191		
Vehicle Reg. No.:	SKA5577J	Date of Loss:	09/09/2019 08:00 - :59
Claim Type:	TP / CMTD1904277	Policy/Cover Note No.:	D18MTHCVE003051 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	XD5732H	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Auto Service (SING MING) Blk 7 Sin Ming Industrial Estate Sector C, #01-80, #01-82, 575642 Sin Ming - Tel: 93884210		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/09/2019]		
Adj Asg. Remarks:	WS: JACKY 93884210 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2019 10:04
Date Of Accident	09/09/2019 08:25
Exact Location Of Accident	ALONG PENJURU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA5577J
Insured/Policyholder	
Name Of Registered Owner	CHUAH TAIK SIM
NRIC No	S0123619I
Email Address	CHUAH_TS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93368181
Alternative Phone No	OTHERS-93368181

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800125608
Cover Note Number	

Driver

Name of Driver	CHUAH TAIK SIM
NRIC No	S0123619I
Date Of Birth	11/10/1953
Occupation	INDOOR
Date Of Driving Pass	18/10/1984
Driving Experience	34 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93368181
Fax Number	
Contact Number	OTHERS-93368181
EEmail Address	CHUAH_TS@HOTMAIL.COM

Address	57 YUK TONG AVENUE
Postcode	596358
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 1 TOH YI DRIVE , POSTCODE: 590001 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4689999 - FAX NO: 64623782
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20190909/2083.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD5732H
Vehicle Make/Model/Colour	TRAILER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHUAH TAIK SIM
Approximate Age	65
Injuries Sustain	
Injured person in which vehicle?	SKA5577J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	57 YUK TONG AVENUE
Postcode	596358

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:
10 SEP 2019
C05004A2




Driver's Signature
(If driver is not the policyholder)
Date & Time: 10/9/2019
C0504A2



Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/FIN No.: S6340583A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SEE POLICE REPORT T/20190909/2083.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

10 SEP 2019

© 2007-2014 Zurich Insurance Ltd

[Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time:

10 Sept 2019

[Signature]

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

.wee Choo
S6340583A



**SINGAPORE
POLICE FORCE**



T/20190909/2083

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

1 of 3

Report No. T/20190909/2083

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/09/2019 14:26	Vide Report No.: D/20190909/0039	Station Diary No.: 13
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: CHUAH TAIK SIM		Address: 57 YUK TONG AVENUE SINGAPORE 596358	
ID Type / ID No.: NRIC NO / S0123619I		Contact No.: Home/Office: Mobile: 93368181	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 65	Date of Birth: 11/10/1953	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: FINANCE MANGER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 09/09/2019 08:25	Type of Location: Straight Road
Location: Along Road 1 PENJURU ROAD				
Lamp Post Number: 55				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKA5577J	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Beige	Seriously Damaged	1
XD5732H	Trailer				Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SKA5577J	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800125608	22/11/2018	21/11/2019



**SINGAPORE
POLICE FORCE**



T/20190909/2083

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

2 of 3

Report No. T/20190909/2083

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHUAH TAIK SIM	ID No.	S0123619I
Related Vehicle	SKA5577J (Car)	Contact No.	93368181
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	09/09/2019	Date Discharge	09/09/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

On the above mentioned date, time and location, I was driving on the extreme left of 2 lanes when suddenly I felt an impact on the right rear and lost control of my vehicle. The car then mount the curb and hit onto a tree. The traffic in front of me was travelling smoothly. The driver wanted change lane and did not see my car thus the collision happened.

I called for the police and shortly after, Traffic Police and Ambulance arrived at the accident location. I was then conveyed to Ng Then Fong General Hospital and received 2 days MC. My car was towed to a car workshop by my husband. There is no in car camera installed in my vehicle.



SINGAPORE
POLICE FORCE



T/20190909/2083

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

3 of 3
Report No. T/20190909/2083

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 3 SAIFULBAHRI BIN SHA'ARI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 09/09/2019 14:26
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI Contact No.: 65476904	Classification Of Case:
Authentication Stamp NP168	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 619I

Vehicle Details

Vehicle No.: SKA5577J

Vehicle to be Exported: No

Intended Deregistration Date: 20 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Beige

Manufacturing Year: 2010

Engine No.: 3ZZB003272

Chassis No.: MR053ZEE106176703

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$16,680.00

Original Registration Date: 22 Nov 2010

First Registration Date: 22 Nov 2010

Transfer Count: 0

Actual ARF Paid: \$16,680.00 $\times 50\% = \underline{\$8340}$

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Nov 2020

PARF Rebate Amount: \$9,174.00

Intended COE Rebate Details

COE Expiry Date: 21 Nov 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$36,162.00

COE Rebate Amount: \$4,228.00

Total Rebate Amount: \$13,402.00

The information contained herein is correct as at 20 Sep 2019

Remaining: 1 year 2 months 12 days (14.3)

OK

Depn: \$11000/yearly \$916.66/monthly

$14.3 \times \$916.66 = \underline{\$13108.23}$

$\$13108.23 + \$8340 = \underline{\underline{\$21448.23}}$



Toyota Corolla Altis 1.6A (New 5-yr COE) \$34,800 \$6,950 /yr 09-Feb-2010 1,598 cc - Sedan Available

One Owner Only! Well Maintained, Unit In Excellent Condition! Don't Miss This Unit! Bank Or In House Loan Available. Call For More Enquiries!

Posted: 13-Sep-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) \$34,800 \$6,950 /yr 04-Jan-2010 1,598 cc 151,000 km Sedan Available

Comes With New Cushion. New Coat Of Paint. Servicing Done Up And Really To Go. 100% Loan Available. High Trade In. Call Our Friendly Sales Representative Now!

ABWIN (1994) Pte Ltd

Posted: 13-Sep-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) \$34,800 \$6,950 /yr 22-Jan-2010 1,598 cc 164,213 km Sedan Available

Very Well Kept Interior, Accident-Free, Road Tax Till Jan 2020, Don't Miss. High Loan, Trade In Welcome.

Posted: 03-Aug-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A \$19,700 \$10,850 /yr 07-Oct-2010 1,598 cc 142,000 km Sedan Available

Genuine Low Mileage Of 142,000km. Best For Short Term Drive! Clean And Neat Interior With Beautiful Paintwork, No Repairs Needed, Well Maintained By A Careful Owner, Full Leather Interior, Mint Condition! Act Fast And Call Now To Fix An Appointment With Us!

Posted: 20-Sep-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



BlackVue DR750S Car Camera

Equipped with Sony Starvis CMOS Sensor, this blackvue full HD cloud camera gives you best image quality under any light condition. Find the list of the best cameras available, each with product information and user reviews.

Find out more!



Toyota Corolla Altis 1.6A Elegance \$17,999 \$11,520 /yr 23-Jul-2010 1,598 cc 168,000 km Sedan Available

Original Paintwork, Very Well Maintained, Practical And Good Fuel Efficiency Ideal For Daily Drives. PARF And Body Value \$10K When Deregister. New Tyres And Mats. Road Tax Paid Till End Of COE. Excellent For COE Renewal. No Car Dealers/Agents.

DIRECT OWNER

Posted: 19-Sep-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A \$16,800 \$12,370 /yr 27-May-2010 1,598 cc 93,123 km Sedan Available

100% Loan Available, We Only Select The Best Unit To Sell. All Our Car Come With Trade In Welcomed. Buy With A Peace Of Mind As Car Is In Fantastic Condition. Hurry, Call For Availability Or Viewing Appointment.

Taxis

Posted: 19-Sep-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A \$16,838 N.A 26-Feb-2010 1,598 cc 165,484 km Sedan Available

Just Arrived! Excellent Condition Assured And Peace Of Mind. Very Well Maintained, Trade In Welcome, Act Fast Before It's Gone! 100% In House Loan Available. View To Believe! Don't Miss, Call Today!

Posted: 14-Sep-2019 Tags: 2010 Toyota Corolla, 2010 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota altis, toyota altis Singapore, used toyota altis Singapore, used toyota altis, used vehicles Singapore or even buy used toyota altis Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2019		10 Sep 2019 17:32 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SENG GUAN CONTAINER SERVICE , Co. Reg. No.: 52287700A								
Main Claimant:	CHUAH TAIK SIM , ID: S0123619I								
Vehicle Reg. No.:	SKA5577J	Date of Loss:	09/09/2019 08:00 - :59 [105 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904277	Policy/Cover Note No.:	D18MTHCVE003051 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	XD5732H	Policy No. (Claimant):							
		Excess:							
Repairer:	Guan Auto Service (SING MING) Blk 7 Sin Ming Industrial Estate Sector C, #01-80, #01-82, 575642 Sin Ming - Tel: 93884210								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/09/2019]								
Adj Asg. Remarks:	WS: JACKY 93884210 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA5577J (CMTD1904277)
 [XD5732H]
 TP
CHUAH TAIK SIM
 Sep 9 2019 8:00AM
[SENG GUAN CONTAINER SERVICE]
 Guan Auto Service

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▼
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
2	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
3	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
4	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
5	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
6	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
7	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
8	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
9	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
10	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
11	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
12	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
13	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
14	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
15	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
16	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
17	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
18	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
19	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
20	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
21	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
22	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
23	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
24	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
25	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
26	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
27	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
28	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
29	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
30	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
31	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
32	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
33	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
34	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
35	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
36	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
37	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
38	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
39	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>
40	17/09/19 12:11	General View		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
60	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
61	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
62	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
63	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
64	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
66	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
67	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
68	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
69	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
70	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
71	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
72	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
73	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
74	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
75	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
76	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
77	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
78	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
79	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
80	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
81	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
82	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
83	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
84	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
85	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
86	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
87	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
88	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
89	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
90	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
91	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
92	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
93	17/09/19 12:11	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
95	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
96	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
97	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
98	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
99	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
100	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
101	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
102	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
103	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
104	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
105	17/09/19 12:11	General View	 Load JPG	<input checked="" type="checkbox"/>
106	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	17/09/19 12:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	25/09/19 09:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
142	25/09/19 09:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
143	25/09/19 09:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
144	25/09/19 09:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
145	25/09/19 09:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
146	25/09/19 09:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
147	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
150	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
151	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
152	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
153	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
154	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
155	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
156	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
157	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
158	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
159	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
160	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
161	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
162	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
163	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
164	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
165	25/09/19 09:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
166	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
167	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
168	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
169	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
170	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
171	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
172	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
173	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
174	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
175	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
176	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
177	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
178	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
179	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
180	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
181	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
182	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
183	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
184	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
185	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
186	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
187	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
188	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
189	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
190	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
191	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
192	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
193	25/09/19 09:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
194	25/09/19 09:59	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
195	25/09/19 09:59	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
196	25/09/19 09:59	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
197	25/09/19 09:59	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
198	25/09/19 09:59	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
199	25/09/19 09:59	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	☑
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
200	25/09/19 09:59	Photo After Spray	 Load JPG	☑
201	25/09/19 09:59	Photo After Spray	 Load JPG	☑
202	25/09/19 09:59	Photo After Spray	 Load JPG	☑
203	25/09/19 09:59	Photo After Spray	 Load JPG	☑
204	25/09/19 09:59	Photo After Spray	 Load JPG	☑
205	25/09/19 09:59	Photo After Spray	 Load JPG	☑
206	25/09/19 09:59	Photo After Spray	 Load JPG	☑

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19016112/FCF3S2

Date: 30/09/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTHCVE003051
Claimant Vehicle No : SKA5577J **Insured Vehicle No :** XD5732H
 Date of Loss: 09/09/2019 Nature of Claim: TP Claim No: CMTD1904277

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA5577J**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZB003272
 Reg. Date: 22/11/2010 (Man. Year: 2010) Chassis No: MR053ZEE106176703
 Colour: Beige Odometer: 148256 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Falken 4 mm Rear Left Side: Falken 4 mm
 Front Right Side: Falken 4 mm Rear Right Side: Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/09/2019
 Date Inspected: 11/09/2019 Inspected At: Guan Auto Service (SING MING)
 Blk 7 Sin Ming Industrial Estate Sector C, #01-80,
 #01-82
 Singapore 575642
 Estimated Period of Repair: 12.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$11,000.00 - \$12,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA5577J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >