

ASS. REC. BY:

REF:

CS3/CTI19016125/Fcd301

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time: 10/9/19 5:04pm

Estimated Cost:

Bill to:

OD / FF / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDU 5084S

Insured:

SMA 7348S

at Workshop m/s

T.W. Lim

Tel:

9740 9067

of

160 Sin Ming Drive # 08-12

Policy No:

DMPCSN32518119000

Claim No:

SNM19D264250C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:23am 11/9/19

Person Contacted:

Mr. Lim

Vehicle

IN OUT

Date/Time	Action/Instruction
	1st time 11/9/19 X
	SDU 5084S - X
	SMA 7348S - X
	Dismantle: 16/9/2019
	After repair: 23/9/2019

PRS

ASSIGNMENT

From: Date: 16/9/19

Veh No: SDU 5084S Yr Regn: AUG T 2006

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SDU 5084S
at Workshop n/s T.W. Lim Motor
of 160 Sin Ming Drive #08-12

Make: MITSUBISHI Grandis c.c 2378

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 215245 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: JMYLRNA4W6Z002272 *

Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt

Steering: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Brake: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Modi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size: F: 215/60 R16 (westlake)

R: 215/60 R16 (Yokohama)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: After 10cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{wp}

Vehicle: IN / OUT

Date: Person Contacted:

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 09/09/2019 D.O.I. 16/09/19

Survey held at T.W. Lim Motor

Des. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$3000-\$4000
	Repair days: 5 days
	<i>[Signature]</i>
	19/9/2019
	MV: \$14000
	PV: \$10468
	NV: \$3000

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: PRS

Lump Sum / LBL: (\$)

190

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Sep 2019		26 Sep 2019 17:58 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	HEAH CHOON THYE PHILIP, ID: S1652850A
Vehicle Reg. No.:	SDU5084S
Date of Loss:	09/09/2019 10:00 - :59
Claim Type:	TP / SNM19D204250C02
Policy/Cover Note No.:	DMPCSN30518119000
Vehicle Reg. No. (Insured):	SMA7348S
Policy No. (Claimant):	19-MJ001316-R01
Excess:	S\$0.00
Repairer:	T.w. Lim Motors Works (HQ) 160 Sin Ming Drive, #08-12 Sin Ming Autocity, 575722 Sin Ming - Tel: 97409067
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 07/10/2019]

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 10 September 2019 5:04 PM
To: pauline@oraclelaw.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D204250-SMA7348S-CBS - OLC REF: SB/PO/Acc/2019-9116
// CNTP REF: INSURER OF SMA 7348S - PRE-REPAIR NOTIFICATION

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, 10 September, 2019 3:11 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow
<sochow.chee@sg.cntaiping.com>; pauline@oraclelaw.sg

Subject: OUR REF: SNM19D204250-SMA7348S-CBS - OLC REF: SB/PO/Acc/2019-9116 // CNTP REF:
INSURER OF SMA 7348S - PRE-REPAIR NOTIFICATION

Dear Boon Sen,

Please conduct PRS for SDU5084S.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Pauline Ong [<mailto:pauline@oraclelaw.sg>]

Sent: Tuesday, 10 September, 2019 11:13 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OLC REF: SB/PO/Acc/2019-9116 // CNTP REF: INSURER OF SMA 7348S - PRE-REPAIR NOTIFICATION

IMMEDIATE ATTENTION

Dear Sirs

ACCIDENT INVOLVING SDU 5084S & SMA 7384S ON 9.9.2019

Please refer to attachment to find a copy of our letter of even date for your immediate attention and action.

Regards

Pauline Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11

The Alexcier, Singapore 159929

Telephone: 6538 6250 Facsimile: 6538 1860

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 2009045722

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg

FACSIMILE TRANSMISSION

EMAIL : claimsdept@sg.cntalping.com

To :	China Talping Insurance (S) Pte Ltd	Date :	10 th September 2019
Attention :	Motor Claims	From :	Mr Stanley Bay / Miss Pauline Ong
Your Ref. :	Insurer of SMA 7348S	Our Ref. :	SB/PO/Acc/2019-9116
Facsimile :	6224-7175 / 6224-7478	No. of Pages :	6 (including this page)

IMMEDIATE ATTENTION

Dear Sirs

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SDU 5084S & SMA 7348S AT TRAFFIC JUNCTION OF JALAN AHMAD IBRAHIM AND JALAN BOON LAY ON 9.9.2019


We act for the owner of vehicle registration no. **SDU 5084S**.

We are instructed by our client to notify you of the above accident involving our client's said vehicle and your insured's vehicle registration no. **SMA 7348S** driven at the material time. A copy of our client's Singapore Accident Statement is enclosed herein.

As a result of the above accident, our client's said vehicle has been damaged. Before our client proceeds to repair his damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client's shall proceed to repair his said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our client's right nor shall it be deemed as a waiver of any of his rights, as such our client's rights are expressly reserved.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong
Enc

Details of Workshop

T.W. Lim Motors Works
160 Sin Ming Drive
#08-12 Sin Ming Autocity S(575722)
Tel No : 9740-9067 (hp) – Lim Tau Wing
Fax No. 6457-2371

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 16:01
Date Of Accident	09/09/2019 10:15
Exact Location Of Accident	TRAFFIC LIGHT TURN RIGHT TO JALAN BOON LAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDU5084S
Insured/Policyholder	
Name Of Registered Owner	HEAH CHOON THYE PHILIP
NRIC No	S1652850A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93879988
Alternative Phone No	OFFICE-93879988

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	GRANDIS-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	19-MJ001316-R01
Cover Note Number	

Driver

Name of Driver	HEAH PENG HONG
NRIC No	S0161467C
Date Of Birth	31/03/1954
Occupation	OUTDOOR
Date Of Driving Pass	18/04/1978
Driving Experience	41 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97858366
Fax Number	
Contact Number	
EEmail Address	HEAHPH@GMAIL.COM

Address	BLK 126A KIM TIAN ROAD #25-507
Postcode	161126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA7348S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AZALI BIN AZIZ
NRIC/Passport Number	S1266309I
Contact Number	92389210
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: - 9 SEP 2019

15 28

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Today, 9th Sep 2019, at around 10.18am. I stopped my car, SOU 5044S, in a queue for green traffic light to make a right-turn to Jalan Boon Lay, along Jalan Ahmad Ibrahim, which is parallel to AYE. A car, driven by Mr Azali Bin Aziz, car number SMA 7348S, knocked into my rear, causing some damage to my car. His icc is S1266309i.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature HEAH PENG HONG

(If driver is not the policyholder)

Date & Time: 9th Sep 2019

1528 L.

NRIC: S0161467C

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	850A

Vehicle Details

Vehicle No.:	SDU5084S
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	GRANDIS2.4SR
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	4G69LX2940
Chassis No.:	JMYLRNA4W6Z002272
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$24,568.00
Original Registration Date:	21 Aug 2006
First Registration Date:	21 Aug 2006
Transfer Count:	0
Actual ARF Paid:	\$27,025.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	20 Aug 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$27,232.00
COE Rebate Amount:	\$10,468.00
Total Rebate Amount:	\$10,468.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Sep 2019

Remaining : 7 years 11 months 11 days (23.3)

Depri : \$7500/yearly \$625/monthly

$23.3 \times \$625 = \14000

OK



**Stop herding packets.
Start managing apps.**
Learn how by reading the EMA report

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Toyota Vios 1.5A E (New 5-yr COE).



2.88% p.a. Annual, \$408
Monthly, \$10 Admin Fee, 2 Years
Warranty
GV Credit Pte Ltd [View](#)



**Lake View
Credit Pte Ltd**

[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by Date Posted

20 results/page

5 vehicles

Mitsubishi Grandis

Search Selection

Mitsubishi Grandis

Any

Any

Any

Any

Any

Any

Available



**Mitsubishi Grandis 2.4A (COE
till 04/2021)**

\$11,500

\$7,270 /yr

18-Apr-2006

2,378 cc

-

MPV

Available

Well-Kept By Owner. Worth The Buy.

Posted: 08-Sep-2019

Tags: 2006 Mitsubishi Grandis, 2006 mitsubishi grandis, Mitsubishi Grandis, mitsubishi grandis, Mitsubishi, Grandis, grandis, Used Mitsubishi

DIRECT OWNER



**Mitsubishi Grandis 2.4A Sports
Gear (COE till 08/2023)**

\$25,700

\$6,530 /yr

26-Aug-2008

2,378 cc

-

MPV

Available

1 Owner, Spacious 7 Seater With New Leather Seat, Serviced Regularly. Accident Free. Engine And Gearbox Still In Good Condition. STA Evaluation Are Welcome Before Purchase. 100% Loan Available. Various In-house Loan Package Available With Attractive Interest Rate....

Posted: 30-Aug-2019

Tags: 2008 Mitsubishi Grandis, 2008 mitsubishi grandis, Mitsubishi Grandis, mitsubishi grandis, Mitsubishi, Grandis, grandis, Used Mitsubishi



**Mitsubishi Grandis 2.4A Sports
Gear (New 5-yr COE)**

\$40,800

\$8,150 /yr

14-Sep-2009

2,378 cc

100,500 km

MPV

Available

Malay Owner. 8 Seaters MPV. Car In Very Good Condition. 6 Months Warranty Engine And Gearbox. Clean And Neat Interior. Full Loan Available! Trade In Welcome. Please Call For Viewing Now!

Posted: 14-Sep-2019

Tags: 2009 Mitsubishi Grandis, 2009 mitsubishi grandis, Mitsubishi Grandis, mitsubishi grandis, Mitsubishi, Grandis, grandis, Used Mitsubishi

PREMIUM ED



**Mitsubishi Grandis 2.4A Sports
Gear (New 10-yr COE)**

\$57,800

\$5,780 /yr

05-Oct-2009

2,378 cc

154,915 km

MPV

Available

Rare 7 Seaters MPV, Lowest In The Market. Genuine Low Mileage, Serviced Regularly. Accident Free. Well-preserved Interior, Good Paintwork. Engine And Gearbox Still In Good Condition. STA Evaluation Are Welcome Before Purchase. 100% Loan Available. Various In-hous...

Posted: 14-Sep-2019

Tags: 2009 Mitsubishi Grandis, 2009 mitsubishi grandis, Mitsubishi Grandis, mitsubishi grandis, Mitsubishi, Grandis, grandis, Used Mitsubishi



Goldbell Engineering Pte Ltd (Mitsubishi Fuso) - New Car Dealers

Goldbell Engineering has been the authorised distributor of Mitsubishi Fuso trucks and buses in Singapore since the 1981

More info about this shop



**Mitsubishi Grandis 2.4A Sports
Gear Sunroof**

\$25,500

\$10,260 /yr

06-Sep-2010

2,378 cc

100,000 km

MPV

Available

Superb Condition! Car Rental Welcome.

Posted: 31-Aug-2019

Tags: 2010 Mitsubishi Grandis, 2010 mitsubishi grandis, Mitsubishi Grandis, mitsubishi grandis, Mitsubishi, Grandis, grandis, Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2019		26 Sep 2019 17:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: HEAH CHOON THYE PHILIP , ID: S1652850A									
Vehicle Reg. No.: SDU5084S		Date of Loss: 09/09/2019 10:00 - :59 [156 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D204250C02		Policy/Cover Note No.: DMPCSN30518119000							
Vehicle Reg. No. (Insured): SMA7348S		Policy No. (Claimant): 19-MJ001316-R01							
		Excess: S\$0.00							
Repairer: T.w. Lim Motors Works (HQ) 160 Sin Ming Drive, #08-12 Sin Ming Autocity, 575722 Sin Ming - Tel: 97409067									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 07/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDU5084S (SNM19D204250C02)**
[SMA7348S]

TP
HEAH CHOON THYE PHILIP
Sep 9 2019 10:00AM
[-]
T.w. Lim Motors Works

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports























































1 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 17:49	Accident Statement		Load HTM	
2	10/09/19 12:17	Addendum Sheet		Load TIF	
3	10/09/19 12:18	Accident Statement Addm. #1		Load HTM	

Photos/Images

3 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 17:48	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
2	09/09/19 17:48	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
3	09/09/19 17:48	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/09/19 16:48	General View		Load JPG	
2	27/09/19 16:48	General View		Load JPG	
3	27/09/19 16:48	General View		Load JPG	
4	27/09/19 16:48	General View		Load JPG	
5	27/09/19 16:48	General View		Load JPG	
6	27/09/19 16:48	General View		Load JPG	
7	27/09/19 16:48	General View		Load JPG	
8	27/09/19 16:48	General View		Load JPG	
9	27/09/19 16:48	General View		Load JPG	
10	27/09/19 16:48	General View		Load JPG	
11	27/09/19 16:48	General View		Load JPG	
12	27/09/19 16:48	General View		Load JPG	
13	27/09/19 16:48	General View		Load JPG	
14	27/09/19 16:48	General View		Load JPG	
15	27/09/19 16:48	General View		Load JPG	
16	27/09/19 16:48	General View		Load JPG	
17	27/09/19 16:48	General View		Load JPG	
18	27/09/19 16:48	General View		Load JPG	
19	27/09/19 16:48	General View		Load JPG	
20	27/09/19 16:48	General View		Load JPG	
21	27/09/19 16:48	General View		Load JPG	
22	27/09/19 16:48	General View		Load JPG	
23	27/09/19 16:48	General View		Load JPG	
24	27/09/19 16:48	General View		Load JPG	
25	27/09/19 16:48	General View		Load JPG	
26	27/09/19 16:48	General View		Load JPG	
27	27/09/19 16:48	General View		Load JPG	
28	27/09/19 16:48	General View		Load JPG	
29	27/09/19 16:48	General View		Load JPG	
30	27/09/19 16:48	General View		Load JPG	
31	27/09/19 16:48	General View		Load JPG	
32	27/09/19 16:48	General View		Load JPG	
33	27/09/19 16:48	General View		Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
34	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
35	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
36	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
37	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
38	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
39	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
40	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
41	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
42	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
43	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
44	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
45	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
46	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
47	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
48	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
49	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
50	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
51	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
52	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
53	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
54	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
55	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
56	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
57	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
58	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
59	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
60	27/09/19 16:48	General View		Load JPG	<input checked="" type="checkbox"/>
61	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
62	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
63	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
64	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
65	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
66	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
67	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
68	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
69	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
70	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
71	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
72	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
73	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
74	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
75	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
76	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
77	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
78	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
79	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
80	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
81	27/09/19 16:49	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
82	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
83	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
84	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
85	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
86	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
87	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
88	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
89	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
90	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
91	27/09/19 16:50	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 17:49	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]		Load TIF	
2	09/09/19 17:49	DRIVER'S NRIC, DRIVING LICENCE + VOCATIONAL LICENCE [Linked Accident Report Documents]		Load TIF	
3	10/09/19 12:18	Sketch Plan [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 17:49	Accident Statement		Load HTM	
2	10/09/19 12:17	Addendum Sheet		Load TIF	
3	10/09/19 12:18	Accident Statement Addm. #1		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 17:48	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	09/09/19 17:48	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	09/09/19 17:48	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 17:49	CERTIFICATE OF INSURANCE		Load TIF	
2	09/09/19 17:49	DRIVER'S NRIC, DRIVING LICENCE + VOCATIONAL LICENCE		Load TIF	
3	10/09/19 12:18	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19016125/FCD3E2

Date: 04/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30518119000
Claimant Vehicle No :	SDU5084S	Insured Vehicle No :	SMA7348S
Date of Loss:	09/09/2019	Nature of Claim: TP	Claim No: SNM19D204250C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDU5084S	Engine No:	4G69LX2940
Make & Model:	MITSUBISHI GRANDIS, 2.4 (A)	Chassis No:	JMYLRNA4W6Z002272
Reg. Date:	21/08/2006 (Man. Year: 2006)	Odometer:	215245 km
Colour:	Silver		
Engine Capacity:	2378 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	26/09/2019	
Date Inspected:	16/09/2019 Inspected At:	T.w. Lim Motors Works (HQ) 160 Sin Ming Drive, #08-12 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2019)

Parts: M1-MPV MITSUBISHI GRANDIS 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDU5084S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >