

ASS. REC. BY

REF:

CS3/ALG19016136/Fcd301

Special Instruction:

Surveyor: Ram

Manman

ASSIGNMENT (Office)

From (Person): Chin Lee Yeng

of

ALG

Date/Time: 11/9/19 @ 10.57am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMM 1824R

Insured:

SLH 9132J

at Workshop m/s

LSM Lynston Motor

Tel:

9727 7987

of

25 Kaki Bukit Road 4 # 05-66/68 synergy

Policy No:

2100490635

Claim No:

434755153486

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1223pm @ 11/9/19

Person Contacted:

Mr. Henry

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Estimate (X)
	SMM 1824R - X
	SLH 9132J - X
	Dismantle: 11/9/2019
	After repair: 18/9/2019

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMM 4824R

at Workshop n/s LSM LYNSTON motor
of 25 KAKI BUKIT RD 4#05-66/68

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SMM 4824R

Yr Regn: JUN / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Freed hybrid C.C 1496

Colour white A/C: Insured / Std / NI / NA

Sp. Reading 013304 T/Radio: Insured / Std / NI / NA

Eng/No: ✓

C/No: GB7-1091138

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 / 65 R15

R: 185 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 08/09/2019 D.O.I. 11/09/2019

Survey held at LSM LYNSTON MOTOR

Des. of Damages: Frt Rear O/S / N/S / U/C / Rooftop or
rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair days: 5 days

Range: \$3000 - \$4000

MV: \$100000

PV: \$52755

NV: \$47000

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: DAR

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

) 3 + RS, \$

) Photos

) Others

) TOTAL

180

11

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Sep 2019 Edit Reg		11 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIM WAH HONG (LIN HUAFENG), ID: S7835026A		
Main Claimant:	E-CUBE VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201607761H		
Vehicle Reg. No.:	SMM4824R	Date of Loss:	08/09/2019 11:00 - :59
Claim Type:	TP / 4347551534SG	Policy/Cover Note No.:	2100490635 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH9132J	Policy No. (Claimant):	
		Excess:	
Repairer:	Lsm Lynston Motor & Spray Works (HQ) 25 KAKI BUKIT ROAD 4 #05-66/68 SYNERGY@KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 20/09/2019]		
Claimant's Solicitor:	Ap Law Practice		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (12/09/2019): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 4 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 9/11/2019 10:57:32 AM

Attachments:  LETTER TO 3P AND AIG.PDF  GIA REPORT SMM4824R.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: sengtata@aplp.com.sg [mailto:sengtata@aplp.com.sg]

Sent: Tuesday, September 10, 2019 3:10 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; sengtata@aplp.com.sg

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLH9132J AND SMM4824R ON 08/09/2019

WITHOUT PREJUDICE

Dear Sir/ Mdm,

We refer to your FAX of even date.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong

- f. Sincere Appraiser
- g. Seah Kwang Boon
- h. L H Teo
- i. Mr Willy Goh
- j. Nicky Seah
- k. Jayson Liaw

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

In the event you are not agreeable to our list of surveyor, please note that our client's vehicle can be inspected at:

LSM Lynston Motor & Spray Works

25 Kaki Bukit Road 4
#05-66/68 Synergy@KB
Singapore 417800

Contact Person: Mr Henry (9727 7987)

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	761H
Vehicle Details	
Vehicle No.:	SMM4824R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	LEB5629990
Chassis No.:	GB71091138
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$26,357.00
Original Registration Date:	28 Jun 2019
First Registration Date:	28 Jun 2019
Transfer Count:	1
Actual ARF Paid:	\$18,900.00 $\times 50\% = \underline{\$9450}$
Intended PARF Rebate Details	
PARF Eligibility:	Yes ✓
PARF Eligibility Expiry Date:	27 Jun 2029
PARF Rebate Amount:	\$14,175.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$41,000.00
COE Rebate Amount:	\$38,580.00
Total Rebate Amount:	\$52,755.00

The information contained herein is correct as at 12 Sep 2019

Remaining: 9 years ⁹ months 19 days (117.6) OK
depr: \$9300/yearly (\$775/monthly)
 $117.6 \times \$775 = \91140
 $\underline{\$91140 + \$9450 = \$100590}$



LIMITED TIME OFFER

1GBPS FIBRE BROADBAND
AT \$39.90/MONTH

FREE 1 MONTH

SIGN UP NOW



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are
Welcome, 100% Deposit Refund
For Unapproved Loan,
Classic Credit StarAd



Browse by Category

Sort by Date Posted

20 results/page

11 vehicles

Honda Freed

Advanced Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection

Honda Freed Any Any 2019 Any Any Any Available



Honda Freed Hybrid 1.5A G

\$100,800

\$9,590 /yr

14-Feb-2019

1,496 cc

256 km

MPV

Available

Fuel Type: Petrol-Electric

1 Owner, Consigning Due To Upgrade, Finance Available, Trade-In Welcome. Call To Enquire Now.

Tan Wei Auto Pte Ltd

Posted: 08-Sep-2019 Tags: 2019 Honda Freed, 2019 honda freed, Honda Freed, honda freed, Honda, Freed, freed, Used Honda



Honda Freed Hybrid 1.5A G
Honda Sensing

\$96,800

\$9,190 /yr

27-Feb-2019

1,496 cc

100 km

MPV

Available

Fuel Type: Petrol-Electric

New Car! Cheapest In The Market, Trade In Welcome, Comes With Honda Sensing Features For The Safety Of All Passengers. Affordable.

Iaxis

Posted: 07-Sep-2019 Tags: 2019 Honda Freed, 2019 honda freed, Honda Freed, honda freed, Honda, Freed, freed, Used Honda



Honda Freed Hybrid 1.5A G
Honda Sensing

\$102,988

\$9,350 /yr

06-Sep-2019

1,496 cc

50 km

MPV

Available

Fuel Type: Petrol-Electric

The New Honda Freed Is The Best Compact 7 Seater 1.5L MPV You Can Get In The Market, Japan Domestic Model, Deliver Immediately. High Trade In Your Existing Car. Flexible Loan Available, Call Us Now For More Information.

TTS Eurocars

Posted: 06-Sep-2019 Tags: 2019 Honda Freed, 2019 honda freed, Honda Freed, honda freed, Honda, Freed, freed, Used Honda



Honda Freed Hybrid 1.5A G
Honda Sensing

\$99,800

\$9,380 /yr

24-Apr-2019

1,496 cc

7,505 km

MPV

Available

Fuel Type: Petrol-Electric

Smell Like A Brand New Car! 7 Seater MPV! Low Deprecation! Bank & In-House 100% Loan Are Available At Low Interest Rate! Still Under Warranty + Free Servicing For An Added Peace Of Mind! No Repairs Needed! High Trade-In Are Welcome! 100% Accident Free! View To...

Starise Automobile

Posted: 05-Sep-2019 Tags: 2019 Honda Freed, 2019 honda freed, Honda Freed, honda freed, Honda, Freed, freed, Used Honda



Honda Fabric Safety Belt Cover (Black)

Honda Fabric Safety Belt Cover (Black)

More info about this product



Honda Freed Hybrid 1.5A G

\$93,800

\$9,070 /yr

11-Jan-2019

1,496 cc

6,500 km

MPV

Available

Fuel Type: Petrol-Electric

Showroom Condition With Attractive Interior. Perfect For Big Families Or With Kids. Good Fuel Economy With Spacious And Comfortable Interior. 100% Loan Available Coupled With Competitive Interest Rates. Do Call Our Professional Sales Consultant For A Non Obligation...

MS Carz

Posted: 02-Sep-2019 Tags: 2019 Honda Freed, 2019 honda freed, Honda Freed, honda freed, Honda, Freed, freed, Used Honda

Honda Freed Hybrid 1.5A G
Honda Sensing

\$111,888

\$10,550 /yr

09-May-2019

1,496 cc

22 km

MPV

Available

Fuel Type: Petrol-Electric

PREMIUM AD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2019 09:37
Date Of Accident	08/09/2019 11:55
Exact Location Of Accident	ALONG JALAN BESAR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM4824R
Insured/Policyholder	
Name Of Registered Owner	E-CUBE VEHICLE RENTAL PTE LTD
Co Reg No	201607761H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82827673
Alternative Phone No	OFFICE-82827673

Vehicle Particulars

Manufacturer	HONDA
Model	FREED
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106778237
Cover Note Number	

Driver

Name of Driver	CHONG SZE WEI
NRIC No	S7642255I
Date Of Birth	26/12/1976
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1997
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82827673
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 124 BEDOK NORTH ROAD #08-143
Postcode	460124
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH9132J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2



A: SMM4824R

B: SLH91323

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8th Sep 2019 at 1155am, I stopped my vehicle SMM4824R along Jalan Besar Road before the junction of Jalan Besar Road and Kitchener Road due to red traffic light. Suddenly, I felt an impact from behind. I turned my head around and realised I have been ~~very~~ hit from behind by another vehicle (SLH91323).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	SCX		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	rec		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	rec		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	Short		
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	aa		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BXC		
1182	991328	Tailgate Emblem	NEC		
1183	994643	Tailgate Outer Handle	SCX		
1184	994640	Tailgate Moulding	SCX		
1185	994545	Tailgate Garnish	SCX		
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	CRA		
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC		
1196	994607	Tailgate Glass Sealant	NEC		
1197	994629	Tailgate Lock	157		
1198	994651	Tailgate Rubber	CRA		
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	CRA		

Vehicle No: 5MM 484R

NAC	INC	Item	CON	A
1202	993784	Spare Tyre Board		
1203	994328	Spare Tyre Panel		
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim		
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender		
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim		
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993401	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019 Edit Reg		11 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIM WAH HONG (LIN HUAFENG), ID: S7835026A		
Main Claimant:	E-CUBE VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201607761H		
Vehicle Reg. No.:	SMM4824R	Date of Loss:	08/09/2019 11:00 - :59 [2 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4347551534SG	Policy/Cover Note No.:	2100490635 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH9132J	Policy No. (Claimant):	
		Excess:	
Repairer:	Lsm Lynston Motor & Spray Works (HQ) 25 KAKI BUKIT ROAD 4 #05-66/68 SYNERGY@KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 20/09/2019]		
Claimant's Solicitor:	Ap Law Practice		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (12/09/2019): TP GIA REPORT











































ALL ASSOCIATED TASKS



















[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMM4824R (4347551534SG)
[SLH9132J]
TP
E-CUBE VEHICLE RENTAL PTE LTD
Sep 8 2019 11:00AM
[LIM WAH HONG (LIN HUAFENG)]
Lsm Lynston Motor & Spray Works

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print
1	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
2	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
3	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
4	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
5	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
6	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
7	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
8	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
9	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
10	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
11	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
12	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
13	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
14	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
15	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
16	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
17	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
18	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
19	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
20	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
21	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
22	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
23	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
24	17/09/19 12:18	General View									 Load JPG	<input checked="" type="checkbox"/>
25	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
26	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
27	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
28	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
29	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
30	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
31	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
32	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
33	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
34	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
35	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
36	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
37	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
38	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
39	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
40	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
41	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
42	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>
43	17/09/19 12:18	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	17/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	20/09/19 09:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/09/19 10:42	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19016136/FCD3E2

Date: 23/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100490635
Claimant
Vehicle No : SMM4824R **Insured Vehicle No :** SLH9132J
Date of Loss: 08/09/2019 **Nature of Claim:** TP **Claim No:** 4347551534SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM4824R
Make & Model: HONDA FREED, 1.5 (A) **Engine No:** LEB5629990
Reg. Date: 28/06/2019 (Man. Year: 2019) **Chassis No:** GB71091138
Colour: White **Odometer:** 13304 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 **Rear Tyre Size:** 185/65 R15
Front Left Side: Yokohama 5 mm **Rear Left Side:** Yokohama 5 mm
Front Right Side: Yokohama 5 mm **Rear Right Side:** Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/09/2019
Date Inspected: 11/09/2019 **Inspected At:** Lsm Lynston Motor & Spray Works (HQ)
25 KAKI BUKIT ROAD 4 #05-66/68
SYNERGY@KB
Singapore 417800

Estimated Period of Repair: 5.0 days**Adjuster:** PARASURAM SHANMUGAM**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
7	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
8	1		*TAILGATE	Buckled	0.00 F	*- F
9	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE LAMP	Cracked	0.00 F	*- F
11	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
12	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
13	1		*TAILGATE LOCK	Bent	0.00 F	*- F
14	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
15	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >